Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 9026 3 Mayfield Grove Block 1-3 Mayfield Grove, Harrogate

Cover Sheet

Photo



Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

10 Aug 2023

10 Aug 2024

12

Annual Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Kevin Jones

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name Mayfield Grove

Scheme Address 3 Mayfield Grove Block 1-3 Mayfield Grove,

Harrogate

Postcode HG1 5HD

Region North East

Scheme Manager

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority North Yorkshire

Other staff in attendance None

Number of on-site Accent staff Scheme Manager Weekdays

Number of other (non-Accent) staff

None

The Building

Accommodation Type General Needs (S30)

Build Date Jan 1 2006

Number Of Homes 3

Homes breakdown Flat

External wall construction Facing Brick

External wall finish Artificial/Natural Stone

Roof construction Timber

Roof covering Flat Roof, Slate Pitched

PEEPs in place where necessary N/A

Current Evacuation Strategy Full (Simultaneous) Evacuation

Conversion or purpose-built Conversion

Number of storeys 3

Number of floors on which car parking is provided 1

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

1 not protected

Number of External Staircases None

External Balcony part of escape route? N/A

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

Flats and common areas not linked Fire Detection and Warning System Grade E Grade of fire alarm Category of fire alarm LD3 Minimum Protection Maintained system - Common areas **Emergency Lighting Provision** Portable Fire Extinguishers supplied/fitted No Fixed Fire Fighting Installations No **Customers** 4 Number of occupants **General Needs** Occupant tenure type breakdown Fire Safety Related Customer Safety Servicing Overdue communal gas safety checks 0 0 Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 Overdue communal PAT testing 0 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests 1 Overdue Annual Emergency Lighting tests 1 0 Overdue Weekly Fire Alarm Testing Overdue Fire Panel - Six Monthly Testing Overdue Fire Safety Equipment tests **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors Communal Fire doors due for replacement within 5 years 0 **Dwelling Doors** 0 Failing Dwelling Fire Doors

3 Mayfield Grove Block 1-3 Mayfield Grove, Harrogate

Dwelling Fire doors due for replacement within 5 years

Asset ID: 9026

0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



Date of Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Risk Assessment

Quantity

Fire & Safety Assessor

Enforcing Fire Authority

Scheme Tel. No

Other staff in attendance

Number of on-site Accent staff

Number of other (non-Accent) staff

Scheme Inspection completed

Number of occupants

Personal Emergency Evacuation Plans in place

Current Evacuation Strategy

Conversion or purpose-built

Number of Storeys

Number of floors on which car parking is provided

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

Number of external staircases

External balcony part of escape route?

Unusual features

10/08/2023

12

Annual Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

1

Kevin Jones

North Yorkshire

None

Scheme Manager Weekdays

None

Yes

4

N/A

Full (Simultaneous) Evacuation

Conversion

3

1

No

1 not protected

None

N/A

None

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Residential

Fire Detection and Warning System Flats and common areas not linked

Grade of Fire Alarm Grade E

Category of Fire Alarm LD3 Minimum Protection

Emergency Lighting Provision Maintained system - Common areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted No

Water Extinguisher(s) present No

Foam Extinguisher(s) present No

Dry Powder Extinguisher(s) present

Carbon Dioxide Extinguisher(s) present No

Fire Blanket(s) present

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no

obvious damage?

Comment Appears to be safe and working

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment Uploaded to Active H

Electrical App/PA Testing - tested within past 12 months?

N/A

Comment No portable appliance identified during assessment

Yes

Yes

Absence of trailing leads and adapters?

Comment None identified

Evidence that mobility scooters are not being stored/charged in No

common areas?

Comment None identified during assessment

Is there a purpose built mobility scooter store/charging area?

Asset ID: 9026 3 Mayfield Grove Block 1-3 Mayfield Grove, Harrogate

Comment

Does the building have a lightning protection system? No

Gas installations

Is there a commercial/domestic gas supply to the scheme?

Comment

Comment

No

Yes

No

No

No

Not required for this property

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered

to?

Comment Communal areas only

Adequate security against arson? Yes

Comment Doors locked with Yale type locks to prevent

unauthorized entry

Are refuse/recycling bin areas managed and suitably located?

Comment Refuse bins are stored in the front garden very close

to front windows. HP informed to relocate bins.

Are there communal cooking facilities at this scheme?

Comment

Housekeeping

Are all electrical/intake/service cupboards secure and free from general

waste, contractors waste and and residents personal items?

Comment Electrical intake cupboard is located in the rear yard

which is in poor repair and not secured

Are unnecessary accumulations of combustible materials or waste

avoided?

Comment General houshold rubbish left on 2nd floor landing

outside flat entrance door.HP informed to gave

cleared. Yes

N/A

Are combustible materials and substances separated from ignition

sources and stored appropriately?

Comment Clear corridors and stairway no storage cupboards

in communal areas.

Furniture/furnishings in good condition, fire retardant/resistant and

comply with modern standards and regulations?

Comment None provided in communal areas

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Comment

Yes

Yes

Yes

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of

escape in case of fire?

Comment Single stair and corridor

Escape routes unobstructed and safe to use?

Comment Clear and unobstructed throughout the premise

Exits immediately openable without a key and/or failsafe's function Yes

correctly?

Comment Front door fitted with Yale night latch type door

Reasonable distances of travel where there is a single/alternative Yes

direction of travel?

Comment Minimal distance to travel

Escape routes lead to final exits and open in direction of escape where

necessary?

Comment Single direction route

Observation Priority Referred To Required By: Task ID

Flat entrance doors appear in good condition

No Action



Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?

oprodu (Wallo, Hoore, collinge).

Comment

Yes

Traditional construction with plaster finish. Small holes in 1st floor ceiling, repair requested.

Yes

Plaster finish

3 Mayfield Grove Block 1-3 Mayfield Grove, Harrogate Asset ID: 9026

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?

Comment

As far as can be reasonably ascertained, is the compartmentation

within roof spaces of a satisfactory standard?

Comment Unable to assess roof space loft hatch inside flat

accomodations

N/A

N/A

N/A

Yes

Yes

N/A Loft hatches fire resisting?

Comment Unable to access loft hatch within flat

accomodations

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory

standard?

No cross corridor doors identified Comment

Do external walls, doors, windows and anything attached to the

exterior, limit fire spread?

Comment Traditional construction

If Smoke Control Systems (AOV's) are fitted, are the records of annual

testing available?

Comment Uploaded to Active H

N/A Are roller shutter doors that are required to be FR, fire resisting and

self-closing?

None fitted Comment

Observation **Priority** Referred To Required By: Task ID

Refuse in rear garden HP requested to deal with.



Housing Partner

14/09/2023

1698718



Yes

Yes



Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per current standards?

Comment

Emergency lighting units in good condition and securely fixed to walls/ceilings?

Appears to be safe and fitted correctly Comment

Records of monthly/annual testing available? Yes

MIS-AMS ActiveH - Fire Risk Assessment Report Page 8 of 14

Generated 11/08/2023 16:04:26

Appears to be safe and fitted correctly

Comment Uploaded to Active H

Observation Priority Referred To Required By: Task ID

Emergency lighting appears in good condition

No Action



Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent

Yes

locations within the common areas?

Comment

Directional fire escape signage in place and adequate?

Comment Throughout the premise

Is there suitable LIFT signage i.e. do not use in case of fire?

Comment

Do common area fire doors display the correct signage on both sides

where applicable?

Comment

Observation Priority Referred To Required By: Task ID

Yes

Evacuation signs refitted during FRA No Action



Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?

Comment

3 Mayfield Grove Block 1-3 Mayfield Grove, Harrogate Asset ID: 9026

Is fire detection and warning system appropriate for occupancy and fire

risk, as per BS 5839-1:2017?

Comment

Is the fire detection and warning system maintained/tested and all

certificates saved on file?

Results uploaded to Active H Comment

Fire alarm components in good condition and securely fixed to

walls/ceilings?

Appears to be safe and fitted correctly Comment

Hold open devices operate at the sounding of the alarm and are in a

serviceable condition?

None identified Comment

Are there heat detectors located in the Kitchen, Boiler, Plant Room and

Laundry?

Unable to verify no access to flats Comment

Is the fire alarm panel remotely monitored, and if so are there records of

regular testing?

No alarm panel fitted Comment

Observation **Priority** Referred To Required By: Task ID

Detector heads in good order

No Action





Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme?

Comment

No

Yes

Yes

Yes

Yes

Yes

N/A

Yes

No

Management of Fire Safety

MIS-AMS ActiveH - Fire Risk Assessment Report

Are these premises regulated by the Building Safety Regulator under

the Building Safety Act?

Comment

Will this FRA be shared will all Accountable Persons for the premises?

Comment

Page 10 of 14

Uploaded to Active H

Generated 11/08/2023 16:04:26

3 Mayfield Grove Block 1-3 Mayfield Grove, Harrogate Asset ID: 9026 Uploaded to Active H How will this sharing be achieved? Are there other Responsible Persons who share or have fire safety No duties in respect of the premises? How will this sharing be achieved? Is an office or IL scheme being inspected? No Comment Passenger Lift Is the scheme fitted with a passenger lift? No Comment **Premises Inspection Box** No Is there a premises information box for fire & rescue service use? Comment **Evacuation Policy** Are there suitable arrangements for summoning the fire service? Yes Occupants dial 999 Comment Taking FRA findings, is the evacuation policy appropriate for the Yes scheme as per latest guidance? Comment

Engagement with Residents

Has information of fire procedures been disseminated to residents?

Comment Induction programme regular communication tools,

customer portal

Is general fire safety information disseminated to residents?

Comment Leafleted during FRA, customer portal and induction

programme

FRA Frequency

Taking the findings of this assessment into account, is the frequency of

the FRA correct?

Comment

Yes

Miscellaneous

No Are there any other observations/actions to raise that are not covered above. Yes Are there fire related remedial works required at this property, that will affect the fabric of the building? Comment **AOV** inoperative Can work be conducted without the need for an asbestos survey. If no, Yes task Customer Safety Surveyor - Asbestos. Comment Yes Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report). No Some fire doors did not fully close so works orders have been raised with our contractors. Yes Some minor works were required which have been raised with our contractors. Unauthorised items were found in communal areas and arrangements Yes were made for their removal. No Not all records were up to date, as noted in the table below. Arrangements have been made for these to be completed.

A number of fire doors were found to be wedged or propped open. Fire

doors are there to keep you safe and me kept shut at all times.

No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW MEDIUM HIGH

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR MAJOR CRITICAL

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial
The Overall Mak Level for this asset is.	