

## ACCENT HOUSING - FIRE RISK ASSESSMENT



<b>Region :</b>	<b>South</b>
<b>Scheme Name :</b>	<b>Chapel Road</b>
<b>Scheme Address :</b>	<b>17-72 Chapel Road Camberley, Surrey GU15 3LT</b>
<b>Date of Assessment:</b>	<b>14/05/2022</b>
<b>Date of Next Assessment:</b>	<b>14/05/2025</b>
<b>FRA Frequency:</b>	<b>3 Year Re-Assessment</b>
<b>Fire &amp; Safety Assessor</b>	<b>Gary Bredin</b>

This Fire Risk Assessment has been conducted upon the instruction of Accent Housing.

Scheme Details		Chapel Road
Region:	South	
Scheme Name:	Chapel Road	
Site Address:	Street:	17-72 Chapel Road
	Town:	Camberley, Surrey
	Post Code:	GU15 3LT
Block & Asset No.	Block 17 - 41 Asset No.24998	
Block & Asset No.	Block 22 - 46 Asset No.24999	
Block & Asset No.	Block 43 - 67 Asset No.25000	
Block & Asset No.	Block 48 - 72 Asset No.25001	
Scheme Tel. No:	-	
Date of this Assessment	14/05/2022	
Date of Next Review	14/05/2025	
Fire Risk Assessment Frequency	3 Years	
Health & Safety Assessment Frequency	-	
Purpose of Fire Risk Assessment	3 Year Re-Assessment	
Fire & Safety Assessor	Gary Bredin	
Director of Customer Experience	-	
Customer Partnership Manager	Kat Wilson	
Contract Manager	Lisa Mitchell	
Scheme Manager/Customer Partner	Zara Byrne	
Other staff in attendance	-	
Use of Building	General Needs	
Approximate Number of occupants	100+	
Occupancy Profile	Families	
Familiarity of the occupants	Slightly Familiar	
Likely state of the Occupants	Alert	
PEEPs in place where necessary	N/A	
Number of on-site Accent staff	None	
Number of other (non-Accent) staff	Contract cleaners in common areas	
Support Agency (Supported Housing)	N/A	
Current Evacuation Strategy.	Stay Put (Delayed) Evacuation	
Evidence that residents have been notified of the evacuation procedure	Advice notices displayed in common areas	
History of fires in the building	None	
Business Continuity Plan in place?	Yes	
Scope of Assessment	Type 3 (Common Parts & Flats - Non Destructive)	
Applicable Fire Safety Guidance	Sleeping Accommodation Guide	
	Purpose-built flats guide	

Building Details	Chapel Road
Construction Date	1962
Construction Type	Concrete Frame
Roof Finish	Pitched-Concrete Tile
External Wall Finish	Brick
Are there any areas of external wall cladding	Yes. Wood G/F small areas.
Are there any balconies	No
Conversion or purpose-built	Purpose Built
Number of flats (self-contained)/rooms (HMOS, shared houses)	32 self contained flats accessed from common area. 19 self contained flats with own entrance.
Number of storeys above ground	Three
Number of storeys below ground	None
Is there a habitable basement?	No
Number of internal Staircases per Block (protected or unprotected?)	One-Protected
Number of External Staircases per Block	None
External Balcony part of escape route?	No
Unusual features	None
Building complexity	Simple
Building Access Conditions for Fire Brigade	Vehicular Access to one or more elevations
Surroundings: Residential/Commercial	Residential
Fire Provision Currently in Place	
Fire Detection and Warning System	Flats only
Grade of fire alarm	Grade D
Category of fire alarm	LD3 Minimum Protection
Additional Comments:	-
Evacuation Alert System (EAS)	N/A
Additional Comments:	-
Emergency Lighting Provision	Non Maintained System - Common Areas
Additional Comments:	
Portable Fire Extinguishers	None fitted
Additional Comments:	
Fixed Fire Fighting Installations	None fitted
Additional Comments:	

Significant Findings - Fire						
Chapel Road					14/05/2022	
Action Ref:	Potential Area of Fire Risk	Yes-No-N/A	Observation/Comments/ Actions Required	Risk Rating	Target Completion Date	Referred To:
<b>Fire Hazards</b>						
<b>1</b>	<b>Electrical Sources of Ignition:</b>					
1.1	Electrical Installation within common areas (Fixed Wiring, sockets, switches, light fittings) in good condition and no obvious damage	Yes	All common area sockets and fittings in a satisfactory condition at the time of inspection.	.		
1.2	Valid Electrical Installation Condition Reports held on file.(Common Areas)	Yes	Commission an electrical safety inspection completed and uploaded to the property file.	.		
1.3	Valid Electrical Installation Condition Reports held on file. (General Needs Flats)	Yes		.		
1.4	Electrical App/PA Testing - all portable appliances tested within past 12 months	N/A	PAT not required, no portable electrical equipment in communal areas	.		
1.5	Absence of trailing leads and adapters	Yes		.		
1.6	Mobility Scooters - Stored/charged in common areas, purpose built store/resident flat	Other	No evidence of any Mobility Scooters being stored or charged on this site at the time of this inspection.	.		
<b>2</b>	<b>Smoking:</b>					
2.1	Are there any risks associated with smoking in the building?	No	No smoking policy within common areas	.		
<b>3</b>	<b>Arson:</b>					
3.1	Adequate security against arson?	No	The front entrance doors to all blocks are easily accessible. Customer Partner to look into the safety measures in place and update if required.	Med	1/12/22	Partnership Manager 2

3.2	Is there an absence of unnecessary fire load in close proximity to building?	Yes	Refuse bin areas provided away from building	.		
<b>4</b>	<b>Heating Installations (Portable/fixed) Gas Installations - Common Areas &amp; General Needs Residential flats.</b>					
4.1	If portable heaters are used, are there suitable controls?	N/A	No portable heaters permitted in communal areas	.		
4.2	Are fixed heating installations subject to regular maintenance?	N/A		.		
4.3	Valid LGSC held on file for each residential flat that contains gas appliances.	Yes	All general needs properties hold valid gas safety reports. No information available for leasehold properties	.		
<b>5</b>	<b>Cooking:</b>					
5.1	Are reasonable measures taken to prevent fires as a result of cooking?	N/A	No communal cooking areas	.		
5.2	Where there is extraction ventilation in communal kitchens are filters changed/cleaned and ductwork cleaned regularly?	N/A		.		
<b>6</b>	<b>Lightning Protection System:</b>					
6.1	Does the building have a lightning protection system, If so, is it adequately maintained?	N/A	According to the lightning protections regulations (as satiated in the RC 35 'Protection of buildings against lightning strikes'), it is not a legal requirement for buildings to be fitted with lightning protection.	.		
<b>7</b>	<b>Housekeeping:</b>					
7.1	Is the standard of housekeeping adequate?	Yes		.		
7.2	Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and residents personal items.	No	Electrical cupboards are being left open by customers. During a fire these will offer little to no protection for persons leaving the building. Customer Partner to deal.	Med	1/7/22	Partnership Manager 2

7.3	Are combustible materials separated from ignition sources and stored appropriately?	No	Gas cylinders are being stored in the means of escape. These were removed to a safe place away from the block by the assessor. Customer partner to speak the the offending customers.	High	1/5/22	Partnership Manager 2
7.4	Are unnecessary accumulations of combustible materials or waste avoided?	Yes		.		
7.5	Are hazardous materials stored appropriately (i.e. oxygen cylinders, flammable materials, explosive products, oxidising products, aerosols)	N/A	No hazardous materials stored on site.	.		
<b>8</b>	<b>Furniture/furnishings on escape routes and other communal areas:</b>					
8.1	Furniture/furnishings in good condition, fire retardant and complies with 1988 Regulations.	N/A	No furniture allowed in the common areas.	.		
<b>9</b>	<b>Other Significant Fire Hazards:</b>					
9.1	Are there other significant fire hazards that are inadequately controlled?	Yes		.		
<b>Fire Protection Measures</b>						
<b>10</b>	<b>Means of Escape from Fire:</b>					
10.1	Is it considered that the building is provided with reasonable means of escape in case of fire?	Yes	Final exit doors in all flats on the means of escape are FD30s and conforming to the latest British Standard.	.		
10.2	Escape routes unobstructed and safe to use?	No	Items are being stored under the stairs in the majority of the blocks. Customer partner to deal.	Med	1/7/22	Partnership Manager 2
10.3	Exits easily and immediately openable where necessary, without a key?	Yes		.		
10.4	Reasonable distances of travel where there is a single/alternative direction of travel?	Yes	All escape routes are within permissible distances some extra signage installed during inspection by	.		
10.5	Escape routes lead to final exits and open in direction of escape where necessary?	Yes		.		

10.6	Do failsafe's on locked exit doors function correctly?	N/A	No locks are fitted to any of the entrance/exit doors	.		
10.7	Is it considered that the building is provided with reasonable arrangements for means of escape for disabled people?	No	Ground floor areas only are suitable for disabled access/egress.	.		
<b>11</b>	<b>Measures to Limit Fire Spread and Development:</b>					
11.1	Is it considered that the compartmentation is of a reasonable standard?	Yes		.		
11.2	Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?	Yes		.		
11.3	Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?	N/A		.		
11.4	Compartmentation within roof spaces of a satisfactory standard?	Yes	The loft fire curtains have been assessed and the loft hatches have been fitted with a tamper proof tag.	.		
11.5	Loft hatches fire resisting?	Yes	Communal area roof hatch's are close fitting and of 1hr fire rated steel construction. Lock missing and hatch screwed shut in block 64-70. Axis 994403	<b>Med</b>	<b>1/12/22</b>	<b>Fire Safety Manager</b>
11.6	Fire stopping above cross-corridor fire doors within suspended ceiling void of a satisfactory standard	N/A		.		
11.7	Smoke Control Systems (AOV's) Are records of annual testing available?	N/A		.		
11.8	Roller shutter doors (fire resisting)	N/A		.		
11.9	Do the external walls, windows, balconies etc pose a risk of significant fire spread?	No		.		
<b>12</b>	<b>Communal Area Fire Doors (Inspection to include - construction, hinges, closure devices, intumescent/smoke seal condition, glazing systems and maximum gaps between door and frame.</b>					

12.1	Communal fire doors to FD30s standard and in a serviceable condition,	No	Most communal fire doors were found to be in good condition and conforming to the latest British Standard. The overhead self closing device in block 50-56 is broken and requires replacing. Axis 994346	Med	1/8/22	Fire Safety Manager
12.2	"Fire door keep shut/locked" signage displayed on both sides of all applicable doors.	Yes	Some signs were missing and were replaced/updated during the inspection.	.		
12.3	Hold open devices operate at the sounding of the alarm and are in a serviceable condition	N/A		.		
<b>13</b>	<b>Flat entrance doors (Internal Common Areas)</b>					
13.1	Do flat entrance doors open onto internal escape routes?	Yes	If yes, see "Residents Front Doors Sheet"	.		
<b>14</b>	<b>Flats with a single direction of escape to a single escape stairway. (External Balcony)</b>					
14.1	Do the flat entrance doors that open onto an external balcony have to be passed during an escape?	N/A	If yes, see "Residents Front Doors Sheet"	.		
14.2	Are the separating walls between the flats and the balcony floor that have to be passed during an escape, fire-resisting up to a height of 1.1m?	N/A		.		
<b>15</b>	<b>Emergency Escape Lighting:</b>					
15.1	Is the emergency lighting correctly specified and installed as per BS 5266-1:2016	Yes	Non-maintained emergency lighting is installed within all escape routes	.		
15.2	Are all emergency lighting units in good condition and securely fixed to walls/ceilings	Yes	All emergency lights fixed to the ceiling and walls.	.		
15.9	Are records of monthly testing available?	Yes	Annual test certs uploaded to P Drive	.		
15.10	Are records of annual testing available?	Yes	Annual test certs uploaded to P Drive - Maintenance program in place	.		
<b>16</b>	<b>Fire Safety Signs and Notices:</b>					



16.1	Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?	Yes	Signage checked and updated during inspection	.		
16.3	Directional fire escape signage in place and adequate?	Yes	Signage checked and updated during inspection	.		
16.4	Is there a suitable LIFT sign i.e. do not use in case of fire.	N/A		.		
<b>17</b>	<b>Means of giving Warning in case of Fire:</b>					
17.1	Is the fire detection and warning system appropriate for the occupancy and fire risk?	Yes	All flats have smoke detection to LD3 standard. An additional heat detector is located in the flats.	.		
17.2	Is the fire detection and warning system correctly specified and installed as per BS 5839-1:2017	N/A		.		
17.3	Is the fire detection and warning system maintained/tested and all certificates saved on file. (BS 5839-1:2017)	N/A		.		
17.4	Are there heat detectors located in the Kitchen, Boiler, Plant Room and Laundry?	N/A		.		
17.5	Is the fire alarm panel remotely monitored, and if so are there records of regular testing?	N/A		.		
17.6	Are smoke/heat detectors within General Needs flats subject to an annual inspection and the results recorded on an in date Landlord Gas Safety Record (LGSR)	Yes	All general needs properties hold valid gas safety reports including conformation of smoke detector testing. No information available for leasehold properties	.		
<b>18</b>	<b>Fire Extinguishing Equipment:</b>					
18.1	Portable fire extinguishers - appropriate type/number/position?	N/A	No Fire Extinguishers on site.	.		
18.2	Correct signage displayed by each fire extinguisher?	N/A		.		
18.3	Fire blanket in communal kitchen, secured to the wall, complete with signage?	N/A		.		

18.4	Hose Reels - fitted, maintained?	N/A	None fitted	.		
18.5	Dry/wet risers - Full access to all inlet/outlet boxes. All inlet/outlets secured and/or securing straps fitted to outlet valves?	N/A	None fitted	.		
18.6	Records available of fire fighting equipment servicing within past 12 months	N/A		.		
<b>19</b>	<b>Management of Fire Safety</b>					
19.1	Are there suitable arrangements for summoning the fire service?	Yes	It is the responsibility of our customers to raise the alarm and call the Emergency Services.	.		
19.2	Do relevant staff carry out regular fire safety checks	Yes	Regular inspections are made by the Customer Partner and any works orders are raised	.		
19.3	Sheltered Schemes & Regional Offices - Are there sufficient number of qualified Fire wardens.	N/A		.		
19.4	Offices - Are there suitable arrangements for ensuring the premises are evacuated?	N/A		.		
19.5	Offices - Are there suitable arrangements for evacuating disabled people?	N/A		.		
19.6	Offices - Are there suitable arrangements for meeting the fire service on arrival and providing relevant information?	N/A		.		
19.7	Offices/IL Schemes - Is there a suitable assembly point?	N/A		.		
19.8	Offices - Are fire drills carried out at appropriate intervals?	N/A		.		
<b>20</b>	<b>Evacuation Policy</b>					
20.1	Taking the findings of the FRA into account, is the evacuation policy appropriate for the scheme?	Yes	Stay put (delayed) evacuation policy in operation for residents within their flats. Residents instructed to fully evacuate if they are in a communal area.	.		

Residents Front Doors						
Chapel Road					14/05/2022	
Flat entrance doors to FD30s specification (Inspection to include - Door condition, construction, closure devices, intumescent/smoke seal condition, glazing systems, fire rated letterplate, door furniture and maximum gaps between door and frame/threshold.						
Flat No.	Access Gained	Asset No.	Observation/Comments / Actions Required	Risk Rating	Completion Date	Referred To:
19			Unable to gain access. External visual inspection only.Condition good.	-		
21			Unable to gain access. External visual inspection only.Condition good.	-		
23			Unable to gain access. External visual inspection only.Condition good.	-		
24			Unable to gain access. External visual inspection only.Condition good.	-		
25			Unable to gain access. External visual inspection only.Condition good.	-		
26			Unable to gain access. External visual inspection only.Condition good.	-		
28			Unable to gain access. External visual inspection only.Condition good.	-		
30			Unable to gain access. External visual inspection only.Letter plate missing.Axis 994337	Med	01/08/22	Fire Safety Manager
33			Unable to gain access. External visual inspection only.Condition good.	-		
35			Unable to gain access. External visual inspection only.Condition good.	-		
37			Unable to gain access. External visual inspection only.Condition good.	-		
38			Unable to gain access. External visual inspection only.Condition good.	-		
39			Unable to gain access. External visual inspection only.Condition good.	-		
40			Unable to gain access. External visual inspection only.Condition good.	-		
42			Unable to gain access. External visual inspection only.Condition good.	-		
44			Unable to gain access. External visual inspection only.Condition good.	-		
45			Unable to gain access. External visual inspection only.Condition good.	-		
47			Unable to gain access. External visual inspection only.Condition good.	-		
49			Unable to gain access. External visual inspection only.Condition good.	-		
50			Unable to gain access. External visual inspection only.Condition good.	-		
51			Unable to gain access. External visual inspection only.Condition good.	-		

52			Unable to gain access. External visual inspection only.Condition good.	-		
54			Unable to gain access. External visual inspection only.Condition good.	-		
56			Unable to gain access. External visual inspection only.Condition good.	-		
59			Unable to gain access. External visual inspection only.Letter plate missing.Axis 994342	Med	01/08/22	Fire Safety Manager
61			Unable to gain access. External visual inspection only.Condition good.	-		
63			Unable to gain access. External visual inspection only.Condition good.	-		
64			Unable to gain access. External visual inspection only.Condition good.	-		
65			Unable to gain access. External visual inspection only.Condition good.	-		
66			Unable to gain access. External visual inspection only.Condition good.	-		
68			Unable to gain access. External visual inspection only.Condition good.	-		
70			Unable to gain access. External visual inspection only.Condition good.	-		

# Photographs - Fire

14/05/2022

Chapel Road



Photo No. 1

Observation - Notice board showing evacuation policy .



Photo No. 2

Observation - Emergency action signage.

Photographs - Fire

14/05/2022

Chapel Road




Photo No. 3

Observation - Fly tipping through out all blocks.Customer Partner to deal.



Photo No. 4

Observation- Loft hatch metal construction tight fitting an locked shut. Loft clear and smoke curtain in good condition with no breaches. All hatches tagged. Next check 2023

### Photographs - Fire

14/05/2022

Chapel Road



Photo No. 5

Observation- Gas cylinders are being stored in the means of escape. These were removed to a place away from the block by the assessor. Customer partner to speak the the offending customers.




Photo No. 6

Observation - Stair treads and risers were found to be in good order in some blocks but some others need attn. Customer partner to raise a works job.

Photographs - Fire	
14/05/2022	Chapel Road





Photo No. 7

Observation - Electrical cupboards left open and not secure. Customer Partner to talk to all customers.



Photo No. 8

Observation - Satisfactory location of newly installed bin area.

## Photographs - Fire

14/05/2022

Chapel Road



Photo No. 9

Observation: External walkways laid with paving slabs.







## 6. Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

(please insert x below)

LOW       MEDIUM       HIGH

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

(please insert x below)

MINOR       MAJOR       CRITICAL

The definition of the above terms is as follows:

### ***FRA Review Frequency***

<b>MINOR</b>	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
<b>MAJOR</b>	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
<b>CRITICAL</b>	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trivial	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

Action Plan - Fire					
Chapel Road				14/05/2022	
Medium					
Potential area of fire risk	Observation/Comments / Actions Required	Risk Rating	Completion Date	Referred To:	Task ID No.
Adequate security against arson?	The front entrance doors to all blocks are easily accessible. Customer Partner to look into the safety measures in place and update if required.	Med	01/12/22	Partnership Manager 2	
Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and residents personal items.	Electrical cupboards are being left open by customers. During a fire these will offer little to no protection for persons leaving the building. Customer Partner to deal.	Med	01/07/22	Partnership Manager 2	
Are combustible materials separated from ignition sources?	Gas cylinders are being stored in the means of escape. These were removed to a safe place away from the block by the assessor. Customer partner to speak the the offending customers.	High	01/05/22	Partnership Manager 2	
Escape routes unobstructed and maintained in a sterile condition?	Items are being stored under the stairs in the majority of the blocks. Customer partner to deal.	Med	01/07/22	Partnership Manager 2	
Fire doors to FD30s standard and in a serviceable condition,	Most communal fire doors were found to be in good condition and conforming to the latest British Standard. The overhead self closing device in block 50-56 is broken and requires replacing. Axis 994346	Med	01/08/22	Fire Safety Manager	

Action Plan - Residents Front Doors						
Chapel Road				14/05/2022		
Flat No.	Asset No.	Observation/Comments / Actions Required	Risk Rating	Completion Date	Referred To:	Task ID No.
30	0	Unable to gain access. External visual inspection only.Letter plate missing.Axis 994337	Med	01/08/22	Fire Safety Manager	
59	0	Unable to gain access. External visual inspection only.Letter plate missing.Axis 994342	Med	01/08/22	Fire Safety Manager	