# Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 8976 14 Marlborough Road Block 1-6 Marlborough Road, Bradford

#### **Cover Sheet**

Photo



Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

10 Jan 2025

10 Jan 2028

36

3 year Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Steven Manners Tech IOSH MIFSM MFPA

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

#### The Scheme

Scheme Name Manningham Rehabilitations

Scheme Address 14 Marlborough Road Block 1-6 Marlborough Road,

**Bradford** 

Postcode BD8 7LE

Region Yorkshire

Scheme Manager

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority West Yorkshire

Other staff in attendance None

Number of on-site Accent staff

None

Number of other (non-Accent) staff

Contract Cleaners in common areas

#### The Building

Accommodation Type General Needs (S30)

Build Date Jan 2 1900

Number Of Homes 6

Homes breakdown Flat

External wall construction Natural Stone

External wall finish Artificial/Natural Stone

Roof construction Timber

Roof covering Slate Pitched

PEEPs in place where necessary N/A

Current Evacuation Strategy Full (Simultaneous) Evacuation

Conversion or purpose-built Conversion

Number of storeys 3

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

1 Protected

Number of External Staircases 1

External Balcony part of escape route?

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

# 14 Marlborough Road Block 1-6 Marlborough Road, Bradford Asset ID: 8976 Flats and common areas linked Fire Detection and Warning System Grade D Grade of fire alarm Category of fire alarm LD3 Minimum Protection Non Maintained System - Common Areas **Emergency Lighting Provision** Portable Fire Extinguishers supplied/fitted No Fixed Fire Fighting Installations No **Customers** 10 Number of occupants **General Needs** Occupant tenure type breakdown Fire Safety Related Customer Safety Servicing Overdue communal gas safety checks 0 0 Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 Overdue communal PAT testing 0 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests 0 0 Overdue Annual Emergency Lighting tests 0 Overdue Weekly Fire Alarm Testing Overdue Fire Panel - Six Monthly Testing Overdue Fire Safety Equipment tests 1 **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors Communal Fire doors due for replacement within 5 years 0 **Dwelling Doors**

Dwelling Fire doors due for replacement within 5 years

Failing Dwelling Fire Doors

0

0

# **Fire Risk Assessment Survey Results**

### **Scheme and Building Information**

Photo



Date of Fire Risk Assessment 10/01/2025

FRA Frequency (Months) 36

Purpose of Fire Risk Assessment 3 year Re-Assessment

Type of Risk Assessment

Type 1 (Common Parts Only - Non Destructive)

Quantity

Fire & Safety Assessor Steven Manners Tech IOSH MIFSM MFPA

Enforcing Fire Authority West Yorkshire

Scheme Tel. No

Other staff in attendance None

Number of on-site Accent staff

None

Number of other (non-Accent) staff

Contract Cleaners in common areas

Scheme Inspection completed Yes

Number of occupants 10

Personal Emergency Evacuation Plans in place N/A

Current Evacuation Strategy Full (Simultaneous) Evacuation

Conversion or purpose-built Conversion

Number of Storeys 3

Number of floors on which car parking is provided 0

Is there a habitable basement?

No. of internal staircases (protected/unprotected) 1 Protected

Number of external staircases 1

External balcony part of escape route?

Unusual features None

14 Marlborough Road Block 1-6 Marlborough Road, Bradford Asset ID: 8976

# Fire Risk Assessment Survey Results

Vehicular Access to one or more elevations Building access conditions for Fire Brigade

Surroundings: Residential/Commercial Residential

Flats and common areas linked Fire Detection and Warning System

Grade D Grade of Fire Alarm

Category of Fire Alarm **LD3 Minimum Protection** 

Non Maintained System - Common Areas **Emergency Lighting Provision** 

No

Yes

Yes

No Portable Fire Extinguishers / Fire Blankets supplied / fitted

Water Extinguisher(s) present No

No Foam Extinguisher(s) present

Dry Powder Extinguisher(s) present

No Carbon Dioxide Extinguisher(s) present

No Fire Blanket(s) present

No Fixed Fire Fighting Installations supplied / fitted

Dry Riser(s) present No

Wet Riser(s) present No

No Sprinkler System present

No Hosereel(s) present

Automatic Opening Vent(s) present No

#### **Electrical Sources of Ignition**

Electrical installation within common areas in good condition and no

obvious damage?

Comment All in good condition at the time of assessment.

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Electrical 5 year test carried out on 21/05/2021 Comment

Electrical App/PA Testing - tested within past 12 months? N/A

Not required Comment

Absence of trailing leads and adapters? N/A

Comment None found at the time of inspection

Yes Evidence that mobility scooters are not being stored/charged in

common areas?

No scooters at this scheme Comment

N/A Is there a purpose built mobility scooter store/charging area?

Comment Not required

Does the building have a lightning protection system?

Comment Not required

Gas installations

Is there a commercial/domestic gas supply to the scheme?

Yes

Comment Thre is a gas supply to individual flats.

Valid LGSR held on file for fixed communal area gas appliances?

N/A

(Boilers)

Comment No communal Gas supply.

Valid LGSR held on file for residential flats that contains gas

appliances?

Comment Individual flats have their own gas checks which are

completed each year around April / May

Are smoke/heat detectors within General Needs flats subject to an

annual inspection and the results

Comment These tests are carried out by our contractors when

the gas check is completed

Yes

Yes

Yes

Yes

No

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered

to?

Comment Smoking is not allowed in the communal areas of

the building but is allowed withinn residents flats.

Adequate security against arson?

Comment There is a Key / Fob entry system to the main

entrance and to the rear fire escape. The door to the escape is damaged and requires a new door and

frame. Order placed.

Are refuse/recycling bin areas managed and suitably located? Yes

Comment Thte refuse is stored at the rear of the building.

Are there communal cooking facilities at this scheme?

Comment

Housekeeping

Are all electrical/intake/service cupboards secure and free from general

waste, contractors waste and and residents personal items?

Comment Nothing found at the time of assessment.

Are unnecessary accumulations of combustible materials or waste avoided?

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 6 of 14

Generated 10/01/2025 16:03:51

Comment

Are combustible materials and substances separated from ignition sources and stored appropriately?

Comment

Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations?

Comment

A bed and a matress were found in the stairway. Hosing Partner and Flytiping have been made aware. Items will be removed within 2 working days.

Yes

None found at the time of assessment.

N/A

No furiture allowed within the communal areas, none found at the time of assessment.

ObservationPriorityReferred ToRequired By:Task IDBed and mattress in escape route. Fly tipping informed.Internal - HighHousing Partner17/01/20251907026





# Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Comment

Yes

None found at the time of assessment.

#### Means of Escape from Fire

Is it considered that the building is provided with reasonable means of escape in case of fire?

Comment

Escape routes unobstructed and safe to use?

Comment

Exits immediately openable without a key and/or failsafe's function correctly?

Comment

Reasonable distances of travel where there is a single/alternative direction of travel?

Comment

Yes

There is an alternative means of escape from the 2nd floor, this leads to en external staircase.

Yes

Thte escape route was unobstructed at the time of assessment. Items were found in the stairway as previously mentioned above.

Yes

Both doors from the property are easily openable although the door from the 2nd floor requires replacement as it is damaged.

Yes

Distance of travel is within the guidelines.

#### 14 Marlborough Road Block 1-6 Marlborough Road, Bradford Asset ID: 8976

Escape routes lead to final exits and open in direction of escape where necessary?

Comment

Comment

Comment

Comment

Comment

Yes

The main door on ground floor opens inwards, there is no vision panel in the door that would alow residents to see if anyone would get injured if the door opened outwards.

#### Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment

Is there reasonable limitation of surface finishes that might promote fire

spread (walls, floors, ceilings)?

Are fire dampers/shutters provided in ducts/refuse chutes to protect

means of escape against fire, smoke and combustion products?

As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?

Loft hatches fire resisting?

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory

standard? Comment

Comment

Do external walls, doors, windows and anything attached to the

exterior, limit fire spread?

If Smoke Control Systems (AOV's) are fitted, are the records of annual

testing available?

Comment

Are roller shutter doors that are required to be FR, fire resisting and

self-closing? Comment

**Emergency Escape Lighting** 

Is the emergency lighting correctly specified and installed as per current standards?

Comment

Emergency lighting units in good condition and securely fixed to walls/ceilings?

Comment

Yes

Of a good standard at the time of assessment.

Yes

Nothing of concern at the time of assessment.

N/A

None fitted at this scheme.

N/A

No access within the communal area.

N/A

None within the communal area.

N/A

No cross corridor doors at this scheme.

Yes

This bukding is of a stone construction.

N/A

None fitted at this scheme.

N/A

None fitted at this scheme.

Yes

Yes

All in good condition at the time of assessment.

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 8 of 14

Generated 10/01/2025 16:03:51

Records of monthly/annual testing available?

Comment Monthly and annual records are available on ActiveH

Last monthly test date :-31/12/2024 Last aannual test : 15/07/2024

**Fire Safety Signs and Notices** 

Are the correct Fire Action/Advice notices displayed in prominent

locations within the common areas?

Comment Signage displayed throughout the bulding.

Directional fire escape signage in place and adequate?

Yes

Comment Signage visible throughout the building at the time of

assessment.

Yes

Is there suitable LIFT signage i.e. do not use in case of fire?

Comment No Lift at this scheme.

Do common area fire doors display the correct signage on both sides Yes

where applicable?

Comment All signage in place at the time of assessment.

Observation Priority Referred To Required By: Task ID

Evacuation policy Fire exit signs





#### Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?

Yes

Comment

Is fire detection and warning system appropriate for occupancy and fire

risk, as per BS 5839-1:2017?

Comment

Is the fire detection and warning system maintained/tested and all

certificates saved on file?

Comment The alarm system is tested and maintained by our contractors Tunstall, all records of tests can be

contractors runstall, all records of tests can be

found on ActiveH.

Yes

Yes

Fire alarm components in good condition and securely fixed to

walls/ceilings?

MIS-AMS ActiveH - Fire Risk Assessment Report Page 9 of 14 Generated 10/01/2025 16:03:51

Comment All in good conditionat the time of assessment.

Hold open devices operate at the sounding of the alarm and are in a

serviceable condition?

Comment None fitted at this scheme.

Are there heat detectors located in the Kitchen, Boiler, Plant Room and

Laundry?

Comment No communal facilities at this scheme.

Is the fire alarm panel remotely monitored, and if so are there records of regular testing?

Comment Not monitored remotely.

Observation Priority Referred To Required By: Task ID

#### Skoke detection in communal area



#### **Fire Extinguishing Equipment**

Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme?

Comment

No

N/A

N/A

N/A

#### Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under the Building Safety Act?

Comment

Are there other Responsible Persons who share or have fire safety

duties in respect of the premises?

How will this sharing be achieved?

Is an office or IL scheme being inspected?

Comment

No

No

No

#### Passenger Lift

Is the scheme fitted with a passenger lift?

No

# 14 Marlborough Road Block 1-6 Marlborough Road, Bradford Asset ID: 8976 Comment **Premises Inspection Box** Is there a premises information box for fire & rescue service use? No Comment **Evacuation Policy** Are there suitable arrangements for summoning the fire service? Yes Comment residents are advised to dial 999 and ask for the Fire Service. Yes Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance? Comment Compartmentation within flats canot be guarenteed threfore a full evac policy is in force. **Engagement with Residents** Has information of fire procedures been disseminated to residents? Yes Comment A leaflet giving information about fire proceedures and the importance of the flat front door has been delivered to each resident. Information is given on habdover of property and all information can be found on the website. Is general fire safety information disseminated to residents? Yes Comment As above A leaflet giving information about fire proceedures and the importance of the flat front door has been delivered to each resident. Information is given on habdover of property and all information can be found on the website FRA Frequency Yes Taking the findings of this assessment into account, is the frequency of the FRA correct? Comment

#### **Miscellaneous**

Are there any other observations/actions to raise that are not covered

above.

Action leading to a repair

Internal administrative Action

Yes

Yes

163

No

| Are there fire related remedial works required at this property, that will affect the fabric of the building?  Comment               | Yes |
|--|-----|
| Can work be conducted without the need for an asbestos survey. If no, task Customer Safety Surveyor - Asbestos.  Comment             | Yes |
| Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).                              | Yes |
| Some fire doors did not fully close so works orders have been raised with our contractors.   | No  |
| Some minor works were required which have been raised with our contractors.  | No  |
| Unauthorised items were found in communal areas and arrangements were made for their removal.  | Yes |
| Not all records were up to date, as noted in the table below.  Arrangements have been made for these to be completed.                | No  |
| A number of fire doors were found to be wedged or propped open. Fire doors are there to keep you safe and me kept shut at all times. | No  |

#### **Risk Calculator - Fire**

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

| systems.   |                 |  |              |          |  |
|--|-----------------|--|--------------|----------|--|
|  |                 |  |              |          |  |
| <ol> <li>Taking into account the fire prevention measures observed at the time of this risk<br/>assessment, it is considered that the hazard from the fire (the probability of ignition) at this<br/>building is:</li> </ol> |                 |  |              |          |  |
| LOW  | X               | MEDIUM   |              | нідн     |  |
| any procedural   | arrangements ob | of the building, the occurrence of the building, the occurrence of the event of a fire would | ne assessmen | •        |  |
| MINOR  |                 | MAJOR  |              | CRITICAL |  |

The definition of the above terms is as follows: FRA Review Frequency

| MINOR    | Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs). |
|----------|---|
| MAJOR    | An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.   |
| CRITICAL | There is significant potential for serious injury or death of one or more occupants.  |

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

| Fire Hazard | Minor     | Major       | Critical    |
|-------------|-----------|-------------|-------------|
| Low         | Trival    | Tolerable   | Moderate    |
| Medium      | Tolerable | Moderate    | Substantial |
| High        | Moderate  | Substantial | Intolerable |

When the level of risk is established, the action level can be read from the table below:

#### Asset ID: 8976

# 14 Marlborough Road Block 1-6 Marlborough Road, Bradford

| Risk Level  | Guide to actions and appropriate timescales  |
|-------------|--|
| Trivial     | No action is required  |
| Moderate    | Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.  |
| Substantial | Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken. |
| Intolerable | The building (or the relevant area) should not be occupied until the risk is reduced.  |

| The Overall Risk Level for this asset is: | Trivial |
|---|---------|
|   |         |