

This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 8823 1-40 Saxondale Court Block 1-40 Saxondale Court, Wakefield

Cover Sheet

Photo



Date of Fire Risk Assessment Date of Next Fire Risk Assessment FRA Frequency (Months) Purpose of Fire Risk Assessment Type of Fire Risk Assessment Fire & Safety Assessor 04 Jan 2024 04 Jan 2025 12 Annual Re-Assessment Type 3 (Common Parts and Flats - Non Destructive) Steven Manners

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name	Saxondale Court
Scheme Address	1-40 Saxondale Court Block 1-40 Saxondale Court, Wakefield
Postcode	WF4 6AX
Region	Yorkshire
Scheme Manager	
Scheme Tel. No	
Scheme Inspection Completed	Yes
Enforcing Fire Authority	West Yorkshire
Other staff in attendance	Stephen Aldred
Number of on-site Accent staff	Scheme Manager Part-Time
Number of other (non-Accent) staff	Contract Cleaners in common areas

The Building

Accommodation Type	CAT2 Housing for Older People (S28)
Build Date	Jan 1 1983
Number Of Homes	39
Homes breakdown	Flat, Maisonette
External wall construction	Facing Brick
External wall finish	Facing Brick
Roof construction	Timber
Roof covering	Interlocking Pitched
PEEPs in place where necessary	Yes
Current Evacuation Strategy	Stay Put (Delayed) Evacuation
Conversion or purpose-built	Purpose Built
Number of storeys	2
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
Number of internal Staircases (protected or unprotected?)	3 Protected
Number of External Staircases	None
External Balcony part of escape route?	No
Unusual features	None
Building Access Conditions for Fire Brigade	Vehicular Access to one or more elevations

Fire Detection and Warning System	Flats and common areas not linked
Grade of fire alarm	Grade A
Category of fire alarm	LD1 Maximum Protection
Emergency Lighting Provision	Non Maintained System - Common Areas
Portable Fire Extinguishers supplied/fitted	Yes
Fixed Fire Fighting Installations	No

Customers

Asset ID: 8823

Number of occupants	50
Occupant tenure type breakdown	General Needs, CAT2 Housing for Older People,
	Staff Accommodation, Designated Supported

Fire Safety Related Customer Safety Servicing

Overdue communal gas safety checks	0
Overdue domestic gas safety checks	0
Overdue communal electrical condition checks	0
Overdue domestic electrical condition checks	0
Overdue alarm call pull chord tests	0
Overdue communal PAT testing	0
Overdue customer mobility scooter PAT testing	0
Overdue Monthly Emergency Lighting Switch Tests	1
Overdue Annual Emergency Lighting tests	1
Overdue Weekly Fire Alarm Testing	0
Overdue Fire Panel - Six Monthly Testing	1
Overdue Fire Safety Equipment tests	1

Building Fire Safety Surveys - Communal Doors

Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	0

Dwelling Doors

Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

Housing for Older People, Sheltered Schemes

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo

		C Surrang Corners Surveille wy Salary Tak A7
Date of Fire Risk Assessment		04/01/2024
FRA Frequency (Months)		12
Purpose of Fire Risk Assessment		Annual Re-
Type of Risk Assessment		Туре 3 (Со
Quantity		1
Fire & Safety Assessor		Steven Ma
Enforcing Fire Authority		West Yorks
Scheme Tel. No		
Other staff in attendance		Stephen Al
Number of on-site Accent staff		Scheme M
Number of other (non-Accent) staff		Contract C
Scheme Inspection completed		Yes
Number of occupants		50
Personal Emergency Evacuation Plans in place		Yes
Current Evacuation Strategy		Stay Put (E
Conversion or purpose-built		Purpose B
Number of Storeys		2
Number of floors on which car parking is provided		0
Is there a habitable basement?		No
No. of internal staircases (protected/unprotected)		3 Protected
Number of external staircases		None
External balcony part of escape route?		No
Unusual features		None
MIS AMS Actival Eiro Dick Accomment Benert	Dogo 4 of 19	Conorat



04/01/2024
12
Annual Re-Assessment
Type 3 (Common Parts and Flats - Non Destructive)
1
Steven Manners
West Yorkshire
Stephen Aldred
Scheme Manager Part-Time
Contract Cleaners in common areas
Yes
50
Yes
Stay Put (Delayed) Evacuation
Purpose Built
2
0
No
3 Protected
None
No

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade	Vehicular Access to one or more elevations
Surroundings: Residential/Commercial	Residential
Fire Detection and Warning System	Flats and common areas not linked
Grade of Fire Alarm	Grade A
Category of Fire Alarm	LD1 Maximum Protection
Emergency Lighting Provision	Non Maintained System - Common Areas
Portable Fire Extinguishers / Fire Blankets supplied / fitted	Yes
Water Extinguisher(s) present	No
Foam Extinguisher(s) present	No
Dry Powder Extinguisher(s) present	No
Carbon Dioxide Extinguisher(s) present	Yes
Fire Blanket(s) present	Yes
Fixed Fire Fighting Installations supplied / fitted	No
Dry Riser(s) present	No
Wet Riser(s) present	No
Sprinkler System present	No
Hosereel(s) present	No
Automatic Opening Vent(s) present	No

Electrical Sources of Ignition

Electrical installation within common areas in good condit obvious damage?	ion and no	Yes
Comment		All in good condition at the time of inspection
Valid Electrical Installation Condition Reports held on file? Areas & General Needs Flats)	? (Common	Yes
Comment		All records are available on ActiveH
Electrical App/PA Testing - tested within past 12 months?		Yes
Comment		Records are available on ActiveH. Stickers are on all electrical appliances
Absence of trailing leads and adapters?		Yes
Comment		None found at the time of inspection
Evidence that mobility scooters are not being stored/charg common areas?	ged in	Yes
Comment		None found at the time of inspection
Is there a purpose built mobility scooter store/charging are	ea?	No
MIS-AMS ActiveH - Fire Risk Assessment Report	Page 5 of 18	Generated 04/01/2024 16:06:05

Comment

Asset ID: 8823

Does the building have a lightning protection system?

Comment

Gas installations

Yes
There is a boiler room at the property which supplies all the flats
Yes
All records are available on ActiveH
Yes
All records are available on ActiveH for the individual flats
Yes
Carried out by Tunstall and recorded on ActiveH
T a Y A Y

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered to?	Yes
Comment	Residents are allowed to smoke within their homes
Adequate security against arson?	Yes
Comment	Electronic door entry system at the scheme
Are refuse/recycling bin areas managed and suitably located?	Yes
Comment	There is a designated area for refuse outside
Are there communal cooking facilities at this scheme?	Yes
Comment	This area is mainly used for making drinks on social events
Are reasonable measures taken to prevent fires as a result of cooking?	Yes
Comment	
Where there is extraction in communal kitchens, are filters and ductwork changed/cleaned regularly?	N/A
Comment	

Housekeeping

Scooters are stored in a garage accessible from

outside the property

No

Asset ID: 8823 1-40 Saxondale Court Block 1-40 Saxondale Court, Wakefield

Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items?	Yes
Comment	Nothing found at the time of inspection
Are unnecessary accumulations of combustible materials or waste avoided?	Yes
Comment	None found at the time of inspection
Are combustible materials and substances separated from ignition sources and stored appropriately?	Yes
Comment	None found at the time of inspection
Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations?	Yes
Comment	All furniture within the scheme has the correct labels

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?	Yes
Comment	Nothing found at the time of inspection

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of escape in case of fire?	Yes
Comment	There is more than one direction of travel to escape exit doors
Escape routes unobstructed and safe to use?	Yes
Comment	No obstructions at the time of inspection
Exits immediately openable without a key and/or failsafe's function correctly?	Yes
Comment	All in good working order at the time of inspection
Reasonable distances of travel where there is a single/alternative direction of travel?	Yes
Comment	All travel distances are within the guidelines
Escape routes lead to final exits and open in direction of escape where necessary?	Yes
Comment	

Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?

Yes All good at the time of inspection Yes

Asset ID: 8823 1-40 Saxondale Court E	Block 1-40 Saxon	idale Court, Wakefield		
Comment		Notice boards have protec	ctive covers	
Are fire dampers/shutters provided in ducts/refuse chutes to means of escape against fire, smoke and combustion produc	•	N/A		
Comment		None fitted on scheme		
As far as can be reasonably ascertained, is the compartmen within roof spaces of a satisfactory standard?	tation	Yes		
Comment		Ther were no compartmen time of inspection	ntation issues found	at the
Loft hatches fire resisting?		Yes		
Comment		All 1 hour rated loft hatche	es	
As far as can be reasonably ascertained, is the fire stopping cross corridor fire doors within suspended ceiling void of a sa standard?		Yes		
Comment		No issues found at the tim	e of inspection	
Do external walls, doors, windows and anything attached to exterior, limit fire spread?	the	Yes		
Comment				
If Smoke Control Systems (AOV's) are fitted, are the records testing available?	of annual	N/A		
Comment		None fitted at the scheme		
Are roller shutter doors that are required to be FR, fire resisti self-closing?	ing and	N/A		
Comment		None fitted at the scheme		
Observation	Priority	Referred To	Required By:	Task ID
Adjust double communal Fire door to reduce the gap	Repair - Non	Building Safety		


Emergency

Adjust double communal Fire door to reduce the gap between doors adjacent to flat 2 and 7 on ground floor. Smoke seal is only on one door



Manager

Observation	Priority	Referred To	Required By:	Task ID
Adjust double communal Fire door to reduce the gap between doors adjacent to flat 20 and 29. Smoke seal	Repair - Non Emergency	Building Safety Manager		
is only on one door	Emergency	Manager		



Asset ID: 8823

Observation	Priority	Referred To	Required By:	Task ID
Adjust double communal Fire door to reduce the gap between doors adjacent to flat 32 and 37. Smoke seal	Repair - Non Emergency	Building Safety Manager		
is only on one door		·		



Observation	Priority	Referred To	Required By:	Task ID
Repair hole in door to meter room2 on first floor	Repair - Non Emergency	Building Safety Manager		
Fire door keep locked				
i i i i i i i i i i i i i i i i i i i				

Observation	Priority	Referred To	Required By:	Task ID
Adjust double communal Fire door to reduce the gap between doors adjacent to flat 10 and 16. Smoke seal	Repair - Non Emergency	Building Safety Manager		
is only on one door				



Asset ID: 8823

Observation	Priority	Referred To	Required By:	Task ID
Adjust double communal Fire door to reduce the gap	Repair - Non	Building Safety		
between doors adjacent to flat 11and 15 . Smoke seal is only on one door	Emergency	Manager		



Observation	Priority	Referred To	Required By:	Task ID
Adjust double communal Fire door to reduce the gap between doors adjacent t flat 3 and 6. Smoke seal is only on one door	Repair - Non Emergency	Building Safety Manager		



Observation	Priority	Referred To	Required By:	Task ID
Repair hole in meter room 1 door	Repair - Non Emergency	Building Safety Manager		
Presedence -	ELS			

Observation	Priority	Referred To	Required By: Task ID
Scheme Manager office door requires replacing	Repair - Non Emergency	Building Safety Manager	



epair - Non	Building Safety
mergency	Manager

Observation	Priority	Referred To	Required By:	Task ID
Door to laundry is warped and needs replacing	Repair - Non Emergency	Building Safety Manager		





Yes

Yes

Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per current standards?

Comment

Asset ID: 8823

Emergency lighting units in good condition and securely fixed to walls/ceilings?

Comment



All in good condition at the time of inspection

Asset ID: 8823 1-40 Saxondale Court Block 1-40 Saxondale Court, Wakefield

Records of monthly/annual testing available? Yes	
	ager conducts monthly test, Tunstall 3 Hour drop test and all records are ActiveH

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?	Yes
Comment	Notices are displayed throughout the building
Directional fire escape signage in place and adequate?	Yes
Comment	
Is there suitable LIFT signage i.e. do not use in case of fire?	Yes
Comment	
Do common area fire doors display the correct signage on both sides where applicable?	Yes
Comment	All signage in place at the time of inspection

Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?	Yes
Comment	
Is fire detection and warning system appropriate for occupancy and fire risk, as per BS 5839-1:2017?	Yes
Comment	This is a stay put building, the fire alarm in the communal area is zoned and not linked to the flats
Is the fire detection and warning system maintained/tested and all certificates saved on file?	Yes
Comment	The fire alarm is tested weekly by the Scheme Manager, the 6 monthly test is carried out by Tunstall and recorded on ActiveH
Fire alarm components in good condition and securely fixed to walls/ceilings?	Yes
Comment	All in good condition at the time of inspection
Hold open devices operate at the sounding of the alarm and are in a serviceable condition?	Yes
Comment	All in good working order at the time of inspection
Are there heat detectors located in the Kitchen, Boiler, Plant Room and Laundry?	Yes
Comment	
Is the fire alarm panel remotely monitored, and if so are there records of regular testing?	Yes
Comment	Monitored by a monitoring agency, Testing done as above

Asset ID: 823 1-40 Saxondale Court Block 1-40 Saxondale Court, Wakefield Observation Priority Referred To Required By: Task ID Secondary fire panel Observation Priority Referred To Required By: Task ID Secondary fire panel Secondary fire panel Secondary fire panel Secondary fire panel Observation Priority Referred To Required By: Task ID

MIn fire panel



Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme?	Yes
Comment	Only in kitchen and laun available within electrica
Portable fire extinguishers - appropriate type/number/position?	Yes
Comment	As above
Correct signage displayed by each fire extinguisher?	Yes
Comment	All in place at the time o
Fire blanket in communal kitchen, secured to the wall, complete with signage?	Yes
Comment	
Dry risers - Inlet/outlet boxes secured and/or securing straps fitted to outlet valves?	N/A
Comment	None fitted
Records available of fire fighting equipment servicing within past 12 months?	Yes
Comment	Signage on extinguisher

Only in kitchen and laundrette. There are CO2 available within electrical cupboard /es As above /es

Signage on extinguishers and recorded on ActiveH

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under the Building Safety Act? Comment	Yes
Will this FRA be shared will all Accountable Persons for the premises?	Yes
Comment	
How will this sharing be achieved?	All records are available on ActiveH and within M-Files
Are there other Responsible Persons who share or have fire safety duties in respect of the premises?	No
How will this sharing be achieved?	
Is an office or IL scheme being inspected?	Yes
Comment	IL Scheme
IL Schemes & Regional Offices - Are there sufficient numbers of qualified Fire wardens?	N/A
Comment	Fire wardens not required at this scheme
Offices - Are there suitable arrangements for ensuring the premises are evacuated?	N/A
Comment	This is a ILS with a stay put policy
Offices - Are there suitable arrangements for evacuating disabled people?	N/A
Comment	As above
Offices - Suitable arrangements for meeting the fire service on arrival and proving relevant information?	N/A
Comment	As above
Offices/IL Schemes - Is there a suitable assembly point?	N/A
Comment	
Offices - Are fire drills carried out at appropriate intervals?	N/A
Comment	
Passenger Lift	
Is the scheme fitted with a passenger lift?	Yes
Comment	
Is the lift in full working order at the time of the FRA?	Yes
Comment	In good working order at the time of inspection
Is the lift fitted with a firefighters switch?	No
Comment	

Asset ID: 8823 1-40 Saxondale Court Block 1-40 Saxondale Court, Wakefield

Observation Priority	Referred To	Required By:	Task ID	
Comment	All records are available on	ActiveH		
Servicing and insurance inspection - Evidence of regular servicing/maintenance?	Yes			

Premises Inspection Box

Is there a premises information box for fire & rescue service use?

Comment

Fire signage

Evacuation Policy

Are there suitable arrangements for summoning the fire service?

Comment

Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance?

Comment

Engagement with Residents

Has information of fire procedures been disseminated to residents?
Comment
Is general fire safety information disseminated to residents?

Comment

FRA Frequency

Taking the findings of this assessment into account, is the frequency of the FRA correct?

No

All IL Schemes are to be fitted with an information box in the near future

Yes

The communal Fire alarm is monitored and there are warden call alarms within the flats. Residents are advised to ring 999as well Yes

Yes

All residents have recently received a letter and leaflets with fire safety information Yes

As above

Yes

Comment

Miscellaneous

Are there any other observations/actions to raise that are not covered above.	Yes
Action leading to a repair	Yes
Internal administrative Action	
Are there fire related remedial works required at this property, that will affect the fabric of the building? Comment	No
Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).	Yes
Some fire doors did not fully close so works orders have been raised with our contractors.	No
Some minor works were required which have been raised with our contractors.	Yes
Unauthorised items were found in communal areas and arrangements were made for their removal.	No
Not all records were up to date, as noted in the table below. Arrangements have been made for these to be completed.	No
A number of fire doors were found to be wedged or propped open . Fire doors are there to keep you safe and me kept shut at all times.	No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW	X	MEDIUM	НІGН	
-----	---	--------	------	--

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR	MAJOR	X	CRITICAL	

The definition of the above terms is as follows: *FRA Review Frequency*

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	intolerable

When the level of risk is established, the action level can be read from the table below:

Asset ID: 8823

1-40 Saxondale Court Block 1-40 Saxondale Court, Wakefield

Risk Level	Guide to actions and appropriate timescales	
Trivial	No action is required	
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.	
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.	
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.	

The Overall Risk Level for this asset is:	Trivial	