Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 24483 Ansell Road

Cover Sheet

Photo

Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

20 Nov 2024

20 Nov 2027

36

3 year Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Gary Bredin AlFireE

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name Ansell Road

Scheme Address Ansell Road

Postcode GU16 5BS

Region South

Scheme Manager

Scheme Tel. No -

Scheme Inspection Completed Yes

Enforcing Fire Authority Surrey Fire and Rescue service

Other staff in attendance None

Number of on-site Accent staff None

Number of other (non-Accent) staff

Contract Cleaners in common areas

The Building

Accommodation Type Garage and Car Parking Bays (S45), General Needs

(S30), Peerless General Needs - LSVT (S29)

Build Date Jan 1 1962

Number Of Homes 67

Homes breakdown Flat, House

External wall construction Facing Brick

External wall finish Cement Render, Facing Brick, Facing Brick

Painted, Hung Tiles, Paint Render, Timber Clad

Roof construction Timbe

Roof covering Interlocking Pitched, Slate Pitched

PEEPs in place where necessary N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys 2, 3

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

One protected

Number of External Staircases None

External Balcony part of escape route?

N/A

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

Asset ID: 24483 Ansell Road	
Fire Detection and Warning System	Flats only
Grade of fire alarm	Grade D
Category of fire alarm	LD3 Minimum Protection
Emergency Lighting Provision	Non Maintained System - Common Areas
Portable Fire Extinguishers supplied/fitted	No
Fixed Fire Fighting Installations	No
Customers	
Number of occupants	75
Occupant tenure type breakdown	General Needs, Leasehold
Fire Safety Related Customer Safety Servicing	
Overdue communal gas safety checks	0
Overdue domestic gas safety checks	0
Overdue communal electrical condition checks	0
Overdue domestic electrical condition checks	0
Overdue alarm call pull chord tests	0
Overdue communal PAT testing	0
Overdue customer mobility scooter PAT testing	0
Overdue Monthly Emergency Lighting Switch Tests	0
Overdue Annual Emergency Lighting tests	0
Overdue Weekly Fire Alarm Testing	0
Overdue Fire Panel - Six Monthly Testing	
Overdue Fire Safety Equipment tests	
Building Fine Onfoto Ouroness Communical Booms	
Building Fire Safety Surveys - Communal Doors	
Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	0
Dwelling Doors	
Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



Date of Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Risk Assessment

Quantity

Fire & Safety Assessor

Enforcing Fire Authority

Scheme Tel. No

Other staff in attendance

Number of on-site Accent staff

Number of other (non-Accent) staff

Scheme Inspection completed

Number of occupants

Personal Emergency Evacuation Plans in place

Current Evacuation Strategy

Conversion or purpose-built

Number of Storeys

Number of floors on which car parking is provided

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

Number of external staircases

External balcony part of escape route?

Unusual features

20/11/2024

36

3 year Re-Assessment

- 1

Gary Bredin AlFireE

Surrey Fire and Rescue service

None

None

Contract Cleaners in common areas

Yes

75

N/A

Stay Put (Delayed) Evacuation

Purpose Built

3

No

0

One protected

None

N/A

None

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Residential

Fire Detection and Warning System Flats only

Grade of Fire Alarm Grade D

Category of Fire Alarm LD3 Minimum Protection

Emergency Lighting Provision Non Maintained System - Common Areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted No

Water Extinguisher(s) present

Foam Extinguisher(s) present

Dry Powder Extinguisher(s) present

Carbon Dioxide Extinguisher(s) present

Fire Blanket(s) present

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present No

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no

obvious damage?

Comment

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment Next test date August 2026

Electrical App/PA Testing - tested within past 12 months?

N/A

Comment

Absence of trailing leads and adapters? Yes

Comment

Evidence that mobility scooters are not being stored/charged in

common areas?

Comment

Is there a purpose built mobility scooter store/charging area?

N/A

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 5 of 14

Generated 21/11/2024 16:02:11

Yes

Yes

Yes

Asset ID: 24483	Ansell Road	
Comment		
Does the building have a lightr	ning protection system?	N/A
Comment		
Is the protection system adequ	uately maintained?	N/A
Comment		
Gas installations		
Is there a commercial/domestic	c gas supply to the scheme?	No
Comment		
Other Sources of Ignit	ion	
Is there a no smoking policy in to?	place, which is enforced and adhered	Yes
Comment		
Adequate security against arso	on?	Yes
Comment		Electronic door entry system in place
Are refuse/recycling bin areas	managed and suitably located?	Yes
Comment		Satisfactory location of the bin areas
Are there communal cooking fa	acilities at this scheme?	No
Comment		
Housekeeping		
Are all electrical/intake/service waste, contractors waste and a	cupboards secure and free from general and residents personal items?	Yes
Comment		
Are unnecessary accumulation avoided?	ns of combustible materials or waste	Yes
Comment		
Are combustible materials and sources and stored appropriate Comment	substances separated from ignition ely?	N/A
	condition fire retardent/resistant and	N/A
comply with modern standards Comment	condition, fire retardant/resistant and and regulations?	N/A
Commont		

Observation Priority Referred To Required By: Task ID

All areas were clear at the time of the audit





Observation Priority Referred To Required By: Task ID

All electrical cupboards were clear at the time of the audit.





Observation Priority Referred To Required By: Task ID

Satisfactory location of the bin areas





Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Yes

Comment

Means of Escape from Fire

Asset ID: 24483	Ansell Road	
Is it considered that the building escape in case of fire? Comment	ng is provided with reasonable means of	Yes
Escape routes unobstructed a	and safe to use?	Yes
Comment		
Exits immediately openable w correctly? Comment	vithout a key and/or failsafe's function	Yes
	el where there is a single/alternative	Yes
Escape routes lead to final ex necessary? Comment	kits and open in direction of escape where	Yes
Fire Spread and Deve	lopment	
Is it considered that the comp	partmentation is of a reasonable standard?	Yes
Comment		
Is there reasonable limitation spread (walls, floors, ceilings) Comment	of surface finishes that might promote fire)?	Yes
	vided in ducts/refuse chutes to protect , smoke and combustion products?	N/A
As far as can be reasonably a within roof spaces of a satisfa	ascertained, is the compartmentation actory standard?	N/A
Comment		This area was not checked during the audit.
Loft hatches fire resisting?		Yes
Comment		Loft hatch in block 5 requires upgrading
	ascertained, is the fire stopping above n suspended ceiling void of a satisfactory	Yes
Comment		
Do external walls, doors, wind exterior, limit fire spread? Comment	dows and anything attached to the	Yes
If Smoke Control Systems (Actesting available? Comment	OV's) are fitted, are the records of annual	N/A
Are roller shutter doors that a self-closing?	re required to be FR, fire resisting and	N/A

Page 8 of 14

MIS-AMS ActiveH - Fire Risk Assessment Report

Generated 21/11/2024 16:02:11

Ansell Road Asset ID: 24483

Comment

Observation **Priority** Referred To Required By: Task ID Internal - Low **Project Manager**

Block 3d-3g loft hatch requires upgrading. Job raised.

(Building Safety)

01/04/2025 1889253



Priority Observation Referred To Required By: Task ID

Electrical cupboards require fire stopping or replacing

Internal - Medium

Project Manager (Building Safety)

01/04/2025

1889252





Priority Observation Referred To Required By: Task ID

Letter plates missing on various flat front doors. Job raised for replacement





Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per current standards?

Yes

Comment

Emergency lighting units in good condition and securely fixed to walls/ceilings?

Yes

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 9 of 14

Generated 21/11/2024 16:02:11

Comment

Records of monthly/annual testing available?

Comment Last drop test 15th November 2024

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent

locations within the common areas?

Comment These are posted throughout the buildings

Yes

Yes

Directional fire escape signage in place and adequate?

Comment

Is there suitable LIFT signage i.e. do not use in case of fire?

Comment

Do common area fire doors display the correct signage on both sides

where applicable?

Comment

Observation Priority Referred To Required By: Task ID

Notice boards in all blocks





Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?

Comment

Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations

provided at this scheme?

Comment

Management of Fire Safety

Asset ID:	24483	Ansell Road		
Are these pre the Building S Comment		by the Building Safety Regulator under	No	
	er Responsible Pe pect of the premise	ersons who share or have fire safety es?	Yes	
Have all details required by regulations been shared with all other Responsible Persons? Comment				
Responsible		gulations to be shared with us from other seived and recorded?	N/A	
Comment			Not applicable	
Will this FRA premises? Comment	be shared will all	other Responsible Persons for the	Yes	
How will this	sharing be achiev	ed?	This is available on request	
Is an office or	r IL scheme being	inspected?	N/A	
Comment				
IL Schemes & qualified Fire Comment		s - Are there sufficient numbers of	N/A	
	4l		N/A	
evacuated?	there suitable arra	angements for ensuring the premises are	IN/A	
Comment				
Offices - Are people? Comment	there suitable arra	angements for evacuating disabled	N/A	
	able arrangement elevant informatio	s for meeting the fire service on arrival on?	N/A	
Offices/IL Sch	hemes - Is there a	suitable assembly point?	N/A	
Comment				
Offices - Are	fire drills carried o	out at appropriate intervals?	N/A	
Comment				
Passenge	er Lift			
Is the scheme	e fitted with a pas	senger lift?	No	
Comment				

Premises Inspection Box

Asset ID: 24483 Ansell Road	
Is there a premises information box for fire & rescue service use?	No
Comment	
Evacuation Policy	
Are there suitable arrangements for summoning the fire service?	Yes
Comment	It's the responsibility of the customers to summon the emergency services.
Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance? Comment	Yes
Engagement with Residents	
Has information of fire procedures been disseminated to residents?	Yes
Comment	
Is general fire safety information disseminated to residents?	Yes
Comment	All emergency action notices are posted in the notice boards located in the main entrances
FRA Frequency	
Taking the findings of this assessment into account, is the frequency of the FRA correct?	Yes
Comment	
Miscellaneous	
Are there any other observations/actions to raise that are not covered above.	No
Are there fire related remedial works required at this property, that will affect the fabric of the building?	No
Comment	
Were there any unsatisfactory aspects of the Fire Risk Assessment?	No

(Visible on Building Safety Report).

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

systems.					
_	•	ntion measures obs e hazard from the fir			is
LOW		MEDIUM		HIGH	
any procedural a	rrangements obser	the building, the occ ved at the time of th event of a fire would	e assessment, it		
MINOR		MAJOR	CI	RITICAL	

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Moderate	