

ACCENT HOUSING - FIRE RISK ASSESSMENT



Region :	South
Scheme Name :	Goldsworth Road
Scheme Address :	147 - 151A Goldsworth Road Woking, Surrey. GU21 6LS
Date of Assessment:	09/01/2024
Date of Next Assessment:	09/01/2025
FRA Frequency:	Annual Re-Assessment
Fire & Safety Assessor	Gary Bredin

This Fire Risk Assessment has been conducted upon the instruction of Accent Housing.

Scheme Details		Goldsworth Road
Region:		South
Scheme Name:		Goldsworth Road
Site Address:	Street:	147 - 151A Goldsworth Road
	Town:	Woking, Surrey.
	Post Code:	GU21 6LS
Block & Asset No.		Asset 25199 Block149a/151a
Date of this Assessment		09/01/2024
Date of Next Review		09/01/2025
Fire Risk Assessment Frequency		Annual
Purpose of Fire Risk Assessment		Annual Re-Assessment
Fire & Safety Assessor		Gary Bredin
Director of Customer Experience		Louise Graham Smith
Customer Partnership Manager		Laura Dillon
Contract Manager		Adam Rickard
Scheme Manager/Customer Partner		Daniel Morgan
Other staff in attendance		None
Use of Building		General Needs
Approximate Number of occupants		6
Occupancy Profile		Families
Familiarity of the occupants		Slightly Familiar
Likely state of the Occupants		Alert
PEEPs in place where necessary		N/A
Number of on-site Accent staff		None
		Contract cleaners in common
Number of other (non-Accent) staff		areas
Support Agency (Supported Housing)		N/A
Current Evacuation Strategy.		Full (Simultaneous) Evacuation
Evidence that residents have been notif	ied of the	Advice notices displayed in
evacuation procedure		common areas
History of fires in the building		None
Business Continuity Plan in place?		Yes
Scone of Assossment		Type 1 (Common Parts Only -
Scope of Assessment		Non Destructive)
Applicable Fire Safety Guidance	Sleeping Accommodation Guide	
		LACORS Guide

Building Details	Goldsworth Road
Construction Date	Originally 1950 Refurb 2019/20
	Joisted or Load Bearing Masonry
Construction Type	(Traditional)
Roof Finish	Pitched-Slate Tile
External Wall Finish	Brick
	N
Are there any areas of external wall cladding	No
Are there any balconies	No
Conversion or purpose-built	Conversion
Number of flats (self-contained)/rooms (HMOS, shared	Two upstairs flats are covered by
houses)	this FRA only. 149a & 151a
Number of storeys above ground	One
Number of storeys below ground	None
Is there a habitable basement?	No
Number of internal Staircases per Block	
(protected or unprotected?)	None
Number of External Staircases per Block	None
External Balcony part of escape route?	N/A
	Converted retail building.
	Communal entrance to two
Unusual features	upstairs self contained flats
Building complexity	Simple
Building Access Conditions for Fire Brigade	Vehicular Access to one or more
Surroundings: Residential/Commercial	elevations Mixed
Fire Provision Currently in F	
Fire Detection and Warning System	Flats and common areas linked
I he betection and warning System	
Grade of fire alarm	Grade D
Category of fire alarm	LD2 Additional Protection
	Upstairs flats and common areas
	linked with radio linked detectors.
Additional Comments:	
Evacuation Alert System (EAS)	N/A
Additional Comments:	-
	Non Maintained System -
Emergency Lighting Provision	Common Areas
Additional Comments:	
Portable Fire Extinguishers	None fitted
	L
	L
Additional Comments:	
Fixed Fire Fighting Installations	None fitted
Additional Comments:	

	Significant Findings - Fire						
	Goldsw	orth	Road		09/01/2024		
Action Ref:	Potential Area of Fire Risk		Observation/Comments/ Actions Required	Risk Rating	Target Completion Date	Referred To:	
			Fire Hazards				
1	Electrical Sources of Ignition:						
1.1	Electrical Installation within common areas (Fixed Wiring, sockets, switches, light fittings) in good condition and no obvious damage	Yes	All common area sockets and fittings in a satisfactory condition at the time of inspection.				
1.2	Valid Electrical Installation Condition Reports held on file.(Common Areas)	Yes	Commission an electrical safety inspection completed and uploaded to the property file.	ı			
1.3	Valid Electrical Installation Condition Reports held on file. (General Needs Flats)	Yes		•			
1.4	Electrical App/PA Testing - all portable appliances tested within past 12 months	N/A	PAT not required, no portable electrical equipment in communal areas				
1.5	Absence of trailing leads and adapters	Yes		I			
1.6	Mobility Scooters - Stored/charged in common areas, purpose built store/resident flat	Other	No evidence of any Mobility Scooters being stored or charged on this site at the time of this inspection.				
2	Smoking:		-	_			
2.1	Are there any risks associated with smoking in the building?	No	No smoking policy within common areas				
3	Arson:						
3.1	Adequate security against arson?	Yes	Building secure - Intercom door entry system with trade button access.				
3.2	Is there an absence of unnecessary fire load in close proximity to building?	Yes	All external common areas clear at time of inspection	ı			

4	Heating Installations (Portable/fixed)					
	Gas Installations - Common Areas & Gener	al Ne	eds Residential flats.			
4.1	If portable heaters are used, are there	N/A	No portable heaters permitted in communal areas			
	suitable controls?	N				
4.2	Are fixed heating installations subject to	Yes				
	regular maintenance?	\succ				
4.3	Valid LGSC held on file for each residential	Yes				
	flat that contains gas appliances.	\succ				
5	Cooking:	-		I	-	
5.1	Are reasonable measures taken to prevent	N/A	No communal cooking areas			
	fires as a result of cooking?	Z				
5.2	Where there is extraction ventilation in	4				
	communal kitchens are filters changed/	N/A		•		
	cleaned and ductwork cleaned regularly?					
6	Lightning Protection System:	-		I	-	
6.1	Does the building have a lightning protection		According to the lightning protections regulations			
	system, If so, is it adequately maintained?	4	(as satiated in the RC 35 'Protection of buildings			
		N/A	against lightning strikes'), it is not a legal	•		
			requirement for buildings to be fitted with lightning			
			protection.			
7	Housekeeping:	-		I	-	
7.1	Is the standard of housekeeping adequate?	Yes				
7.2	Are all electrical/intake/service cupboards		All supporte secure and clear at time of			
1.2	secure and free from general waste,		All cupboards secure and clear at time of inspection			
	contractors waste and residents personal	Yes	Inspection			
7.3	items. Are combustible materials separated from	(0)				
1.3	-	Yes				
7.4	ignition sources and stored appropriately? Are unnecessary accumulations of					
/.4	combustible materials or waste avoided?	Yes				
ļ						

7.5	Are hazardous materials stored appropriately (i.e. oxygen cylinders, flammable materials, explosive products, oxidising products, aerosols)	N/A	No hazardous materials stored on site.		
8	Furniture/furnishings on escape routes and	loth	er communal areas:		
8.1	Furniture/furnishings in good condition, fire retardant and complies with 1988 Regulations.	N/A	No furniture allowed in the common areas.		
9	Other Significant Fire Hazards:				
9.1	Are there other significant fire hazards that are inadequately controlled?	No		•	
		Fire	e Protection Measures		
10	Means of Escape from Fire:				
10.1	Is it considered that the building is provided with reasonable means of escape in case of fire?	Yes	Final exit doors in all flats on the means of escape are FD30s and conforming to the latest British Standard.	ı	
10.2	Escape routes unobstructed and safe to use?	Yes		ı	
10.3	Exits easily and immediately openable where necessary, without a key?	Yes	All exit doors are of the push bar, push pad or thumb turn type	•	
10.4	Reasonable distances of travel where there is a single/alternative direction of travel?	Yes	All escape routes are within permissible distances some extra signage installed during inspection by	•	
10.5	Escape routes lead to final exits and open in direction of escape where necessary?	Yes		•	
	Do failsafe's on locked exit doors function correctly?	Yes	Some needed minor attention (completed during the inspection) by the Assessor.	•	
	Is it considered that the building is provided with reasonable arrangements for means of escape for disabled people?	No	Ground floor areas only are suitable for disabled access/egress.	•	
	Measures to Limit Fire Spread and Develop	men	t:		
11.1	Is it considered that the compartmentation is of a reasonable standard?	Yes		·	

11.2	Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?	Yes		•		
	Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?	N/A		•		
11.4	Compartmentation within roof spaces of a satisfactory standard?	Other	Findings previously submitted to compartment survey project			
11.5	Loft hatches fire resisting?	Yes	Communal area roof hatch's are close fitting and of 1hr fire rated steel construction.	ı		
11.6	Fire stopping above cross-corridor fire doors within suspended ceiling void of a satisfactory standard	V/N		•		
11.7	Smoke Control Systems (AOV's) Are records of annual testing available?	N/A	No Automatic vents fitted at this building.			
11.8	Roller shutter doors (fire resisting)	N/A		ı		
11.9	Do the external walls, windows, balconies etc pose a risk of significant fire spread?	No		I		
12	•		de - construction, hinges, closure devices, intum	nesce	ent/smoke s	eal condition,
	glazing systems and maximum gaps betwe	en d		-	•	
12.1	Communal fire doors to FD30s standard and in a serviceable condition,	Yes	There are no communal area fire doors fitted	•		
12.2	"Fire door keep shut/locked" signage displayed on both sides of all applicable doors.	Yes	Some signs were missing and were replaced/updated during the inspection.	•		
12.3	Hold open devices operate at the sounding of the alarm and are in a serviceable condition	A/N		•		
13	Flat entrance doors (Internal Common Area	is)				
13.1	Do flat entrance doors open onto internal escape routes?	Yes	If yes, see "Residents Front Doors Sheet"	ı		
14	Flats with a single direction of escape to a	sing	e escape stairway. (External Balcony)			

14.1	Do the flat entrance doors that open onto an external balcony have to be passed during an escape?	N/A	If yes, see "Residents Front Doors Sheet"	ı	
14.2	Are the separating walls between the flats and the balcony floor that have to be passed during an escape, fire-resisting up to a height of 1.1m?	N/A		I	
15	Emergency Escape Lighting:				
	Is the emergency lighting correctly specified and installed as per BS 5266-1:2016	Yes	Non-maintained emergency lighting is installed within all escape routes	•	
15.2	Are all emergency lighting units in good condition and securely fixed to walls/ceilings	Yes	All emergency lights fixed to the ceiling and walls.		
15.9	Are records of monthly testing available?	Yes	Annual test certs uploaded to M Files	I	
15.10	Are records of annual testing available?	Yes	Annual test certs uploaded to M Files Maintenance program in place	I	
16	Fire Safety Signs and Notices:				
16.1	Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?	Yes	Signage checked and updated during inspection		
16.3	Directional fire escape signage in place and adequate?	Yes	Signage checked and updated during inspection	I	
16.4	Is there a suitable LIFT sign i.e. do not use in case of fire.	N/A		·	
17	Means of giving Warning in case of Fire:				
17.1	Is the fire detection and warning system appropriate for the occupancy and fire risk?	Yes	All flats have smoke detection to LD2 standard. An additional heat detector is located in the flats.	I	
17.2	Is the fire detection and warning system correctly specified and installed as per BS 5839-1:2017	N/A		I	

17.3	Is the fire detection and warning system maintained/tested and all certificates saved on file. (BS 5839-1:2017)	N/A				
17.4	Are there heat detectors located in the Kitchen, Boiler, Plant Room and Laundry?	N/A		1		
	Is the fire alarm panel remotely monitored, and if so are there records of regular testing?	N/A				
17.6	Are smoke/heat detectors within General Needs flats subject to an annual inspection and the results recorded on an in date Landlord Gas Safety Record (LGSR)	Yes	A contract is in place with Tunstall to annually test the detection within each flat.			
18	Fire Extinguishing Equipment:				•	
	Portable fire extinguishers - appropriate type/number/position?	N/A	No Fire Extinguishers on site.			
18.2	Correct signage displayed by each fire extinguisher?	N/A		I		
	Fire blanket in communal kitchen, secured to the wall, complete with signage?	N/A		I		
18.4	Hose Reels - fitted, maintained?	A/N	None fitted	•		
18.5	Dry/wet risers - Full access to all inlet/outlet boxes. All inlet/outlets secured and/or securing straps fitted to outlet valves?	N/A	None fitted			
18.6	Records available of fire fighting equipment servicing within past 12 months	N/A				
19		N	lanagement of Fire Safety			
	Are there suitable arrangements for summoning the fire service?	Yes	It is the responsibility of our customers to raise the alarm and call the Emergency Services.	I		
	Do relevant staff carry out regular fire safety checks	Yes	Regular inspections are made by the Customer Partner and any works orders are raised	P		

19.3	Sheltered Schemes & Regional Offices - Are there sufficient number of qualified Fire wardens.	N/A		I		
19.4	Offices - Are there suitable arrangements for ensuring the premises are evacuated?	N/A		ı		
19.5	Offices - Are there suitable arrangements for evacuating disabled people?	N/A		ı		
19.6	Offices - Are there suitable arrangements for meeting the fire service on arrival and providing relevant information?	N/A				
19.7	Offices/IL Schemes - Is there a suitable assembly point?	N/A		I		
19.8	Offices - Are fire drills carried out at appropriate intervals?	N/A		I		
20	Evacuation Policy					
20.1	Taking the findings of the FRA into account, is the evacuation policy appropriate for the scheme?	Yes	Full (simultaneous) evacuation policy in operation			

	Residents Front Doors								
Goldsworth Road						/2024			
	Flat entrance doors to FD30s specification (Inspection to include - Door condition, construction, closure devices, intumescent/smoke seal condition, glazing systems, fire rated letterplate, door furniture and maximum gaps between door and frame/threshold.								
Flat No.	Access Gained	Asset No.	Observation/Comments / Actions Required	Risk Rating	Completion Date	Referred To:			
149A	No		Unable to gain access. External visual inspection only.Condition good.	-					

09/01/2024

Photographs - Fire Goldsworth Road





Photographs - Fire					
09/01/2024	Goldsworth Road				



All areas clear at the side of the building.

Photo No. 3

Photo No. 4 Flat Doors in good condition from the external inspection.

Photographs - Fire09/01/2024Goldsworth Road



6. Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

(please insert x below)

HIGH

2. Taking into account the nature of the building, the occupants, the fire protection afforded and

consequences for life safety in the event of a fire would be:

(please insert x below)



The definition of the above terms is as follows:

rka Review Frequency			
MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant		
	(other than the occupant sleeping in a bedroom in which a fire occurs).		
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely		
	to lead to fatalities.		
CRITICAL	There is significant potential for serious injury or death of one or more occupants.		

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trivial	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

Action Plan - Fire	
Goldsworth Road	09/01/2024
Low	

Action Plan - Residents Front Doors						
Goldsworth Road 09/01/2024						
Flat No.	Asset No.	Observation/Comments / Actions Required	Risk Rating	Completion Date	Referred To:	Task ID No.
		No Actions Raused.	-			