# Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 8823 1-40 Saxondale Court Block 1-40 Saxondale Court, Wakefield

#### **Cover Sheet**

Photo



Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

31 Dec 2024

31 Dec 2025

12

Annual Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Steven Manners TECH IOSH MIFSM MFPA

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

#### The Scheme

Scheme Name Saxondale Court

Scheme Address 1-40 Saxondale Court Block 1-40 Saxondale Court,

Wakefield

Postcode WF4 6AX

Region Yorkshire

Scheme Manager

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority West Yorkshire

Other staff in attendance Cherie Ackie

Number of on-site Accent staff Scheme Manager Part-Time

Number of other (non-Accent) staff

Contract Cleaners in common areas

# The Building

Accommodation Type CAT2 Housing for Older People (S28)

Build Date Jan 1 1983

Number Of Homes 39

Homes breakdown Flat, Maisonette

External wall construction Facing Brick

External wall finish Facing Brick

Roof construction Timber

Roof covering Interlocking Pitched

PEEPs in place where necessary

Yes

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys 2

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?) 3 Protected

Number of External Staircases None

External Balcony part of escape route?

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

# 1-40 Saxondale Court Block 1-40 Saxondale Court, Wakefield Asset ID: 8823 Fire Detection and Warning System Flats and common areas not linked Grade of fire alarm Grade A Category of fire alarm LD2 Additional Protection Non Maintained System - Common Areas **Emergency Lighting Provision** Portable Fire Extinguishers supplied/fitted Yes Fixed Fire Fighting Installations No **Customers** 50 Number of occupants Occupant tenure type breakdown CAT2 Housing for Older People, Designated Supported Housing for Older People, General Needs, Sheltered Schemes, Staff Accommodation Fire Safety Related Customer Safety Servicing 0 Overdue communal gas safety checks 0 Overdue domestic gas safety checks 0 Overdue communal electrical condition checks Overdue domestic electrical condition checks Overdue alarm call pull chord tests n 0 Overdue communal PAT testing Overdue customer mobility scooter PAT testing 0 Overdue Monthly Emergency Lighting Switch Tests 0 0 Overdue Annual Emergency Lighting tests 0 Overdue Weekly Fire Alarm Testing 1 Overdue Fire Panel - Six Monthly Testing Overdue Fire Safety Equipment tests 1 **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors Communal Fire doors due for replacement within 5 years 0 **Dwelling Doors** Failing Dwelling Fire Doors 0 Dwelling Fire doors due for replacement within 5 years 0

# Fire Risk Assessment Survey Results

# **Scheme and Building Information**

Photo



Date of Fire Risk Assessment 31/12/2024

FRA Frequency (Months) 12

Purpose of Fire Risk Assessment Annual Re-Assessment

Type of Risk Assessment

Type 1 (Common Parts Only - Non Destructive)

Quantity 1

Fire & Safety Assessor Steven Manners TECH IOSH MIFSM MFPA

Enforcing Fire Authority West Yorkshire

Scheme Tel. No

Other staff in attendance Cherie Ackie

Number of on-site Accent staff Scheme Manager Part-Time

Number of other (non-Accent) staff

Contract Cleaners in common areas

Scheme Inspection completed Yes

Number of occupants 50

Personal Emergency Evacuation Plans in place Yes

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of Storeys 2

Number of floors on which car parking is provided 0

Is there a habitable basement?

No. of internal staircases (protected/unprotected) 3 Protected

Number of external staircases

None

External balcony part of escape route?

Unusual features None

# Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Residential

Fire Detection and Warning System Flats and common areas not linked

Grade of Fire Alarm Grade A

Category of Fire Alarm LD2 Additional Protection

Emergency Lighting Provision Non Maintained System - Common Areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted Yes

Water Extinguisher(s) present No

Foam Extinguisher(s) present

Dry Powder Extinguisher(s) present No

Carbon Dioxide Extinguisher(s) present

Yes

Fire Blanket(s) present Yes

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present No

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present No

## **Electrical Sources of Ignition**

Electrical installation within common areas in good condition and no

obvious damage?

Comment All electrical installations are in good condition at

the time of inspection.

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment Certificate are available on ActiveH. Last test date

19/06/2023

Yes

Yes

Electrical App/PA Testing - tested within past 12 months?

Yes

Comment Tested 05/07/2024

Absence of trailing leads and adapters? Yes

Comment Nonne found at the time of inspection.

Evidence that mobility scooters are not being stored/charged in Yes

common areas?

Comment None found at the time of inspection.

Is there a purpose built mobility scooter store/charging area? Yes

Comment There is a garage external to the main building

where mobility scooters are stored and charged.

Does the building have a lightning protection system?

Comment N/A

Gas installations

Is there a commercial/domestic gas supply to the scheme?

Comment There are commercial and domestic gas supplies to

the scheme

Valid LGSR held on file for fixed communal area gas appliances?

Yes

(Boilers)

Comment The communal are a suply was tested 27/11/2024

Valid LGSR held on file for residential flats that contains gas

Yes

appliances?

Comment Each residence has a gas certificate if supplied with

gas. Yes

Yes

Are smoke/heat detectors within General Needs flats subject to an

annual inspection and the results

Comment Tested by Tunstall, all records held on ActiveH

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered

to?

Comment Smoking is not llowed in communal areas but

smoking is allowed in residents flats.

Adequate security against arson?

Comment There is a fob entry system and exits are alarmed.

Are refuse/recycling bin areas managed and suitably located?

Comment The refuse area is seperate t the main building and

is accessed from the outside.

Are there communal cooking facilities at this scheme?

Comment There is a small kitchen adjasent to the communal

lounge.

N/A

Are reasonable measures taken to prevent fires as a result of cooking?

Comment There is always more than one person when cooking

is taking place in the kitchen. The kitchen is mostly

used for coffe and tea making.

Where there is extraction in communal kitchens, are filters and

ductwork changed/cleaned regularly?

Comment None fitted.

#### 1-40 Saxondale Court Block 1-40 Saxondale Court, Wakefield Asset ID: 8823

# Housekeeping

Are all electrical/intake/service cupboards secure and free from general

waste, contractors waste and and residents personal items?

Are unnecessary accumulations of combustible materials or waste

avoided?

Comment

Comment

Comment Nnone found at the time of inspection.

Are combustible materials and substances separated from ignition

sources and stored appropriately?

Furniture/furnishings in good condition, fire retardant/resistant and

comply with modern standards and regulations?

Comment The furniture in the communal lounge is compliant with the latest regulations.

# Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Comment None found at the time of inspection.

### Means of Escape from Fire

Is it considered that the building is provided with reasonable means of

escape in case of fire?

Escape routes unobstructed and safe to use?

Exits immediately openable without a key and/or failsafe's function

correctly?

Comment

Comment

Comment

Reasonable distances of travel where there is a single/alternative

direction of travel?

Escape routes lead to final exits and open in direction of escape where

necessary?

Comment

Comment

Yes

Yes

Yes

Yes

Yes

All free of waste at the time of inspection.

none found at the time of inspection.

There are several means of escape throughout the

building.

Yes

All escape routes are available at the time of

inspection.

Yes

All exits are either Push bars or thumb turns.

Yes

All single directions of travel are within the

quidelines.

Yes

Observation Priority Referred To Required By: Task ID

Door mats excessive thickness could cause trip hazard. Flat 21 and 24. Dog ornament outside 24.



Internal - Medium Independent Living Coordinator



# Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?

Comment

Comment

As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?

Loft hatches fire resisting?

Comment

Comment

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?

Do external walls, doors, windows and anything attached

Do external walls, doors, windows and anything attached to the exterior, limit fire spread?

Comment

Comment

If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?

Comment

Are roller shutter doors that are required to be FR, fire resisting and self-closing?

scii-closing:

Comment

Yes

All compartmenttion is of a reasonable standard at the time of inspection.

Yes

All notices are behind perspex.

N/A

None fitted on scheme.

N/A

No access to roof space during this inspection.

Yes

Yes

no breaches found at the time of inspection.

Yes

The scheme is of a brick built type with a clay slate

roof. N/A

None fitted.

N/A

None fitted.

Observation Priority Referred To Required By: Task ID

Hole in meter room 1 door needs repair or replacement.

Internal - Medium



Observation Priority Referred To Required By: Task ID

Laundry room door requires replacing an order has been placed for this to be done.





Observation Priority Referred To Required By: Task ID

New flat door fitted to flat 17.



Observation Priority Referred To Required By: Task ID

Office door requires replacing, an order has been placed for this to be done.





Observation Priority Referred To Required By: Task ID

Other combustible items stored in scooter store to be removed.



Internal - Medium Independent Living Coordinator



Observation Priority Referred To Required By: Task ID

Repair hole in door to meter room 2



Internal - Medium

# **Emergency Escape Lighting**

Is the emergency lighting correctly specified and installed as per current standards?

Comment

Emergency lighting units in good condition and securely fixed to walls/ceilings?

Comment

Yes

Yes

All in good conditionat the time of inspection.

1-40 Saxondale Court Block 1-40 Saxondale Court, Wakefield Asset ID: 8823

Records of monthly/annual testing available? Yes

Comment Monthly tests are carried out by the Scheme

manager, the Annual drop test is completed by Tunstall. All records are available on ActiveH.

Monthly test 05/12/2024 Annual test 11/05/2024

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent

locations within the common areas?

Comment Signage displayed throughout the building.

Directional fire escape signage in place and adequate? Yes

Comment Adequate signage is displayed throughout the

building.

Yes

Is there suitable LIFT signage i.e. do not use in case of fire? Yes

Comment lift signage displayed adjacent to the lifts on each

> floor. Yes

Do common area fire doors display the correct signage on both sides

where applicable?

Comment Signage displayed on communal fire doors

throughout the building.

Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm? Yes

Comment

Comment

Comment

Yes Is fire detection and warning system appropriate for occupancy and fire

risk, as per BS 5839-1:2017?

Is the fire detection and warning system maintained/tested and all

certificates saved on file?

Comment All records and certificates can be found on ActiveH

Fire alarm components in good condition and securely fixed to Yes

walls/ceilings?

Comment All components in good conditionat the time of

inspection.

Yes

Yes

Yes

Hold open devices operate at the sounding of the alarm and are in a

serviceable condition?

Comment All in good condition at the time of inspection.

Are there heat detectors located in the Kitchen, Boiler, Plant Room and Laundry?

Yes Is the fire alarm panel remotely monitored, and if so are there records of regular testing?

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 11 of 17

Generated 02/01/2025 12:58:27

Comment

All records are available on ActiveH. Last test date 06/11/2024

Observation Priority Referred To Required By: Task ID

Fire alarm panels and plan.





no firefighting equipment provided in the communal area. Equipment is provided in high risk areas.

All correct at the time of inspection.

# Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme?

Comment

Portable fire extinguishers - appropriate type/number/position?

Correct signage displayed by each fire extinguisher?

Fire blanket in communal kitchen, secured to the wall, complete with

signage?

Comment

Comment

Comment

Dry risers - Inlet/outlet boxes secured and/or securing straps fitted to

outlet valves?

Comment None fitted.

Records available of fire fighting equipment servicing within past 12

months?

Comment tested 16/07/2024

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under

the Building Safety Act?

Comment

Are there other Responsible Persons who share or have fire safety

duties in respect of the premises?

How will this sharing be achieved?

Is an office or IL scheme being inspected?

No

Yes

No

Yes

Yes

Yes

Yes

N/A

Yes

As above.

Page 12 of 17

Generated 02/01/2025 12:58:27

Comment

IL Schemes & Regional Offices - Are there sufficient numbers of

qualified Fire wardens?

Comment None required.

Offices - Are there suitable arrangements for ensuring the premises are

evacuated?

Comment The residents are aware of the fire proceedures

within the building.

N/A

Yes

Yes

N/A

Offices - Are there suitable arrangements for evacuating disabled

people?

Comment A PCFRA is due to be completed for each resident

to determine if a PEEP is required.

Offices - Suitable arrangements for meeting the fire service on arrival

and proving relevant information?

Comment Only during the working hours of the Scheme

Manager.

Offices/IL Schemes - Is there a suitable assembly point?

Yes

Comment It can be found in the carpark to the Scheme.

Offices - Are fire drills carried out at appropriate intervals?

N/A

Comment Not required, this is an ILS

**Passenger Lift** 

Is the scheme fitted with a passenger lift?

Comment

Is the lift in full working order at the time of the FRA?

Yes

Comment In good working order at the time of inspection.

Is the lift fitted with a firefighters switch?

Comment

Servicing and insurance inspection - Evidence of regular Yes

servicing/maintenance?

Comment All records are available on ActiveH

**Premises Inspection Box** 

Is there a premises information box for fire & rescue service use?

Comment All ILS schemes are to be provided with one in the

near future.

**Evacuation Policy** 

Are there suitable arrangements for summoning the fire service?

MIS-AMS ActiveH - Fire Risk Assessment Report Page 13 of 17 Generated 02/01/2025 12:58:27

Taking FRA findings, is the evacuation policy appropriate for the

scheme as per latest guidance?

Comment

Comment

There is a communal fire alarm which auto dials a monitoring system. Residents have a warden call system. Residents are also instructed to dial 999.

Yes

**Engagement with Residents** 

Has information of fire procedures been disseminated to residents?

Comment

Is general fire safety information disseminated to residents?

Comment

Yes

All residents received a leaflet explaining the evacuation protocol and information about their flat front doors. This information is also available on the website and is given during handover proceedures.

Yes

All residents received a leaflet explaining the evacuation protocol and information about their flat front doors. This information is also available on the website and is given during handover proceedures.

**FRA Frequency** 

Taking the findings of this assessment into account, is the frequency of the FRA correct?

Comment

Yes

Miscellaneous

Are there any other observations/actions to raise that are not covered

Are there fire related remedial works required at this property, that will affect the fabric of the building?

Comment

Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).

Some fire doors did not fully close so works orders have been raised with our contractors.

Some minor works were required which have been raised with our contractors.

Unauthorised items were found in communal areas and arrangements were made for their removal.

Not all records were up to date, as noted in the table below. Arrangements have been made for these to be completed.

A number of fire doors were found to be wedged or propped open. Fire doors are there to keep you safe and me kept shut at all times.

No

No

Some works that are required have been ordered pre

FRA

Yes

No

Yes

Yes

No

No

Observation Priority Referred To Required By: Task ID

Upvc door to garden from communal lounge requires adjusting to open fully. It is catching on the floor.



Internal - Medium

#### **Risk Calculator - Fire**

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW

MEDIUM

HIGH

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR MAJOR	X	CRITICAL	
-------------	---	----------	--

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial
	<u> </u>