Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 707 2 - 7 Southwick Close, Peterborough

Cover Sheet

Photo

Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

06 Feb 2023

06 Feb 2026

36

3 year Re-Assessment

Type 3 (Common Parts and Flats - Non Destructive)

Lynn Betteridge

This report has been validated by:

Name: K D John

Date: 22/02/2023

Comment: Report is complete and legible

Asset ID: 707 2 - 7 Southwick Close, Peterborough

The Scheme

Scheme Name Paston

Scheme Address 2 - 7 Southwick Close, Peterborough

Postcode PE4 7PP

Region East

Scheme Manager

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority CAMBBRIDGESHIRE FIRE AND RESCUE

Other staff in attendance

Number of on-site Accent staff

None

Number of other (non-Accent) staff

The Building

Accommodation Type General Needs (S30)

Build Date Jan 1 1983

Number Of Homes 6

Homes breakdown Flat

External wall construction Facing Brick

External wall finish Facing Brick, Timber Clad

Roof construction Timber

Roof covering Flat Roof, Interlocking Pitched

PEEPs in place where necessary

Yes

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

Number of External Staircases None

External Balcony part of escape route? N/A

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

2 - 7 Southwick Close, Peterborough Asset ID: 707 Fire Detection and Warning System Flats only Grade D Grade of fire alarm Category of fire alarm LD3 Minimum Protection **Emergency Lighting Provision** Non Maintained System - Common Areas Portable Fire Extinguishers supplied/fitted No Fixed Fire Fighting Installations No **Customers** 12 Number of occupants General Needs, Leasehold Occupant tenure type breakdown Fire Safety Related Customer Safety Servicing Overdue communal gas safety checks 0 0 Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 Overdue communal PAT testing 0 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests Overdue Annual Emergency Lighting tests 1 Overdue Weekly Fire Alarm Testing 0 Overdue Fire Panel - Six Monthly Testing Overdue Fire Safety Equipment tests **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors Communal Fire doors due for replacement within 5 years 0 **Dwelling Doors** 0 Failing Dwelling Fire Doors

Dwelling Fire doors due for replacement within 5 years

0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



Date of Fire Risk Assessment 06/02/2023

FRA Frequency (Months) 36

Purpose of Fire Risk Assessment 3 year Re-Assessment

Type of Risk Assessment

Type 3 (Common Parts and Flats - Non Destructive)

Quantity

Fire & Safety Assessor Lynn Betteridge

Enforcing Fire Authority CAMBBRIDGESHIRE FIRE AND RESCUE

Scheme Tel. No

Other staff in attendance

Number of on-site Accent staff

None

Number of other (non-Accent) staff

Scheme Inspection completed Yes

Number of occupants 12

Personal Emergency Evacuation Plans in place Yes

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of Storeys 3

Number of floors on which car parking is provided 0

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

Number of external staircases None

External balcony part of escape route? N/A

Unusual features None

Asset ID: 707 2 - 7 Southwick Close, Peterborough

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Residential

Fire Detection and Warning System Flats only

Grade of Fire Alarm Grade D

Category of Fire Alarm LD3 Minimum Protection

Emergency Lighting Provision Non Maintained System - Common Areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted No

Water Extinguisher(s) present

Foam Extinguisher(s) present

Dry Powder Extinguisher(s) present

Carbon Dioxide Extinguisher(s) present

Fire Blanket(s) present

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present No

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no

obvious damage?

Comment

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment Located on Active H in safety files.

Electrical App/PA Testing - tested within past 12 months?

Yes

Comment ELECTRICAL 5 YEAR CERT 18/12/18

Absence of trailing leads and adapters? Yes

Comment

Evidence that mobility scooters are not being stored/charged in No

common areas?

Comment

Is there a purpose built mobility scooter store/charging area?

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 5 of 12

Generated 06/02/2023 13:38:40

Yes

Yes

Asset ID: 707 2 - 7 Southwick Close, Peterborough	
Comment	
Does the building have a lightning protection system?	No
Comment	
Gas installations	
Is there a commercial/domestic gas supply to the scheme?	Yes
Comment	Sample flat no7 gas safety tests annually dated 5/10/22
Valid LGSR held on file for fixed communal area gas appliances? (Boilers)	Yes
Comment	
Valid LGSR held on file for residential flats that contains gas appliances?	Yes
Comment	As above no60
Are smoke/heat detectors within General Needs flats subject to an annual inspection and the results	Yes
Comment	Tested 5/10/22
Other Sources of Ignition	
Is there a no smoking policy in place, which is enforced and adhered to?	Yes
Comment	Signage in place.
Adequate security against arson?	Yes
Comment	At time of inspection main door secure.
Are refuse/recycling bin areas managed and suitably located?	Yes
Comment	
Are there communal cooking facilities at this scheme?	No
Comment	
Housekeeping	
Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items? Comment	Yes
Are unnecessary accumulations of combustible materials or waste	Yes
avoided? Comment	None found at time of inspection.
Are combustible materials and substances separated from ignition sources and stored appropriately?	Yes

Page 6 of 12

MIS-AMS ActiveH - Fire Risk Assessment Report

Generated 06/02/2023 13:38:40

2 - 7 Southwick Close, Peterborough Asset ID: 707 Comment Yes Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations? Comment Other Significant Fire Hazards Are all other significant fire hazards adequately controlled? Yes Comment Means of Escape from Fire Yes Is it considered that the building is provided with reasonable means of escape in case of fire? Exit route only one direction of travel. Comment Yes Escape routes unobstructed and safe to use? Comment Yes Exits immediately openable without a key and/or failsafe's function correctly? Comment Reasonable distances of travel where there is a single/alternative Yes direction of travel? Comment Escape routes lead to final exits and open in direction of escape where Yes necessary? Comment The escape route meets code of practice Doc B3 Fire Spread and Development Yes Is it considered that the compartmentation is of a reasonable standard? Comment Yes Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)? ALL FINISHES WILL NOT ENABLE FIRE SPREAD. Comment N/A Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products? Comment Yes As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard? Comment 1 HOUR FIRE RESISTING LOFT HATCH ACCESSED. Yes Loft hatches fire resisting?

Page 7 of 12

Generated 06/02/2023 13:38:40

MIS-AMS ActiveH - Fire Risk Assessment Report

2 - 7 Southwick Close, Peterborough Asset ID: 707 Comment Yes As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard? Comment Complient smoke lobbies on each floor floor to ceiling with Georgian glass and FD30 fire door. Do external walls, doors, windows and anything attached to the No exterior, limit fire spread? Comment The external walls doors and windows will not propagate fire spread around the envelope of the building. N/A If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available? Comment Are roller shutter doors that are required to be FR, fire resisting and N/A self-closing? Comment **Emergency Escape Lighting** Is the emergency lighting correctly specified and installed as per Yes current standards? Checked and tested by tunstall contract. Comment Yes Emergency lighting units in good condition and securely fixed to walls/ceilings? Comment All in good condition at time of inspection. Yes Records of monthly/annual testing available? Comment Tunstalls carry out monthly and annual drop test dates Annual 12/9/22 Monthly 3/1/23. Fire Safety Signs and Notices Are the correct Fire Action/Advice notices displayed in prominent Yes locations within the common areas? Main access door. Comment Directional fire escape signage in place and adequate? Yes One direction of travel. Comment Is there suitable LIFT signage i.e. do not use in case of fire? No Comment Yes Do common area fire doors display the correct signage on both sides

where applicable?

Comment

2 - 7 Southwick Close, Peterborough Asset ID: 707 Means of giving Warning in case of Fire Is the scheme fitted with a communal area fire alarm? No Comment Fire Extinguishing Equipment No Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme? Comment Management of Fire Safety Yes Are these premises regulated by the Building Safety Regulator under the Building Safety Act? Comment Will this FRA be shared will all Accountable Persons for the premises? Yes Comment Communication with residents and fire authority. How will this sharing be achieved? The fire risk assessment for this building will be held on active H and shared with the Residence or any of the persons who wish to look at the high risk assessment details Yes Are there other Responsible Persons who share or have fire safety duties in respect of the premises? Have all details required by regulations been shared with all other Yes Responsible Persons? Comment Yes Have all details required by regulations to be shared with us from other Responsible Persons been received and recorded? Comment Yes Will this FRA be shared will all other Responsible Persons for the premises? Comment The FRA will be located on the organisations files in the ACtive H software and communication to requesting bodies. How will this sharing be achieved? Is an office or IL scheme being inspected? No

Passenger Lift

Is the scheme fitted with a passenger lift?

Comment

Comment

No

2 - 7 Southwick Close, Peterborough Asset ID: 707 **Premises Inspection Box** Is there a premises information box for fire & rescue service use? No Comment **Evacuation Policy** Are there suitable arrangements for summoning the fire service? Yes Comment Residents responsible for contacting FRService. Yes Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance? Comment **Engagement with Residents** Has information of fire procedures been disseminated to residents? Yes Comment When residents move into a property they are given fire Safety advice also leaflets and access to the organisation fire safety website. Yes Is general fire safety information disseminated to residents? Comment **FRA Frequency** Yes Taking the findings of this assessment into account, is the frequency of the FRA correct? Comment Miscellaneous

Are there any other observations/actions to raise that are not covered above.

Are there fire related remedial works required at this property, that will

affect the fabric of the building?

Comment

Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).

No

No

No

Asset ID: 707 2 - 7 Southwick Close, Peterborough

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management

Systems.					
_	•	evention measures the hazard from the			at this
LOW	X	MEDIUM		HIGH	
any procedural	arrangements ob	of the building, the served at the time on the event of a fire wo	of the assessn	•	
MINOR		MAJOR	$\overline{\mathbf{x}}$	CRITICAL	

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Asset ID: 707

2 - 7 Southwick Close, Peterborough

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial
	