Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 30982 2-10 Maple Croft Block 2-10, Leeds

Cover Sheet

Photo



Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

13 Jun 2024

13 Jun 2025

12

Annual Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Steven Manners

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name Maple Croft

Scheme Address 2-10 Maple Croft Block 2-10, Leeds

Postcode LS17 6AN

Region Yorkshire

Scheme Manager Lavena Lawrence

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority West Yorkshire

Other staff in attendance None

Number of on-site Accent staff Scheme Manager Part-Time

Number of other (non-Accent) staff

Contract Cleaners in common areas

The Building

Accommodation Type Leasehold for Older People (S60)

Build Date Jan 1 1920

Number Of Homes 5

Homes breakdown Flat

External wall construction Facing Brick

External wall finish Cement Render, Facing Brick

Roof construction Timber

Roof covering Flat Roof, Plain Pitched

PEEPs in place where necessary N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Conversion

Number of storeys

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?) 1 protected

Number of External Staircases None

External Balcony part of escape route?

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

Asset ID: 30982 2-10 Maple Croft Block 2-10, Leeds Fire Detection and Warning System Flats and common areas not linked Grade D Grade of fire alarm Category of fire alarm LD3 Minimum Protection **Emergency Lighting Provision** Non Maintained System - Common Areas Portable Fire Extinguishers supplied/fitted Yes Fixed Fire Fighting Installations No **Customers** 10 Number of occupants Leasehold for Older People, Leasehold Occupant tenure type breakdown Fire Safety Related Customer Safety Servicing Overdue communal gas safety checks 0 0 Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 Overdue communal PAT testing 0 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests Overdue Annual Emergency Lighting tests 1 0 Overdue Weekly Fire Alarm Testing Overdue Fire Panel - Six Monthly Testing Overdue Fire Safety Equipment tests **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors Communal Fire doors due for replacement within 5 years 0 **Dwelling Doors** 0 Failing Dwelling Fire Doors

Dwelling Fire doors due for replacement within 5 years

0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



Date of Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Risk Assessment

Quantity

Fire & Safety Assessor

Enforcing Fire Authority

Scheme Tel. No

Other staff in attendance

Number of on-site Accent staff

Number of other (non-Accent) staff

Scheme Inspection completed

Number of occupants

Personal Emergency Evacuation Plans in place

Current Evacuation Strategy

Conversion or purpose-built

Number of Storeys

Number of floors on which car parking is provided

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

Number of external staircases

External balcony part of escape route?

Unusual features

13/06/2024

12

Annual Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

1

Steven Manners

West Yorkshire

None

Scheme Manager Part-Time

Contract Cleaners in common areas

Yes

10

N/A

Stay Put (Delayed) Evacuation

Conversion

2

0

No

1 protected

None

No

None

2-10 Maple Croft Block 2-10, Leeds Asset ID: 30982

Fire Risk Assessment Survey Results

Vehicular Access to one or more elevations Building access conditions for Fire Brigade

Surroundings: Residential/Commercial Residential

Flats and common areas not linked Fire Detection and Warning System

Grade D Grade of Fire Alarm

Category of Fire Alarm **LD3 Minimum Protection**

Non Maintained System - Common Areas **Emergency Lighting Provision**

Portable Fire Extinguishers / Fire Blankets supplied / fitted Yes

Water Extinguisher(s) present No

No Foam Extinguisher(s) present

Dry Powder Extinguisher(s) present No

Yes Carbon Dioxide Extinguisher(s) present

No Fire Blanket(s) present

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present No

No Sprinkler System present

No Hosereel(s) present

Automatic Opening Vent(s) present No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no

obvious damage?

Comment

THere is no electrical equiepment within the communal areas.

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment All electrical test records can ber found on ActiveH

Yes Electrical App/PA Testing - tested within past 12 months?

Comment Labels on the equipment in the office are within

date, thte certificates for testing can bee found on

ActiveH.

N/A

Yes

Absence of trailing leads and adapters?

Comment The use of adaptores within the office is kept to a

minimum.

Evidence that mobility scooters are not being stored/charged in

common areas?

Yes

Is there a purpose built mobility scooter store/charging area?

Comment

Does the building have a lightning protection system?

Comment

Comment

No

Gas installations

Is there a commercial/domestic gas supply to the scheme?

Comment

No

N/A

Not required.

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered

to?

Adequate security against arson?

Comment

Comment

Are refuse/recycling bin areas managed and suitably located?

Comment

Are there communal cooking facilities at this scheme?

Comment

Yes

Nno smoking allowed within the communal areas

THere are no Mobility scooters at this scheme.

but residents may smoke within their flats.

Yes

Bith doors are secured by a lock and key. Thumb

turn to egress on each door. there is CCTV

surrounding the building.

Yes

Bins are clear of the building at the time of

insprction.

No

Housekeeping

Are all electrical/intake/service cupboards secure and free from general

waste, contractors waste and and residents personal items?

Are unnecessary accumulations of combustible materials or waste

avoided?

Comment

Comment

Comment

Are combustible materials and substances separated from ignition

sources and stored appropriately?

Furniture/furnishings in good condition, fire retardant/resistant and

comply with modern standards and regulations?

Yes

Nothing found at the time of inspection.

No

Waste bin in Scheme Managers Office needs to be

emptied at the end of day. Schene Manager

informed and is dealing.

Yes

None found at the time of inspection.

N/A

2-10 Maple Croft Block 2-10, Leeds Asset ID: 30982

Observation **Priority** Referred To Required By: Task ID

of the building.

Bins should be emptied at the end of the day to reduce

fire loading

Comment



Internal - Medium

Independent Living Coordinator

Furniture is not allowed within the communal areas

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled? Yes

None found at the time of inspection Comment

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of

escape in case of fire?

Escape routes unobstructed and safe to use?

Exits immediately openable without a key and/or failsafe's function

correctly? Comment

Comment

Comment

Reasonable distances of travel where there is a single/alternative

direction of travel?

Comment

Escape routes lead to final exits and open in direction of escape where

necessary?

Comment

Yes

The first floor leads to a protected staircase. At the foot of the staircase there is 2 directions of travel.

TH etravel distances are within the guidlines.

No

There were some conmbustible items at the foot of

the stairs that require removing. The Scheme

Manager has been informed.

Yes

Thumb turn locks are fitted to both exit doors.

Yes

As Above.

No

Both external doors open inwards due to the nature


of the building.

Observation Priority Referred To Required By: Task ID

Flammable items at foot of stairs on the escape route to be removed

Internal - Medium

Independent Living Coordinator



Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?

Comment

Comment

Comment

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?

As far as can be reasonably ascertained, is the compartmentation

within roof spaces of a satisfactory standard?

within roof spaces of a satisfactory standard?

Loft hatches fire resisting?

Comment

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory

standard? Comment

Do external walls, doors, windows and anything attached to the

exterior, limit fire spread?

Comment

If Smoke Control Systems (AOV's) are fitted, are the records of annual

testing available?

Yes

There were no compartmentation issues at the time of inspection. The communal fire doors at the top and bottom of the stairs were in good condition, all gaps were to tolerance and seals were in good

condition.

Yes

N/A

None fitted at this scheme

No

A survey is required in the loft space, there is an old fire curtain within the loft space that may need

replacing.

No

the loft hatch is not a fire rated loft hatch. It would

however give some fire resistance.

N/A

There are no cross corridor doors at this scheme.
THe communal fire doors at the end of the corridor

have no voids above them.

Yes

N/A

2-10 Maple Croft Block 2-10, Leeds Asset ID: 30982

Comment Nnone fitted at this scheme.

Are roller shutter doors that are required to be FR, fire resisting and

self-closing? C

ıe.
E

Priority

A fire curtain in the roof space needs either replacing or re-fixing. there may be other areas within the roof space that require attention. could not gain full access to the loft space. A survey is required in the roof space to determine compartmentation.



Referred To Required By: Task ID 31/07/2024 1827895 Repair - Non **Project Manager Emergency** (Building Safety)

No

Yes

Emergency Escape Lighting

walls/ceilings?

Observation

is the emergency lighting correctly specified	and installed as per
current etandarde?	

Comment This scheme has a non-maintained system in the common areas.

Yes Emergency lighting units in good condition and securely fixed to

All EL in good condition at the time of inspection. Comment

Records of monthly/annual testing available? Yes

Comment The monthly and Anual tests are carried out by Tunstall, results can be found on ActiveH.

Fire Safety Signs and Notices

Yes Are the correct Fire Action/Advice notices displayed in prominent

locations within the common areas?

Comment Notices are displayed in the communal areas. A review of the evacuation strategy will take place due to compartmentation issues in the roof space. There is detection within the communal areas which may

need to be removed in the future.

There is signage throughoutt the building. Comment

Is there suitable LIFT signage i.e. do not use in case of fire? N/A

Directional fire escape signage in place and adequate?

Do common area fire doors display the correct signage on both sides

where applicable?

Comment

Comment

No Lift at this scheme.

Hard wired smoke detection with no alarm Panel.

All componenets in good conditiopn at the time of

Yes

Yes

Yes

Yes

Yes

No

N/A

Yes

inspection. N/A

None fitted at this scheme.

None fitted at this scheme.

Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?

Comment

Is fire detection and warning system appropriate for occupancy and fire risk, as per BS 5839-1:2017?

Comment

Is the fire detection and warning system maintained/tested and all

certificates saved on file?

Comment

Comment

Fire alarm components in good condition and securely fixed to

walls/ceilings?

Hold open devices operate at the sounding of the alarm and are in a

serviceable condition?

Are there heat detectors located in the Kitchen, Boiler, Plant Room and

Laundry?

Comment

Comment

Is the fire alarm panel remotely monitored, and if so are there records of

regular testing?

Comment This sis a stand alaone system.

Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations

provided at this scheme?

Comment Extinguisher in Scheme Managers Office.

Portable fire extinguishers - appropriate type/number/position? Yes

Comment

Correct signage displayed by each fire extinguisher? Yes

Comment

Fire blanket in communal kitchen, secured to the wall, complete with N/A

signage?

Comment No Communal Kitchen on this site.

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 10 of 14

Generated 18/06/2024 16:01:46

Dry risers - Inlet/outlet boxes secured and/or securing straps fitted to

outlet valves?

Records available of fire fighting equipment servicing within past 12

months?

Comment

Comment

N/A

None fitted at this scheme.

Yes

Label on extinguishers in date and all records are

available on ActiveH.

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under

the Building Safety Act?

Are there other Responsible Persons who share or have fire safety

duties in respect of the premises?

How will this sharing be achieved?

Is an office or IL scheme being inspected?

Comment

Comment

No

Not in scope.

No

No

Passenger Lift

Is the scheme fitted with a passenger lift?

Comment

No

Premises Inspection Box

Is there a premises information box for fire & rescue service use?

Comment

No

Evacuation Policy

Are there suitable arrangements for summoning the fire service?

Comment

Yes

residents are instructed to dial 999.

Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance?

scrience as per latest guidance

Comment

The evacuation strategy is under review, the scheme Manager has been instructed to inform the residents that a full evacuation policy will be in place until the compartmentation in the loft space has been completed.

Engagement with Residents

Has information of fire procedures been disseminated to residents?

Comment

Is general fire safety information disseminated to residents?

Comment

Yes

All redidents have ben given information about Fire safety in the form of a letter and information leaflets.

Yes

All redidents have ben given information about Fire safety in the form of a letter and information leaflets. More information is available on the website.

FRA Frequency

Taking the findings of this assessment into account, is the frequency of the FRA correct?

Comment

Yes

Miscellaneous

Are there any other observations/actions to raise that are not covered above.

Action leading to a repair

Internal administrative Action

Are there fire related remedial works required at this property, that will affect the fabric of the building?

Comment

Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).

Some fire doors did not fully close so works orders have been raised with our contractors.

Some minor works were required which have been raised with our contractors.

Unauthorised items were found in communal areas and arrangements were made for their removal.

Not all records were up to date, as noted in the table below. Arrangements have been made for these to be completed.

A number of fire doors were found to be wedged or propped open. Fire doors are there to keep you safe and me kept shut at all times.

Yes

Yes

Yes

No

Yes

No

Yes

Yes

No

No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

systems.					
	•	revention measures obs at the hazard from the fir			is
LOW	X	MEDIUM		HIGH	
any procedura	al arrangements o	e of the building, the occ bserved at the time of th the event of a fire would	e assessment,	•	
MINOF		MAJOR V		CRITICAL	

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial
	