

This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 8670 1-39 Astura Court Block 1-39 Astura Court, Leeds

Cover Sheet

Photo

Date of Fire Risk Assessment Date of Next Fire Risk Assessment FRA Frequency (Months) Purpose of Fire Risk Assessment Type of Fire Risk Assessment Fire & Safety Assessor



02 Feb 2024 02 Feb 2025 12 Annual Re-Assessment Type 1 (Common Parts Only - Non Destructive) Steven Manners

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name	Astura Court
Scheme Address	1-39 Astura Court Block 1-39 Astura Court, Leeds
Postcode	LS7 2DL
Region	Yorkshire
Scheme Manager	
Scheme Tel. No	01132623599
Scheme Inspection Completed	Yes
Enforcing Fire Authority	West Yorkshire
Other staff in attendance	Lavena Lawrence
Number of on-site Accent staff	Scheme Manager Part-Time
Number of other (non-Accent) staff	Contract Cleaners in common areas

The Building

Accommodation Type	CAT2 Housing for Older People (S28)
Build Date	Jan 1 1977
Number Of Homes	38
Homes breakdown	Bedsit, Flat
External wall construction	Facing Brick
External wall finish	Facing Brick
Roof construction	Timber
Roof covering	Flat Roof, Interlocking Pitched
PEEPs in place where necessary	Yes
Current Evacuation Strategy	Stay Put (Delayed) Evacuation
Conversion or purpose-built	Purpose Built
Number of storeys	2
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
Number of internal Staircases (protected or unprotected?)	2 not protected
Number of External Staircases	None
External Balcony part of escape route?	No
Unusual features	None
Building Access Conditions for Fire Brigade	Vehicular Access to one or more elevations

Fire Detection and Warning System	Flats and common areas not linked
Grade of fire alarm	Grade D
Category of fire alarm	LD3 Minimum Protection
Emergency Lighting Provision	Mixed system - Common areas
Portable Fire Extinguishers supplied/fitted	Yes
Fixed Fire Fighting Installations	No

Customers

Number of occupants	38
Occupant tenure type breakdown	General Needs, CAT2 Housing for Older People,
	Staff Accommodation

Fire Safety Related Customer Safety Servicing

Overdue communal gas safety checks	0
Overdue domestic gas safety checks	0
Overdue communal electrical condition checks	0
Overdue domestic electrical condition checks	0
Overdue alarm call pull chord tests	0
Overdue communal PAT testing	0
Overdue customer mobility scooter PAT testing	0
Overdue Monthly Emergency Lighting Switch Tests	1
Overdue Annual Emergency Lighting tests	1
Overdue Weekly Fire Alarm Testing	1
Overdue Fire Panel - Six Monthly Testing	1
Overdue Fire Safety Equipment tests	1
Building Fire Safety Surveys - Communal Doors	
Failing Communal Fire Doors	0

Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	0

Dwelling Doors

Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo

Date of Fire Risk Assessment
FRA Frequency (Months)
Purpose of Fire Risk Assessment
Type of Risk Assessment
Quantity
Fire & Safety Assessor
Enforcing Fire Authority
Scheme Tel. No
Other staff in attendance
Number of on-site Accent staff
Number of other (non-Accent) staff
Scheme Inspection completed
Number of occupants
Personal Emergency Evacuation Plans in place
Current Evacuation Strategy
Conversion or purpose-built
Number of Storeys
Number of floors on which car parking is provided
Is there a habitable basement?
No. of internal staircases (protected/unprotected)
Number of external staircases
External balcony part of escape route?
Unusual features



12
Annual Re-Assessment
Type 1 (Common Parts Only - Non Destructive)
1
Steven Manners
West Yorkshire
01132623599
Lavena Lawrence
Scheme Manager Part-Time
Contract Cleaners in common areas
Yes
38
Yes
Stay Put (Delayed) Evacuation
Purpose Built
2
0
Νο
2 not protected
None
No
None

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade	Vehicular Access to one or more elevations
Surroundings: Residential/Commercial	Residential
Fire Detection and Warning System	Flats and common areas not linked
Grade of Fire Alarm	Grade D
Category of Fire Alarm	LD3 Minimum Protection
Emergency Lighting Provision	Mixed system - Common areas
Portable Fire Extinguishers / Fire Blankets supplied / fitted	Yes
Water Extinguisher(s) present	No
Foam Extinguisher(s) present	No
Dry Powder Extinguisher(s) present	No
Carbon Dioxide Extinguisher(s) present	Yes
Fire Blanket(s) present	Yes
Fixed Fire Fighting Installations supplied / fitted	No
Dry Riser(s) present	No
Wet Riser(s) present	No
Sprinkler System present	No
Hosereel(s) present	No
Automatic Opening Vent(s) present	No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no obvious damage?	Yes
Comment	All installations in good condition at the time of inspection
Valid Electrical Installation Condition Reports held on file? (Common Areas & General Needs Flats)	Yes
Comment	All records are available on ActiveH
Electrical App/PA Testing - tested within past 12 months?	Yes
Comment	All equipment labelled and up to date
Absence of trailing leads and adapters?	Yes
Comment	None found at the time of inspection
Evidence that mobility scooters are not being stored/charged in common areas?	No

0070

1.20 Acture Court Block 1.20 Acture Court Loode

ASSET ID: 8670 1-39 ASTURA COURT BIOCK 1-39 AS	stura Court, Leeds
Comment	A resident has been persistently leaving his mobility scooter in the communal lounge and charging it. I have asked the gentleman not to charge and leave it in the communal lounge. The purpose built scooter room is 10 feet away. Further action will be taken to ensure that the scooter is not being charged within the communal lounge
Is there a purpose built mobility scooter store/charging area?	Yes
Comment	New room built awaiting hold open self closer
Does the building have a lightning protection system?	No
Comment	

Gas installations

Is there a commercial/domestic gas supply to the scheme?

Comment

Valid LGSR held on file for fixed communal area gas appliances? (Boilers) Comment

Valid LGSR held on file for residential flats that contains gas appliances?

Comment

Are smoke/heat detectors within General Needs flats subject to an annual inspection and the results

Comment

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered to?
Comment
Adequate security against arson?
Comment
Are refuse/recycling bin areas managed and suitably located?
Comment
Are there communal cooking facilities at this scheme?
Comment
Are reasonable measures taken to prevent fires as a result of cooking?
Comment

Yes

There is a boiler room that is accessible from the outside Yes

Records are available on ActiveH

Yes

All records are available on ActiveH

Yes

Tests carried out by Tunstall and recorded on ActiveH

Yes

No smoking in the communal areas but smoking is allowed in residents flats Yes A fob entry system at the scheme Yes

A separate area is designated for refuse

Yes

Kitchen area only for microwave and making drinks Yes

1-39 Astura Court Block 1-39 Astura Court, Leeds Asset ID: 8670

N/A
None fitted

Housekeeping

Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items?	Ye
Comment	A
Are unnecessary accumulations of combustible materials or waste avoided?	Ye
Comment	N
Are combustible materials and substances separated from ignition sources and stored appropriately?	Ye
Comment	N
Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations?	Ye
Comment	A

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Comment

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of escape in case of fire?

Comment

Escape routes unobstructed and safe to use?

Comment

Exits immediately openable without a key and/or failsafe's function correctly? Comment

Reasonable distances of travel where there is a single/alternative direction of travel?

Comment

Escape routes lead to final exits and open in direction of escape where necessary?

Yes

Il clear at the time of inspection

es

one found at the time of inspection

es

one found at the time of inspection

es

Il have correct labelling

Yes

Some residents have oxygen within the flats, these have been recorded for the fire service

Yes

Ther is more than one direction of travel from most flats, the flats on dead ends are within the permitted travel distance to a place where 2 directions of travel are available

Yes

All clear at the time of inspection

Yes

There are push bars on external escape doors, the electronic front door defaults to open if the fir alarm acctuates

Yes

As above

Yes

Asset ID: 8670

Comment

Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard? Comment Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)? Comment Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products? Comment

As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?

Comment

Loft hatches fire resisting?

Comment

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?

Comment

Do external walls, doors, windows and anything attached to the exterior, limit fire spread?

Comment

If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?

Comment

Are roller shutter doors that are required to be FR, fire resisting and self-closing?

Comment

Yes All compartmentation is intact at the time of inspection Yes Notice boards are protected by perspex and lockable No Yes All of satisfactory standard at the time of inspection Yes All loft hatches are 1 hour rated N/A Cross corridor fire doors are flush to the ceiling Yes This building is of a brick built construction N/A None fitted N/A

None fitted

Observation	Priority	Referred To	Required By:	Task ID
Flat 34 door needs adjusting to close to rebate and possibly requires a new self closer	Repair - Non Emergency	Building Safety Manager		





Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per current standards?	Yes
Comment	A new EL system was installed last year and is to the correct specification
Emergency lighting units in good condition and securely fixed to walls/ceilings?	Yes
Comment	All in good condition at the time of inspection
Records of monthly/annual testing available?	Yes
Comment	Monthly tests are carried out by the Scheme Manager and a drop test is completed by Tunstall. All records are completed and are available on ActiveH
Fire Safety Signs and Notices	
Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?	Yes
Comment	Signage displayed throughout the building
Directional fire escape signage in place and adequate?	Yes
Comment	
Is there suitable LIFT signage i.e. do not use in case of fire?	N/A
Comment	No lift at this scheme
Do common area fire doors display the correct signage on both sides where applicable?	Yes
Comment	
Means of giving Warning in case of Fire	
Is the scheme fitted with a communal area fire alarm?	Yes
Comment	There is a communal Fire alarm system, the alarm is not connected to the flats within the scheme
Is fire detection and warning system appropriate for occupancy and fire risk, as per BS 5839-1:2017?	Yes
Comment	
Is the fire detection and warning system maintained/tested and all certificates saved on file?	Yes

Comment

Fire alarm components in good condition and securely fixed to walls/ceilings?

Yes

on ActiveH

The scheme Manager completes the weekly test and records the findings, Tunstall complete the 6 monthly test and record it. All records are available

Comment	All in good condition at the time of inspection
Hold open devices operate at the sounding of the alarm and are in a serviceable condition?	Yes
Comment	Tested at the time of inspection, all in good working order
Are there heat detectors located in the Kitchen, Boiler, Plant Room and Laundry?	Yes
Comment	
s the fire alarm panel remotely monitored, and if so are there records of regular testing?	Yes
Comment	All records are available on ActiveH

Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme?	Yes
Comment	Only provided in high risk areas, all extinguishers have been removed from the communal areas due to residents not being trained on extinguishers use
Portable fire extinguishers - appropriate type/number/position?	Yes
Comment	
Correct signage displayed by each fire extinguisher?	Yes
Comment	
Fire blanket in communal kitchen, secured to the wall, complete with signage?	Yes
Comment	
Dry risers - Inlet/outlet boxes secured and/or securing straps fitted to outlet valves?	N/A
Comment	None fitted
Records available of fire fighting equipment servicing within past 12 months?	Yes
Comment	Labels visible on the extinguishers and recorded on ActiveH
Management of Fire Safety	
Are these premises regulated by the Building Safety Regulator under the Building Safety Act?	Yes
Comment	
Will this FRA be shared will all Accountable Persons for the premises?	Yes
Comment	A copy of the completed Risk assessment will be given to the scheme Manager

How will this sharing be achieved?

As above and will be available on M-Files

Are there other Responsible Persons who share or have fire sa duties in respect of the premises? How will this sharing be achieved?	fety	No				
Is an office or IL scheme being inspected?		Yes				
Comment						
IL Schemes & Regional Offices - Are there sufficient numbers o qualified Fire wardens?	of	N/A				
Comment		Nt re	quired at ILS			
Offices - Are there suitable arrangements for ensuring the premises are evacuated?			N/A			
Comment						
Offices - Are there suitable arrangements for evacuating disabled people?			N/A			
Comment						
Offices - Suitable arrangements for meeting the fire service on and proving relevant information?	arrival	N/A				
Comment						
Offices/IL Schemes - Is there a suitable assembly point?		Yes				
Comment		Gher put	e is an assembly poin	t but the scheme i	s stay	
Offices - Are fire drills carried out at appropriate intervals?		N/A				
Comment		Not r	required			
Observation	Priority		Referred To	Required By:	Task ID	
A resident is persistently leaving his mobility scooter on charge in the communal lounge	Internal - High		Independent Living Coordinator			



Passenger Lift

Is the scheme fitted with a passenger lift?

Comment

Premises Inspection Box

No

Asset ID: 8670 1-39 Astura Court Block 1-39 Astura	Court, Leeds
Is there a premises information box for fire & rescue service use?	No
Comment	Boxes are being ordered and will be provided when they arrive
Evacuation Policy	
Are there suitable arrangements for summoning the fire service?	Yes
Comment	Ther is an automated dialer on the fire alarm system, warden call is fitted in residents flats. Residents are also instructed to contact details fire service by dialing 999
Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance?	Yes
Comment	
Engagement with Residents	
Has information of fire procedures been disseminated to residents?	Yes
Comment	Residents received a letter and leaflets with information about fire safety. Ther is signage throughout the building giving advice about action in case of fire
Is general fire safety information disseminated to residents?	Yes
Comment	As above
FRA Frequency	
Taking the findings of this assessment into account, is the frequency of the FRA correct?	Yes
Comment	I will visit to police the resident with the mobility scooter
Miscellaneous	
Are there any other observations/actions to raise that are not covered above.	Νο
Are there fire related remedial works required at this property, that will affect the fabric of the building?	No
Comment	
Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).	Yes
Some fire doors did not fully close so works orders have been raised with our contractors.	Νο

MIS-AMS ActiveH - Fire Risk Assessment Report

contractors.

Some minor works were required which have been raised with our

Yes

Unauthorised items were found in communal areas and arrangements were made for their removal.	Yes
Not all records were up to date, as noted in the table below. Arrangements have been made for these to be completed.	No
A number of fire doors were found to be wedged or propped open . Fire doors are there to keep you safe and me kept shut at all times.	No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW	X	MEDIUM	нідн		
-----	---	--------	------	--	--

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR	MAJOR	X	CRITICAL	

The definition of the above terms is as follows: *FRA Review Frequency*

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	intolerable

When the level of risk is established, the action level can be read from the table below:

Asset ID: 8670

1-39 Astura Court Block 1-39 Astura Court, Leeds

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial	