

This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 8952 1-12 Stansfield Grange Block 1-12 Stansfield Grange, Sowerby Bridge

Cover Sheet

Photo



Date of Fire Risk Assessment Date of Next Fire Risk Assessment FRA Frequency (Months) Purpose of Fire Risk Assessment Type of Fire Risk Assessment Fire & Safety Assessor 16 Jan 2024 16 Jan 2027 36 3 year Re-Assessment Type 1 (Common Parts Only - Non Destructive) Steven Manners

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name	Stansfield Grange
Scheme Address	1-12 Stansfield Grange Block 1-12 Stansfield Grange, Sowerby Bridge
Postcode	HX6 3SE
Region	Yorkshire
Scheme Manager	
Scheme Tel. No	
Scheme Inspection Completed	Yes
Enforcing Fire Authority	West Yorkshire
Other staff in attendance	
Number of on-site Accent staff	None
Number of other (non-Accent) staff	Contract Cleaners in common areas

The Building

Accommodation Type	General Needs (S30)
Build Date	Jan 1 1979
Number Of Homes	12
Homes breakdown	Flat
External wall construction	Natural Stone
External wall finish	Artificial/Natural Stone
Roof construction	Timber
Roof covering	Slate Pitched
PEEPs in place where necessary	N/A
Current Evacuation Strategy	Full (Simultaneous) Evacuation
Conversion or purpose-built	Conversion
Number of storeys	3
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
Number of internal Staircases (protected or unprotected?)	3 protected
Number of External Staircases	One
External Balcony part of escape route?	No
Unusual features	None
Building Access Conditions for Fire Brigade	Vehicular Access to one or more elevations

1-12 Stansfield Grange Block 1-12 Stansfield Grange, Sowerby Bridge

Fire Detection and Warning System	Flats and common areas linked
Grade of fire alarm	Grade B
Category of fire alarm	LD3 Minimum Protection
Emergency Lighting Provision	Maintained system - Common areas
Portable Fire Extinguishers supplied/fitted	No
Fixed Fire Fighting Installations	No

Customers

Asset ID: 8952

Number of occupants	24
Occupant tenure type breakdown	General Needs

Fire Safety Related Customer Safety Servicing

Overdue communal gas safety checks	0
Overdue domestic gas safety checks	0
Overdue communal electrical condition checks	0
Overdue domestic electrical condition checks	0
Overdue alarm call pull chord tests	0
Overdue communal PAT testing	0
Overdue customer mobility scooter PAT testing	0
Overdue Monthly Emergency Lighting Switch Tests	1
Overdue Annual Emergency Lighting tests	1
Overdue Weekly Fire Alarm Testing	1
Overdue Fire Panel - Six Monthly Testing	1
Overdue Fire Safety Equipment tests	1

Building Fire Safety Surveys - Communal Doors

Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	0

Dwelling Doors

Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



Date of Fire Risk Assessment	16/01/2024
FRA Frequency (Months)	36
Purpose of Fire Risk Assessment	3 year Re-Assessment
Type of Risk Assessment	Type 1 (Common Parts Only - Non Destructive)
Quantity	1
Fire & Safety Assessor	Steven Manners
Enforcing Fire Authority	West Yorkshire
Scheme Tel. No	
Other staff in attendance	
Number of on-site Accent staff	None
Number of other (non-Accent) staff	Contract Cleaners in common areas
Scheme Inspection completed	Yes
Number of occupants	24
Personal Emergency Evacuation Plans in place	N/A
Current Evacuation Strategy	Full (Simultaneous) Evacuation
Conversion or purpose-built	Conversion
Number of Storeys	3
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
No. of internal staircases (protected/unprotected)	3 protected
Number of external staircases	One
External balcony part of escape route?	No
Unusual features	None

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade	Vehicular Access to one or more elevations
Surroundings: Residential/Commercial	Residential
Fire Detection and Warning System	Flats and common areas linked
Grade of Fire Alarm	Grade B
Category of Fire Alarm	LD3 Minimum Protection
Emergency Lighting Provision	Maintained system - Common areas
Portable Fire Extinguishers / Fire Blankets supplied / fitted	No
Water Extinguisher(s) present	No
Foam Extinguisher(s) present	No
Dry Powder Extinguisher(s) present	No
Carbon Dioxide Extinguisher(s) present	No
Fire Blanket(s) present	No
Fixed Fire Fighting Installations supplied / fitted	No
Dry Riser(s) present	No
Wet Riser(s) present	No
Sprinkler System present	No
Hosereel(s) present	No
Automatic Opening Vent(s) present	No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no obvious damage?		Yes		
Comment		All in good condition at the time of inspection		
Valid Electrical Installation Condition Reports held on file? (Common Areas & General Needs Flats)		Yes		
Comment		All records are available on ActiveH		
Electrical App/PA Testing - tested within past 12 months?		N/A		
Comment		Jo electrical equipment within communal areas. No office on site		
Absence of trailing leads and adapters?		Yes		
Comment		As above		
Evidence that mobility scooters are not being stored/cha common areas?	rged in	Yes		
Comment		None on scheme		
Is there a purpose built mobility scooter store/charging a	rea?	Νο		
MIS-AMS ActiveH - Fire Risk Assessment Report	Page 5 of 16	Generated 17/01/2024 16:03:58		

Asset ID: 8952 1-12 Stansfield Grange Block 1-12 Stansfield Grange, Sowerby Bridge

Comment

Does the building have a lightning protection system?

Comment

Gas installations

Is there a commercial/domestic gas supply to the scheme?
Comment
Valid LGSR held on file for fixed communal area gas appliances? (Boilers)
Comment
Valid LGSR held on file for residential flats that contains gas appliances?
Comment
Are smoke/heat detectors within General Needs flats subject to an annual inspection and the results
Comment

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered to? Comment Adequate security against arson?

Comment

Are refuse/recycling bin areas managed and suitably located?

Comment

Are there communal cooking facilities at this scheme?

Comment

Housekeeping

Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items? Comment

Are unnecessary accumulations of combustible materials or waste avoided?

Comment

Yes

Individual flats have their own gas supply

No

No

Yes

All records are available on ActiveH

Yes

Tunstall complete the annual checks and records are available on ActiveH

Yes

No smoking allowed in the communal areas but smoking is allowed in residents flats Yes

Door entry system is in place at this scheme

Yes

Sited away from the building in a purpose built compound No

Yes

All clear at the time of inspection

No

Some residents have stored items within the escape routes, the housing partner has been informed and is dealing. See pictures

Asset ID: 8952 1-12 Stansfield Grange Block 1-12 Stansfield Grange, Sowerby Bridge

Are combustible materials and substances separated from ignition sources and stored appropriately?

Comment

Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations? Comment Yes

None found at the time of inspection

N/A

No furniture allowed in the communal areas

Observation	Priority	Referred To	Required By:	Task ID
The resident at flat number 12 has hoarding issues. The	Internal - High	Housing Partner		

The resident at flat number 12 has hoarding issues. Th Housing Partner has engaged with the resident to try and resolve the issue. Referrals have been made to social services and a PET is in place. A





 Observation
 Priority
 Referred To
 Required By:
 Task ID

 Flammable items in the communal area outside flat 11
 Internal - High
 Housing Partner

required to be removed





Observation

Priority ____ _

gh Ho

Housing Partner

Referred To

Required By: Task ID

Flammable items in the communal area outside flat 9 required to be removed





Other Significant Fire Hazards Are all other significant fire hazards adequately controlled? Yes None found at the time of inspection Comment Means of Escape from Fire Yes Is it considered that the building is provided with reasonable means of escape in case of fire? Comment No Escape routes unobstructed and safe to use? Comment See housekeeping section Yes Exits immediately openable without a key and/or failsafe's function correctly? Comment All available at the time of inspection Reasonable distances of travel where there is a single/alternative Yes direction of travel? Comment Yes Escape routes lead to final exits and open in direction of escape where necessary? Comment

Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?	No
Comment	Some flat doors have not got self closer device and are missing smoke seals. See observations. Door to electrical room requires self closer and smoke seals. The door frame to the electrical room requires fire stopping as per observations
Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?	Yes
Comment	
Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?	N/A
Comment	None on scheme
As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?	Yes
Comment	No access to the roof space
Loft hatches fire resisting?	N/A
Comment	None found

Asset ID:	8952	1-12 Stansfield Grange E	Block 1-12 St	ansfield Grange, Sowerb	y Bridge	
		bly ascertained, is the fire stopping a ithin suspended ceiling void of a sat		N/A		
Comment				No suspended ceiling wit	hin the scheme	
Do external v exterior, limit		windows and anything attached to th	е	Yes		
Comment						
If Smoke Cor testing availa	•	(AOV's) are fitted, are the records o	of annual	N/A		
Comment				None fitted		
Are roller shu self-closing?	itter doors tha	at are required to be FR, fire resistin	g and	N/A		
Comment				None fitted		
Observatio	n		Priority	Referred To	Required By:	Task ID

Door to flat 8 is bowed requires adjusting or replacing Repair - Non





Building Safety

Manager

Observation No self closer on door to flat 5, install closer and adjust door to close to rebate if required

Priority Repair - Non Emergency

Building Safety Manager

Required By:

Task ID

Referred To





1-12 Stansfield Grange Block 1-12 Stansfield Grange, Sowerby Bridge



Fire stopping required to inside of electrical meter room door(Right hand side viewed from inside). Code to room is 2014. Door requires a self closer and smoke seals to door or frame

Repair - Non Emergency

Priority


Building Safety Manager

Referred To

Required By: Task ID

Required By:

Task ID





Observation

Observation

Asset ID: 8952

Self closer and smoke seals required for door to flat 3 either in the door or frame






Referred To







Asset ID: 8952 1-12 Stansfield Grange Block 1-12 Stansfield Grange, Sowerby Bridge

Observation	Priority	Referred To	Required By:	Task ID
Self closer and smoke seals required for door to flat 4 either in the door or frame	Repair - Non Emergency	Building Safety Manager		

Emergency Escape Lighting

Emergency lighting units in good condition and securely fixed to walls/ceilings?YesCommentAll in good condition at the time of inspection	
Comment All in good condition at the time of inspection	
Records of monthly/annual testing available? Yes	
Comment Tunstall complete all the monthly and annual checks, the results are all available on ActiveH	
Fire Safety Signs and Notices	
Are the correct Fire Action/Advice notices displayed in prominent Yes locations within the common areas?	
Comment Notices are displayed throughout the building	
Directional fire escape signage in place and adequate? Yes	
Comment	
Is there suitable LIFT signage i.e. do not use in case of fire? N/A	
Comment No lift at this scheme	
Do common area fire doors display the correct signage on both sides Yes where applicable?	
Comment All correct at the time of inspection	
Means of giving Warning in case of Fire	
Is the scheme fitted with a communal area fire alarm? Yes	

1-12 Stansfield Grange Block 1-12 Stansfield Grange, Sowerby Bridge Asset ID: 8952

ls fire detection and warning system appropriate for occupancy and fire risk, as per BS 5839-1:2017? Comment	Yes
Is the fire detection and warning system maintained/tested and all certificates saved on file?	Yes
Comment	Tunstall complete the weekly and 6 monthly tests and all records are available on ActiveH
Fire alarm components in good condition and securely fixed to walls/ceilings?	Yes
Comment	All in all condition at the time of inspection
Hold open devices operate at the sounding of the alarm and are in a serviceable condition?	N/A
Comment	None fitted
Are there heat detectors located in the Kitchen, Boiler, Plant Room and Laundry?	N/A
Comment	None on scheme
Is the fire alarm panel remotely monitored, and if so are there records of regular testing?	Νο
Comment	

Observation	Priority	Referred To	Required By:	Task ID

Fire Panel





No

Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme? Comment

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under	Yes
the Building Safety Act?	
Comment	
Will this FRA be shared will all Accountable Persons for the premises?	Yes

Will this FRA be shared will all Accountable Persons for the premises?

1-12 Stansfield Grange Block 1-12 Stansfield Grange, Sowerby Bridge Asset ID: 8952 Comment How will this sharing be achieved? Documents are available in M files and can be accessed from there Are there other Responsible Persons who share or have fire safety No duties in respect of the premises? How will this sharing be achieved? Is an office or IL scheme being inspected? No Comment Passenger Lift No Is the scheme fitted with a passenger lift? Comment **Premises Inspection Box** No Is there a premises information box for fire & rescue service use? Comment **Evacuation Policy** Yes Are there suitable arrangements for summoning the fire service? Comment Residents are instructed to contact the fire service by dialing 999 Taking FRA findings, is the evacuation policy appropriate for the Yes scheme as per latest guidance? Comment **Engagement with Residents** Yes Has information of fire procedures been disseminated to residents? Comment All residents have had a letter and leaflets giving information about evacuation and flat front doors Yes Is general fire safety information disseminated to residents? Comment As above FRA Frequency Yes Taking the findings of this assessment into account, is the frequency of the FRA correct?

Asset ID: 8952

1-12 Stansfield Grange Block 1-12 Stansfield Grange, Sowerby Bridge

Comment

Although ghere is one resident at high risk, processes are in place e for regular visits by social workers an the Housing Partner. Information is passed to the Fire safety team on a regular basis.

Miscellaneous

Are there any other observations/actions to raise that are not covered above.	No
Are there fire related remedial works required at this property, that will affect the fabric of the building? Comment	Yes
Can work be conducted without the need for an asbestos survey. If no, task Customer Safety Surveyor - Asbestos. Comment	Yes
Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).	Yes
Some fire doors did not fully close so works orders have been raised with our contractors.	Yes
Some minor works were required which have been raised with our contractors.	Yes
Unauthorised items were found in communal areas and arrangements were made for their removal.	Yes
Not all records were up to date, as noted in the table below. Arrangements have been made for these to be completed.	No
A number of fire doors were found to be wedged or propped open . Fire doors are there to keep you safe and me kept shut at all times.	No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW	MEDIUM	X	HIGH	
-----	--------	---	------	--

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR	MAJOR	X	CRITICAL	

The definition of the above terms is as follows: *FRA Review Frequency*

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	intolerable

When the level of risk is established, the action level can be read from the table below:

Asset ID: 8952

1-12 Stansfield Grange Block 1-12 Stansfield Grange, Sowerby Bridge

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Moderate	