Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 6530 Fairfield (s/o), Leeds

Cover Sheet

Photo

Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

05 Sep 2023

05 Sep 2026

36

3 year Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Steven Manners

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name Fairfield (S/O)

Scheme Address Fairfield (s/o), Leeds

Postcode

Region Yorkshire

Scheme Manager

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority West Yorkshire

Other staff in attendance None

Number of on-site Accent staff None

Number of other (non-Accent) staff

Contract Cleaners in common areas

The Building

Accommodation Type Shared Ownership (S40)

Build Date

Number Of Homes 40

Homes breakdown House, Bungalow

External wall construction

External wall finish

Roof construction

Roof covering

PEEPs in place where necessary N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys 3

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

1 per block not protected

Number of External Staircases None

External Balcony part of escape route?

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

Asset ID: 6530 Fairfield (s/o), Leeds	
Fire Detection and Warning System	Flats only
Grade of fire alarm	Grade C
Category of fire alarm	LD3 Minimum Protection
Emergency Lighting Provision	Non Maintained System - Common Areas
Portable Fire Extinguishers supplied/fitted	No
Fixed Fire Fighting Installations	No
Customers	
Number of occupants	40
Occupant tenure type breakdown	Freehold with charges, Shared Ownership
Fire Safety Related Customer Safety Servicing	
Overdue communal gas safety checks	0
Overdue domestic gas safety checks	0
Overdue communal electrical condition checks	0
Overdue domestic electrical condition checks	0
Overdue alarm call pull chord tests	0
Overdue communal PAT testing	0
Overdue customer mobility scooter PAT testing	0
Overdue Monthly Emergency Lighting Switch Tests	
Overdue Annual Emergency Lighting tests	
Overdue Weekly Fire Alarm Testing	0
Overdue Fire Panel - Six Monthly Testing	
Overdue Fire Safety Equipment tests	
Building Fire Safety Surveys - Communal Doors	
Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	0
Dwelling Doors	
Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



Date of Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Risk Assessment

Quantity

Fire & Safety Assessor

Enforcing Fire Authority

Scheme Tel. No

Other staff in attendance

Number of on-site Accent staff

Number of other (non-Accent) staff

Scheme Inspection completed

Number of occupants

Personal Emergency Evacuation Plans in place

Current Evacuation Strategy

Conversion or purpose-built

Number of Storeys

Number of floors on which car parking is provided

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

Number of external staircases

External balcony part of escape route?

Unusual features

05/09/2023

36

3 year Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Steven Manners

West Yorkshire

None

None

Contract Cleaners in common areas

Yes

40

N/A

Stay Put (Delayed) Evacuation

Purpose Built

3

0 No

1 per block not protected

None

No

None

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Residential

Fire Detection and Warning System Flats only

Grade of Fire Alarm Grade C

Category of Fire Alarm LD3 Minimum Protection

Emergency Lighting Provision Non Maintained System - Common Areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted No

Water Extinguisher(s) present

Foam Extinguisher(s) present No

Dry Powder Extinguisher(s) present No

Carbon Dioxide Extinguisher(s) present

Fire Blanket(s) present

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present No

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present

Yes

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no

obvious damage?

Comment All in good condition at the time of inspection

Valid Electrical Installation Condition Reports held on file? (Common Yes

Areas & General Needs Flats)

Comment All records are available on ActiveH

Electrical App/PA Testing - tested within past 12 months?

Comment No electrical installations within communal areas

Absence of trailing leads and adapters? Yes

Comment

Evidence that mobility scooters are not being stored/charged in Yes

common areas?

Comment None on scheme

Is there a purpose built mobility scooter store/charging area?

Fairfield (s/o), Leeds Asset ID: 6530 Comment No Does the building have a lightning protection system? Comment **Gas installations** Is there a commercial/domestic gas supply to the scheme? No Comment Other Sources of Ignition Is there a no smoking policy in place, which is enforced and adhered Yes to? Comment Residents are allowed to smoke within their homes Yes Adequate security against arson? Comment Door entry system on all blocks Are refuse/recycling bin areas managed and suitably located? Yes Comment Located away from the main building Are there communal cooking facilities at this scheme? No Comment Housekeeping No Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items? Comment One cupboard requires a new digital keypad No Are unnecessary accumulations of combustible materials or waste avoided? Comment Some cupboards have items that require removing. **HP** informed Yes Are combustible materials and substances separated from ignition sources and stored appropriately?

comply with modern standards and regulations?

Furniture/furnishings in good condition, fire retardant/resistant and

Comment

Comment

None found at the time of inspection

Not allowed in the communal areas

N/A

 Observation
 Priority
 Referred To
 Required By:
 Task ID

 Combustible items stored on escape route outside
 Internal - Medium
 Housing Partner
 10/10/2023
 1707134



Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Comment None found at the time of inspection

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of

escape in case of fire?

direction of travel?

Comment

Escape routes unobstructed and safe to use?

Comment All clear at the time of inspection

Exits immediately openable without a key and/or failsafe's function

Yes

correctly?

Comment Thumb turn on all exits

Reasonable distances of travel where there is a single/alternative

Yes

Comment All distance are within the guidelines

Escape routes lead to final exits and open in direction of escape where

necessary?
Comment

Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment There are some compartmentation issues within the

Yes

Yes

electrical cupboards

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?

Comment No issues at the time of inspection

MIS-AMS ActiveH - Fire Risk Assessment Report Page 7 of 15 Generated 05/09/2023 16:04:04

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?

None fitted

As far as can be reasonably ascertained, is the compartmentation

Yes

N/A

Comment

Comment

Comment

Loft hatches fire resisting?

within roof spaces of a satisfactory standard?

Yes

Lon natches me resisting:

All fire resisting in each block

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?

N/A

Comment

None fitted

Do external walls, doors, windows and anything attached to the exterior, limit fire spread?

Yes

Comment

Ther are balconies to some flats which ar3 made of

steel

If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?

Yes

Comment

All records are available on ActiveH

Are roller shutter doors that are required to be FR, fire resisting and

N/A

self-closing?
Comment

Observation

None fitted

Replace pink foam in electrical cupboard with intumescent sealant. Adjacent to flat number 5 Fairfield court code 2104

Repair - Non Emergency

Priority

Building Safety Manager

Referred To

30/11/2023 1707133

Task ID

Required By:

/ Manager





Observation **Priority** Referred To Repair - Non **Building Safety** Replace none compliant foam in ceiling of electrical **Emergency** Manager

cupboard. Apply intumescent mastic to services in the floor of the electrical cupboard adjacent to flat 3.

Fairfield Court code 2104

Observation

Observation





Replace digital lock on electrical cupboard door. New

code 2014 adjacent to flat 1 Fairfield Court



Priority Repair - Non **Emergency**

Building Safety Manager

Referred To

01/11/2023

Required By:


Required By:

01/11/2023

Task ID 1707136

Task ID

1707135



Replace foam at floor and ceiling level with Intumescent mastic. Electrical cupboard adjacent to flat 8 code 2014



Repair - Non **Emergency**

Priority

Referred To **Building Safety** Manager

Required By: 01/11/2023

Task ID 1707137



Observation Priority Referred To Required By: Task ID

Fire stop service cables and pipes in electrical cupboard adjacent to flat 10. Fairfield Court code 2014. Floor and ceiling

Repair - Non Emergency Building Safety Manager 01/11/2023

1707138





Observation

Replace fire foam with intumescent mastic floor and ceiling in electrical cupboard opposite flat 8 Fairfield View code 2014

Priority

Repair - Non Emergency Referred To

Building Safety Manager Required By:

01/11/2023

Task ID

1707139





Observation

Replace fire foam around services on floor to electrical cupboard opposite flat 9 Fairfield View code 2014 with intumescent sealant

Repair - Non Emergency

Priority

Referred To
Building Safety

Manager

Required By:

Task ID

01/11/2023 1707140



Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per current standards?

Comment

Yes

Fairfield (s/o), Leeds Asset ID: 6530

Emergency lighting units in good condition and securely fixed to

walls/ceilings?

All in good condition at the time of inspection Comment

Records of monthly/annual testing available? Yes

Comment All records are available on ActiveH

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent

locations within the common areas?

Comment Notices are displayed throughout the building

Yes Directional fire escape signage in place and adequate?

Comment Exit is only in one direction

Is there suitable LIFT signage i.e. do not use in case of fire? N/A

No lift Comment

Do common area fire doors display the correct signage on both sides

where applicable?

Comment

Means of giving Warning in case of Fire

No Is the scheme fitted with a communal area fire alarm?

Comment There is a smoke detector for the AOV

Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations

provided at this scheme?

Comment

Portable fire extinguishers - appropriate type/number/position?

Comment

N/A Correct signage displayed by each fire extinguisher?

Comment

Fire blanket in communal kitchen, secured to the wall, complete with

signage? Comment

Comment

months?

Dry risers - Inlet/outlet boxes secured and/or securing straps fitted to

outlet valves?

Records available of fire fighting equipment servicing within past 12

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 11 of 15 Generated 05/09/2023 16:04:04

Yes

Yes

Yes

Yes

AOV Fitted in each block

N/A

N/A

N/A

N/A

Comment

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under

the Building Safety Act?

Comment

Are there other Responsible Persons who share or have fire safety

duties in respect of the premises? How will this sharing be achieved?

Is an office or IL scheme being inspected?

Comment

No

No

No

Passenger Lift

Is the scheme fitted with a passenger lift?

Comment

No

Premises Inspection Box

Is there a premises information box for fire & rescue service use?

Comment

No

Evacuation Policy

Are there suitable arrangements for summoning the fire service?

Comment

Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance?

Comment

Yes

Residents are instructed to contact the fire service

by dialing 999

Yes

Engagement with Residents

Has information of fire procedures been disseminated to residents?

Comment

Yes

Information given at the time of induction and on the website action notices are displayed throughout the

building

Yes

Is general fire safety information disseminated to residents?

Comment

As above

FRA Frequency

Taking the findings of this assessment into account, is the frequency of the FRA correct?

Comment

Yes

Yes

No

No

Miscellaneous

Are there any other observations/actions to raise that are not covered above.

Action leading to a repair Yes

Internal administrative Action Yes

Are there fire related remedial works required at this property, that will affect the fabric of the building?

Comment

Can work be conducted without the need for an asbestos survey. If no,

task Customer Safety Surveyor - Asbestos.

Comment

contractors.

Were there any unsatisfactory aspects of the Fire Risk Assessment? Yes (Visible on Building Safety Report).

Some fire doors did not fully close so works orders have been raised No with our contractors.

Some minor works were required which have been raised with our Yes

Unauthorised items were found in communal areas and arrangements

were made for their removal.

Not all records were up to date, as noted in the table below.

Arrangements have been made for these to be completed.

A number of fire doors were found to be wedged or propped open. Fire

doors are there to keep you safe and me kept shut at all times.

Observation Priority Referred To Required By: Task ID

AOV Fairfield Court





Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

systems.					
_	•	evention measures t the hazard from the			at this
LOW	X	MEDIUM		HIGH	
any procedural	arrangements ob	of the building, the eserved at the time one e event of a fire wo	of the assessm	•	
MINOR		MAJOR	Y	CRITICAL	

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial
	