Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 8876 1-39 Holmfield Court Block 1-39 Holmfield Court, Bradford

Cover Sheet

Photo



Date of Fire Risk Assessment Date of Next Fire Risk Assessment FRA Frequency (Months) Purpose of Fire Risk Assessment Type of Fire Risk Assessment Fire & Safety Assessor 30 Jan 2024 30 Jan 2025 12 Annual Re-Assessment Type 1 (Common Parts Only - Non Destructive) Steven Manners

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name	Holmfield Court
Scheme Address	1-39 Holmfield Court Block 1-39 Holmfield Court, Bradford
Postcode	BD1 2DW
Region	Yorkshire
Scheme Manager	
Scheme Tel. No	
Scheme Inspection Completed	Yes
Enforcing Fire Authority	West Yorkshire
Other staff in attendance	Charlotte Jackson
Number of on-site Accent staff	None
Number of other (non-Accent) staff	Contract Cleaners in common areas

The Building

Accommodation Type	General Needs (S30)
Build Date	Jan 2 1900
Number Of Homes	38
Homes breakdown	Flat
External wall construction	Natural Stone
External wall finish	Artificial/Natural Stone
Roof construction	Timber
Roof covering	Slate Pitched
PEEPs in place where necessary	N/A
Current Evacuation Strategy	Stay Put (Delayed) Evacuation
Conversion or purpose-built	Conversion
Number of storeys	4
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
Number of internal Staircases (protected or unprotected?)	2 protected
Number of External Staircases	None
External Balcony part of escape route?	No
Unusual features	None
Building Access Conditions for Fire Brigade	Vehicular Access to one or more elevations

Fire Detection and Warning System	Flats and common areas not linked
Grade of fire alarm	Grade B
Category of fire alarm	LD3 Minimum Protection
Emergency Lighting Provision	Non Maintained System - Common Areas
Portable Fire Extinguishers supplied/fitted	No
Fixed Fire Fighting Installations	No

Customers

Number of occupants	60
Occupant tenure type breakdown	General Needs, Staff Accommodation

Fire Safety Related Customer Safety Servicing

Overdue communal gas safety checks	0
Overdue domestic gas safety checks	0
Overdue communal electrical condition checks	0
Overdue domestic electrical condition checks	0
Overdue alarm call pull chord tests	0
Overdue communal PAT testing	0
Overdue customer mobility scooter PAT testing	0
Overdue Monthly Emergency Lighting Switch Tests	1
Overdue Annual Emergency Lighting tests	1
Overdue Weekly Fire Alarm Testing	1
Overdue Fire Panel - Six Monthly Testing	1
Overdue Fire Safety Equipment tests	

Building Fire Safety Surveys - Communal Doors

Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	0

Dwelling Doors

Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo

Date of Fire Risk Assessment	30/01/2024
FRA Frequency (Months)	12
Purpose of Fire Risk Assessment	Annual Re-Assessment
Type of Risk Assessment	Type 1 (Common Parts Only - Non Destructive)
Quantity	1
Fire & Safety Assessor	Steven Manners
Enforcing Fire Authority	West Yorkshire
Scheme Tel. No	
Other staff in attendance	Charlotte Jackson
Number of on-site Accent staff	None
Number of other (non-Accent) staff	Contract Cleaners in common areas
Scheme Inspection completed	Yes
Number of occupants	60
Personal Emergency Evacuation Plans in place	N/A
Current Evacuation Strategy	Stay Put (Delayed) Evacuation
Conversion or purpose-built	Conversion
Number of Storeys	4
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
No. of internal staircases (protected/unprotected)	2 protected
Number of external staircases	None
External balcony part of escape route?	No
Unusual features	None

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade	Vehicular Access to one or more elevations
Surroundings: Residential/Commercial	Light Commercial
Fire Detection and Warning System	Flats and common areas not linked
Grade of Fire Alarm	Grade B
Category of Fire Alarm	LD3 Minimum Protection
Emergency Lighting Provision	Non Maintained System - Common Areas
Portable Fire Extinguishers / Fire Blankets supplied / fitted	No
Water Extinguisher(s) present	No
Foam Extinguisher(s) present	No
Dry Powder Extinguisher(s) present	No
Carbon Dioxide Extinguisher(s) present	No
Fire Blanket(s) present	No
Fixed Fire Fighting Installations supplied / fitted	No
Dry Riser(s) present	No
Wet Riser(s) present	No
Sprinkler System present	No
Hosereel(s) present	No
Automatic Opening Vent(s) present	No

Electrical Sources of Ignition

Electrical installation within common areas in good conditi obvious damage? Comment	on and no	Yes All in good condition at the time of inspection
Valid Electrical Installation Condition Reports held on file? Areas & General Needs Flats)	? (Common	Yes
Comment		All records are available on ActiveH
Electrical App/PA Testing - tested within past 12 months?		Yes
Comment		The equipment in the office has test labels and records of the tests are available on ActiveH
Absence of trailing leads and adapters?		Yes
Comment		None found at the time of inspection
Evidence that mobility scooters are not being stored/charg common areas?	ged in	Yes
Comment		None on the scheme
Is there a purpose built mobility scooter store/charging are	ea?	Νο
MIS-AMS ActiveH - Fire Risk Assessment Report	Page 5 of 14	Generated 01/02/2024 16:07:15

1-39 Holmfield Court Block 1-39 Holmfield Court, Bradford

No

Comment	Not required
Does the building have a lightning protection system?	No
Comment	An assessment has been made, a quotation has been received and is awaiting approval

Gas installations

Asset ID: 8876

Is there a commercial/domestic gas supply to the scheme? Comment

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered to?	Yes
Comment	Smoking is not allowed in the communal areas but smoking is allowed in residents flats
Adequate security against arson?	Yes
Comment	CCTV Throughout the building and a fob door entry system to the building
Are refuse/recycling bin areas managed and suitably located?	Yes
Comment	Doors to refuse rooms have been locked, residents use the bin store on ground floor
Are there communal cooking facilities at this scheme?	No

Comment

Housekeeping

Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items?	Yes
Comment	None found at the time of inspection
Are unnecessary accumulations of combustible materials or waste avoided?	Yes
Comment	All clear at the time of inspection, The housing partner makes regular visits to the property as this has been a problem in the past.
Are combustible materials and substances separated from ignition sources and stored appropriately?	Yes
Comment	None found at the time of inspection
Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations?	Yes
Comment	No furniture allowed in the communal areas

1-39 Holmfield Court Block 1-39 Holmfield Court, Bradford

Observation	Priority	Referred To	Required By:	Task ID
Setee in bin area needs removing	Internal - Medium	Housing Partner		



Other Significant Fire Hazards

Asset ID: 8876

Are all other significant fire hazards adequately controlled?	Yes
Comment	Nothing found at the time of inspection
Means of Escape from Fire	
Is it considered that the building is provided with reasonable means of escape in case of fire?	Yes
Comment	Each flat has more than one direction of travel to escape from the building,
Escape routes unobstructed and safe to use?	
Comment	
Exits immediately openable without a key and/or failsafe's function correctly?	Yes
Comment	All routes have push pad or failsafe door mechanism
Reasonable distances of travel where there is a single/alternative direction of travel?	Yes
Comment	
Escape routes lead to final exits and open in direction of escape where necessary?	Yes
Comment	
Fire Spread and Development	

Is it considered that the compartmentation is of a reasonable standard?

Comment

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?

Comment

MIS-AMS ActiveH - Fire Risk Assessment Report

Generated 01/02/2024 16:07:15

Nothing found at the time of inspection

A survey was carried out by CLC. New communal Fire doors are bring fitted at the time of inspection

Yes

Yes

Are fire dampers/shutters provided in ducts/refuse chutes to pr means of escape against fire, smoke and combustion products		Yes		
Comment		past residents ha	have been locked shut as in ve accumulated rubbish in th npromised compartmentatior	e
As far as can be reasonably ascertained, is the compartmenta within roof spaces of a satisfactory standard?	tion	Yes		
Comment		Survey carried ou	t by CLC	
Loft hatches fire resisting?		Yes		
Comment				
As far as can be reasonably ascertained, is the fire stopping al cross corridor fire doors within suspended ceiling void of a sati standard?		Yes		
Comment		Survey as above		
Do external walls, doors, windows and anything attached to the exterior, limit fire spread?	е	Yes		
Comment		Stone built buildin	g with no external cladding	
If Smoke Control Systems (AOV's) are fitted, are the records o testing available?	f annual	N/A		
Comment		None fitted		
Are roller shutter doors that are required to be FR, fire resisting self-closing?	g and	N/A		
Comment		None fitted		
Observation	Priority	Referred To	Required By:	Task ID
Door to flat 36 requires replacing due to damage to lock and handle	Repair - Non Emergency	Building Sa Manager	fety	





New communal Fire doors





Yes

Yes

Yes

Yes

Yes

inspection

ActiveH

Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per	
current standards?	

Comment

Emergency lighting units in good condition and securely fixed to walls/ceilings?

Comment

Records of monthly/annual testing available?

Comment

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?

Comment

Directional fire escape signage in place and adequate?

Comment

Signage displayed throughout the building

All units are in good condition at the time of

Records completed by Tunstall and can be found on

Is there suitable LIFT signage i.e. do not use in case of fire?	Yes
Comment	
Do common area fire doors display the correct signage on both sides where applicable? Comment	Yes
Means of giving Warning in case of Fire	
Is the scheme fitted with a communal area fire alarm?	Yes
Comment	
Is fire detection and warning system appropriate for occupancy and fire risk, as per BS 5839-1:2017? Comment	Yes
Is the fire detection and warning system maintained/tested and all certificates saved on file?	Yes
Comment	System is maintained by Tunstall and recorded on ActiveH
Fire alarm components in good condition and securely fixed to walls/ceilings?	Yes
Comment	All in good condition at the time of inspection
Hold open devices operate at the sounding of the alarm and are in a serviceable condition?	N/A
Comment	None fitted at the scheme
Are there heat detectors located in the Kitchen, Boiler, Plant Room and Laundry?	Yes
Comment	No kitchen or boiler roomat this scheme
Is the fire alarm panel remotely monitored, and if so are there records of regular testing?	Yes
Comment	Monitoring station call fire service. System is maintained and tested by Tunstall and recorded on ActiveH
Fire Extinguishing Equipment	
Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme? Comment	No
Management of Fire Safety	
Are these premises regulated by the Building Safety Regulator under the Building Safety Act?	Yes
Comment	11 meters

1-39 Holmfield Court Block 1-39 Holmfield Court, Bradford

Asset ID: 8876

Asset ID:	8876	1-39 Holmfield Court Block 1-39 Holmfiel	d Court, Bradford
Will this FRA	be shared will all	Accountable Persons for the premises?	Yes
Comment			
How will this	sharing be achiev	/ed?	Available on ActiveH and in M-Files
	er Responsible P pect of the premise	ersons who share or have fire safety es?	No
How will this	sharing be achiev	/ed?	
ls an office o	r IL scheme being	j inspected?	No
Comment			
Passenge	er Lift		
Is the schem	e fitted with a pas	senger lift?	Yes
Comment			
Is the lift in fu	ıll working order a	t the time of the FRA?	Yes
Comment			All working at the time of inspection
Is the lift fitte	d with a firefighter	rs switch?	No
Comment			
Servicing and servicing/mail		ction - Evidence of regular	Yes
Comment			All service and insurance records are available on ActiveH
Premises	Inspection B	Box	
Is there a pre	emises informatior	n box for fire & rescue service use?	No
Comment			
Evacuatio	on Policy		
Are there sui	table arrangemen	ts for summoning the fire service?	Yes
Comment			Fire alarm monitored and residents are instructed to contact the fire service by dialing 999
	indings, is the eva er latest guidance	acuation policy appropriate for the ?	Yes
Engagem	ent with Resi	idents	
Has informat	ion of fire procedu	ures been disseminated to residents?	Yes
Comment			

Is general fire safety information disseminated to residents?	Yes
Comment	Fire procedures are displayed throughout the building and a leaflet with information about evacuation and flat doors has been sent to everyone in the building
FRA Frequency	
Taking the findings of this assessment into account, is the frequency of the FRA correct?	Yes
Comment	A 3 monthly check on all communal doors is carried out as per legislation.
Miscellaneous	
Are there any other observations/actions to raise that are not covered above.	No
Are there fire related remedial works required at this property, that will affect the fabric of the building?	Yes
Comment	All communal doors are being replaced.
Can work be conducted without the need for an asbestos survey. If no, task Customer Safety Surveyor - Asbestos. Comment	Yes
Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).	No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW	MEDIUM	Х	HIGH	
-----	--------	---	------	--

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR	MAJOR	X	CRITICAL	

The definition of the above terms is as follows: *FRA Review Frequency*

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	intolerable

When the level of risk is established, the action level can be read from the table below:

Asset ID: 8876

1-39 Holmfield Court Block 1-39 Holmfield Court, Bradford

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Moderate	