

This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

#### Asset ID: 33482 1 Silverdale Street, Barrow In Furness

#### **Cover Sheet**

Photo



Date of Fire Risk Assessment Date of Next Fire Risk Assessment FRA Frequency (Months) Purpose of Fire Risk Assessment Type of Fire Risk Assessment Fire & Safety Assessor 04 Jan 2024 04 Jan 2027 36 3 year Re-Assessment Type 1 (Common Parts Only - Non Destructive) Ian Potter

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

### The Scheme

Scheme Name	Silverdale Street Hostel
Scheme Address	1 Silverdale Street, Barrow In Furness
Postcode	LA14 1AT
Region	North West
Scheme Manager	
Scheme Tel. No	N/A
Scheme Inspection Completed	Yes
Enforcing Fire Authority	Cumbria
Other staff in attendance	None
Number of on-site Accent staff	None
Number of other (non-Accent) staff	Contract Cleaners in common areas

### The Building

Accommodation Type	General Needs (S30)
Build Date	
Number Of Homes	8
Homes breakdown	Flat
External wall construction	Facing Brick
External wall finish	Cement Render, Facing Brick
Roof construction	Timber
Roof covering	Interlocking Pitched
PEEPs in place where necessary	N/A
Current Evacuation Strategy	Full (Simultaneous) Evacuation
Conversion or purpose-built	Purpose Built
Number of storeys	2
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
Number of internal Staircases (protected or unprotected?)	1 protected
Number of External Staircases	0
External Balcony part of escape route?	No
Unusual features	None
Building Access Conditions for Fire Brigade	Vehicular Access to one or more elevations

Fire Detection and Warning System	Flats and common areas not linked
Grade of fire alarm	Grade A
Category of fire alarm	LD3 Minimum Protection
Emergency Lighting Provision	Maintained system - Common areas
Portable Fire Extinguishers supplied/fitted	No
Fixed Fire Fighting Installations	No

### Customers

Number of occupants	8
Occupant tenure type breakdown	General Needs

### Fire Safety Related Customer Safety Servicing

Overdue communal gas safety checks	0
Overdue domestic gas safety checks	0
Overdue communal electrical condition checks	0
Overdue domestic electrical condition checks	0
Overdue alarm call pull chord tests	0
Overdue communal PAT testing	0
Overdue customer mobility scooter PAT testing	0
Overdue Monthly Emergency Lighting Switch Tests	1
Overdue Annual Emergency Lighting tests	1
Overdue Weekly Fire Alarm Testing	1
Overdue Fire Panel - Six Monthly Testing	1
Overdue Fire Safety Equipment tests	

### **Building Fire Safety Surveys - Communal Doors**

Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	0

### **Dwelling Doors**

Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

# Fire Risk Assessment Survey Results

### Scheme and Building Information

Photo

Date of Fire Risk Assessment	04/01/2024
FRA Frequency (Months)	36
Purpose of Fire Risk Assessment	3 year Re-Assessment
Type of Risk Assessment	Type 1 (Common Parts
Quantity	1
Fire & Safety Assessor	Ian Potter
Enforcing Fire Authority	Cumbria
Scheme Tel. No	N/A
Other staff in attendance	None
Number of on-site Accent staff	None
Number of other (non-Accent) staff	Contract Cleaners in co
Scheme Inspection completed	Yes
Number of occupants	8
Personal Emergency Evacuation Plans in place	N/A
Current Evacuation Strategy	Full (Simultaneous) Eva
Conversion or purpose-built	Purpose Built
Number of Storeys	2
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
No. of internal staircases (protected/unprotected)	1 protected
Number of external staircases	0
External balcony part of escape route?	No
Unusual features	None



36
3 year Re-Assessment
Type 1 (Common Parts Only - Non Destructive)
1
lan Potter
Cumbria
N/A
None
None
Contract Cleaners in common areas
Yes
8
N/A
Full (Simultaneous) Evacuation
Purpose Built
2
0
No
1 protected
0
No
N.

# Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade	Vehicular Access to one or more elevations	
Surroundings: Residential/Commercial	Residential	
Fire Detection and Warning System	Flats and common areas not linked	
Grade of Fire Alarm	Grade A	
Category of Fire Alarm	LD3 Minimum Protection	
Emergency Lighting Provision	Maintained system - Common areas	
Portable Fire Extinguishers / Fire Blankets supplied / fitted	No	
Water Extinguisher(s) present	No	
Foam Extinguisher(s) present	No	
Dry Powder Extinguisher(s) present	No	
Carbon Dioxide Extinguisher(s) present	No	
Fire Blanket(s) present	No	
Fixed Fire Fighting Installations supplied / fitted	No	
Dry Riser(s) present	No	
Wet Riser(s) present	No	
Sprinkler System present	No	
Hosereel(s) present	No	
Automatic Opening Vent(s) present	No	

### **Electrical Sources of Ignition**

Valid Electrical Installation Condition Reports held on file? (Common Areas & General Needs Flats)YesCommentAll checked and in dateElectrical App/PA Testing - tested within past 12 months?N/A
Electrical App/PA Testing - tested within past 12 months? N/A
Comment None in communal area
Absence of trailing leads and adapters? Yes
Comment None seen
Evidence that mobility scooters are not being stored/charged in Yes common areas?
Comment None seen at time of inspection
Is there a purpose built mobility scooter store/charging area? No

#### **1 Silverdale Street, Barrow In Furness** Asset ID: 33482

Comment	Not required
Does the building have a lightning protection system?	No
Comment	Not required

### **Gas installations**

Is there a commercial/domestic gas supply to the scheme?	Yes
Comment	Flats only
Valid LGSR held on file for fixed communal area gas appliances? (Boilers)	N/A
Comment	None in communal area
Valid LGSR held on file for residential flats that contains gas appliances?	Yes
Comment	All checked Flat 2 is out of date by 2 weeks. Appointment by gas engineer scheduled for 15th Jan
Are smoke/heat detectors within General Needs flats subject to an annual inspection and the results	Yes
Comment	As part of Gas safety check

### **Other Sources of Ignition**

Is there a no smoking policy in place, which is enforced and adhered to?	Yes
Comment	Smoking allowed in flats
Adequate security against arson?	Yes
Comment	Secure front door
Are refuse/recycling bin areas managed and suitably located?	Yes
Comment	Neat
Are there communal cooking facilities at this scheme?	N/A
Comment	None at scheme
Are reasonable measures taken to prevent fires as a result of cooking?	N/A
Comment	No communal kitchen
Where there is extraction in communal kitchens, are filters and ductwork changed/cleaned regularly?	N/A
Comment	See above
Housekeeping	

Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items? Comment

hen Yes

None seen

MIS-AMS ActiveH - Fire Risk Assessment Report

Are unnecessary accumulations of combustible materials or wa avoided?	aste	No		
Comment		Outdoor yard store was open and contained combustible items - mainly tyres. This store is directly under the main staircase. HP to arrange removal and secure doors		
Are combustible materials and substances separated from igni sources and stored appropriately?	tion			
Comment		None seen		
Furniture/furnishings in good condition, fire retardant/resistant a comply with modern standards and regulations?	and	N/A		
Comment		None in communal area		
Observation	Priority	Referred To	Required By:	Task ID
Flammable Items such as tyres stored in external rear	Internal - High	Housing Partner	12/02/2024	1754619

store under staircase. Store is insecure. Items need removing and doors securing to prevent







## **Other Significant Fire Hazards**

Are all other significant fire hazards adequately controlled?	Yes
Comment	None seen
Means of Escape from Fire	
Is it considered that the building is provided with reasonable means of escape in case of fire?	Yes
Comment	
Escape routes unobstructed and safe to use?	Yes
Comment	All clear
Exits immediately openable without a key and/or failsafe's function correctly?	Yes
Comment	Thumb turns on exit doors
Reasonable distances of travel where there is a single/alternative direction of travel?	Yes

Comment

Escape routes lead to final exits and open in direction of escape where necessary? Comment Yes

### **Fire Spread and Development**

Is it considered that the compartmentation is of a reasonable standard?	No
Comment	Glazed Screens between the entrance lobby and the hallway don't appear to be fitted with fire resisting glazing and will require replacing Flat doors for 1, 5 and 7 were damaged and will require replacement Some smoke seals and Intumescent straps missing
Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?	Yes
Comment	Painted walls
Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?	N/A
Comment	None fitted
As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?	N/A
Comment	No communal loft hatches
Loft hatches fire resisting?	N/A
Comment	None in communal area
As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?	N/A
Comment	None fitted
Do external walls, doors, windows and anything attached to the exterior, limit fire spread?	Yes
Comment	
If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?	N/A
Comment	None fitted
Are roller shutter doors that are required to be FR, fire resisting and self-closing?	N/A
Comment	None fitted

Observation	Priority	Referred To	Required By:	Task ID
Flat front doors for 1, 5 and 7 are badly damaged and require replacing. Quotes requested	Repair - Non Emergency			
			TIE	





Observation	Priority	Referred To	Required By:	Task ID
The glazed screens between the entrance foyer and the	Repair - Non			

Emergency

Priority

Repair - Non

I he glazed screens between the entrance toyer and the gf hallway doesn't appear to be FR and requires replacing



Observation

All the communal doors have not been fitted with smoke seals and the door between the foyer and the gf hallway has neither Intumescent strips and smoke seals. The door into thr corridor for flats 1 &



**Required By:** 

Task ID

**Referred To** 





### **Emergency Escape Lighting**

Is the emergency lighting correctly specified and installed as per current standards?

Yes

Comment	
Emergency lighting units in good condition and securely fixed to walls/ceilings?	Yes
Comment	
Records of monthly/annual testing available?	Yes
Comment	Annual tested 20th September 23 Monthly tested 10th January 24

### **Fire Safety Signs and Notices**

Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?	Yes
Comment	Replaced by Assessor at the time
Directional fire escape signage in place and adequate?	Yes
Comment	
Is there suitable LIFT signage i.e. do not use in case of fire?	N/A
Comment	No lift
Do common area fire doors display the correct signage on both sides where applicable?	Yes

Comment

### Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?	Yes
Comment	
Is fire detection and warning system appropriate for occupancy and fire risk, as per BS 5839-1:2017?	Yes
Comment	
Is the fire detection and warning system maintained/tested and all certificates saved on file?	Yes
Comment	Tested 20th September 23
Fire alarm components in good condition and securely fixed to walls/ceilings?	Yes
Comment	
Hold open devices operate at the sounding of the alarm and are in a serviceable condition?	N/A
Comment	None fitted
Are there heat detectors located in the Kitchen, Boiler, Plant Room and Laundry?	N/A
Comment	None
Is the fire alarm panel remotely monitored, and if so are there records of regular testing?	No
	O

#### MIS-AMS ActiveH - Fire Risk Assessment Report

Asset ID: 33482	1 Silverdale Street, I	Barrow In Furness	
Comment			Not monitored
Fire Extinguishing Eq	uipment		
Is fire extinguishing equipmen provided at this scheme?	t and/or fixed fire fighting ir	nstallations	No
Comment			Not required
Management of Fire S	afety		
Are these premises regulated the Building Safety Act? Comment	by the Building Safety Reg	ulator under	Νο
Are there other Responsible P duties in respect of the premis How will this sharing be achie	ses?	fire safety	No
Is an office or IL scheme being	g inspected?		No
Comment			
Passenger Lift			
Is the scheme fitted with a pas	ssenger lift?		No
Comment			
Promises Increation F	Poy		
Premises Inspection E			
Is there a premises informatio	n box for fire & rescue serv	vice use?	No
Comment			Not required
Evacuation Policy			
Are there suitable arrangemer	nts for summoning the fire s	service?	Yes
Comment			999 by residents
Taking FRA findings, is the eva scheme as per latest guidance Comment		e for the	Yes
Engagement with Res	idents		
Has information of fire proced	ures been disseminated to	residents?	Yes
Comment			By letter
MIS-AMS ActiveH - Fire Risk As	ssessment Report	Page 11 of 14	Generated 15/01/2024 16:10:43

Is general fire safety information disseminated to residents?	Yes
Comment	By letter

### **FRA Frequency**

Taking the findings of this assessment into account, is the frequency of	Yes
the FRA correct?	

Comment

#### **Miscellaneous**

Are there any other observations/actions to raise that are not covered above.	Yes
Action leading to a repair	Yes
Internal administrative Action	Yes
Are there fire related remedial works required at this property, that will affect the fabric of the building? Comment	No
Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).	Yes
Some fire doors did not fully close so works orders have been raised with our contractors.	Yes
Some minor works were required which have been raised with our contractors.	Yes
Unauthorised items were found in communal areas and arrangements were made for their removal.	Yes
Not all records were up to date, as noted in the table below. Arrangements have been made for these to be completed.	Yes
A number of fire doors were found to be wedged or propped open. Fire doors are there to keep you safe and me kept shut at all times.	No

#### **Risk Calculator - Fire**

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW	X	MEDIUM	нісн		
-----	---	--------	------	--	--

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR	MAJOR	Y	CRITICAL	
		Λ	ORITIOAL	

The definition of the above terms is as follows: *FRA Review Frequency* 

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	intolerable

When the level of risk is established, the action level can be read from the table below:

#### Asset ID: 33482

### 1 Silverdale Street, Barrow In Furness

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial	