Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 8876 1-39 Holmfield Court Block 1-39 Holmfield Court, Bradford

Cover Sheet

Photo



Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

22 Jan 2025

22 Jan 2026

12

Annual Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Steven Manners Tech IOSH MIFSM MFPA

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name Holmfield Court

Scheme Address 1-39 Holmfield Court Block 1-39 Holmfield Court,

Bradford

Postcode BD1 2DW

Region Yorkshire

Scheme Manager

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority West Yorkshire

Other staff in attendance Cheryl Gledhil-kucuk.

Number of on-site Accent staff

None

Number of other (non-Accent) staff

Contract Cleaners in common areas

The Building

Accommodation Type General Needs (S30)

Build Date Jan 2 1900

Number Of Homes 38

Homes breakdown Flat

External wall construction Natural Stone

External wall finish Artificial/Natural Stone

Roof construction Timber

Roof covering Slate Pitched

PEEPs in place where necessary N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Conversion

Number of storeys 5

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?) 2 protected

Number of External Staircases None

External Balcony part of escape route?

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

Fire Detection and Warning System Flats and common areas not linked Grade of fire alarm Grade B Category of fire alarm LD2 Additional Protection Non Maintained System - Common Areas **Emergency Lighting Provision** Portable Fire Extinguishers supplied/fitted No Fixed Fire Fighting Installations No **Customers** 60 Number of occupants General Needs, Staff Accommodation Occupant tenure type breakdown Fire Safety Related Customer Safety Servicing Overdue communal gas safety checks 0 0 Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 Overdue communal PAT testing 0 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests Overdue Annual Emergency Lighting tests 0 1 Overdue Weekly Fire Alarm Testing Overdue Fire Panel - Six Monthly Testing 1 Overdue Fire Safety Equipment tests **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors Communal Fire doors due for replacement within 5 years 0 **Dwelling Doors** 0 Failing Dwelling Fire Doors

1-39 Holmfield Court Block 1-39 Holmfield Court, Bradford

Dwelling Fire doors due for replacement within 5 years

Asset ID: 8876

0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



Date of Fire Risk Assessment 22/01/2025

FRA Frequency (Months) 12

Purpose of Fire Risk Assessment Annual Re-Assessment

Type of Risk Assessment

Type 1 (Common Parts Only - Non Destructive)

Quantity

Fire & Safety Assessor Steven Manners Tech IOSH MIFSM MFPA

Enforcing Fire Authority West Yorkshire

Scheme Tel. No

Other staff in attendance Cheryl Gledhil-kucuk.

Number of on-site Accent staff

None

Number of other (non-Accent) staff

Contract Cleaners in common areas

Scheme Inspection completed Yes

Number of occupants 60

Personal Emergency Evacuation Plans in place N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Conversion

Number of Storeys 5

Number of floors on which car parking is provided 0

Is there a habitable basement?

No. of internal staircases (protected/unprotected) 2 protected

Number of external staircases None

External balcony part of escape route?

Unusual features None

1-39 Holmfield Court Block 1-39 Holmfield Court, Bradford Asset ID: 8876

Fire Risk Assessment Survey Results

Vehicular Access to one or more elevations Building access conditions for Fire Brigade

Surroundings: Residential/Commercial **Light Commercial**

Fire Detection and Warning System Flats and common areas not linked

Grade B Grade of Fire Alarm

Category of Fire Alarm LD2 Additional Protection

Non Maintained System - Common Areas **Emergency Lighting Provision**

No Portable Fire Extinguishers / Fire Blankets supplied / fitted

Water Extinguisher(s) present No

No Foam Extinguisher(s) present

Dry Powder Extinguisher(s) present

Yes Carbon Dioxide Extinguisher(s) present

No Fire Blanket(s) present

No Fixed Fire Fighting Installations supplied / fitted

Dry Riser(s) present No

Wet Riser(s) present No

No Sprinkler System present

No Hosereel(s) present

Automatic Opening Vent(s) present No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no

obvious damage?

Comment All electrical items were in good condition at the

time of inspection.

Yes

Yes

No

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment Reports can be found on ActiveH

Last Test date :- 19/05/2023

Yes Electrical App/PA Testing - tested within past 12 months?

Last PAT test date 17/09/2024 Comment

Absence of trailing leads and adapters? Yes

Comment None Found at the time of inspection.

Yes Evidence that mobility scooters are not being stored/charged in

common areas?

Comment No mobility scooters at this scheme.

Is there a purpose built mobility scooter store/charging area?

N/A

Comment not required.

Does the building have a lightning protection system?

Comment A survey has been carried out with a view to

installing a system in the future.

Gas installations

Is there a commercial/domestic gas supply to the scheme?

Comment

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered Yes

to?

Comment Smoking is not allowed in the communal areas but

ersidents are llowed to smoke within their flats.

Adequate security against arson?

Comment There is a Fob entry system to the main entrance

and CCTV thorughout the building.

Are refuse/recycling bin areas managed and suitably located?

Comment Ther is a seperate bin store within the building. The

bin chutes have been closed as ther was a history of items being left in bin chute lobbies on each floor

leaving door open causing a fire risk.

Yes

Yes

Yes

N/A

Are there communal cooking facilities at this scheme?

Comment None at this scheme

Housekeeping

Are all electrical/intake/service cupboards secure and free from general

waste, contractors waste and and residents personal items?

Comment None found at the time of inspection.

Are unnecessary accumulations of combustible materials or waste

avoided?

Comment None found at the time of inspection.

Are combustible materials and substances separated from ignition

sources and stored appropriately?

Comment None found at the time of inspection.

Furniture/furnishings in good condition, fire retardant/resistant and

comply with modern standards and regulations?

Comment Furniture not allowed in the communal areas. None

found at the time of inspection.

1-39 Holmfield Court Block 1-39 Holmfield Court, Bradford Asset ID: 8876

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

None found at the time of inspection. Comment

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of

escape in case of fire?

Comment

Comment

Escape routes unobstructed and safe to use?

Comment

Exits immediately openable without a key and/or failsafe's function correctly?

Reasonable distances of travel where there is a single/alternative

direction of travel?

Comment

Escape routes lead to final exits and open in direction of escape where

necessary?

Comment

Comment

Yes

N/A

There are two protected staircases within the

building.

Yes

All clear at the time of inspection.

Yes

All openable at the time of inspection.

Yes

There is two directions of travel on each floor.

Yes

Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment

Is there reasonable limitation of surface finishes that might promote fire

spread (walls, floors, ceilings)?

Are fire dampers/shutters provided in ducts/refuse chutes to protect

means of escape against fire, smoke and combustion products? Comment

As far as can be reasonably ascertained, is the compartmentation

within roof spaces of a satisfactory standard?

Loft hatches fire resisting?

Comment

Comment

No

There was a compartmentation Issue in the lobby of the ground floor electric room. A works order has been raised. See observations.

Yes

All walls are free from combustible materials.

Yes

There is a fire damper in the refuse room.

Yes

A survey has been completed within the roof spaces, there was no access at the time of

inspection.

Yes

1 Hour loft hatches are fitted throughout the building.

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?

Yes

Comment

Cross coridor doors are flush to the ceiling.

Do external walls, doors, windows and anything attached to the exterior, limit fire spread?

Yes

Comment

THe building is of Stone construction.

If Smoke Control Systems (AOV's) are fitted, are the records of annual

N/A

testing available?

None fitted.

Are roller shutter doors that are required to be FR, fire resisting and

N/A

self-closing?

Observation

Comment

Comment None Fitted.

Ceiling in lobby to ground floor electrical room requires repair. Works Order 1250681 raised

Repair - Non Emergency

Priority

Project Manager

Referred To

30/04/2025 1912512

Task ID

Required By:

ncy (Building Safety)



Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per current standards?

Yes

Comment

Emergency lighting units in good condition and securely fixed to walls/ceilings?

Yes

Comment

All in good condition at the time of inspection.

Records of monthly/annual testing available?

Yes

Comment

All records are available on ActiveH.

Last monthly test date :- 09/01/2025

Last Annual test date :- 15/10/2024

Observation Priority Referred To Required By: Task ID

Emergency lighting



Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?

Comment

Directional fire escape signage in place and adequate?

Comment

Is there suitable LIFT signage i.e. do not use in case of fire?

Comment

Do common area fire doors display the correct signage on both sides where applicable?

Comment

Yes

Notices are displayed throughout the building.

Yes

Notices are displayed throughout the building.

Yes

Signage adjacent to the lifts on each floor at the time of inspection.

Yes

Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?

Comment

Is fire detection and warning system appropriate for occupancy and fire risk, as per BS 5839-1:2017?

Comment

Yes

Yes

The rresidants at this scheme tend to smoke and or cvape on the corridors even though there is a no-smoking policy throughout the building. A quote has been received to instll extra detection to allow a double knock system to reduce number of unwanted alarms.

Yes

All test certificates are available on ActiveH. Weekly Test Date: -15/01/2025
6 Month tested on 10/10/2024

Yes

Is the fire detection and warning system maintained/tested and all certificates saved on file?

Comment

Fire alarm components in good condition and securely fixed to walls/ceilings?

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 9 of 15

Generated 24/01/2025 16:03:01

Comment All in good condition at the time of inspection.

Hold open devices operate at the sounding of the alarm and are in a

serviceable condition?

Comment None Fitted.

Are there heat detectors located in the Kitchen, Boiler, Plant Room and

Laundry?

Comment

Is the fire alarm panel remotely monitored, and if so are there records of

regular testing?

Comment As Above.

Observation Priority Referred To Required By: Task ID

Fire panel



Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme?

provided at this solicine:

Comment Only in High risk areas such as lift and electrical

room. Yes

N/A

Yes

N/A

N/A

Yes

Portable fire extinguishers - appropriate type/number/position?

Comment

Correct signage displayed by each fire extinguisher? Yes

Comment

Fire blanket in communal kitchen, secured to the wall, complete with N/A

signage?

Comment

Dry risers - Inlet/outlet boxes secured and/or securing straps fitted to

outlet valves?

Comment

Records available of fire fighting equipment servicing within past 12 Yes

months?

Comment On labels and on ActiveH

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under

the Building Safety Act?

Above 11M but below 18M

Will this FRA be shared will all Accountable Persons for the premises?

Yes

No

Yes

Yes

Yes

Comment

Comment

How will this sharing be achieved?

All records are available on ActiveHand M-Files.

Are there other Responsible Persons who share or have fire safety

duties in respect of the premises?

How will this sharing be achieved?

Is an office or IL scheme being inspected?

Comment

Passenger Lift

Is the scheme fitted with a passenger lift?

Comment

Is the lift in full working order at the time of the FRA?

Yes

Comment

Is the lift fitted with a firefighters switch?

Comment

Servicing and insurance inspection - Evidence of regular

servicing/maintenance?

Comment All available on ActiveH

Last test Date :- 01/11/2024

Premises Inspection Box

Is there a premises information box for fire & rescue service use?

Comment

Evacuation Policy

Are there suitable arrangements for summoning the fire service?

Comment The fire alarm is monitored, residents are advised to

dial 999 and ask for FIRE service.

Taking FRA findings, is the evacuation policy appropriate for the

scheme as per latest guidance?

Comment Due to residents behaviour a double knock system

will be installe in the near future.

1-39 Holmfield Court Block 1-39 Holmfield Court, Bradford Asset ID: 8876

Engagement with Residents

Has information of fire procedures been disseminated to residents?

proceedure and information about their flat doors. A program instaling new Fire doors has begun and

Yes

Yes

Yes

should be finished shortly. Other fire related

All residents received a letter explaining the fire

informatio is available on the website.

Yes Is general fire safety information disseminated to residents?

Comment All residents received a letter explaining the fire proceedure and information about their flat doors. A

> program instaling new Fire doors has begun and should be finished shortly. Other fire related

informatio is available on the website.

FRA Frequency

Comment

Taking the findings of this assessment into account, is the frequency of

the FRA correct?

Comment The premises are visited regularly to complete 3

Monthly Communal fire door checks.

Miscellaneous

above.

Comment

Are there any other observations/actions to raise that are not covered Yes

Action leading to a repair

Internal administrative Action No

No Are there fire related remedial works required at this property, that will

affect the fabric of the building?

Yes Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).

No Some fire doors did not fully close so works orders have been raised

with our contractors.

Some minor works were required which have been raised with our Yes contractors.

No Unauthorised items were found in communal areas and arrangements were made for their removal.

No Not all records were up to date, as noted in the table below.

Arrangements have been made for these to be completed. No

A number of fire doors were found to be wedged or propped open. Fire doors are there to keep you safe and me kept shut at all times.

Observation Priority Referred To Required By: Task ID

Lift signage



Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW

MEDIUM

HIGH

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR	MAJOR	X	CRITICAL	
-------	-------	---	----------	--

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).	
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.	
CRITICAL	RITICAL There is significant potential for serious injury or death of one or more occupants.	

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales	
Trivial	No action is required	
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.	
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.	
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.	

The Overall Risk Level for this asset is:	Trivial