

ACCENT HOUSING - FIRE RISK ASSESSMENT



Region: East

Scheme Name: Hooton Road

Scheme Address : Carlton

Nottingham NG4 1FZ

Date of Assessment: 15/08/2022

Date of Next Assessment: 14/08/2025

FRA Frequency: 3 Year Re-Assessment

Fire & Safety Assessor Lynn Betteridge

This Fire Risk Assessment has been conducted upon the instruction of Accent Housing.

Scheme Details		Hooton Road
Region:		East
Scheme Name:		Hooton Road
Site Address:	Street:	Carlton
	Town:	Nottingham
	Post Code:	NG4 1FZ
Block & Asset No.		14-28 = Block 22-28 Asset 757
		Block 14-20 Asset 756
Block & Asset No.		15-37 = Block 15-25 Asset 758
		Block 27-37 Asset 759
Block & Asset No.		30-52 = Block 30-40 Asset 760
		Block 42-52 Asset 761
Block & Asset No.		39-57 = Block 39-45 Asset 762
		Block 47-57 Asset 763
Block & Asset No.		54-72 = Block 54-64 Asset 764
		Block 66-72 Asset 765
Block & Asset No.		59-74 = Block 59-65 Asset 766
		Block 67-75 Asset 767
Block & Asset No.		74-88 = Block 74-80 Asset 768
		Block 82-88 Asset 769
Block & Asset No.		77-91 = Block 77-83 Asset 770
		Block 85-91 Asset 771
Block & Asset No.		90-99 = Block 90-96 Asset 772
		Block 93-99 Asset 773
Scheme Tel. No:		
Date of this Assessment		15/08/2022
Date of Next Review		14/08/2025
Fire Risk Assessment Frequency		3 Years
Health & Safety Assessment Frequency	y	3 Years
Purpose of Fire Risk Assessment		3 Year Re-Assessment
Fire & Safety Assessor		Lynn Betteridge
Director of Customer Experience		Alex Liburd
Customer Partnership Manager		Lucky Khan
Contract Manager		Kevin Turner
Scheme Manager/Customer Partner		Denise Watt
Other staff in attendance		non
Use of Building		General Needs
Approximate Number of occupants		140-50 Over 86 flats 18 Blocks.
Occupancy Profile		Families
Familiarity of the occupants		Slightly Familiar
Likely state of the Occupants		Alert
PEEPs in place where necessary		N/A
Number of on-site Accent staff		None
		Contract cleaners in common
Number of other (non-Accent) staff		areas
Support Agency (Supported Housing)		N/A
Current Evacuation Strategy.		Stay Put (Delayed) Evacuation
Evidence that residents have been noti	ified of the	Advice notices displayed in
evacuation procedure		common areas
History of fires in the building		None

Business Continuity Plan in place?	Yes
	Type 3 (Common Parts & Flats -
Scope of Assessment	Non Destructive)
Applicable Fire Safety Guidance	Sleeping Accommodation Guide
	Purpose-built flats guide

Building Details	Hooton Road
Construction Date	1982
	Joisted or Load Bearing Masonry
Construction Type	(Traditional)
Roof Finish	Pitched-Concrete Tile
External Wall Finish	Brick
	Cement Render
Are there any areas of external wall cladding	No
Are there any balconies	No
Conversion or purpose-built	Purpose Built
Number of flats (self-contained)/rooms (HMOS, shared	
houses)	86
Number of storeys above ground	Three- Four on different levels
Number of storeys below ground	One-Two diferent Blocks
Is there a habitable basement?	No
Number of internal Staircases per Block	
(protected or unprotected?)	One-Protected
Number of External Staircases per Block	None
External Balcony part of escape route?	N/A
Unusual features	Different levels to each Block
Building complexity	Complex
Building Access Conditions for Fire Brigade	Vehicular Access to one or more
	elevations
Surroundings: Residential/Commercial	Residential
Fire Provision Currently in I	Place
Fire Detection and Warning System	Flats only
Grade of fire alarm	Grade D
Category of fire alarm	LD3 Minimum Protection
Evacuation Alert System (EAS)	Yes-Alarm Sounder
Additional Comments:	Located in Flats
	Non Maintained System -
Emergency Lighting Provision	Common Areas
Portable Fire Extinguishers	None fitted
Fixed Fire Fighting Installations	None fitted
Additional Comments:	

		Siar	nificant Findings - Fire					
	Hooton Road					15/09/2022		
Tiodion Road					15/08/2022			
Action Ref:	Potential Area of Fire Risk	Yes-No-N/A	Observation/Comments/ Actions Required	Risk Rating	Target Completion Date	Referred To:		
			Fire Hazards					
	Electrical Sources of Ignition:							
1.1	Electrical Installation within common areas (Fixed Wiring, sockets, switches, light fittings) in good condition and no obvious damage	Yes	Note; All common area fittings in a satisfactory condition at time of inspection.	•				
1.2	Valid Electrical Installation Condition Reports held on file.(Common Areas)	Yes	Note: Valid Communal EIC reports for this block uploaded to scheme & Active "H". Dated 6/4/20.(5 year inspection due 2025).	-				
1.3	Valid Electrical Installation Condition Reports held on file. (General Needs Flats)	Yes	Note: Valid General needs flats EIC report uploaded to property/scheme file & Active "H". Sample Flat 22 EIC 13/6/22.(5 year inspection due 2027)	-				
1.4	Electrical App/PA Testing - all portable appliances tested within past 12 months	N/A	Note:PAT not required electrical portable equipment not permitted in communal area's	-				
1.5	Absence of trailing leads and adapters	Yes	Note: Clear corridor policy so no Electrical cables from Flats into communal areas.	-				
	Mobility Scooters - Stored/charged in common areas, purpose built store/resident flat	Yes	Note: No evidence or reports that any resident owns a mobility scooter at time of inspection at any of the Blocks.	-				
	Smoking:							
	Are there any risks associated with smoking in the building?	Yes		•				
3	Arson:							

	T					
3.1	Adequate security against arson?	es	Note:At time of inspection all buildings secure			
		>	intercom/keypad/trades button.	-		
3.2	Is there an absence of unnecessary fire load		Note: Generally clear & tidy scheme on day of			
	in close proximity to building?	Yes	inspection all area's Externally.A partnership day			
			was taking part and area's Cleared.			
4	Heating Installations (Portable/fixed)	-		•		
	Gas Installations - Common Areas & Gener	al N	eeds Residential flats.			
4.1	If portable heaters are used, are there		Note: No portable heaters in Communal stair			
	suitable controls?	တ	wells, Unable to control residents heaters within			
		Yes	Flats but through communication & media advice	•		
			Given on Electrical/Gas safety.			
4.2	Are fixed heating installations subject to	es	Note: Flat Heating Systems maintained via			
	regular maintenance?	Хе	contract and recorded on Active "H".	•		
4.3	Valid LGSC held on file for each residential		Note Sample Flat 22 (2107)Gas safety Cert			
	flat that contains gas appliances.	Yes	Uploaded to Active "H" Dated 17/8/21			
	gas apparation	>	Co/Smokes/Heat Checked.			
5	Cooking:					
5 5.1	Cooking: Are reasonable measures taken to prevent		Note: Cooking only permitted in Resident			
	Are reasonable measures taken to prevent	,es	Note: Cooking only permitted in Resident Flats.Fire safety advice given to residents through			
		Yes	Note: Cooking only permitted in Resident Flats.Fire safety advice given to residents through Media comms from Accent.			
	Are reasonable measures taken to prevent		Flats.Fire safety advice given to residents through	•		
5.1	Are reasonable measures taken to prevent fires as a result of cooking? Where there is extraction ventilation in		Flats.Fire safety advice given to residents through			
5.1	Are reasonable measures taken to prevent fires as a result of cooking?	N/A Yes	Flats.Fire safety advice given to residents through			
5.1	Are reasonable measures taken to prevent fires as a result of cooking? Where there is extraction ventilation in communal kitchens are filters changed/		Flats.Fire safety advice given to residents through			
5.1	Are reasonable measures taken to prevent fires as a result of cooking? Where there is extraction ventilation in communal kitchens are filters changed/ cleaned and ductwork cleaned regularly? Lightning Protection System:		Flats.Fire safety advice given to residents through Media comms from Accent.			
5.1 5.2	Are reasonable measures taken to prevent fires as a result of cooking? Where there is extraction ventilation in communal kitchens are filters changed/ cleaned and ductwork cleaned regularly?	A/Z	Flats.Fire safety advice given to residents through Media comms from Accent. Note:No Lighting conducter system fitted due to			
5.1 5.2	Are reasonable measures taken to prevent fires as a result of cooking? Where there is extraction ventilation in communal kitchens are filters changed/cleaned and ductwork cleaned regularly? Lightning Protection System: Does the building have a lightning protection	A/Z	Flats.Fire safety advice given to residents through Media comms from Accent. Note:No Lighting conducter system fitted due to building height and no surge protection			
5.1 5.2	Are reasonable measures taken to prevent fires as a result of cooking? Where there is extraction ventilation in communal kitchens are filters changed/cleaned and ductwork cleaned regularly? Lightning Protection System: Does the building have a lightning protection		Flats.Fire safety advice given to residents through Media comms from Accent. Note:No Lighting conducter system fitted due to building height and no surge protection required.Review underway as per building height			
5.1 5.2	Are reasonable measures taken to prevent fires as a result of cooking? Where there is extraction ventilation in communal kitchens are filters changed/cleaned and ductwork cleaned regularly? Lightning Protection System: Does the building have a lightning protection	A/Z	Flats.Fire safety advice given to residents through Media comms from Accent. Note:No Lighting conducter system fitted due to building height and no surge protection			
5.1 5.2	Are reasonable measures taken to prevent fires as a result of cooking? Where there is extraction ventilation in communal kitchens are filters changed/cleaned and ductwork cleaned regularly? Lightning Protection System: Does the building have a lightning protection	A/Z	Flats.Fire safety advice given to residents through Media comms from Accent. Note:No Lighting conducter system fitted due to building height and no surge protection required.Review underway as per building height			
5.1 5.2 6 6.1	Are reasonable measures taken to prevent fires as a result of cooking? Where there is extraction ventilation in communal kitchens are filters changed/cleaned and ductwork cleaned regularly? Lightning Protection System: Does the building have a lightning protection system, If so, is it adequately maintained?	A/N	Flats.Fire safety advice given to residents through Media comms from Accent. Note:No Lighting conducter system fitted due to building height and no surge protection required.Review underway as per building height			
5.1 5.2 6 6.1	Are reasonable measures taken to prevent fires as a result of cooking? Where there is extraction ventilation in communal kitchens are filters changed/cleaned and ductwork cleaned regularly? Lightning Protection System: Does the building have a lightning protection system, If so, is it adequately maintained? Housekeeping:	A/Z	Flats.Fire safety advice given to residents through Media comms from Accent. Note:No Lighting conducter system fitted due to building height and no surge protection required.Review underway as per building height and generic weather assessment strategy.			

		T			
•					
secure and free from general waste,	SS	cupboards upgrade and locked.			
contractors waste and residents personal	×		•		
items.					
Are combustible materials separated from	S	Note: On this inspection no accumulation of			
ignition sources and stored appropriately?	Ϋ́e	furniture or Combustable items.	•		
	S				
,	≺e		•		
Are hazardous materials stored appropriately		Note:No reports of medical Oxygen in use on			
		,			
,	\rightarrow	·			
	_				
,					
	d oth				
	1				
retardant and complies with 1988	\geqslant	FSO, furniture is not permitted in communal areas.	•		
Regulations.					
Other Significant Fire Hazards:					
Are there other significant fire hazards that	0	Note: Clear areas all over scheme generally	_		
are inadequately controlled?	Z	significan improvement on scheme.	•		
	Fire	Protection Measures			
Means of Escape from Fire:					
Is it considered that the building is provided		Note: All Escape route are within permissible			
• .	es	•			
-	>	•			
_		·			
Locape routes anobotracted and care to use.	es				
	>	identified obstruction tasked for removal.occ 7.4			
Exits easily and immediately openable where	(0	Note:all Blocks have exit thumh style turn			
,	Υe	Troto.ali biooks nave exit triamb style turn.	•		
		Noto:Thoro are soveral variations as building on			
	S				
a single/alternative direction of traver?	, ≺e		•		
		ischeme has an alternative Exit on lower floor.			
Escape routes lead to final exits and open in	S	Note: Clear from Obstructions on Exiting the			
	(1)				
	items. Are combustible materials separated from ignition sources and stored appropriately? Are unnecessary accumulations of combustible materials or waste avoided? Are hazardous materials stored appropriately (i.e. oxygen cylinders, flammable materials, explosive products, oxidising products, aerosols) Furniture/furnishings on escape routes and Furniture/furnishings in good condition, fire retardant and complies with 1988 Regulations. Other Significant Fire Hazards: Are there other significant fire hazards that are inadequately controlled?	secure and free from general waste, contractors waste and residents personal items. Are combustible materials separated from ignition sources and stored appropriately? Are unnecessary accumulations of combustible materials or waste avoided? Are hazardous materials stored appropriately (i.e. oxygen cylinders, flammable materials, explosive products, oxidising products, aerosols) Furniture/furnishings on escape routes and other furniture/furnishings in good condition, fire retardant and complies with 1988 Regulations. Other Significant Fire Hazards: Are there other significant fire hazards that are inadequately controlled? Fire Means of Escape from Fire: Is it considered that the building is provided with reasonable means of escape in case of fire? Escape routes unobstructed and safe to use? Exits easily and immediately openable where necessary, without a key? Reasonable distances of travel where there is a single/alternative direction of travel?	secure and free from general waste, contractors waste and residents personal items. Are combustible materials separated from ignition sources and stored appropriately? Are unnecessary accumulations of combustible materials or waste avoided? Are hazardous materials stored appropriately (i.e. oxygen cylinders, flammable materials, explosive products, oxidising products, aerosols) Furniture/furnishings on escape routes and other communal areas: Furniture/furnishings in good condition, fire retardant and complies with 1988 Regulations. Other Significant Fire Hazards: Are there other significant fire hazards that are inadequately controlled? Mote: Clear areas all over scheme generally significan improvement on scheme. Fire Protection Measures Mote: All Escape route are within permissible distances of travel where there is a single/alternative direction of travel? Note: All Escape route are within permissible distances of travel where there is a single/alternative direction of travel? Note: All Escape route are within permissible distances of travel where there is a single/alternative direction of travel? Note: All Escape route are within permissible distances of travel where there is a single/alternative direction of travel? Note: All Escape route are within permissible distances of travel where there is a single/alternative direction of travel? Note: All Escape route are within permissible distances of travel where there is a single/alternative direction of travel? Note: All Escape route are within permissible distances of travel where there is an alternative Exit on lower floor.	secure and free from general waste, contractors waste and residents personal items. Are combustible materials separated from ignition sources and stored appropriately? Are unnecessary accumulations of combustible materials or waste avoided? Are hazardous materials stored appropriately (i.e. oxygen cylinders, flammable materials, explosive products, oxidising products, aerosols) Furniture/furnishings on escape routes and other communal areas: Furniture/furnishings in good condition, fire retardant and complies with 1988 Regulations. Are there other significant fire hazards that are inadequately controlled? Mote: On this inspection no accumulation of furniture or Combustable items. Note: No reports of medical Oxygen in use on scheme. Cleaning contractors responsible for COSHH. Whote: Clear corridoor policy in force by Accent & FSO, furniture is not permitted in communal areas. Note: Clear areas all over scheme generally significan improvement on scheme. Fire Protection Measures Means of Escape from Fire: Is it considered that the building is provided with reasonable means of escape in case of fire? Solution: Solution: Note: All Escape route are within permissible distances of travel the escape route leads to a place of safety and safe Air. Whole scheme Communal areas Note: All Escape route are within permissible distances of travel the escape route leads to a place of safety and safe Air. Whole scheme Communal areas Clear and identified obstruction tasked for removal. See 7.4 Note: All Blocks have exit thumb style turn. Note: There are several variations as building on incline, Main access Floor has rear access so scheme has an alternative Exit on lower floor.	secure and free from general waste, contractors waste and residents personal items. Are combustible materials separated from ignition sources and stored appropriately? Are unnecessary accumulations of combustible materials or waste avoided? Are hazardous materials stored appropriately (i.e. oxygen cylinders, flammable materials, explosive products, oxidising products, aerosols) Furniture/furnishings on escape routes and other communal areas: Furniture/furnishings in good condition, fire retardant and complies with 1988 Regulations. Other Significant Fire Hazards: Are there other significant fire hazards that are inadequately controlled? Sit it considered that the building is provided with reasonable means of escape in case of fire? Escape routes unobstructed and safe to use? Reasonable distances of travel where there is a single/alternative direction of travel? Source of travel where there is a single/alternative direction of travel? Anote: On this inspection no accumulation of furniture or Combustable items. Note: On this inspection no accumulation of furniture or Combustable items. Note: Note: Note: Note: Note: On this inspection no accumulation of furniture or Combustable items. Note: On this inspection no accumulation of furniture or Combustable items. Note: Note: Note: Note: Note: Note: On this inspection no accumulation of furniture or Combustable items. Note: Note: Note: Note: Note: On this inspection no accumulation of furniture or Combustable items. Note: Note: Note: Note: On this inspection no accumulation of furniture or Combustable items. Note: Note: Note: Note: Note: On this inspection no accumulation of furniture or Combustable items. Note: Clear corridor opolicy in force by Accent & FSO, furniture is not permitted in communal areas. For protection Measures Note: All Escape route are within permissible distances of travel the escape route leads to a place of safety and safe Air. Whole scheme Communal areas Clear and identified obstruction tasked for removal. See 7.4 Note: A

10.6	Do failsafe's on locked exit doors function correctly?	N/A			
10.7	Is it considered that the building is provided with reasonable arrangements for means of escape for disabled people?	Other	Note:No mobility issue's on this scheme at time of inspection, However only ground floor Flats would be suitable across all four Blocks. Due to severe incline on scheme.	-	
11	Measures to Limit Fire Spread and Develop	men	t:		
11.1	Is it considered that the compartmentation is of a reasonable standard?	Yes	Note: Stairwells protected from Fire spread and meets Approved Doc B 1/3.CIC compartmentation works 2021.	-	
11.2	Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?	Yes	Note: Walls are solid Brick throughout and plastered and emulsion finish, steps and floor covering is Carpetl. This construction 2008 Wood framed with Breeze block infill.	-	
11.3	Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?	W/A		-	
11.4	Compartmentation within roof spaces of a satisfactory standard?	Хes	Note: Complete overhaul of compartmentation 2021 by CIC.	•	
11.5	Loft hatches fire resisting?	Yes	Note: Signage affixed.	-	
11.6	Fire stopping above cross-corridor fire doors within suspended ceiling void of a satisfactory standard	N/A		-	
11.7	Smoke Control Systems (AOV's) Are records of annual testing available?	N/A		ı	
	Roller shutter doors (fire resisting)	N/A		ı	
11.9	Do the external walls, windows, balconies etc pose a risk of significant fire spread?	ON	Note: This scheme externally will not propogate fire spread to the external Envelope of this building.	-	

12	2 Communal Area Fire Doors (Inspection to include - construction, hinges, closure devices, intumescent/smoke seal condition, glazing systems and maximum gaps between door and frame.						
12.1	Communal fire doors to FD30s standard and in a serviceable condition,	Yes	Note: All communal doors uploaded to active H. 37 Doors across all various either 3 or 5 doors	ı			
12.2	"Fire door keep shut/locked" signage displayed on both sides of all applicable doors.	Yes	Note: See examples on photos.				
12.3	Hold open devices operate at the sounding of the alarm and are in a serviceable condition	N/A					
13	Flat entrance doors (Internal Common Area	is)					
13.1	Do flat entrance doors open onto internal escape routes?		If yes, see "Residents Front Doors Sheet"	ı			
14	Flats with a single direction of escape to a	sing	le escape stairway. (External Balcony)				
14.1	Do the flat entrance doors that open onto an external balcony have to be passed during an escape?	l (n	Note: Resident Fire Doors inspection to be recorded onto Active "H". Visual Inspection if no access, This Inspection several doors Knocked to seek permission with full PPE and recorded if access achieved See 2A				
14.2	Are the separating walls between the flats and the balcony floor that have to be passed during an escape, fire-resisting up to a height of 1.1m?	N/A	Note: No external balconies on this scheme.	•			
15	Emergency Escape Lighting:	-		-			
15.1	Is the emergency lighting correctly specified and installed as per BS 5266-1:2016	Yes	Note; Non Maintained System Emergency lighting installed within escape routes.				
15.2	Are all emergency lighting units in good condition and securely fixed to walls/ceilings	Yes	Note;All Emergency lights secure and working at time of inspection.				
15.9	Are records of monthly testing available?	Yes	Note; Monthly certs uploaded to property file & Active "H". Dates 1/8/22.				
15.10	Are records of annual testing available?	Yes	Note: Annual 3 hr Drop test dated14/9/21 & uploaded to Active "H"	ı			

16	Fire Safety Signs and Notices:					
	Are the correct Fire Action/Advice notices		Nista Circa and alto all and undetend an all		ı	
16.1		S	Note:Signage checked and updated on all			
	displayed in prominent locations within the	Yes	Blocks.After Compartmention works completed all	•		
40.0	common areas?		signage updated.			
16.3	Directional fire escape signage in place and	Yes				
	adequate?					
16.4	Is there a suitable LIFT sign i.e. do not use in	N/A				
	case of fire.	Z				
17	Means of giving Warning in case of Fire:				_	
17.1	Is the fire detection and warning system	(0	Note: LD3 Smoke & heat detectors fitted located in			
	appropriate for the occupancy and fire risk?	Yes	flats.	•		
17.2	Is the fire detection and warning system		Note:The Fire Detection and Fire alarm system for			
	correctly specified and installed as per BS	Yes	this scheme meets the updated BS5839-6: 2019			
	5839-1:2017		Code of Practice for Design Installation.			
17.3	Is the fire detection and warning system		Note: Contractor Tunstalls test and uploaded to			
	maintained/tested and all certificates saved	es	scheme folder and active "H".Communal Stand			
	on file. (BS 5839-1:2017)	×	alone test recorded Active "H"105/7/22.	•		
	,					
17.4	Are there heat detectors located in the	V				
	Kitchen, Boiler, Plant Room and Laundry?	N/A		'		
17.5	Is the fire alarm panel remotely monitored,					
17.5	and if so are there records of regular testing?	N/A		_		
	and it so are there records or regular testing?	Ž		'		
47.0	Ann ann also the art state of the state of t		Nation Con Cofety Charles			
17.6	Are smoke/heat detectors within General		Note: Gas Safety Check Completed For Flat 22 as			
	Needs flats subject to an annual inspection	Yes	sample flat of scheme recorded an uploaded to			
	and the results recorded on an in date	×	Active "H" 5/10/21.	•		
	Landlord Gas Safety Record (LGSR)					
18	Fire Extinguishing Equipment:					
18.1	Portable fire extinguishers - appropriate	4	Note: General Needs Fire Fighting Equipment			
	type/number/position?	N/A	not Provided.	•		
18.2	Correct signage displayed by each fire					
10.2	extinguisher?	N/A		•		
	oxungulonor:					1

18.3	Fire blanket in communal kitchen, secured to	⋖			
	the wall, complete with signage?	NA		•	
18.4	Hose Reels - fitted, maintained?	N/A		-	
18.5	Dry/wet risers - Full access to all inlet/outlet				
	boxes. All inlet/outlets secured and/or	N N			
	securing straps fitted to outlet valves?	Z		-	
18.6	Records available of fire fighting equipment				
	servicing within past 12 months	N		•	
19		N	lanagement of Fire Safety		
19.1	Are there suitable arrangements for	Yes	Note; Residents to call emergency services in the		
	summoning the fire service?	۶	event of a Fire.	•	
19.2	Do relevant staff carry out regular fire safety		Note: CP carries out scheme inspections which		
	checks	≺e	contain partial F/S observations also clear corridor	_	
			policy enforcement and door functuality last	•	
			inspection 8/8/22.Recorded on Active "H".		
19.3	Sheltered Schemes & Regional Offices - Are				
	there sufficient number of qualified Fire	N A			
	wardens.	_			
19.4	Offices - Are there suitable arrangements for	N/A			
	ensuring the premises are evacuated?	Ž		•	
19.5	Offices - Are there suitable arrangements for	N/A			
	evacuating disabled people?	Ž		•	
19.6	Offices - Are there suitable arrangements for	_			
	meeting the fire service on arrival and	N A		•	
	providing relevant information?				
19.7	Offices/IL Schemes - Is there a suitable	N N			
	assembly point?	Z			
19.8	Offices - Are fire drills carried out at	N N			
	appropriate intervals?	Z			
20	Evacuation Policy				

20.1	Taking the findings of the FRA into account,	(0	Note: Stay put (Delayed) Evacuation policy in		
	is the evacuation policy appropriate for the	Ğ	operation.		
	scheme?				
21	Miscellaneous				
21.1	The 18 Blocks are not all similar as contructed on a major incline access can be gained at one level and exit via Fire Door 2 floors which is not an entry door.Blocks at lower level of scheme are accessed via Elevated walk way.			-	

Residents Front Doors

Hooton Road

15/08/2022

Flat entrance doors to FD30s specification (Inspection to include - Door condition, construction, closure devices, intumescent/smoke seal condition, glazing systems, fire rated letterplate, door furniture and maximum gaps between door and frame/threshold.

Flat No.	Access Gained	Asset No.	Observation/Comments / Actions Required	Risk Rating	Completion Date	Referred To:
28	No	2110	Access not achieved visual inspection from Communal area door in situ sits firmly on rebates .	-		
34	No	2125	Access not achieved visual inspection from Communal area door in situ sits firmly on rebates .	-		
59	No	2161	Access not achieved visual inspection from Communal area door in situ sits firmly on rebates .	-		
22	Yes	2101	Resident Fire Door Inspected and found to meet the FD30 Specification.	-		
82	Yes	2180	Resident Fire Door Inspected and found to meet the FD30 Specification.	-		
89	No	2190	Access not achieved visual inspection from Communal area door in situ sits firmly on rebates .	-		
95	Yes	2196	Resident Fire Door Inspected and found to meet the FD30 Specification.	-		

Photographs - Fire 15/08/2022 Hooton Road



Photo No. 1

Note: Typical Block entrance made at main door some block Exit at 2 lower floors as inclined build fire exit found lower floor.



Photo No. 2

Note: As detailed above Exit found lower level.

Photographs - Fire

Hooton Road



Photo No. 3

Note: Internal staircase all blocks.



Photo No. 4

Note: Standard door fit to all blocks.

Photographs - Fire

15/08/2022

Hooton Road



Photo No. 5

Note: As Above standard front Access with intercom or key safe.



Photo No. 6

Note: Non Maintained - Fire resistant hatch

Photographs - Fire 15/08/2022 Hooton Road



Photo No. 7

Note: Smoke lobby on most landings.



Photo No. 8

Note: Lower floor Fire exit door

Photographs - Fire 15/08/2022 Hooton Road



Photo No. 9

Note; Top floor no smoke lobby.



Photo No. 10

Note; Compartmentation work 2021 replacement doors loft hatches This is the utilities storage.

6. Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

 Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

(please insert x below)

LOW

MEDIUM

HIGH

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

(please insert x below)

MINOR

MAJOR



CRITICAL

The definition of the above terms is as follows:

FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant				
	(other than the occupant sleeping in a bedroom in which a fire occurs).				
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely				
	to lead to fatalities.				
CRITICAL	There is significant potential for serious injury or death of one or more occupants.				

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trivial	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

Action Plan - Fire							
Hooton Road			15/08/2022				
TOLERABLE							
Potential area of fire risk	Observation/Comments / Actions Required	Risk Rating	Completion Date	Referred To: Task ID No.			
Fire Hazards	On partnership day held on scheme major clean up taken place by all agencies at time of inpection no action to detail minor issue's and CP on site with Regional Scheme manager.						

Action Plan - Fire Page 20 of 21

Action Plan - Residents Front Doors						
Hooton Road			15/08/2022			
Flat No.	Asset No.	Observation/Comments / Actions Required		Completion Date	Referred To:	Task ID No.
		RESIDENT FIRE DOOR INSPECTION IS SATISFACTORY AND NO ACTIONS REQUIRED ON THIS SCHEME. MANY DOORS NOT ACCESSED BUT THOSE ACCESSED MEET THE INSPECTION REGIME OF FD30 DOORS.	-			