Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 1030 1-16 Keyworth Court Block 1-16 Princes Street, Huntingdon

Cover Sheet

Photo



Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

14 Aug 2024

14 Aug 2025

12

Annual Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Lynn Betteridge GlfireE (Dip) NEBOSH.

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name Keyworth Court

Scheme Address 1-16 Keyworth Court Block 1-16 Princes Street,

Huntingdon

Postcode PE29 3PU

Region East

Scheme Manager

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority Cambridgeshire Fire and Rescue Service.

Other staff in attendance None

Number of on-site Accent staff None

Number of other (non-Accent) staff

Contract Cleaners in common areas

The Building

Accommodation Type

Build Date Mar 26 2010

Number Of Homes 15

Homes breakdown Flat

External wall construction Steel Frame

External wall finish Facing Brick, UPVC Cladding

Roof construction Metal

Roof covering Interlocking Pitched

PEEPs in place where necessary No

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys 5

Number of floors on which car parking is provided 1

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

1 in this scheme Block 1-16.

Number of External Staircases None

External Balcony part of escape route? N/A

Unusual features Deceptive front to back elevation.

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

Flats and common areas not linked Fire Detection and Warning System Grade of fire alarm Grade A Category of fire alarm LD3 Minimum Protection Non Maintained System - Common Areas **Emergency Lighting Provision** Portable Fire Extinguishers supplied/fitted No Fixed Fire Fighting Installations No **Customers** 25 Number of occupants Occupant tenure type breakdown Intermediate, Non Social Housing Intermediate Fire Safety Related Customer Safety Servicing 0 Overdue communal gas safety checks Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 0 Overdue communal PAT testing 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests 0 Overdue Annual Emergency Lighting tests Overdue Weekly Fire Alarm Testing 0 Overdue Fire Panel - Six Monthly Testing n Overdue Fire Safety Equipment tests **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors 0 Communal Fire doors due for replacement within 5 years **Dwelling Doors** 0 Failing Dwelling Fire Doors Dwelling Fire doors due for replacement within 5 years 0

1-16 Keyworth Court Block 1-16 Princes Street, Huntingdon

Asset ID: 1030

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



Date of Fire Risk Assessment 14/08/2024

FRA Frequency (Months) 12

Purpose of Fire Risk Assessment Annual Re-Assessment

Type of Risk Assessment

Type 1 (Common Parts Only - Non Destructive)

Quantity

Fire & Safety Assessor Lynn Betteridge GlfireE (Dip) NEBOSH.

Enforcing Fire Authority Cambridgeshire Fire and Rescue Service.

Scheme Tel. No

Other staff in attendance None

Number of on-site Accent staff None

Number of other (non-Accent) staff

Contract Cleaners in common areas

Scheme Inspection completed Yes

Number of occupants 25

Personal Emergency Evacuation Plans in place No

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of Storeys

Number of floors on which car parking is provided 1

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

1 in this scheme Block 1-16.

Number of external staircases None

External balcony part of escape route? N/A

Unusual features Deceptive front to back elevation.

5

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Residential

Fire Detection and Warning System Flats and common areas not linked

Grade of Fire Alarm Grade A

Category of Fire Alarm LD3 Minimum Protection

Emergency Lighting Provision Non Maintained System - Common Areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted No

Water Extinguisher(s) present No

Foam Extinguisher(s) present

Dry Powder Extinguisher(s) present

Carbon Dioxide Extinguisher(s) present

Fire Blanket(s) present

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present Yes

Wet Riser(s) present

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present

Yes

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no

obvious damage?

Comment All electrical equipment components on each floor

found to be secure and not damaged.

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment The EICR is required every 5 years and has been

tested and recorded date of 6/11/2023. The

cerfication has been uploaded to Active"H " and M

files.

Yes

Yes

Yes

Electrical App/PA Testing - tested within past 12 months?

N/A

Comment

Absence of trailing leads and adapters? Yes

Comment On the day of inspection there was no visible signs

of leads and adapters on all floors.

Evidence that mobility scooters are not being stored/charged in

common areas?

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 5 of 15

Generated 27/08/2024 16:00:57

Comment No mobility scooters identified on scheme Housing

partner confirms.

Is there a purpose built mobility scooter store/charging area?

N/A

Comment There is no external storage or charging provision at

this scheme.

Does the building have a lightning protection system?

Comment

Gas installations

Is there a commercial/domestic gas supply to the scheme?

Comment The scheme is not covered by any gas compliance

regulations.

Yes

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered

to?

Comment Communal areas are designated no smoking and

residents are made aware of by signage and a reminder that this in Accents policy statement in the

tenancy agreement.

Adequate security against arson?

Comment At time of inspection all doors secure and access

only by keypad. There is also a secure fire door leading to the carpark area opening in the direction

of travel.

No

Yes

Yes

Are refuse/recycling bin areas managed and suitably located? Yes

Comment Commercial size bins in purpose bin storage area

located and locked only access by residents.

Are there communal cooking facilities at this scheme?

Comment

Housekeeping

Are all electrical/intake/service cupboards secure and free from general

waste, contractors waste and and residents personal items?

Are unnecessary accumulations of combustible materials or waste

avoided?

Comment

Comment Generally the scheme is well maintained and each

floor communal area clear. Externally the scheme

Cupboards containing electrical intake/electrical equipment at each level are Fire resisting doors and

area is clear and tidy.

are kept locked.

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 6 of 15

Generated 27/08/2024 16:00:57

Are combustible materials and substances separated from ignition

sources and stored appropriately?

Comment

Furniture/furnishings in good condition, fire retardant/resistant and

comply with modern standards and regulations?

Comment

This is a General Needs block and no furniture

provision in communal areas.

N/A

N/A

Yes

Yes

Yes

Yes

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Comment I will be meeting the housing partner on this scheme as the communal Doors will be required to be

checked 3 monthly and flat doors annually. We will be providing advice to the residents in this scheme

and the housing partner.

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of

escape in case of fire?

Comment All flats lead into a protected staircase communal area, the travel distance meets the code of practice

and residents proceed to safe air via the staircase.

Escape routes unobstructed and safe to use?

Comment At the time of inspection there was no

obstructions.residents are reminded of the clear

corridor policy.

Exits immediately openable without a key and/or failsafe's function

correctly?

Comment Safe egress by residents is maintained in direction

> of travel and a emergency release installation is provided by the final exit. This equipment door release mechanism was tested on the day of

inspection.

Yes

Yes

Reasonable distances of travel where there is a single/alternative

direction of travel?

Comment Travel distances from residents flats meets the

code of practice

Escape routes lead to final exits and open in direction of escape where

necessary?

Comment All fire doors on each landing open in direction of

travel to safe Air.

Fire Spread and Development

Yes Is it considered that the compartmentation is of a reasonable standard?

Comment

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?

Comment

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?

Comment

As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?

Comment

Loft hatches fire resisting?

Comment

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?

Comment

Do external walls, doors, windows and anything attached to the exterior, limit fire spread?

Comment

If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?

Comment

Are roller shutter doors that are required to be FR, fire resisting and self-closing?

Comment

Yes

The surface linings of walls and ceilings are designed to meet classification C-s3,d2.

Yes

The AOV smoke chutes travel from ground floor to louvre escape roof line. Each landing has manual operation for fire service use.

Yes

Yes

Fire resisting loft hatches are on top landing in the communal area stairwell landing at top floor level.

N/A

This scheme is to have a full survey to establish the external wall materials and front fascard. This includes the roof area on the scheme the results will then be updated into the Fire Risk Assessment.

Yes

The AOV system was completely replaced in 2023 as previous system was faulty all certification is uploaded to Active "H" and M files. Test dated as 29/7/2024. Each landing has a standard Fire door operated via Fire alarm activation. Control panel in block 17-36 for both blocks.

N/A

The carpark area has a double steal shutter which is not fire rated on fire alarm activation shutter opens.

Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per current standards?

Comment

Emergency lighting units in good condition and securely fixed to walls/ceilings?

Yes

Certification on installation is uploaded to Active"H"and M files and meets BS5266-1.

Contractor Tunstalls maintain and text the system.

Yes

Comment On the day of inspection the emergency lighting

system was found in good condition and all equipment on each landing was secure and

operational.

Yes

Records of monthly/annual testing available?

Comment The emergency lighting system at this scheme has

been tested monthly on the 3/7/2024 and the annual drop test was completed on 19/4/2024.All recorded by Tunstalls and uploaded to Active"H" and M files.

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent

locations within the common areas?

Comment Fire action notices in all communal areas by the final exit on this inspection all were replaced.

Directional fire escape signage in place and adequate?

Comment Signage is provided above each fire exit and on other

floors the direction of travel and all signs in

accordance with BS5499-4.

Is there suitable LIFT signage i.e. do not use in case of fire?

Comment Each floor landing has fire routine notification do not

use the lift in the event of a fire situation.

Do common area fire doors display the correct signage on both sides

where applicable?

Comment All communal fire doors are denoted both sides Fire

Door.

Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?

Yes

Comment The fire panel is located in the main foyer along with

the floor plan and denoted Zones

Of each floor.

Yes

Yes

Is fire detection and warning system appropriate for occupancy and fire

risk, as per BS 5839-1:2017?

Is the fire detection and warning system maintained/tested and all

MIS-AMS ActiveH - Fire Risk Assessment Report

certificates saved on file?

Comment The fire panel is tested 6 monthly by the main

contractor Tunstalls date of last test

dated15/2/2024. The scheme fire alarm is also tested weekly last test date 8/8/2024 by the

contractor all records are uploaded to Active "H" and

M files.

Yes

Fire alarm components in good condition and securely fixed to

walls/ceilings?

Comment

Page 9 of 15

Generated 27/08/2024 16:00:57

Comment At the time of inspection all components were

identified on each floor in good condition.

Hold open devices operate at the sounding of the alarm and are in a

serviceable condition?

N/A

Comment

Are there heat detectors located in the Kitchen, Boiler, Plant Room and

Laundry?

Comment

Is the fire alarm panel remotely monitored, and if so are there records of

regular testing?

No

N/A

Comment

As previously stated the fire alarm maintenance contract is established with Tunstalls and monthly

/Weekly and Bi annual testing regime.

Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations

provided at this scheme?

Yes

No

N/A

Yes

Yes

Comment Dry risers located each floor.

Portable fire extinguishers - appropriate type/number/position?

Comment

N/A Correct signage displayed by each fire extinguisher?

Comment

Fire blanket in communal kitchen, secured to the wall, complete with

signage?

Comment

outlet valves?

Dry risers - Inlet/outlet boxes secured and/or securing straps fitted to

Comment

All checked on day of inspection at each floor level.

Records available of fire fighting equipment servicing within past 12

months?

Comment The Dry Riser annual check has been serviced by

Morgan Fire on 19/8/2024.

Observation **Priority** Referred To Required By: Task ID

Dry riser requires an annual inspection testing. This is now completed dated 19/8/2024.



Internal - Medium **Project Manager** (Building Safety)

30/08/2024

1856295



Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under the Building Safety Act?

Comment

Comment

Will this FRA be shared will all Accountable Persons for the premises?

How will this sharing be achieved?

Are there other Responsible Persons who share or have fire safety

duties in respect of the premises?

How will this sharing be achieved?

Is an office or IL scheme being inspected?

Comment

Yes

This block is five storeys in height which means the building is in scope of the Building Safety Act

Yes

FRA will be made available on the Accent website.

FRA will be made available on the Accent website

Nο

No

Passenger Lift

Is the scheme fitted with a passenger lift? Yes

Comment New signage displayed on adjacent wall, not to be

used in the event of a fire.

Is the lift in full working order at the time of the FRA? Yes

Comment

Is the lift fitted with a firefighters switch? No

Comment

Servicing and insurance inspection - Evidence of regular Yes

servicing/maintenance?

Comment The lift for this scheme has undergone a inspection and servicing on 9/5/24 and result uploaded to Active "H" and M files.on day of Fire Risk Assessment the lift was functioning correctly and at each level.

Premises Inspection Box

Is there a premises information box for fire & rescue service use?

Comment

No

Evacuation Policy

Are there suitable arrangements for summoning the fire service?

Comment

Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance?

Comment

Yes

All residents call the fire and Rescue service in the event of a fire.

Yes

Yes

The "Stay put"policy has been implemented so as to limit the risk that residents will ignore alarm signals.

Engagement with Residents

Has information of fire procedures been disseminated to residents?

Comment

When the residents take ownership of their flat they are given fire safety advice and also leaflets and a link into the website. The residents are also given notification of the Evacuation procedure for there scheme and can request a copy of the FRA, Accent fire safety assessor details are shared for any advice

and support.

Yes

Is general fire safety information disseminated to residents?

Comment

Residents are distributed leaflets on current fire safety initiatives, the website provides additional

information on and safety advice.

FRA Frequency

Taking the findings of this assessment into account, is the frequency of the FRA correct?

Comment

Yes

This has been changed and updated to Annual inspection.

Miscellaneous

Are there any other observations/actions to raise that are not covered above.

Are there fire related remedial works required at this property, that will affect the fabric of the building?

Comment

No

No

Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).

No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW	X	MEDIUM		HIGH	
-----	---	--------	--	------	--

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).	
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.	
CRITICAL	ITICAL There is significant potential for serious injury or death of one or more occupants.	

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Asset ID: 1030 1-16 Keyv

1-16 Keyworth Court Block 1-16 Princes Street, Huntingdon

Risk Level	Guide to actions and appropriate timescales	
Trivial	No action is required	
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.	
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.	
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.	

ne Overall Risk Level for this asset is:	Trivial
ne Overali Risk Level for this asset is:	