

#### **ACCENT HOUSING - FIRE RISK ASSESSMENT**



Region: East

Scheme Name : Addington Court

Scheme Address: Addington Court

Radcliffe-on-Trent

**NG12 1DW** 

Date of Assessment: 03/08/2022

Date of Next Assessment: 02/08/2025

FRA Frequency: 3 Year Re-Assessment

Fire & Safety Assessor Lynn Betteridge

This Fire Risk Assessment has been conducted upon the instruction of Accent Housing.

Scheme Details		Addingto	on Court
Region:		East	
Scheme Name:		Addington Court	
Site Address:	Street:	Addington Court	
	Town:	Radcliffe-on-Trer	nt
	Post Code:	NG12 1DW	
Block & Asset No.		Block 1-6	Asset 802
Block & Asset No.		Block 7-17	Asset 803
Block & Asset No.		Block 18-28	Asset 804
Block & Asset No.		Block 29-34	Asset 805
Scheme Tel. No:			
Date of this Assessment		03/08/2022	
Date of Next Review		02/08/2025	
Fire Risk Assessment Frequency		3 Years	
Health & Safety Assessment Frequency	1	3 Years	
Purpose of Fire Risk Assessment		3 Year Re-Asses	sment
Fire & Safety Assessor		Lynn Betteridge	
Director of Customer Experience		Vacant	
Customer Partnership Manager		Keith Bowman	
Contract Manager		Kevin Turner	
Scheme Manager/Customer Partner		Natalie Bennett	
Other staff in attendance		None	
Use of Building		General Needs	
Approximate Number of occupants		40-50	
Occupancy Profile		Families	
Familiarity of the occupants		Fully Familiar	
Likely state of the Occupants		Alert	
PEEPs in place where necessary		No	
Number of on-site Accent staff		Scheme Manage	r Part-time
		Contract cleaners	s in common
Number of other (non-Accent) staff		areas	
Support Agency (Supported Housing)		N/A	
Current Evacuation Strategy.		Stay Put (Delaye	d) Evacuation
Evidence that residents have been notif	fied of the	Advice notices di	splayed in
evacuation procedure		common areas	
History of fires in the building		None	
Business Continuity Plan in place?		Yes	
		Type 3 (Commor	
Scope of Assessment		Non Destructive)	
		Sleeping Accomr	modation Guide
Applicable Fire Safety Guidance			
		Purpose-built flat	s guide
		LACORS Guide	

Building Details	Addington Court
Construction Date	1984
	Joisted or Load Bearing Masonry
Construction Type	(Traditional)
Roof Finish	Pitched-Concrete Tile
External Wall Finish	Brick
	Cement Render
Are there any areas of external wall cladding	No
Are there any balconies	No
Conversion or purpose-built	Purpose Built
Number of flats (self-contained)/rooms (HMOS, shared	
houses)	36
Number of storeys above ground	Three
Number of storeys below ground	None
Is there a habitable basement?	N/A
Number of internal Staircases per Block	
(protected or unprotected?)	One-Protected
Number of External Staircases per Block	None
External Balcony part of escape route?	N/A
Unusual features	None
Building complexity	Simple
Building Access Conditions for Fire Brigade	Vehicular Access to one or more
	elevations
Surroundings: Residential/Commercial	Residential
Fire Provision Currently in P	lace
Fire Detection and Warning System	Flats and common areas not
	linked
Grade of fire alarm	Grade E
Category of fire alarm	LD3 Minimum Protection
Evacuation Alert System (EAS)	Yes-Alarm Sounder
	Maintained system - Common
Emergency Lighting Provision	Areas
Portable Fire Extinguishers	None fitted
Fixed Fire Fighting Installations	None fitted
Additional Comments:	

		Siar	nificant Findings - Fire					
	Addington Court					03/08/2022		
	9				00,00,			
Action Ref:	Potential Area of Fire Risk	Yes-No-N/A	Observation/Comments/ Actions Required	Risk Rating	Target Completion Date	Referred To:		
			Fire Hazards					
	Electrical Sources of Ignition:							
1.1	Electrical Installation within common areas (Fixed Wiring, sockets, switches, light fittings) in good condition and no obvious damage	sə	Note: All common area fittings in satisfactory condition at time of inspection.	•				
1.2	Valid Electrical Installation Condition Reports held on file.(Common Areas)	Yes	Note: Valid Communal EIC reports for this block uploaded to scheme & Active "H". Dated 1/11/18.(5 year inspection due 2023).	-				
1.3	Valid Electrical Installation Condition Reports held on file. <b>(General Needs Flats)</b>	Yes	Note: Valid General needs flats EIC report uploaded to property/scheme file & Active "H". Sample Flat 16 EIC 9/2/20(5 year inspection due 2025)	•				
1.4	Electrical App/PA Testing - all portable appliances tested within past 12 months	N/A	Note:PAT not required electrical portable equipment not permitted in communal area's	•				
1.5	Absence of trailing leads and adapters	Yes	Note: Clear corridor policy so no Electrical cables from Flats into communal areas.	•				
	Mobility Scooters - Stored/charged in common areas, purpose built store/resident flat	Other	Note: No evidence or reports that any resident owns a mobility scooter at time of inspection at any of the Blocks.					
	Smoking:							
	Are there any risks associated with smoking in the building?	Yes	Note: Smoking permitted in flats only and not communal areas.					
3	Arson:							

- 1	A de que te e e e unita a e e in et e un e un O		Nieta Attino of increation all buildings account		T	T .
3.1	Adequate security against arson?	Yes	Note: At time of inspection all buildings secure			
			intercom/keypad/trades button.			
3.2	Is there an absence of unnecessary fire load	Yes	Note: Generally clear & tidy scheme on day of			
	in close proximity to building?	>	inspection all area's Externally.			
4	Heating Installations (Portable/fixed)					
	Gas Installations - Common Areas & Gener	al Ne	eeds Residential flats.			
4.1	If portable heaters are used, are there		Note: No portable heaters in Communal stair			
	suitable controls?	S	wells, Unable to control residents heaters within			
		Yes	Flats but through communication & media advice	•		
			Given on Electrical/Gas safety.			
4.2	Are fixed heating installations subject to	S	Note: Heating Systems maintained via contract			
	regular maintenance?	Yes	and recorded on Active "H".	•		
4.3	Valid LGSC held on file for each residential		Note Sample Flat 16 (2382)Gas safety Cert			
	flat that contains gas appliances.	Yes	Uploaded to Active "H" Dated 10/6/22			
	That that contains gus appliances.	>	Co/Smokes/Heat Checked.			
<b>E</b>	Cooking		CO/SITIONES/FIEAR CHECKEG.		ļ	
5	Cooking:	ı	Note: Cooking only pagetted in Decident		T	
5.1	Are reasonable measures taken to prevent	S	Note: Cooking only permitted in Resident			
	fires as a result of cooking?	Yes	Flats.Fire safety advice given to residents through	•		
			Media comms from Accent.			
5.2	Where there is extraction ventilation in	d				
	communal kitchens are filters changed/	N/A		•		
	cleaned and ductwork cleaned regularly?					
6	Lightning Protection System:					
6.1	Does the building have a lightning protection		Note:No Lighting conducter system fitted due to			
	system, If so, is it adequately maintained?		building height and no surge protection			
		N/A	required.Review underway as per building height			
		_	and generic weather assessment strategy.			
7	Housekeeping:				•	
7.1	Is the standard of housekeeping adequate?		Note: All areas well maintained and clear at time of			
		Other	inspection.On day of inspection it was a	_		
		<u></u>	partnership day and area's being tidied up and	•		
			skip supplied.			

	Ţ				
7.2	Are all electrical/intake/service cupboards		Note: All Storage cupboards at locked and		
	secure and free from general waste,	es	unavaliable to check.Signage added to		
	contractors waste and residents personal	×	Doors.Limited Storage in Blocks and Entrance	•	
	items.		area .		
7.3	Are combustible materials separated from	es	Note: On this inspection no accumulation of		
	ignition sources and stored appropriately?	×	furniture or Combustable items.	•	
7.4	Are unnecessary accumulations of	S			
	combustible materials or waste avoided?	Yes		•	
7.5	Are hazardous materials stored appropriately		Note:No reports of medical Oxygen in use on		
	(i.e. oxygen cylinders, flammable materials,		scheme.On ILS schemes when resident has		
	explosive products, oxidising products,	N/A	Oxygen Therapy sign affixed to Flat door to alert		
	aerosols)	_	FRS.Cleaning contractors responsible for COSHH.		
			β		
8	Furniture/furnishings on escape routes and	oth	er communal areas:		
8.1	Furniture/furnishings in good condition, fire		Note; Clear corridoor policy in force by Accent &		
	retardant and complies with 1988	es	FSO, furniture is not permitted in communal		
	Regulations.	Ϋ́	areas.On inspection some items found and	•	
			removed.		
9	Other Significant Fire Hazards:				
9.1	Are there other significant fire hazards that				
	are inadequately controlled?	8		•	
		Fire	Protection Measures		
10	Means of Escape from Fire:				
10.1	Is it considered that the building is provided		Note:All Escape route are within permissible		
	with reasonable means of escape in case of	Yes	distances of travel the escape route leads to a		
	fire?	_	place of safety and safe Air.		
10.2	Escape routes unobstructed and safe to use?	es	Whole scheme Communal areas Clear and		
		Хе	identified obstruction tasked for removal.	•	
10.3	Exits easily and immediately openable where	es	Note:all Blocks have exit thumb style turn and		
	necessary, without a key?	Ye	push to release exits.	•	
10.4	Reasonable distances of travel where there is	es	Note:Ground Floor has rear access so scheme		
	a single/alternative direction of travel?	∠e	has an alternative Exit.	•	
10.5	Escape routes lead to final exits and open in		Note: Clear from Obstructions on Exiting the		
10.5	<b>.</b>	Yes	Building.		
Ī	direction of escape where necessary?		pullulity.		

10.6	Do failsafe's on locked exit doors function correctly?	Yes	Note: Pushbars on rear exits.			
	Is it considered that the building is provided with reasonable arrangements for means of escape for disabled people?	Yes	Note:one Resident has mobility issue's on this scheme at time of inspection,he is located to exit doors and ground level. However only ground floor Flats on this schem would be suitable across all four Blocks.	-		
11	Measures to Limit Fire Spread and Develop	men	t:			
11.1	Is it considered that the compartmentation is of a reasonable standard?	Other	Note: There is Panel missing in the commual area Ceiling tasked to be replaced. Block 7-17	Med	1/11/22	Fire Safety Manager
11.2	Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?	sə <sub>A</sub>	Note: Walls are solid Brick throughout and emulsion finish, steps and floor covering is Vinyl. The ceilings are covered in wood pannelling and coated in zero rated paint.	-		
11.3	Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?	N/A		-		
11.4	Compartmentation within roof spaces of a satisfactory standard?	Yes		-		
11.5	Loft hatches fire resisting?	No	Note: Loft Hatches to be replaced in each Block to Fire Resisting.	Med	1/11/22	Fire Safety Manager
	Fire stopping above cross-corridor fire doors within suspended ceiling void of a satisfactory standard	Yes	Note: Communal smoke lobbies floor to ceilings provide compartmentation via georgian glass and fire door.	-		
11.7	Smoke Control Systems (AOV's) Are records of annual testing available?	N/A		-		
	Roller shutter doors (fire resisting)	N/A		-		_
11.9	Do the external walls, windows, balconies etc pose a risk of significant fire spread?	No	Note: This scheme externally will not propogate fire spread to the external Envelope of this building.	-		

12	Communal Area Fire Doors (Inspection to i	nclud	de - construction, hinges, closure devices, intum	esce	nt/smoke s	eal condition.
	glazing systems and maximum gaps betwe					,
12.1	Communal fire doors to FD30s standard and in a serviceable condition,	Yes	Note: Each Block has 2 communal doors on each landing and are satisfactory in operation.	•		
12.2	"Fire door keep shut/locked" signage displayed on both sides of all applicable doors.	Yes		•		
12.3	Hold open devices operate at the sounding of the alarm and are in a serviceable condition	N/A				
13	Flat entrance doors (Internal Common Area	ıs)		,		
13.1	Do flat entrance doors open onto internal escape routes?	Yes	Note: Resident Fire Doors inspection to be recorded onto Active "H". Visual Inspection if no access, This Inspection several doors Knocked to seek permission with full PPE and recorded if access achieved See 2A	•		
14	Flats with a single direction of escape to a	sing	le escape stairway. (External Balcony)			
14.1	Do the flat entrance doors that open onto an external balcony have to be passed during an escape?	N/A				
14.2	Are the separating walls between the flats and the balcony floor that have to be passed during an escape, fire-resisting up to a height of 1.1m?	N/A	Note: No external balconies on this scheme.			
15	Emergency Escape Lighting:					
15.1	Is the emergency lighting correctly specified and installed as per BS 5266-1:2016	Yes	Note: This Scheme has a <b>Non Maintained</b> system illuminated when normal lighting supply Fails.For			
15.2	Are all emergency lighting units in good condition and securely fixed to walls/ceilings	Yes	Note:All Emergency lights secure and working at time of inspection.			
15.9	Are records of monthly testing available?	Yes	Note; Monthly certs uploaded to property file & Active "H". Dates 28/7/22.	•		

15 10	Are records of annual testing available?	- 10	Note: Appual 2 hr Drap toot dated 19/10/21 9		
15.10	Are records of annual testing available?	Yes	Note: Annual 3 hr Drop test dated 18/10/21 &		
40	Fire Cofety Ciana and Nations.		uploaded to Active "H"		
	Fire Safety Signs and Notices:		IN . O		
16.1	Are the correct Fire Action/Advice notices	S	Note:Signage checked and updated Final exit		
	displayed in prominent locations within the	Yes	signes placed on all Doors.	•	
	common areas?				
16.3	Directional fire escape signage in place and	Yes			
	adequate?				
16.4	Is there a suitable LIFT sign i.e. do not use in	N/A			
	case of fire.	Z			
	Means of giving Warning in case of Fire:				
17.1	Is the fire detection and warning system	(0	Note: Smoke and Heat detectors located in flats.		
	appropriate for the occupancy and fire risk?	Yes	Stand alone test recorded Active "H".10/7/22	•	
		`			
17.2	Is the fire detection and warning system		Note:The Fire Detection and Fire alarm system for		
	correctly specified and installed as per BS	Yes	this scheme meets the <b>updated</b> BS5839-6: 2019		
	5839-1:2017		Code of Practice for Design Installation.		
17.3	Is the fire detection and warning system		Note: Yes for Flats only.		
	maintained/tested and all certificates saved	Yes	·		
	on file. (BS 5839-1:2017)	Ϋ́		•	
	,				
17.4	Are there heat detectors located in the	V	Note: General Needs Scheme.		
	Kitchen, Boiler, Plant Room and Laundry?	N/A		•	
17.5	Is the fire alarm panel remotely monitored,				
17.5	and if so are there records of regular testing?	N/A			
	and it so are there records or regular testing:	Ž		•	
47.0	And another the act data at the contribute Order		Nata Car Orfoli Obash C		
17.6	Are smoke/heat detectors within General		Note: Gas Safety Check Completed For Flat 16 as		
	Needs flats subject to an annual inspection	Yes	sample flat of scheme recorded an uploaded to	_	
	and the results recorded on an in date	Ϋ́	Active "H" 10/7/22.	'	
	Landlord Gas Safety Record (LGSR)				
18	Fire Extinguishing Equipment:				
18.1	Portable fire extinguishers - appropriate		Note: General Needs Fire Fighting Equipment		
10.1	type/number/position?	N/A	not Provided.		
Į.	туре/пипповт/розниот:		not Frovided.		

					1	
	Correct signage displayed by each fire	N/A				
	extinguisher?	Z				
18.3	Fire blanket in communal kitchen, secured to	N/A				
	the wall, complete with signage?			•		
18.4	Hose Reels - fitted, maintained?	N/A		-		
18.5	Dry/wet risers - Full access to all inlet/outlet					
	boxes. All inlet/outlets secured and/or	N/A				
	securing straps fitted to outlet valves?	_				
18.6	Records available of fire fighting equipment					
	servicing within past 12 months	N/A		•		
19		M	lanagement of Fire Safety			
19.1	Are there suitable arrangements for	S	Note; Residents to call emergency services in the			
	summoning the fire service?	λе	event of a Fire.	•		
19.2	Do relevant staff carry out regular fire safety		Note: CP carries out scheme inspections which			
	checks	S	contain partial F/S observations also clear corridor			
		Yes	policy enforcement and door functuality last	'		
			inspection 3/5/22.Recorded on Active "H".			
19.3	Sheltered Schemes & Regional Offices - Are	_				
	there sufficient number of qualified Fire	N/A		•		
	wardens.	_				
19.4	Offices - Are there suitable arrangements for	N/A				
	ensuring the premises are evacuated?	Ž				
	Offices - Are there suitable arrangements for	N/A				
	evacuating disabled people?	Ž				
19.6	Offices - Are there suitable arrangements for					
	meeting the fire service on arrival and	N/A		•		
	providing relevant information?					
	Offices/IL Schemes - Is there a suitable	N/A				
	assembly point?	Z				
	Offices - Are fire drills carried out at	N/A				
	appropriate intervals?	Z				
20	Evacuation Policy					

	Taking the findings of the FRA into account, is the evacuation policy appropriate for the scheme?	ဟ	Note: Stay put ( Delayed) Evacuation policy in operation.	•				
21	Miscellaneous							
21.1				•				

#### Residents Front Doors

### **Addington Court**

03/08/2022

Flat entrance doors to FD30s specification (Inspection to include - Door condition, construction, closure devices, intumescent/smoke seal condition, glazing systems, fire rated letterplate, door furniture and maximum gaps between door and frame/threshold.

Flat No.	Access Gained	Asset No.	Observation/Comments / Actions Required	Risk Rating	Completion Date	Referred To:
8	No	2374	Access not achieved visual inspection from Communal area door in situ sits firmly on rebates .	-		
16	Yes	2382	Resident Fire Door Inspected and found to meet the FD30 Specification.	-		
19	No	2385	Access not achieved visual inspection from Communal area door in situ sits firmly on rebates .	-		
21	No	2387	Access not achieved visual inspection from Communal area door in situ sits firmly on rebates .	-		
25	No	2391	Access not achieved visual inspection from Communal area door in situ sits firmly on rebates .	-		
26	Yes	2392	Resident Fire Door Inspected and found to meet the FD30 Specification.	-		



Photo No. 1

Note: All Blocks loft Hatches to be replaced by Fire Resisting and lockable.



Photo No. 2

Note: Communal Cladding from ceiling miss taked to be replaced.



Photo No. 3

Note: This door was tasked as emergency Replacement



Photo No. 4

Note:Main Access to Block.



Photo No. 5

Note: Access staircase to main blocks.



Photo No. 6

Note: Communal Doors on each Floor.



Photo No. 7

Note: Typical Flat door on shceme.



Photo No. 8

Note: Flat Door.

Photographs - Fire						
03/08/2022	Addington Court					



#### 6. Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

(please insert x below)

LOW

MEDIUM

HIGH

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

(please insert x below)

MAJOR X



CRITICAL

The definition of the above terms is as follows:

FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant				
	(other than the occupant sleeping in a bedroom in which a fire occurs).				
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely				
	to lead to fatalities.				
CRITICAL	There is significant potential for serious injury or death of one or more occupants.				

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trivial	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

	Action Plan - Fire							
Addington Court			03/08/2022					
TOLERABLE								
Potential area of fire risk  Observation/Comments / Actions Required		Risk Rating	Completion Date	Referred To:	Task ID No.			
Fire Hazards Is it considered that the compartmentation is of a reasonable standard?	Note: There is Panel missing in the commual area Ceiling tasked to be replaced. Block 7-17	Med	01/11/22	Fire Safety Manager	1557995			
Loft hatches fire resisting?	Note: Loft Hatches to be replaced in each Block to Fire Resisting.	Med	01/11/22	Fire Safety Manager	1557992 1557993 1558000 1558001			

Action Plan - Fire Page 19 of 20

Action Plan - Residents Front Doors						
Addington Court			03/08/2022			
Flat No.	Asset No.	Observation/Comments / Actions Required		<b>Completion</b> Date	Referred To:	Task ID No.
		RESIDENT FIRE DOOR INSPECTION IS SATISFACTORY AND NO ACTIONS REQUIRED ON THIS SCHEME. MANY DOORS NOT ACCESSED BUT THOSE ACCESSED MEET THE INSPECTION REGIME OF FD30 DOORS.	-			