

This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 35116 1 - 6, 31 Morinsbury Road, Graze Hill Block 1 - 6, Ravensden

Cover Sheet

Photo



Date of Fire Risk Assessment Date of Next Fire Risk Assessment FRA Frequency (Months) Purpose of Fire Risk Assessment Type of Fire Risk Assessment Fire & Safety Assessor 28 Mar 2024 28 Mar 2025 12 New Build (Initial Assessment) Type 3 (Common Parts and Flats - Non Destructive) Lynn.betteridge@accentgroup.org

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name	Graze Hill
Scheme Address	1 - 6, 31 Morinsbury Road, Graze Hill Block 1 - 6, Ravensden
Postcode	MK44 2FL
Region	East
Scheme Manager	
Scheme Tel. No	
Scheme Inspection Completed	Yes
Enforcing Fire Authority	Bedfordshire fire and Rescue service.
Other staff in attendance	Development team
Number of on-site Accent staff	None
Number of other (non-Accent) staff	Contract Cleaners in common areas

The Building

Accommodation Type	General Needs (S30)
Build Date	Jan 1 2024
Number Of Homes	6
Homes breakdown	Flat
External wall construction	
External wall finish	
Roof construction	
Roof covering	
PEEPs in place where necessary	Yes
Current Evacuation Strategy	Stay Put (Delayed) Evacuation
Conversion or purpose-built	Purpose Built
Number of storeys	3
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
Number of internal Staircases (protected or unprotected?)	1
Number of External Staircases	None
External Balcony part of escape route?	N/A
Unusual features	None
Building Access Conditions for Fire Brigade	Vehicular Access to one or more elevations

Asset ID: 35116 1 - 6, 31 Morinsbury Road, Graze Hill Block 1 - 6, Ravensden

Fire Detection and Warning System	Flats and common areas not linked
Grade of fire alarm	Grade D
Category of fire alarm	LD3 Minimum Protection
Emergency Lighting Provision	Maintained system - Common areas
Portable Fire Extinguishers supplied/fitted	No
Fixed Fire Fighting Installations	No

Customers

Number of occupants	12
Occupant tenure type breakdown	General Needs

Fire Safety Related Customer Safety Servicing

Overdue communal gas safety checks	0
Overdue domestic gas safety checks	0
Overdue communal electrical condition checks	0
Overdue domestic electrical condition checks	0
Overdue alarm call pull chord tests	0
Overdue communal PAT testing	0
Overdue customer mobility scooter PAT testing	0
Overdue Monthly Emergency Lighting Switch Tests	
Overdue Annual Emergency Lighting tests	
Overdue Weekly Fire Alarm Testing	0
Overdue Fire Panel - Six Monthly Testing	
Overdue Fire Safety Equipment tests	

Building Fire Safety Surveys - Communal Doors

Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	0

Dwelling Doors

Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo

Date of Fire Risk Assessment	28/03/2024
FRA Frequency (Months)	12
Purpose of Fire Risk Assessment	New Build (Initial Assessment)
Type of Risk Assessment	Type 3 (Common Parts and Flats - Non Destructive)
Quantity	1
Fire & Safety Assessor	Lynn.betteridge@accentgroup.org
Enforcing Fire Authority	Bedfordshire fire and Rescue service.
Scheme Tel. No	
Other staff in attendance	Development team
Number of on-site Accent staff	None
Number of other (non-Accent) staff	Contract Cleaners in common areas
Scheme Inspection completed	Yes
Number of occupants	12
Personal Emergency Evacuation Plans in place	Yes
Current Evacuation Strategy	Stay Put (Delayed) Evacuation
Conversion or purpose-built	Purpose Built
Number of Storeys	3
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
No. of internal staircases (protected/unprotected)	1
Number of external staircases	None
External balcony part of escape route?	N/A
Unusual features	None

P

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade	Vehicular Access to one or more elevations	
Surroundings: Residential/Commercial	Residential	
Fire Detection and Warning System	Flats and common areas not linked	
Grade of Fire Alarm	Grade D	
Category of Fire Alarm	LD3 Minimum Protection	
Emergency Lighting Provision	Maintained system - Common areas	
Portable Fire Extinguishers / Fire Blankets supplied / fitted	No	
Water Extinguisher(s) present	No	
Foam Extinguisher(s) present	No	
Dry Powder Extinguisher(s) present	No	
Carbon Dioxide Extinguisher(s) present	No	
Fire Blanket(s) present	No	
Fixed Fire Fighting Installations supplied / fitted	No	
Dry Riser(s) present	No	
Wet Riser(s) present	No	
Sprinkler System present	No	
Hosereel(s) present	No	
Automatic Opening Vent(s) present	Yes	

Electrical Sources of Ignition

Electrical installation within common areas in good condit obvious damage?	ion and no	Yes
Comment		New build all secure.
Valid Electrical Installation Condition Reports held on file Areas & General Needs Flats)	? (Common	Yes
Comment		Details as above new build all certificates have been uploaded to active H and M files.
Electrical App/PA Testing - tested within past 12 months?		N/A
Comment		
Absence of trailing leads and adapters?		N/A
Comment		
Evidence that mobility scooters are not being stored/char common areas?	ged in	N/A
Comment		
Is there a purpose built mobility scooter store/charging ar	ea?	N/A
MIS-AMS ActiveH - Fire Risk Assessment Report	Page 5 of 12	Generated 02/04/2024 16:02:50

Asset ID: 35116 1 - 6, 31 Morinsbury Road, Graze Hill Block 1 - 6, Ravensden		
Comment		
Does the building have a lightning protection system?	No	
Comment		
Gas installations		
Is there a commercial/domestic gas supply to the scheme?	No	
Comment	Heat Source Pumps located internally and externally includes all associated equipment.	
Other Sources of Ignition		
Is there a no smoking policy in place, which is enforced and adhered	Yes	

to? Comment Adequate security against arson? Comment Are refuse/recycling bin areas managed and suitably located? Comment Are there communal cooking facilities at this scheme? No

Are there communal cooking facilities at this scheme?

Comment

Housekeeping

Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items?	Yes
Comment	Secured by FB2 key.
Are unnecessary accumulations of combustible materials or waste avoided?	Yes
Comment	New build.
Are combustible materials and substances separated from ignition sources and stored appropriately?	N/A
Comment	
Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations?	N/A
Comment	

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Comment

Yes

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of escape in case of fire?	Yes
Comment	This new build scheme has 2 directions of travel at ground floor level to exit to safe air.
Escape routes unobstructed and safe to use?	Yes
Comment	
Exits immediately openable without a key and/or failsafe's function correctly? Comment	Yes
	Yes
Reasonable distances of travel where there is a single/alternative direction of travel? Comment	165
	Vec
Escape routes lead to final exits and open in direction of escape where necessary?	Yes
Comment	Both exit to safe air.
Fire Spread and Development	
Is it considered that the compartmentation is of a reasonable standard?	Yes
Comment	The compartmentation meets approved code of practice Doc B1.
Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?	Yes
Comment	No lateral fire spread due to materials used in communal areas. Fire stopping certification carried out by East Anglia Fire protection dated 13/2/24.
Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products? Comment	N/A
As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?	Yes
Comment	Roof inspection via fire resisting loft hatch compartmentation meets approved code of practice Doc B32.8.
Loft hatches fire resisting?	Yes
Comment	Located top floor communal staircase.
As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?	N/A
Comment	
Do external walls, doors, windows and anything attached to the exterior, limit fire spread?	Yes

Asset ID: 35116 1 - 6, 31 Morinsbury Road, Graze Hill B	Block 1 - 6, Ravensden
Comment	The external walls doors and windows will not propagate fire spread around the envelope of the building.
If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?	Yes
Comment	On the day of inspection the block AOV was found to fuction correctly on activation of the smoke detectors. Certification from Central Fire security installations dated 18/3/24.
Are roller shutter doors that are required to be FR, fire resisting and self-closing?	N/A
Comment	
Emergency Escape Lighting	
Is the emergency lighting correctly specified and installed as per current standards?	Yes
Comment	New build all certificates have been uploaded to active H and M files contractor Tunstalls. Installed by NME Electrical Ltd.
Emergency lighting units in good condition and securely fixed to walls/ceilings?	Yes
Comment	
Records of monthly/annual testing available?	Yes
Comment	New build all certificates have been uploaded to active H and M files and dated the annual/monthly testing by contractor Tunstalls.
Fire Safety Signs and Notices	
Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas? Comment	Yes
Directional fire escape signage in place and adequate?	Yes

Comment

Is there suitable LIFT signage i.e. do not use in case of fire?

Comment

Do common area fire doors display the correct signage on both sides where applicable?

Comment

Means of giving Warning in case of Fire

No Is the scheme fitted with a communal area fire alarm?

N/A

N/A

Comment

Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations	No
provided at this scheme?	
Comment	

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under the Building Safety Act?	Yes		
Comment			
Will this FRA be shared will all Accountable Persons for the premises?	Yes		
Comment			
How will this sharing be achieved?	Communication with all parties within the Accent Housing Association and the residents.		
Are there other Responsible Persons who share or have fire safety duties in respect of the premises?	Yes		
Have all details required by regulations been shared with all other Responsible Persons?	Yes		
Comment	Regulation 38 All the relevant information has been passed to all that are responsible person's for the building to manage its safety.		
Have all details required by regulations to be shared with us from other Responsible Persons been received and recorded?	Yes		
Comment			
Will this FRA be shared will all other Responsible Persons for the premises?	Yes		
Comment	The FRA will be held on active H if residents or any other person's wish to look at the FRA the details will be shared and communicated on request.		
How will this sharing be achieved?	Communication		
Is an office or IL scheme being inspected?	No		
Comment			
Passenger Lift			
Is the scheme fitted with a passenger lift?	No		

Comment

Premises Inspection Box

Asset ID: 35116 1 - 6, 31 Morinsbury Road, Graze Hill Block 1 - 6, Ravensden			
Is there a premises information box for fire & rescu	ue service use?	No	
Comment			
Evacuation Policy			
Are there suitable arrangements for summoning the	ne fire service?	Yes	
Comment		Residents are responsible for contacting the fire and rescue service in the event of a fire.	
Taking FRA findings, is the evacuation policy appr scheme as per latest guidance?	opriate for the	Yes	
Comment			
Engagement with Residents			
Has information of fire procedures been dissemination	ated to residents?	Yes	
Comment		Fire routine notices are located in the communal area with advice on the stay put policy on the scheme.	
Is general fire safety information disseminated to r	residents?	Yes	
Comment		When residents move into the flats they are given fire safety advice and also leaflets and a link into the website to look at the FRA the details will be shared and communicated on request.	
FRA Frequency			
Taking the findings of this assessment into accoun the FRA correct? Comment	it, is the frequency of	Yes	
Comment			
Miscellaneous			
Are there any other observations/actions to raise t above.	hat are not covered	No	
Are there fire related remedial works required at the affect the fabric of the building? Comment	is property, that will	No	
Were there any unsatisfactory aspects of the Fire (Visible on Building Safety Report).	Risk Assessment?	Νο	

Asset ID: 35116 1 - 6, 31 Morinsbury Road, Graze Hill Block 1 - 6, Ravensden

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW	X	MEDIUM	НІСН	
-----	---	--------	------	--

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR MAJOR X CRITICAL	
------------------------	--

The definition of the above terms is as follows: *FRA Review Frequency*

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	intolerable

When the level of risk is established, the action level can be read from the table below:

Asset ID: 35116

1 - 6, 31 Morinsbury Road, Graze Hill Block 1 - 6, Ravensden

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial	