Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 41 Rayner Court Ilkeston Road, Nottingham

Cover Sheet

Photo



Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

13 Nov 2023

16 Nov 2023

36

3 year Re-Assessment

Type 3 (Common Parts and Flats - Non Destructive)

Lynn.betteridge@accentgroup.org

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name Rayner Court

Scheme Address Rayner Court Ilkeston Road, Nottingham

Postcode NG7 3GA

Region

Scheme Manager

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority Nottinghamshire Fire and rescue.

Other staff in attendance None

Number of on-site Accent staff

None

Number of other (non-Accent) staff

Contract Cleaners in common areas

The Building

Accommodation Type General Needs (S30)

Build Date Jan 1 1981

Number Of Homes 15

Homes breakdown Flat

External wall construction Facing Brick

External wall finish Facing Brick

Roof construction Timber

Roof covering Slate Pitched

PEEPs in place where necessary Yes

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

Number of External Staircases None

External Balcony part of escape route? N/A

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

Rayner Court Ilkeston Road, Nottingham Asset ID: 41 Flats only Fire Detection and Warning System Grade D Grade of fire alarm Category of fire alarm LD3 Minimum Protection **Emergency Lighting Provision** Non Maintained System - Common Areas Portable Fire Extinguishers supplied/fitted No Fixed Fire Fighting Installations No **Customers** 12 Number of occupants **General Needs** Occupant tenure type breakdown Fire Safety Related Customer Safety Servicing Overdue communal gas safety checks 0 0 Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 Overdue communal PAT testing 0 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests 2 2 Overdue Annual Emergency Lighting tests 0 Overdue Weekly Fire Alarm Testing Overdue Fire Panel - Six Monthly Testing Overdue Fire Safety Equipment tests **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors Communal Fire doors due for replacement within 5 years 0 **Dwelling Doors** 0 Failing Dwelling Fire Doors

Dwelling Fire doors due for replacement within 5 years

0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



Date of Fire Risk Assessment 13/11/2023

FRA Frequency (Months) 36

Purpose of Fire Risk Assessment 3 year Re-Assessment

Type of Risk Assessment

Type 3 (Common Parts and Flats - Non Destructive)

Quantity

Fire & Safety Assessor Lynn.betteridge@accentgroup.org

Enforcing Fire Authority Nottinghamshire Fire and rescue.

Scheme Tel. No

Other staff in attendance None

Number of on-site Accent staff None

Number of other (non-Accent) staff

Contract Cleaners in common areas

Scheme Inspection completed Yes

Number of occupants 12

Personal Emergency Evacuation Plans in place
Yes

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of Storeys

Number of floors on which car parking is provided 0

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

Number of external staircases None

External balcony part of escape route? N/A

Unusual features None

2

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Residential

Fire Detection and Warning System Flats only

Grade of Fire Alarm Grade D

Category of Fire Alarm LD3 Minimum Protection

Emergency Lighting Provision Non Maintained System - Common Areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted No

Water Extinguisher(s) present No

Foam Extinguisher(s) present No

Dry Powder Extinguisher(s) present

Carbon Dioxide Extinguisher(s) present No

Fire Blanket(s) present

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present No

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no

obvious damage?

Comment No damage to the electrical equipment at the time of

inspection.

Yes

Yes

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment Details of testing recorded on Active "H" and M

Files. Dated 23/1/2019, retesting due 2024.

Electrical App/PA Testing - tested within past 12 months?

N/A

Comment

Absence of trailing leads and adapters? Yes

Comment

Evidence that mobility scooters are not being stored/charged in N/A

common areas?

Comment

Asset ID: 41	Rayner Court Ilkeston Road, Nottingham	ı
Is there a purpose built mobil	lity scooter store/charging area?	N/A
Comment		
Does the building have a ligh	ntning protection system?	No
Comment		
Gas installations		
Is there a commercial/domes	stic gas supply to the scheme?	Yes
Comment		
Valid LGSR held on file for fix (Boilers) Comment	xed communal area gas appliances?	N/A
Valid LGSR held on file for reappliances?	esidential flats that contains gas	Yes
Comment		The gas safety tests are uploaded to Active "H" and M files recorded. Sample flat for this scheme Flat 4 Asset 2331 tests completed on all detectors 20/92023.
Are smoke/heat detectors wire annual inspection and the res	thin General Needs flats subject to an sults	Yes
Comment		All tested as above and uploaded to systems.
Other Sources of Ign	ition	
Is there a no smoking policy to? Comment	in place, which is enforced and adhered	Yes
Adequate security against ar	son?	Yes
Comment		On the day of inspection the block was found to be secure and intact.
Are refuse/recycling bin area	s managed and suitably located?	Yes
Comment		To the rear of the scheme.
Are there communal cooking	facilities at this scheme?	No
Comment		
Housekeeping		
	ce cupboards secure and free from general d and residents personal items?	Yes
Are unnecessary accumulation avoided?	ons of combustible materials or waste	Yes

Page 6 of 13

Generated 13/11/2023 16:03:25

MIS-AMS ActiveH - Fire Risk Assessment Report

Rayner Court Ilkeston Road, Nottingham Asset ID: 41

Comment Clear single staircase.

Are combustible materials and substances separated from ignition sources and stored appropriately?

Furniture/furnishings in good condition, fire retardant/resistant and

comply with modern standards and regulations?

Comment

Comment

Yes

N/A

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Comment

Yes

Yes

Yes

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of escape in case of fire?

Comment

first floor level.

Escape routes unobstructed and safe to use?

Comment

The relative simplicity of the building means the escape route can be easily identified from each flat.

A single communal staircase with final exit only from

Yes

Exits immediately openable without a key and/or failsafe's function correctly?

Comment

Reasonable distances of travel where there is a single/alternative

direction of travel?

Comment

Yes

Escape routes lead to final exits and open in direction of escape where necessary?

Comment

Yes

Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment

Comment

Yes

Yes

approved code B3.

Is there reasonable limitation of surface finishes that might promote fire

spread (walls, floors, ceilings)?

All finishes will not enable fire spread.

Compartmentation on both levels is of reasonable standard. At each level compartmentation meets the

Are fire dampers/shutters provided in ducts/refuse chutes to protect

means of escape against fire, smoke and combustion products?

N/A

Asset ID: 41 Rayner Court Ilkeston Road, Nottinghan	n
Comment	
As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard? Comment	Yes
Loft hatches fire resisting?	N/A
Comment	
As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?	N/A
Comment	
Do external walls, doors, windows and anything attached to the exterior, limit fire spread?	Yes
Comment	The external walls doors and windows will not propagate fire spread around the envelope of the building.
If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?	N/A
Comment	
Are roller shutter doors that are required to be FR, fire resisting and self-closing? Comment	N/A
Emergency Escape Lighting	
Is the emergency lighting correctly specified and installed as per current standards?	Yes
Comment	A non maintained system and the fire strategy ie Emergency lighting is installed to BS5266.
Emergency lighting units in good condition and securely fixed to walls/ceilings?	Yes
Comment	System tested by contractor Tunstalls.
Records of monthly/annual testing available?	Yes
Comment	All records are available on Active "H" and M files. Tunstalls carry out the monthly reports and also annual drop test was completed on the 11/8/2023 and 31/10/2023.
Fire Safety Signs and Notices	
Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas? Comment	Yes
Directional fire escape signage in place and adequate?	N/A

Rayner Court Ilkeston Road, Nottingham Asset ID: 41

Comment The simplicity of the means of escape it is

considered that fire signage is not required on this

scheme.

Is there suitable LIFT signage i.e. do not use in case of fire?

Comment

Do common area fire doors display the correct signage on both sides

where applicable?

Comment

N/A

N/A

Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?

Comment

No

Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme?

Comment

No

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under the Building Safety Act?

Comment

No

Are there other Responsible Persons who share or have fire safety duties in respect of the premises?

Have all details required by regulations been shared with all other Responsible Persons?

Comment

Yes

Yes

Under regulation 38 of the Building regulations the responsible has all the information to enable to

manage the building safely.

Have all details required by regulations to be shared with us from other

Responsible Persons been received and recorded?

Comment

Yes

Yes

Will this FRA be shared will all other Responsible Persons for the

premises? Comment

How will this sharing be achieved?

To meet Regulation 38.

The FRA for the building will be held on active H if residents or any other person's wish to look at the FRA the details will be shared and communicated

on request.

No

Is an office or IL scheme being inspected?

Comment

Rayner Court Ilkeston Road, Nottingham Asset ID: 41 Passenger Lift Is the scheme fitted with a passenger lift? No Comment **Premises Inspection Box** Is there a premises information box for fire & rescue service use? No Comment **Evacuation Policy** Are there suitable arrangements for summoning the fire service? Yes Comment Residents call the fire and rescue service in the event of a fire. Yes Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance? Comment **Engagement with Residents** Yes Has information of fire procedures been disseminated to residents? Comment When the residents take ownership of their flat they're given fire safety advice and also leaflets and a link into the website to look at the FRA the details will be shared and communicated on request. Is general fire safety information disseminated to residents? Comment Fire routine notices are located in the communal area with advice on the stay put policy. Fire safety campaigns are also published on the website. FRA Frequency Yes Taking the findings of this assessment into account, is the frequency of the FRA correct? Comment Miscellaneous No Are there any other observations/actions to raise that are not covered above.

affect the fabric of the building?

Are there fire related remedial works required at this property, that will

No

Comment

Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).

On the last FRA works was required to remove varnished wooden overhead panel in the comunal stairwell. The remedial works was completed with the addition of zero rated paint finish. on this FRA it was noted works completed.

No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

systems.				
_		evention measures observention measures observention the fire (t		
LOW	X	MEDIUM	нідн	
any procedural	arrangements ob	of the building, the occup served at the time of the a e event of a fire would be:	ssessment, it is consider	
MINOR		MAJOR X	CRITICAL	

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial
	<u> </u>