Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 51 Westhay Court Radford Bridge Road, Nottingham

Cover Sheet

Photo



Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

30 Apr 2024

28 Apr 2024

12

Annual Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Lynn.betteridge@accentgroup.org

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name Westhay Court

Scheme Address Westhay Court Radford Bridge Road, Nottingham

Postcode NG8 1NQ

Region East

Scheme Manager Kemi Enigbokan, Sue Broddel

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority Nottinghamshire Fire and Rescue Service.

Other staff in attendance Scheme manager

Number of on-site Accent staff Scheme Manager Weekdays

Number of other (non-Accent) staff

Contract Cleaners in common areas

The Building

Accommodation Type CAT2 Housing for Older People (S28), Supported

Housing (S50)

Build Date Jan 1 1990

Number Of Homes 56

Homes breakdown Flat, House, Bungalow

External wall construction Facing Brick

External wall finish Facing Brick

Roof construction Timber

Roof covering Interlocking Pitched

PEEPs in place where necessary

Yes

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys 2

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

12

Number of External Staircases None

External Balcony part of escape route? N/A

Unusual features

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

Westhay Court Radford Bridge Road, Nottingham Asset ID: 51 Flats and common areas linked Fire Detection and Warning System Grade of fire alarm Grade A Category of fire alarm **LD1 Maximum Protection** Non Maintained System - Common Areas **Emergency Lighting Provision** Portable Fire Extinguishers supplied/fitted Yes Fixed Fire Fighting Installations No **Customers** 60 Number of occupants General Needs, CAT2 Housing for Older People Occupant tenure type breakdown Fire Safety Related Customer Safety Servicing Overdue communal gas safety checks 0 0 Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 Overdue communal PAT testing 0 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests 1 Overdue Annual Emergency Lighting tests 1 2 Overdue Weekly Fire Alarm Testing Overdue Fire Panel - Six Monthly Testing 1 Overdue Fire Safety Equipment tests 1 **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors Communal Fire doors due for replacement within 5 years 0 **Dwelling Doors**

Dwelling Fire doors due for replacement within 5 years

Failing Dwelling Fire Doors

0

0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



Date of Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Risk Assessment

Quantity

Fire & Safety Assessor

Enforcing Fire Authority

Scheme Tel. No

Other staff in attendance

Number of on-site Accent staff

Number of other (non-Accent) staff

Scheme Inspection completed

Number of occupants

Personal Emergency Evacuation Plans in place

Current Evacuation Strategy

Conversion or purpose-built

Number of Storeys

Number of floors on which car parking is provided

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

Number of external staircases

External balcony part of escape route?

Unusual features

28/04/2023

12

Annual Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

1

Lynn.betteridge@accentgroup.org

Nottinghamshire Fire and Rescue Service.

Scheme manager

Scheme Manager Weekdays

Contract Cleaners in common areas

Yes

60

Yes

Stay Put (Delayed) Evacuation

Purpose Built

2

0

No

12 None

N/A

Ollusual leatures

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Mixed

Fire Detection and Warning System Flats and common areas linked

Grade of Fire Alarm Grade A

Category of Fire Alarm LD1 Maximum Protection

Emergency Lighting Provision Non Maintained System - Common Areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted Yes

Water Extinguisher(s) present Yes

Foam Extinguisher(s) present No

Dry Powder Extinguisher(s) present

Carbon Dioxide Extinguisher(s) present No

Fire Blanket(s) present Yes

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no

obvious damage?

Comment

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment The electrical condition report was carried out on the

fourth of March 2022.

Yes

Yes

Yes

Electrical App/PA Testing - tested within past 12 months? Yes

Comment Tested and recorded on Active H dated 24/4/2024.

Absence of trailing leads and adapters? Yes

Comment

Evidence that mobility scooters are not being stored/charged in

common areas?

Comment

Is there a purpose built mobility scooter store/charging area?

Yes

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 5 of 15

Comment The 2 mobility scooters charging units PAT tested, a

fridge freezer was found inthe store the specialist housing manager informed and pointed out fire safety concerns and freezer requires removal within

7 days noted on this report and fire RIsk

assessment.

No

Does the building have a lightning protection system?

Comment

Gas installations

Is there a commercial/domestic gas supply to the scheme? Yes

Commercial heating system

Valid LGSR held on file for fixed communal area gas appliances?

Yes

(Boilers)

Comment Commercial heating system tested 3/11/2023 and

uploaded to Active H and M files.

Valid LGSR held on file for residential flats that contains gas

appliances?

Comment Sample flat No20 asset 2611 Gas safety inspection

dated 14/6/2023 and uploaded to Active H and M

files

Are smoke/heat detectors within General Needs flats subject to an

annual inspection and the results

Comment Residents are expected to carry out a monthly

detector tests also each flat contains Warden call.

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered Yes

to?

Comment No smoking permitted in the communal area only

residents flats.

Adequate security against arson?

Comment CCTV on the scheme monitor in scheme manager

office access to all areas via fob system.on day of

inspection building secure.

Are refuse/recycling bin areas managed and suitably located? Yes

Comment

Are there communal cooking facilities at this scheme?

Yes

Comment

Are reasonable measures taken to prevent fires as a result of cooking?

Comment A fire blanket is located in the kitchen area.

Where there is extraction in communal kitchens, are filters and

ductwork changed/cleaned regularly?

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 6 of 15

Comment

Housekeeping

Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items?

Comment

avoided?

Are unnecessary accumulations of combustible materials or waste

None found at time of inspection. Comment

Are combustible materials and substances separated from ignition

sources and stored appropriately?

Comment Cleaners cupboard found secure at time of

inspection.

Yes

Yes

Yes

Yes

Furniture/furnishings in good condition, fire retardant/resistant and

comply with modern standards and regulations?

Comment Labels inspected in all lounge areas.

Other Significant Fire Hazards

Yes Are all other significant fire hazards adequately controlled?

No other hazards found attime of inspection. Comment

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of escape in case of fire?

travel to safe air.

Yes

Yes

Yes

Yes

Yes

Escape routes unobstructed and safe to use?

Comment At the time of inspection there was no comunal

areas preventing MOE.

Exits immediately openable without a key and/or failsafe's function

correctly?

Comment

Comment Generally all final exits are pushbar and there are

several checked for functionality at the time of

All exit signs in place and more than one direction of

inspection.

Reasonable distances of travel where there is a single/alternative

direction of travel?

Escape routes lead to final exits and open in direction of escape where

necessary?

Comment

Comment The escape routes meets code of practice Doc B1

MOE legislation.

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 7 of 15

Observation **Priority** Referred To Required By: Task ID

The scheme has had new fire doors fitted to fd30 specification from 11-54 doors fitted mid March 2024.



No Action **Project Manager** (Building Safety)



Observation **Priority** Referred To Required By: Task ID

Not all of the communal doors have been replaced but flat doors have.



Internal - Medium **Project Manager** (Building Safety)



Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard? Yes

this scheme with installation of FB70 Envirograf curtain Barriers in loft space areas and New fire doors throughout.all works carried out in 2020 just prior to covid.

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?

Comment

Comment

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?

Comment

Comment

As far as can be reasonably ascertained, is the compartmentation

within roof spaces of a satisfactory standard?

Loft hatches fire resisting?

Comment

A major compartmentation project was completed at

Yes

N/A

Yes

See note above 8.1.100.

Yes

There are over 34 fire resisting loft hatches.

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?

Yes

Comment

Do external walls, doors, windows and anything attached to the

exterior, limit fire spread?

Comment

If Smoke Control Systems (AOV's) are fitted, are the records of annual

testing available? Comment

Are roller shutter doors that are required to be FR, fire resisting and

self-closing?

Comment

Yes

The external walls doors and windows will not propagate fire spread around the envelope of the

building.

N/A

A AOV was decommissioned 2019 as not required.

Yes

Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per

current standards?

Comment

Comment

Comment

Emergency lighting units in good condition and securely fixed to

walls/ceilings?

Records of monthly/annual testing available?

Yes

Yes

All secure at time of inspection.

Yes

The Emergency lighting system at this scheme has been tested monthly on 4/3/2024 and the annual drop test was completed on the 22/9/2023. All uploaded to active H and M files.

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent

locations within the common areas?

Directional fire escape signage in place and adequate?

Is there suitable LIFT signage i.e. do not use in case of fire?

Comment

Comment

Comment

Do common area fire doors display the correct signage on both sides

where applicable?

Comment

Yes

Signage inspection on the day of inspection found to

be suitable and sufficient to aid residents.

All checked on the day of inspection all denote

MOE.

N/A

Yes

All scheme doors replaced on compartmentation

works and signage affixed.

Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm? Yes Comment Yes Is fire detection and warning system appropriate for occupancy and fire risk, as per BS 5839-1:2017? Comment Yes Is the fire detection and warning system maintained/tested and all certificates saved on file? Comment The fire panel and system tested by the electrical contractor Tunstalls bi annually last test date8/3/2024 all certificates have been uploaded to active H and M files. Yes Fire alarm components in good condition and securely fixed to walls/ceilings? Comment All secure at time of inspection. Yes Hold open devices operate at the sounding of the alarm and are in a serviceable condition? Comment Doors tested for functionality and closure. Yes Are there heat detectors located in the Kitchen, Boiler, Plant Room and Laundry? Comment Yes Is the fire alarm panel remotely monitored, and if so are there records of regular testing? Comment The fire alarm system is monitored by a collecting station Astraline who cover Warden call all testing recorded and uploaded to Active H and M files. Fire Extinguishing Equipment Yes Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme? Comment Portable fire extinguishers - appropriate type/number/position? Yes Comment Yes Correct signage displayed by each fire extinguisher? Comment Yes Fire blanket in communal kitchen, secured to the wall, complete with signage? Comment N/A Dry risers - Inlet/outlet boxes secured and/or securing straps fitted to

outlet valves? Comment

Records available of fire fighting equipment servicing within past 12

months?

Comment Firefighting equipment tested by Morgan Fire dated

Yes

Yes

Yes

Yes

Yes

Yes

Yes

N/A

N/A

N/A

11/7/2023. All uploaded to active H and M files.

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under

the Building Safety Act?

Comment

Will this FRA be shared will all Accountable Persons for the premises?

Comment

How will this sharing be achieved? Communication with all parties within the Accent

Housing Association and the residents.

Are there other Responsible Persons who share or have fire safety

duties in respect of the premises?

Have all details required by regulations been shared with all other

Responsible Persons?

Fire Authority carry out fire Audits. Comment

Have all details required by regulations to be shared with us from other

Responsible Persons been received and recorded?

Comment All recorded on active H and M files.

Will this FRA be shared will all other Responsible Persons for the

premises?

Comment The FRA will be held on active H if residents or any

> other person's wish to look at the FRA the details will be shared and communicated on request. Communication with all responsible stakeholders.

Is an office or IL scheme being inspected? Yes

Comment

IL Schemes & Regional Offices - Are there sufficient numbers of Yes

qualified Fire wardens?

How will this sharing be achieved?

Comment E learning training given annually.

Offices - Are there suitable arrangements for ensuring the premises are

evacuated? Comment

Offices - Are there suitable arrangements for evacuating disabled

people? Comment

Offices - Suitable arrangements for meeting the fire service on arrival

and proving relevant information?

Comment

Yes Offices/IL Schemes - Is there a suitable assembly point?

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 11 of 15

Westhay Court Radford Bridge Road, Nottingham Asset ID: 51 Comment N/A Offices - Are fire drills carried out at appropriate intervals? Comment Ils scheme not an office. Passenger Lift Is the scheme fitted with a passenger lift? No Comment **Premises Inspection Box** Is there a premises information box for fire & rescue service use? No Comment The PEEPS information is held in a key safe which can be opened by Astraline remotely in the event of a fire and evacuation. **Evacuation Policy** Are there suitable arrangements for summoning the fire service? Yes Comment Suitable instruction is given to the residence of the scheme in the event of a fire to call 999 the residents have the ability to use their warden call system Yes Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance? Comment **Engagement with Residents** Has information of fire procedures been disseminated to residents? Comment When residents move into the flats they are given fire safety advice and also leaflets and a link into the website to look at the FRA the details will be shared and communicated on request to afire safety assessor. Is general fire safety information disseminated to residents? Yes Comment A fire routine notices is located in communal areas which reminds residents of fire procedures and evacuation policy.icy for there specific building. FRA Frequency Yes Taking the findings of this assessment into account, is the frequency of

the FRA correct?

Comment

Miscellaneous

Are there any other observations/actions to raise that are not covered above.

Are there fire related remedial works required at this property, that will affect the fabric of the building?

Comment

Were there any unsatisfactory aspects of the Fire Risk Assessment?

No (Visible on Building Safety Report).

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW MEDIUM HIGH

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

IINOR MAJOR	X	CRITICAL	
-------------	---	----------	--

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).	
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.	
CRITICAL	There is significant potential for serious injury or death of one or more occupants.	

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales	
Trivial	No action is required	
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.	
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.	
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.	

The Overall Risk Level for this asset is:	Trivial
	<u> </u>