Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 9433 1-41 Ramsey Park Block 1-41 Ramsey Park, Barrow-in-Furness

Cover Sheet

Photo



Date of Fire Risk Assessment Date of Next Fire Risk Assessment FRA Frequency (Months) Purpose of Fire Risk Assessment Type of Fire Risk Assessment Fire & Safety Assessor 09 Jan 2025 09 Jan 2026 12 Annual Re-Assessment Type 1 (Common Parts Only - Non Destructive) Ian Potter

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name	Cavendish Street
Scheme Address	1-41 Ramsey Park Block 1-41 Ramsey Park, Barrow-in-Furness
Postcode	LA14 1SY
Region	North West
Scheme Manager	
Scheme Tel. No	N/A
Scheme Inspection Completed	Yes
Enforcing Fire Authority	Cumbria FRS
Other staff in attendance	Kayleigh Irving- Scheme Manager
Number of on-site Accent staff	Scheme Manager Weekdays
Number of other (non-Accent) staff	Contract Cleaners in common areas

The Building

Accommodation Type	CAT2 Housing for Older People (S28)
Build Date	Jan 1 1986
Number Of Homes	41
Homes breakdown	Flat
External wall construction	Facing Brick
External wall finish	Facing Brick
Roof construction	Timber
Roof covering	Interlocking Pitched
PEEPs in place where necessary	Yes
Current Evacuation Strategy	Stay Put (Delayed) Evacuation
Conversion or purpose-built	Purpose Built
Number of storeys	3
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
Number of internal Staircases (protected or unprotected?)	3 protected
Number of External Staircases	0
External Balcony part of escape route?	No
Unusual features	None
Building Access Conditions for Fire Brigade	Vehicular Access to one or more elevations

Fire Detection and Warning System	Flats and common areas not linked
Grade of fire alarm	Grade A
Category of fire alarm	LD2 Additional Protection
Emergency Lighting Provision	Maintained system - Common areas
Portable Fire Extinguishers supplied/fitted	Yes
Fixed Fire Fighting Installations	No

Customers

Number of occupants	50
Occupant tenure type breakdown	CAT2 Housing for Older People

Fire Safety Related Customer Safety Servicing

Overdue communal gas safety checks	0
Overdue domestic gas safety checks	0
Overdue communal electrical condition checks	0
Overdue domestic electrical condition checks	0
Overdue alarm call pull chord tests	0
Overdue communal PAT testing	0
Overdue customer mobility scooter PAT testing	0
Overdue Monthly Emergency Lighting Switch Tests	0
Overdue Annual Emergency Lighting tests	0
Overdue Weekly Fire Alarm Testing	1
Overdue Fire Panel - Six Monthly Testing	1
Overdue Fire Safety Equipment tests	1

Building Fire Safety Surveys - Communal Doors

Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	0

Dwelling Doors

Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



09/01/2025
12
Annual Re-Assessment
Type 1 (Common Parts Only - Non Destructive)
1
lan Potter
Cumbria FRS
N/A
Kayleigh Irving- Scheme Manager
Scheme Manager Weekdays
Contract Cleaners in common areas
Yes
50
Yes
Stay Put (Delayed) Evacuation
Purpose Built
3
0
No
3 protected
0
No
None

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade	Vehicular Access to one or more elevations
Surroundings: Residential/Commercial	Residential
Fire Detection and Warning System	Flats and common areas not linked
Grade of Fire Alarm	Grade A
Category of Fire Alarm	LD2 Additional Protection
Emergency Lighting Provision	Maintained system - Common areas
Portable Fire Extinguishers / Fire Blankets supplied / fitted	Yes
Water Extinguisher(s) present	No
Foam Extinguisher(s) present	Yes
Dry Powder Extinguisher(s) present	Yes
Carbon Dioxide Extinguisher(s) present	Yes
Fire Blanket(s) present	No
Fixed Fire Fighting Installations supplied / fitted	No
Dry Riser(s) present	No
Wet Riser(s) present	No
Sprinkler System present	No
Hosereel(s) present	No
Automatic Opening Vent(s) present	No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no obvious damage?	Yes
Comment	No damage observed at time of inspection
Valid Electrical Installation Condition Reports held on file? (Common Areas & General Needs Flats)	Yes
Comment	Completed 14th December 2020
Electrical App/PA Testing - tested within past 12 months?	Yes
Comment	Completed 5th November 24
Absence of trailing leads and adapters?	Yes
Comment	None seen at time of inspection
Evidence that mobility scooters are not being stored/charged in common areas?	Yes
Comment	None seen at time of inspection.
Is there a purpose built mobility scooter store/charging area?	Yes

Comment	At rear of premises. Unable to gain access
Does the building have a lightning protection system?	No
Comment	Not required

Gas installations

Is there a commercial/domestic gas supply to the scheme?	Yes
Comment	Gas boiers
Valid LGSR held on file for fixed communal area gas appliances? (Boilers)	Yes
Comment	Tested 23rd May 24
Valid LGSR held on file for residential flats that contains gas appliances?	N/A
Comment	No gas in flats
Are smoke/heat detectors within General Needs flats subject to an annual inspection and the results	N/A
Comment	ILS

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered to? Comment
Adequate security against arson?
Comment
Are refuse/recycling bin areas managed and suitably located?
Comment
Are there communal cooking facilities at this scheme?
Comment
Are reasonable measures taken to prevent fires as a result of cooking?
Comment
Where there is extraction in communal kitchens, are filters and ductwork changed/cleaned regularly? Comment

Housekeeping

Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items? Comment Yes

Smoking allowed in flats but not communal areas

Yes

All doors secure and CCTV coverage

Yes

All clean and tidy at time of inspection

Yes

Microwave only, no hob or oven

N/A

No means of cooking food other than microwave

Yes

Vent axia only

Yes

No flammable storage observed at time of inspection

Are unnecessary accumulations of combustible materials or avoided?	waste	No		
Comment		A number of flats have artificial flowers and oth their front doors. Wheelchairs and shopp communal stairs	er personal effects ou	utside
Are combustible materials and substances separated from ignition sources and stored appropriately?		Yes		
Comment		None seen at time of in	spection	
Furniture/furnishings in good condition, fire retardant/resistant comply with modern standards and regulations?	nt and	Yes		
Comment		Labelling checked		
Observation	Priority	Referred To	Required By:	Task ID
Flammable items found outside many flat front doors. Wheelchairs and a wheeled shopping bag found in	Internal - Me	dium		

communal staircases wooden board and zimmer framevin escape corridor Old water cooler in ground floor foyer scheme manager to arrange removal





Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Comment

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of escape in case of fire?

Comment

Escape routes unobstructed and safe to use?

Comment

Exits immediately openable without a key and/or failsafe's function correctly?

Yes

None found at time of inspection

Yes

Escape routes clear at time of inspection

Yes

All clear

No

1-41 Ramsey Park Block 1-41 Ramsey Park, Barrow-in-Furness

Comment		Break glass security bolt tub doors. Locking bolts held in which was difficult to remove	place with the ha	mmer
Reasonable distances of travel where there is a single/alternativ direction of travel?	re .	Yes		
Comment		All within acceptable limits		
Escape routes lead to final exits and open in direction of escape necessary?	where	Yes		
Comment		Checked		
Observation	Priority	Referred To	Required By:	Task ID
Final exit doors in the following locations require a break glass tube for the security bolt Near flat 5 bottom of the stairs Neat flat 9 Near flat 16 Work order 1248621	Repair - Non Emergency			





Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment

Asset ID: 9433

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?

Comment

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products? Comment

As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?

Comment

Loft hatches fire resisting?

Comment

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?

No

Some fire doors require attention to ensure they are self closing and close fitting in their frame Yes

Mainly painted plaster walls

N/A

No rubbish chutes

Yes

From what could be observed at time of inspection

Yes

N/A

Comment	No false ceilings
Do external walls, doors, windows and anything attached to the exterior, limit fire spread?	Yes
Comment	Brick construction no cladding
If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?	N/A
Comment	None fitted
Are roller shutter doors that are required to be FR, fire resisting and self-closing?	N/A
Comment	None fitted

Observation	Priority	Referred To	Required By:	Task ID
Corridor door nr flat 40. Multiple screws missing from	No Action			

hinges. Replaced at time of inspection





		 Referred To	
Fire doors in the following locations require attention to	Repair - Non		
ensure they are compliant	Emergency		
Corridor door nr flats 28/29 not self closing			
Combined intumescent strip and seal missing from			

Corridor door near Flats 10 and 11 not closing from shallow angles Work order 1248625

meter cupboard door adjacent to bin store and cleaners

cupboard





Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per current standards?

Yes

Comment	New system recently installed
Emergency lighting units in good condition and securely fixed to walls/ceilings?	Yes
Comment	No damage seen at time of inspection
Records of monthly/annual testing available?	Yes
Comment	Monthly check carried out 7th Jan 25 Annual drop test carried out 24th June 24

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?	Yes
Comment	Checked
Directional fire escape signage in place and adequate?	Yes
Comment	Checked
Is there suitable LIFT signage i.e. do not use in case of fire?	No
Comment	Missing from 1st floor. Replaced at time of inspection
Do common area fire doors display the correct signage on both sides where applicable?	Yes
Comment	Checked

Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?	Yes
Comment	
Is fire detection and warning system appropriate for occupancy and fire risk, as per BS 5839-1:2017?	Yes
Comment	Part 6 system
Is the fire detection and warning system maintained/tested and all certificates saved on file?	Yes
Comment	Tested 7th June 25 2x Faults showing on panel. Detector in flat which was faulty and being replaced Buzzer on panel isolated
Fire alarm components in good condition and securely fixed to walls/ceilings?	Yes
Comment	No damage seen at time of inspection
Hold open devices operate at the sounding of the alarm and are in a serviceable condition?	Yes
Comment	Tested weekly by Scheme manager
Are there heat detectors located in the Kitchen, Boiler, Plant Room and Laundry?	Yes

1-41 Ramsey Park Block 1-41 Ramsey Park, Barrow-in-Furness Asset ID: 9433 Checked Comment Is the fire alarm panel remotely monitored, and if so are there records of Yes regular testing? Comment Monitored by Astraline. Tested by Scheme manager weekly Observation Priority **Referred To Required By:** Task ID Repair - Non Fire alarm panel showing 2 faults Emergency loop device missing - this is being replaced by Tunstall Panel buzzer isolated - this does nit affect the operation of the alarm. Tunstall to be notified Work order 1248632

Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme?	Yes
Comment	Fire ectinguishers
Portable fire extinguishers - appropriate type/number/position?	Yes
Comment	In high risk areas
Correct signage displayed by each fire extinguisher?	Yes
Comment	Checked
Fire blanket in communal kitchen, secured to the wall, complete with signage?	N/A
Comment	Not required no cooking
Dry risers - Inlet/outlet boxes secured and/or securing straps fitted to outlet valves?	N/A
Comment	None at scheme
Records available of fire fighting equipment servicing within past 12 months?	Yes
Comment	Tested June 24

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under the Building Safety Act?

No

1-41 Ramsey Park Block 1-41 Ramsey Park, Barrow-in-Furness

Comment	Low rise
Are there other Responsible Persons who share or have fire safety duties in respect of the premises?	No
How will this sharing be achieved?	
Is an office or IL scheme being inspected?	Yes
Comment	ILS
IL Schemes & Regional Offices - Are there sufficient numbers of qualified Fire wardens?	N/A
Comment	Not required staff not in attendance 24/7
Offices - Are there suitable arrangements for ensuring the premises are evacuated?	N/A
Comment	ILS
Offices - Are there suitable arrangements for evacuating disabled people?	N/A
Comment	ILS
Offices - Suitable arrangements for meeting the fire service on arrival and proving relevant information?	N/A
Comment	ILS
Offices/IL Schemes - Is there a suitable assembly point?	Yes
Comment	Front car park
Offices - Are fire drills carried out at appropriate intervals?	N/A
Comment	ILS

Passenger Lift

Asset ID: 9433

Is the scheme fitted with a passenger lift?	Yes
Comment	one only
Is the lift in full working order at the time of the FRA?	Yes
Comment	Observed in use
Is the lift fitted with a firefighters switch?	Yes
Comment	In lift control room
Servicing and insurance inspection - Evidence of regular servicing/maintenance?	Yes
Comment	Last service 5th Dec 24

Observation	Priority	Referred To	Required By:	Task ID
Lift sign missing from 1st floor. Replaced at time of inspection.				
	Ē			

Premises Inspection Box

Is there a premises	information	box for fire &	rescue service use?

Comment

Evacuation Policy

Are there suitable arrangements for summoning the fire service?

Comment

Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance? Comment

Engagement with Residents

Has information of fire procedures been disseminated to residents?

Comment

Is general fire safety information disseminated to residents?

Comment

FRA Frequency

Taking the findings of this assessment into account, is the frequency of the FRA correct? Comment

Miscellaneous

Yes Warden call and 999 Yes Stay put

Yes

No

Annual letter, website and on taking up the lease

Master key and emergency Information contained with wall safe accessible through warden call

Yes

Yes annual letter, website and taking up the lease

Yes

Annual

Are there any other observations/actions to raise that are not covered above.	No
Are there fire related remedial works required at this property, that will affect the fabric of the building?	No
Comment	
Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).	Yes
Some fire doors did not fully close so works orders have been raised with our contractors.	Yes
Some minor works were required which have been raised with our contractors.	Yes
Unauthorised items were found in communal areas and arrangements were made for their removal.	Yes
Not all records were up to date, as noted in the table below. Arrangements have been made for these to be completed.	No
A number of fire doors were found to be wedged or propped open. Fire doors are there to keep you safe and me kept shut at all times.	No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW	X	MEDIUM	НІGН	
-----	---	--------	------	--

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR	MAJOR	X	CRITICAL	
		Λ		

The definition of the above terms is as follows: *FRA Review Frequency*

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	intolerable

When the level of risk is established, the action level can be read from the table below:

Asset ID: 9433

1-41 Ramsey Park Block 1-41 Ramsey Park, Barrow-in-Furness

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial