# Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 107 Plackett Close, Nottingham

#### **Cover Sheet**

Photo



Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

11 Jan 2023

11 Jan 2026

36

3 year Re-Assessment

Type 3 (Common Parts and Flats - Non Destructive)

Lynn.betteridge@accentgroup.org

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

#### The Scheme

Scheme Name Plackett Close

Scheme Address Plackett Close, Nottingham

Postcode NG9 8QF

Region East

Scheme Manager

Scheme Tel. No N/A

Scheme Inspection Completed Yes

Enforcing Fire Authority

Nottinghamshire Fire And Rescue Service

Other staff in attendance Customer partner.

Number of on-site Accent staff

None

Number of other (non-Accent) staff

Contract Cleaners in common areas

### The Building

Accommodation Type General Needs (S30)

Build Date Jan 1 1998

Number Of Homes 35

Homes breakdown Flat

External wall construction Timber Frame

External wall finish Facing Brick, UPVC Cladding

Roof construction Timber

Roof covering Interlocking Pitched, Plain Pitched, Slate Pitched

PEEPs in place where necessary No

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

Number of External Staircases 0

External Balcony part of escape route?

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

**Plackett Close, Nottingham** Asset ID: 107 Fire Detection and Warning System Flats only Grade D Grade of fire alarm Category of fire alarm LD3 Minimum Protection **Emergency Lighting Provision** Non Maintained System - Common Areas Portable Fire Extinguishers supplied/fitted No Fixed Fire Fighting Installations No **Customers** 40 Number of occupants **General Needs** Occupant tenure type breakdown Fire Safety Related Customer Safety Servicing Overdue communal gas safety checks 0 0 Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 Overdue communal PAT testing 0 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests 5 5 Overdue Annual Emergency Lighting tests Overdue Weekly Fire Alarm Testing 0 Overdue Fire Panel - Six Monthly Testing Overdue Fire Safety Equipment tests **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors Communal Fire doors due for replacement within 5 years 0 **Dwelling Doors** Failing Dwelling Fire Doors 0

Dwelling Fire doors due for replacement within 5 years

0

# Fire Risk Assessment Survey Results

### **Scheme and Building Information**

Photo



Date of Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Risk Assessment

Quantity

Fire & Safety Assessor

**Enforcing Fire Authority** 

Scheme Tel. No

Other staff in attendance

Number of on-site Accent staff

Number of other (non-Accent) staff

Scheme Inspection completed

Number of occupants

Personal Emergency Evacuation Plans in place

**Current Evacuation Strategy** 

Conversion or purpose-built

Number of Storeys

Number of floors on which car parking is provided

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

Number of external staircases

External balcony part of escape route?

Unusual features

11/01/2023

36

3 year Re-Assessment

Type 3 (Common Parts and Flats - Non Destructive)

1

Lynn.betteridge@accentgroup.org

Nottinghamshire Fire And Rescue Service

N/A

Customer partner.

None

Contract Cleaners in common areas

Yes

40

No

Stay Put (Delayed) Evacuation

Purpose Built

3

0

No

0

No

NO

None

## Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Residential

Fire Detection and Warning System Flats only

Grade of Fire Alarm Grade D

Category of Fire Alarm LD3 Minimum Protection

Emergency Lighting Provision Non Maintained System - Common Areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted No

Water Extinguisher(s) present

Foam Extinguisher(s) present

Dry Powder Extinguisher(s) present

Carbon Dioxide Extinguisher(s) present

Fire Blanket(s) present No

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present No

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present No

#### **Electrical Sources of Ignition**

Electrical installation within common areas in good condition and no obvious damage?

Comment

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment Common areas and flats electrical test recorded as

the 28th of the 10th 2018

Yes

Electrical App/PA Testing - tested within past 12 months?

N/A

Comment

Absence of trailing leads and adapters? Yes

Comment

Evidence that mobility scooters are not being stored/charged in N/A

common areas?

Comment No scooters or storage

Is there a purpose built mobility scooter store/charging area?

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 5 of 14

Generated 29/08/2023 16:14:05

Asset ID: 107 Plackett Close, Nottingham	
Comment	
Does the building have a lightning protection system?	No
Comment	
Gas installations	
Is there a commercial/domestic gas supply to the scheme?	No
Comment	
Other Sources of Ignition	
Is there a no smoking policy in place, which is enforced and adhered to?	Yes
Comment	In communal areas.
Adequate security against arson?	Yes
Comment	On arrival for inspection all doors main doors were found to be secure and provide security against Arson.
Are refuse/recycling bin areas managed and suitably located?	Yes
Comment	
Are there communal cooking facilities at this scheme?	No
Comment	
Housekeeping	
Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items?  Comment	Yes
Are unnecessary accumulations of combustible materials or waste avoided?	No
Comment	There was found to be accumulation of of waste and residence property in a communal area customer partner attended on site and we dealt with the resident and informed them of the need to remove from the communal area.
Are combustible materials and substances separated from ignition sources and stored appropriately?	Yes
Comment	
Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations?	Yes
Comment	Solid brick walls in communal areas.

## **Other Significant Fire Hazards**

Are all other significant fire hazards adequately controlled?

Comment

#### Means of Escape from Fire

Is it considered that the building is provided with reasonable means of

escape in case of fire?

Comment

Escape routes unobstructed and safe to use?

Comment

Exits immediately openable without a key and/or failsafe's function

correctly?

Comment

Reasonable distances of travel where there is a single/alternative

direction of travel?

Comment

Escape routes lead to final exits and open in direction of escape where

necessary?

Comment

Observation	Priority	Referred To	Required By:	Task ID
2 doors you are required to have works completed to	Internal - Medium	Fire & Safety	03/04/2023	1608488
enable them to close correctly when entering the		Manager		

Yes

Yes

Yes

Yes

Yes



#### **Fire Spread and Development**

Is it considered that the compartmentation is of a reasonable standard?

Comment

Is there reasonable limitation of surface finishes that might promote fire

spread (walls, floors, ceilings)?

Comment

Yes

## Asset ID: 107 **Plackett Close, Nottingham** N/A Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products? Comment As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard? Comment No Loft hatches fire resisting? Comment N/A As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard? Comment No Do external walls, doors, windows and anything attached to the exterior, limit fire spread? Comment The external walls doors and windows will not propagate fire spread around the envelope of the building N/A If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available? Comment Are roller shutter doors that are required to be FR, fire resisting and N/A self-closing? Comment **Emergency Escape Lighting** Yes Is the emergency lighting correctly specified and installed as per current standards? Comment Yes Emergency lighting units in good condition and securely fixed to walls/ceilings? Comment Records of monthly/annual testing available? Yes

#### **Fire Safety Signs and Notices**

Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?

Comment

Comment

Directional fire escape signage in place and adequate?

Comment

is recorded as the 3rd of the 10th 22

The monthly emergency light testing was carried out on the 29th of the 12th 22 and the annual drop test

Asset ID: 107 PI	ackett Close, Nottingham	
Is there suitable LIFT signage i.e.	do not use in case of fire?	N/A
Comment		
Do common area fire doors displa where applicable? Comment	y the correct signage on both sides	N/A
Means of giving Warning	in case of Fire	
Is the scheme fitted with a commu	ınal area fire alarm?	N/A
Comment		The communal smoke detectors on each floor are due to be removed as per the stay Put policy andno longerl required.
Is fire detection and warning systerisk, as per BS 5839-1:2017? Comment	em appropriate for occupancy and fire	N/A
Is the fire detection and warning s certificates saved on file?  Comment	ystem maintained/tested and all	No
Fire alarm components in good cowalls/ceilings?  Comment	ondition and securely fixed to	Yes
Hold open devices operate at the serviceable condition?  Comment	sounding of the alarm and are in a	N/A
Are there heat detectors located in Laundry?  Comment	n the Kitchen, Boiler, Plant Room and	N/A
	onitored, and if so are there records of	N/A
Comment		
Fire Extinguishing Equip	ment	
Is fire extinguishing equipment an provided at this scheme?  Comment	d/or fixed fire fighting installations	No
Management of Fire Safe	ty	
Are these premises regulated by the Building Safety Act?  Comment	he Building Safety Regulator under	Yes
Will this FRA be shared will all Acc	countable Persons for the premises?	Yes

Page 9 of 14

Generated 29/08/2023 16:14:05

MIS-AMS ActiveH - Fire Risk Assessment Report

Comment	
How will this sharing be achieved?	Communication with all parties.
Are there other Responsible Persons who share or have fire safety duties in respect of the premises?  How will this sharing be achieved?	No
Is an office or IL scheme being inspected?	
Comment	
IL Schemes & Regional Offices - Are there sufficient numbers of qualified Fire wardens?  Comment	N/A
Offices - Are there suitable arrangements for ensuring the premises are evacuated?  Comment	N/A
Offices - Are there suitable arrangements for evacuating disabled people?  Comment	N/A
Offices - Suitable arrangements for meeting the fire service on arrival and proving relevant information?  Comment	N/A
Offices/IL Schemes - Is there a suitable assembly point?	N/A
Comment	
Offices - Are fire drills carried out at appropriate intervals?	N/A
Comment	
Passenger Lift	
Is the scheme fitted with a passenger lift?	N/A
Comment	
Is the lift in full working order at the time of the FRA?	N/A
Comment	
Is the lift fitted with a firefighters switch?	N/A
Comment	
Servicing and insurance inspection - Evidence of regular servicing/maintenance?  Comment	N/A

**Plackett Close, Nottingham** 

Asset ID: 107

Is there a premises information box for fire & rescue service use?

**Premises Inspection Box** 

No

# **Plackett Close, Nottingham** Asset ID: 107 Comment **Evacuation Policy** Are there suitable arrangements for summoning the fire service? Residents call 999 Fire and Rescue Service. Comment Yes Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance? Stay put policy. Comment **Engagement with Residents** Yes Has information of fire procedures been disseminated to residents? Comment Yes Is general fire safety information disseminated to residents? Comment FRA Frequency Yes Taking the findings of this assessment into account, is the frequency of the FRA correct? Comment Miscellaneous Yes Are there any other observations/actions to raise that are not covered above. Action leading to a repair Yes Yes Internal administrative Action Yes Are there fire related remedial works required at this property, that will affect the fabric of the building? Comment Block 21 to 24 as a defective front door along with the customer partner the Works is outstanding how to replace the locking mechanism and booked for

Can work be conducted without the need for an asbestos survey. If no,

task Customer Safety Surveyor - Asbestos.

Comment

the customer partner the Works is outstanding how to replace the locking mechanism and booked for replacement I will be contacting Surveyors to discuss to fire doors that have recently been repaired

No

Of the 4 blocks have been inspected to have fire resistant loft hatches and two blocks require replacement loft hatches I will be booking these jobs to be completed

doors are there to keep you safe and me kept shut at all times.

Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).	Yes
Some fire doors did not fully close so works orders have been raised with our contractors.	Yes
Some minor works were required which have been raised with our contractors.	Yes
Unauthorised items were found in communal areas and arrangements were made for their removal.	Yes
Not all records were up to date, as noted in the table below.  Arrangements have been made for these to be completed.	No
A number of fire doors were found to be wedged or propped open. Fire	No

#### **Risk Calculator - Fire**

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

	nt, it is	-			he time of this risk bability of ignition) at this
LO	w	X	MEDIUM		нідн
any proce	dural ar	rangements ob	•	e of the assessi	he fire protection afforded and ment, it is considered that the

**CRITICAL** 

The definition of the above terms is as follows: FRA Review Frequency

**MINOR** 

MINOR Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).	
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales	
Trivial	No action is required	
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.	
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.	
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.	

The Overall Risk Level for this asset is:	Trivial
	<u> </u>