Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 143 The Cloisters Priory Road, St Ives

Cover Sheet

Photo



Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

22 Nov 2022

22 Nov 2025

36

3 year Re-Assessment

Type 3 (Common Parts and Flats - Non Destructive)

Lynn Betteridge

This report has been validated by:

Name: Paul McMillan - Fire + Safety Manager

Date: 28/11/2022

Comment: Suitable & Sufficient

The Scheme

Scheme Name The Cloisters

Scheme Address The Cloisters Priory Road, St Ives

Postcode PE27 5ZD

Region East

Scheme Manager

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority Cambridgeshire Fire and Rescue Service

Other staff in attendance Keith Bowman

Number of on-site Accent staff

None

Number of other (non-Accent) staff

Contract Cleaners in common areas

The Building

Accommodation Type General Needs (S30)

Build Date Jan 1 1999

Number Of Homes 25

Homes breakdown Flat

External wall construction Facing Brick

External wall finish Facing Brick

Roof construction Timber

Roof covering Slate Pitched

PEEPs in place where necessary N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built

Number of storeys 3

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

Number of External Staircases None

External Balcony part of escape route? N/A

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

Asset ID: 143 The Cloisters Priory Road, St Ives	
Fire Detection and Warning System	Flats only
Grade of fire alarm	Grade E
Category of fire alarm	
Emergency Lighting Provision	Non Maintained System - Common Areas
Portable Fire Extinguishers supplied/fitted	No
Fixed Fire Fighting Installations	No
Customers	
Number of occupants	26
Occupant tenure type breakdown	General Needs, Leasehold
Fire Safety Related Customer Safety Servicing	
Overdue communal gas safety checks	0
Overdue domestic gas safety checks	0
Overdue communal electrical condition checks	0
Overdue domestic electrical condition checks	0
Overdue alarm call pull chord tests	0
Overdue communal PAT testing	0
Overdue customer mobility scooter PAT testing	0
Overdue Monthly Emergency Lighting Switch Tests	3
Overdue Annual Emergency Lighting tests	3
Overdue Weekly Fire Alarm Testing	0
Overdue Fire Panel - Six Monthly Testing	0
Overdue Fire Safety Equipment tests	0
Building Fire Safety Surveys - Communal Doors	
Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	0
Dwelling Doors	
Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



Date of Fire Risk Assessment 22/11/2022

FRA Frequency (Months) 36

Purpose of Fire Risk Assessment 3 year Re-Assessment

Type of Risk Assessment

Type 3 (Common Parts and Flats - Non Destructive)

Quantity

Fire & Safety Assessor Lynn Betteridge

Enforcing Fire Authority Cambridgeshire Fire and Rescue Service

Scheme Tel. No

Other staff in attendance Keith Bowman

Number of on-site Accent staff

None

Number of other (non-Accent) staff

Contract Cleaners in common areas

Scheme Inspection completed Yes

Number of occupants 26

Personal Emergency Evacuation Plans in place N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built

Number of Storeys 3

Number of floors on which car parking is provided 0

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

Number of external staircases None

External balcony part of escape route? N/A

Unusual features None

Fire Risk Assessment Survey Results

Vehicular Access to one or more elevations Building access conditions for Fire Brigade

Surroundings: Residential/Commercial Residential

Flats only Fire Detection and Warning System

Grade E Grade of Fire Alarm

Category of Fire Alarm

Non Maintained System - Common Areas **Emergency Lighting Provision**

Portable Fire Extinguishers / Fire Blankets supplied / fitted No

Water Extinguisher(s) present No

No Foam Extinguisher(s) present

Dry Powder Extinguisher(s) present No

No Carbon Dioxide Extinguisher(s) present

Fire Blanket(s) present No

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

No Wet Riser(s) present

No Sprinkler System present

No Hosereel(s) present

Automatic Opening Vent(s) present No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no

obvious damage?

Comment

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment

Currently there is a valid electrical installation report

Yes

Yes

dated from the 8th of October 2021 this is currently in date and will require an inspection again in 2026

Electrical App/PA Testing - tested within past 12 months?

Comment

Yes Absence of trailing leads and adapters?

Comment

N/A Evidence that mobility scooters are not being stored/charged in

common areas?

Comment

The Cloisters Priory Road, St Ives Asset ID: 143 Is there a purpose built mobility scooter store/charging area? No Comment Does the building have a lightning protection system? No Comment Gas installations No Is there a commercial/domestic gas supply to the scheme? No gas to scheme. Comment Other Sources of Ignition Is there a no smoking policy in place, which is enforced and adhered Yes to? Comment Adequate security against arson? Yes Comment Yes Are refuse/recycling bin areas managed and suitably located? Comment Nο Are there communal cooking facilities at this scheme? Comment Housekeeping Are all electrical/intake/service cupboards secure and free from general Yes waste, contractors waste and and residents personal items? Comment On inspection the storage cupboards under the staircase accessed by a fb1 key and found speak clear of combustibles and waste products Yes Are unnecessary accumulations of combustible materials or waste avoided? Comment N/A Are combustible materials and substances separated from ignition sources and stored appropriately? Comment Yes

Other Significant Fire Hazards

Comment

comply with modern standards and regulations?

Furniture/furnishings in good condition, fire retardant/resistant and

The Cloisters Priory Road, St Ives Asset ID: 143

Are all other significant fire hazards adequately controlled?

Yes

Yes

Yes

Comment

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of

escape in case of fire?

Comment

Escape routes unobstructed and safe to use?

Comment All escape routes which are through the main door were found to be clear ear of combustibles in the

common areas and no obstruction to the fire exit

door Yes

Yes

Yes

Exits immediately openable without a key and/or failsafe's function

correctly?

Comment

Reasonable distances of travel where there is a single/alternative

direction of travel?

Comment

Escape routes lead to final exits and open in direction of escape where

necessary? Comment

Observation

Priority Referred To Required By: Task ID

3 fire doors need attention.

Internal - Medium

Fire & Safety Manager

03/01/2022

1593194





Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment

Is there reasonable limitation of surface finishes that might promote fire

spread (walls, floors, ceilings)?

Comment

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?

N/A

Yes

Yes

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 7 of 13

Generated 23/11/2022 11:58:55

Asset ID. 145 The Gloisters I flory Road, of Ives	
Comment	
As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard? Comment	Yes
Loft hatches fire resisting?	Yes
Comment	
As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard? Comment	N/A
Do external walls, doors, windows and anything attached to the exterior, limit fire spread? Comment	No
If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available? Comment	N/A
Are roller shutter doors that are required to be FR, fire resisting and self-closing? Comment	N/A
Emergency Escape Lighting	
Is the emergency lighting correctly specified and installed as per current standards? Comment	Yes
Emergency lighting units in good condition and securely fixed to walls/ceilings? Comment	Yes
Records of monthly/annual testing available?	Yes
Comment	The monthly emergency lighting test was carried out out on the 25th of October 20-22 2 and the annual emergency lighting inspection was completed on the 1st of September 2022
Fire Safety Signs and Notices	
Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas? Comment	Yes
Directional fire escape signage in place and adequate?	Yes

The Cloisters Priory Road, St Ives

Asset ID: 143

The Cloisters Priory Road, St Ives Asset ID: 143 Comment On this scheme each block has one staircase communal area exit and access is via the main door there is no requirement for a fire exit sign to be on this door as only one one-way to leave the building in case of Fire Is there suitable LIFT signage i.e. do not use in case of fire? N/A Comment N/A Do common area fire doors display the correct signage on both sides where applicable? Comment Means of giving Warning in case of Fire No Is the scheme fitted with a communal area fire alarm? Comment Only flats Fire Extinguishing Equipment No Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme? Comment Management of Fire Safety Yes Are these premises regulated by the Building Safety Regulator under the Building Safety Act? Comment Yes Will this FRA be shared will all Accountable Persons for the premises? Comment How will this sharing be achieved? Communication No Are there other Responsible Persons who share or have fire safety duties in respect of the premises? How will this sharing be achieved? No Is an office or IL scheme being inspected?

Passenger Lift

Is the scheme fitted with a passenger lift?

N/A

Comment

Comment

Is the lift in full working order at the time of the FRA?

N/A

The Cloisters Priory Road, St Ives Asset ID: 143 Comment N/A Is the lift fitted with a firefighters switch? Comment N/A Servicing and insurance inspection - Evidence of regular servicing/maintenance? Comment **Premises Inspection Box** Is there a premises information box for fire & rescue service use? No Comment **Evacuation Policy** Yes Are there suitable arrangements for summoning the fire service? Comment The residents on this scheme are expected to dial 999 and ask for the fire service in the event of a fire fire routine notices are supplied for the residents to take action in a fire situation and the Residence have been given notification that this scheme is a stay put scheme. Yes Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance? Comment **Engagement with Residents** Has information of fire procedures been disseminated to residents? Yes Comment The residents have been made aware are of the stay put policy and information required is found on the fire routine notices media and and communication is given to the residents when moving and moving into the scheme. Is general fire safety information disseminated to residents? Comment FRA Frequency Yes Taking the findings of this assessment into account, is the frequency of the FRA correct? Comment

Miscellaneous

Are there any other observations/actions to raise that are not covered above.	Yes
Action leading to a repair	Yes
Internal administrative Action	Yes
Are there fire related remedial works required at this property, that will affect the fabric of the building? Comment	No
Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).	Yes
Some fire doors did not fully close so works orders have been raised with our contractors.	Yes
Some minor works were required which have been raised with our contractors.	Yes
Unauthorised items were found in communal areas and arrangements were made for their removal.	No
Not all records were up to date, as noted in the table below. Arrangements have been made for these to be completed.	No
A number of fire doors were found to be wedged or propped open. Fire	No

doors are there to keep you safe and me kept shut at all times.

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

systems.					
1. Taking into a	ccount the fire pre	evention measures	 observed at th	ne time of this risk	
assessment, it is building is:	s considered that	the hazard from the	e fire (the prob	bability of ignition) a	at this
LOW	X	MEDIUM		HIGH	
any procedural	arrangements ob	of the building, the served at the time on the event of a fire wo	of the assessm	•	
MINOR		MAJOR	$\overline{\mathbf{x}}$	CRITICAL	

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales	
Trivial	No action is required	
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.	
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.	
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.	

The Overall Risk Level for this asset is:	Trivial	
The Overall Risk Level for this asset is.		