

## **ACCENT HOUSING - HEALTH & SAFETY ASSESSMENT**



Region: East

Scheme Name: Stowehill Road

Scheme Address: Stowehill Road

Peterborough

**PE4 7PY** 

Date of Assessment: 31/03/2020

Date of Next Assessment: 31/03/2023

H&S Frequency: 3 Years

Fire & Safety Assessor 3 Years

Scheme Details		Stowehill Road
Region:		East
Scheme Name:		Stowehill Road
Site Address: Street:		Stowehill Road
	Town:	Peterborough
	Post Code:	PE4 7PY
Block & Asset No.		14-24 Asset 699
Block & Asset No.		32-42 Asset 700
Scheme Tel. No:		
Date of this Assessment		31/03/2020
Date of Next Review		31/03/2023
Fire Risk Assessment Frequency		3 Years
<b>Health &amp; Safety Assessment Frequenc</b>	y	3 Years
Purpose of Fire Risk Assessment		3 Year Re-Assessment
Fire & Safety Assessor		Lynn Betteridge
Director of Customer Experience		Dominic Roche
Customer Partnership Manager		Keith Bowman
Contract Manager		Kevin Turner
Scheme Manager/Customer Partner		Alan Percival
Other staff in attendance		
Use of Building		General Needs
Approximate Number of occupants		18
Occupancy Profile		Families
Familiarity of the occupants		Fully Familiar
Likely state of the Occupants		Alert
PEEPs in place where necessary		N/A
Number of on-site Accent staff		None
		Contract cleaners in common
Number of other (non-Accent) staff		areas
Support Agency (Supported Housing)		N/A

Current Evacuation Strategy.	Stay Put (Delayed) Evacuation
Current Evacuation Strategy. Evidence that residents have been notified of the	Advice notices displayed in
evacuation procedure	common areas
History of fires in the building	None
Business Continuity Plan in place?	Yes
, i	Type 1 (Common Parts Only -
Scope of Assessment	Non Destructive)
Applicable Fire Safety Guidance	Purpose-built flats guide
Building Details	Stowehill Road
Construction Date	1983
	Joisted or Load Bearing Masonry
Construction Type	(Traditional)
Roof Finish	Pitched-Concrete Tile
Conversion or purpose-built	Purpose Built
Number of flats (self-contained)/rooms (HMOS, shared	
houses)	12
Number of storeys above ground	Two
Number of storeys below ground	None
Is there a habitable basement?	No
Number of internal Staircases per Block	
(protected or unprotected?)	One-Protected
Number of External Staircases per Block	None
External Balcony part of escape route?	None No
External Balcony part of escape route? Unusual features	None No None
External Balcony part of escape route? Unusual features Building complexity	None No None Simple
External Balcony part of escape route? Unusual features	None No None Simple Vehicular Access to one or more
External Balcony part of escape route? Unusual features Building complexity	None No None Simple

	Significant Findings - Health & Safety						
	Sto	weh	nill Road		31/03/2020		
Action Ref:	ribailir a barbty ribit	Yes-No- N/A	Observation/Comments/ Actions Required	<del>Risk</del> Rating	Target Completio n Date	Referred To:	
1	Asbestos			,			
	Asbestos Survey held on file (if pre 2000 construction)	Yes		٠.			
	Evidence that any confirmed asbestos containing materials left in situ are being regularly re-inspected and managed.	Yes					
	Legionella						
	Legionella Risk Assessment within the past two years (If applicable)	N/A	Note: No Legionella risk associated with this scheme.				
2.2	Evidence that the legionella risk is being managed as per contract.	N/A					
2.3	Evidence that exceptions raised are being addressed and the portal updated.	N/A					
3	Maintenance of common internal access ro	utes					
3.1	Satisfactory condition of floor & floor covering	Yes	Note: Generally floor coverings satisfactory.				
3.2	Satisfactory condition of stairs (nosing) and the stability of staircase handrails and balustrades	Yes					
3.3	Artificial lighting (suitable/sufficient/working)	Yes					
4	Security						
	Serviceability of door entry system	Yes	Note; Keypad Operation satisfatory				
4.2	Satisfactory security of other exit doors	sə ,					
4.3	Satisfactory security measures	e	Note: One main accesses through security door.				
5	Exterior of Building						
5.1	Satisfactory condition of site	Yes	Note: Generally all external area clean and tidy.				

5.3	Satisfactory condition of external walls, roof,	es		١.		
	tiles & guttering	>				
5.4	Satisfactory condition of walkways and other	w				
	areas (Trip hazards including tree roots)	Yes				
5.5	Satisfactory condition of external steps	es		١.		
		<b>&gt;</b>				
5.6	Satisfactory condition of external handrails	$\geq \triangleleft$				
5.7	Satisfactory condition/safety of boundary	S				
"	walls/fences	Yes		'		
5.8	Artificial lighting (suitable/sufficient/working)			1.		
	J	Yes		'		
5.9	Satisfactory condition of site signage	es				
F 40		> 0				
5.10	Satisfactory condition/safety of trees/hedges	Yes				
6	Housing Officer/Scheme Manager Checks/l	_	ctions			
6.1	Are regular inspections/checks carried out by		Note: Generic and raised on other schemes should be			
	HO/SM '	Yes	individual per scheme.	'		
6.2	Is the frequency suitable for the scheme	es				
		<b>&gt;</b>				
6.3	Was the most recent check carried out on	Yes				
	time					
6.4	Do the recorded findings appear correct	Yes	As above 6.1 Generic to paston area.			
6.5	Are any identified actions complete					
0.0	The any lacrimod denone complete	Yes		•		
7	Staff Training					
7.1	Have the Scheme Managers and appointed	-				
	office based staff received First Aid training	N/A				
	within the past 2 years					
7.2	Are there sufficient number of qualified First					
	Aiders. (Sheltered Schemes & Regional	N/A		•		
	Offices only)					
8	Documents and Policies - Workplaces and	Shel	tered Schemes only			
8.1	Health & Safety Policy Statement displayed	≥∢		.		
8.2	Health & Safety Poster in office - correctly	4				
0.2	completed	NA		•		
	Journalioted				1	1

8.3	Do relevant staff carry out regular H&S checks	N/A		•		
8.6	First Aid Equipment - Serviceability	N A				
8.8	COSHH Records - Up to date and available for viewing.	N/A	Note Cleaners contract responsible.	-		
9	Occupational Health - Workplaces and She	lterec	Schemes only		-	
9.1	Staff Welfare - Satisfactory Standards	≥ <		ı		
9.2	Satisfactory Building Hygiene	≥ <				
Lifting	g Equipment					
	Passenger lift					
	LOLER thorough examination report dated within past 6 months	N/A		-		
10.2	Evidence that remedial actions have been completed	N/A		-		
10.3	Servicing report dated within past 6 months	Ν		•		
	Evidence that remedial action have been completed	N/A		-		
10.5	Lift levelling correctly at all landings?	≥∢		•		
10.6	Door sensors working?	Ν		•		
10.7	Door sensors appropriate for type of building?	N/A		-		
10.8	Warning notice in lift?	≥ <		-		
11	Stairlifts					
11.1	LOLER thorough examination report dated within past 6 months	N/A				
11.2	Evidence that remedial actions have been completed	N/A		-		
11.3	Servicing report dated within past 12 months	≥ <				
	Evidence that remedial action have been completed	N/A		ı		
11.5	Evidence that all users have been assessed by an OT	N/A		-		

			·			
11.6	Pictographs displayed	≥∢				
12	Other lifting equipment (bath lifts, wheelch	air lif	its)			
12.1	LOLER thorough examination report dated within past 6 months	N/A		ı		
12.2	Evidence that remedial actions have been completed	N/A		ı		
12.3	Servicing report dated within past 12 months	≥∢				
12.4	Evidence that remedial action have been completed	N/A		•		
13	Other Equipment Requiring Inspection					
13.1	Are Carbon Monoxide detectors within General Needs flats subject to an annual inspection and the results recorded on an in date Landlord Gas Safety Record (LGSR)	Yes		-		
13.2	Automatic sliding/swing doors - Satisfactory function, evidence of regular servicing/maintenance	N/A		•		
14						
14.8				ı		

	Photographs - Health & Safety
31/03/2020	Stowehill Road

No Photos no sugnificant risks.

## 7. RISK CALCULATOR HEALTH & SAFETY

Injury/Health Risk	Likelil	Likelihood of accident/incident occurring						
Major	Н	Н	M	M				
Significant	Н	M	M	L				
Serious	M	M	L	L				
Minor	M	L	L	L				
	PROBABLE	POSSIBLE	REMOTE	NEGLIGIBLE				

	Possible injury risk/ possible health risk				
Major Personal	(fatal or major) or Serious Health Effect				
Injury	(permanent, progressive or irreversible				
	condition, or permanently disabling)				
Significant Injury	(RIDDOR reportable) or Significant Health Effect				
	(non-permanent, reversible or non-progressive				
	condition, or temporary disability)				
Serious	Non RIDDOR reportable injury any lead to time off work				
	(Non RIDDOR, first-aid only) or Minor Health Effect				
Minor Injury	(conditions not included above)				

Taking into account the potential injury/health risk and the likelihood of an accident/incident occurring the risk rating for this site is:

**LOW** 

Risk rating	Guide to actions and appropriate timescales
Low	No immediate action is action is required.  Overall the site is well maintained and good health and safety standards are in place
Medium	Action is required to reduce the risk level and this should be carried out within the specified time periods of the action plan
High	Immediate action is required to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.

	Action Plan - Health & Safety				
	Stowehill Road				
	LOW				
Potential Area of Health & Safety Risk	Observation/Comments / Actions Required	Risk Rating	Completion Date	Referred To:	Task ID No.