# Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 1031 17-36 Keyworth Court Block 17-36 Princes Street, Huntingdon

### **Cover Sheet**

Photo



Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

14 Aug 2024

14 Aug 2025

12

Annual Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Lynn.betteridge GlfireE (Dip) NEBOSH

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

### The Scheme

Scheme Name Keyworth Court

Scheme Address 17-36 Keyworth Court Block 17-36 Princes Street,

Huntingdon

Postcode PE29 3PU

Region East

Scheme Manager

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority Cambridgeshire Fire and Rescue Service.

Other staff in attendance No staff on day of inspection a meeting arranged.

Number of on-site Accent staff

None

Number of other (non-Accent) staff

Contract Cleaners in common areas

### The Building

Accommodation Type General Needs (S30)

Build Date Mar 29 2010

Number Of Homes 20

Homes breakdown Flat

External wall construction Steel Frame

External wall finish Facing Brick, UPVC Cladding

Roof construction Metal

Roof covering Interlocking Pitched

PEEPs in place where necessary N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys 4

Number of floors on which car parking is provided 1

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

1 protected in block 17-36.

Number of External Staircases None

External Balcony part of escape route? N/A

Unusual features None on this block.

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

# 17-36 Keyworth Court Block 17-36 Princes Street, Huntingdon Asset ID: 1031 Flats and common areas not linked Fire Detection and Warning System Grade of fire alarm Grade A Category of fire alarm LD3 Minimum Protection Non Maintained System - Common Areas **Emergency Lighting Provision** Portable Fire Extinguishers supplied/fitted No Fixed Fire Fighting Installations No **Customers** 36 Number of occupants **General Needs** Occupant tenure type breakdown Fire Safety Related Customer Safety Servicing Overdue communal gas safety checks 0 0 Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 Overdue communal PAT testing 0 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests 0 Overdue Annual Emergency Lighting tests 0 0 Overdue Weekly Fire Alarm Testing 0 Overdue Fire Panel - Six Monthly Testing 0 Overdue Fire Safety Equipment tests **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors Communal Fire doors due for replacement within 5 years 0 **Dwelling Doors** 0 Failing Dwelling Fire Doors

Dwelling Fire doors due for replacement within 5 years

0

## Fire Risk Assessment Survey Results

### **Scheme and Building Information**

Photo



Date of Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Risk Assessment

Quantity

Fire & Safety Assessor

**Enforcing Fire Authority** 

Scheme Tel. No

Other staff in attendance

Number of on-site Accent staff

Number of other (non-Accent) staff

Scheme Inspection completed

Number of occupants

Personal Emergency Evacuation Plans in place

**Current Evacuation Strategy** 

Conversion or purpose-built

Number of Storeys

Number of floors on which car parking is provided

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

Number of external staircases

External balcony part of escape route?

Unusual features

14/08/2024

12

Annual Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

1

Lynn.betteridge GlfireE (Dip) NEBOSH

Cambridgeshire Fire and Rescue Service.

No staff on day of inspection a meeting arranged.

None

Contract Cleaners in common areas

Yes

36

N/A

Stay Put (Delayed) Evacuation

Purpose Built

4

1 No

1 protected in block 17-36.

None

N/A

None on this block.

# Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Mixed

Fire Detection and Warning System Flats and common areas not linked

Grade of Fire Alarm Grade A

Category of Fire Alarm LD3 Minimum Protection

Emergency Lighting Provision Non Maintained System - Common Areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted No

Water Extinguisher(s) present No

Foam Extinguisher(s) present

Dry Powder Extinguisher(s) present

Carbon Dioxide Extinguisher(s) present

Fire Blanket(s) present

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present Yes

Wet Riser(s) present

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present Yes

### **Electrical Sources of Ignition**

Electrical installation within common areas in good condition and no

obvious damage?

Comment All electrical components on each floor found to to

be secure and not damaged.

Yes

Yes

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment The EICR is required every 5 years and has been

tested and recorded and dated 1/10/2020. A Sample flat 20 dated 20/1/2020 was also checked for compliance, all certificates have been uploaded to

active "H" and M files.

Electrical App/PA Testing - tested within past 12 months?

N/A

Comment General Needs scheme no requirement.

Absence of trailing leads and adapters? Yes

Comment On the day of inspection there was no visible signs

of leads or any adapters on all floors.

Evidence that mobility scooters are not being stored/charged in

common areas?

Comment There was no mobility scooters identified on this

scheme and housing partner confirms.

Is there a purpose built mobility scooter store/charging area?

Comment There is no external charging facilities on this

scheme.

Yes

N/A

Does the building have a lightning protection system?

Comment

Is the protection system adequately maintained?

Comment

Gas installations

Is there a commercial/domestic gas supply to the scheme?

Comment This scheme does not have any Gas distribution on

this scheme and no requirement to meet Gas safety

regulations.

Yes

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered

to?

Comment Communal areas are designated no smoking and

residents are made aware of by signage and a reminder that this is stipulated in the tenancy

agreement.

Adequate security against arson? Yes

Comment On the day of inspection all access doors found

secure, there is also a fire door leading to internal final exit door underground car park which was

secure on the ground floor.

Are refuse/recycling bin areas managed and suitably located?

Yes

Commercial storage waste bins are located in a

internal storage area, the steel doors are accessed

only by residents.

Are there communal cooking facilities at this scheme?

Comment

Housekeeping

Are all electrical/intake/service cupboards secure and free from general

waste, contractors waste and and residents personal items?

Comment

Yes

Storage cupboards containing electrical services

equipment at each level are kept locked.

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 6 of 15

Generated 29/08/2024 16:02:16

Are unnecessary accumulations of combustible materials or waste

avoided?

Comment Generally the scheme is well maintained and each

floor level clear. Externally the scheme is clear from

combustible.

Yes

N/A

N/A

Are combustible materials and substances separated from ignition

sources and stored appropriately?

Comment

Furniture/furnishings in good condition, fire retardant/resistant and

comply with modern standards and regulations?

Comment This is a General needs block and no furniture

provision in communal area.

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Comment This block consists of 4 floors and is part of 2

blocks with similar fire protection measures and will

be subject to a annual inspection.

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of

escape in case of fire?

Comment All flats lead into a protected staircase via a

communal fire door, the travel distance meets the code of practice and residents proceed to safe Air

via the protected staircase.

Escape routes unobstructed and safe to use?

Comment At the time of inspection there was no obstructions

residents are reminded of the clear corridor policy by

signage. Yes

Yes

Yes

Yes

Exits immediately openable without a key and/or failsafe's function

correctly?

Comment safe egress by residents is maintained in the

direction of travel and a emergency release installation is provided by the final exit. This equipment door release mechanism was tested on

the day of inspection for functionality.

Reasonable distances of travel where there is a single/alternative

direction of travel?

Comment Travel distances from the residents flats meets the

code of practice.

Escape routes lead to final exits and open in direction of escape where

necessary?

Comment All fire doors communal on each landing open in the

direction of travel.

### Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?

Comment

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?

Comment

As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?

Comment

Comment

Loft hatches fire resisting?

-

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?

Comment

Do external walls, doors, windows and anything attached to the exterior, limit fire spread?

Comment

If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?

Comment

Are roller shutter doors that are required to be FR, fire resisting and self-closing?

Comment

Yes

Yes

The surface linings of walls and ceilings are designed to meet C-s3,d2.

Yes

This building has smoke shafts operated as AOV from ground floor ceiling via louvre opening and floor level fire doors on each landing have a manual operation override.

Smoke travel through the shaft to fresh Air on operation of the fire alarm.

Yes

Yes

Fire resisting loft hatch located on top floor landing.

N/A

This scheme is to have a full external survey to establish wall and roof materials.

Once established the Fire Risk Assessment will

be updated.

Yes

The AOV system was completely replaced in 2023 as previous system was faulty all certification is uploaded to Active "H" and M files. Test dated as 29/7/2024.

Each landing has a standard fire door operated via Fire alarm activation, also window vent. The control panel located 3rd floor lockable fire door storage area.

N/A

The car park area has a double size steel shutter which is not fire rated and opens when the fire alarm activates.

### **Emergency Escape Lighting**

Is the emergency lighting correctly specified and installed as per current standards?

Comment

Emergency lighting units in good condition and securely fixed to walls/ceilings?

Comment

Records of monthly/annual testing available?

Comment

Yes

Certification on installation is uploaded to Active "H" and M files and meets BS5266-1 the contractor Tunstalls maintain and test the system.

Yes

On the day of inspection the emergency lighting was found in good condition and all equipment on each landing was secure and operational.

Yes

The emergency lighting system at this scheme has been tested monthly on the 3/7/2024 and the annual drop test was completed on the 19/4/2024.Al recorded by Tunstall and uploaded to Active "H"and M files.

### Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?

Comment

Directional fire escape signage in place and adequate?

Comment

Is there suitable LIFT signage i.e. do not use in case of fire?

Comment

Do common area fire doors display the correct signage on both sides where applicable?

Comment

Yes

The fire action notices are located in all the communal areas.on the ground floor adjacent to final exit.New signs installed on the day of inspection.

Yes

Signage is provided on each floor only one travel direction to final exit to safe air.

Yes

Each floor landing has a fire routine notification do not use the lift in the event of a fire situation.

Yes

All doors denoted both sides.

Observation Priority Referred To Required By: Task ID

Replacement of signage.

No Action





#### 17-36 Keyworth Court Block 17-36 Princes Street, Huntingdon Asset ID: 1031

# Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?

Is fire detection and warning system appropriate for occupancy and fire

risk, as per BS 5839-1:2017?

Comment

Comment

Is the fire detection and warning system maintained/tested and all

certificates saved on file?

Comment

Fire alarm components in good condition and securely fixed to

walls/ceilings?

Hold open devices operate at the sounding of the alarm and are in a

serviceable condition?

Comment

Comment

Are there heat detectors located in the Kitchen, Boiler, Plant Room and

Laundry?

Comment

Is the fire alarm panel remotely monitored, and if so are there records of

regular testing?

Comment

Yes

The fire panel is located in the main foyer along with the floor plan and denoted fire Zones on each floor.

Yes

Yes

The fire panel is tested 6 monthly by the main contractor Tunstalls the date of last test dated 15/2/2024. The scheme fire alarm is also tested weekly the last test date 8//2024 by the contractor all records are uploaded to Active"H" and M files.

Yes

At the time of inspection all components were

identified on each floor in good condition.

N/A

N/A

No

As previously stated the alarm maintenance contract is established with Tunstalls but not

remotely monitored.

# Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations

provided at this scheme?

Portable fire extinguishers - appropriate type/number/position?

Comment

Comment

Correct signage displayed by each fire extinguisher?

Comment

Fire blanket in communal kitchen, secured to the wall, complete with

signage?

Comment

Yes

Dry risers located at every level.

No

N/A

N/A

Dry risers - Inlet/outlet boxes secured and/or securing straps fitted to

outlet valves?

Comment All checked on the day of inspection.

Records available of fire fighting equipment servicing within past 12

months?

Comment Annual check completed on 19/8/2024 by Morgan

Fire.

No

N/A

N/A

N/A

N/A

No

Yes

Yes

Yes

This record updated.

**Management of Fire Safety** 

Are these premises regulated by the Building Safety Regulator under

the Building Safety Act?

Comment This Block 17-36 only 4 floors.

Are there other Responsible Persons who share or have fire safety

duties in respect of the premises?

Have all details required by regulations been shared with all other

Responsible Persons?

Have all details required by regulations to be shared with us from other

Responsible Persons been received and recorded?

Comment

Comment

Will this FRA be shared will all other Responsible Persons for the

premises?

Comment

How will this sharing be achieved? FRA will be made available on Accent website.

Is an office or IL scheme being inspected?

Is the scheme fitted with a passenger lift?

Comment

Passenger Lift

-

Comment New signage displayed on adjacent wall denoted as

not to be used in the event of a fire.

Is the lift in full working order at the time of the FRA?

Yes

Comment This lift was operated to establish functioning

correctly.

Is the lift fitted with a firefighters switch?

Comment

Servicing and insurance inspection - Evidence of regular Yes

servicing/maintenance?

Comment The lift for this scheme has undergone a inspection and servicing on 9/5/2024 and the results uploaded

to Active"H" and M files.

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 11 of 15

Generated 29/08/2024 16:02:16

### **Premises Inspection Box**

Is there a premises information box for fire & rescue service use?

Comment

No

### **Evacuation Policy**

Are there suitable arrangements for summoning the fire service?

Comment

Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance?

1 0

Comment

Yes

 $\mbox{\sc All}$  residents call the fire and rescue service in the

event of a fire.

Yes

The "Stay put" policy has been implemented and resident all made aware by formal notification.

### **Engagement with Residents**

Has information of fire procedures been disseminated to residents?

Comment

Yes

When residents move into the flats they are given fire safety advice and also leaflets and a link into the website. The residents are also given notification of the Evacuation procedure for this scheme and can request a copy of the FRA, Accent Fire safety assessor details are shared for any advice and support.

Yes

Is general fire safety information disseminated to residents?

Comment

Residents are distributed leaflets on current fire safety initiatives, the website provides additional

information on fire safety advice.

# FRA Frequency

Taking the findings of this assessment into account, is the frequency of

the FRA correct?

Comment

Yes

12 month inspection is required on this scheme.

### Miscellaneous

Are there any other observations/actions to raise that are not covered .

above.

Are there fire related remedial works required at this property, that will

affect the fabric of the building?

Comment

No

No

Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).

No

### **Risk Calculator - Fire**

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW MEDIUM HIGH

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial
	<u> </u>