

This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 34800

6 Eastwick Close, Bedford

Cover Sheet

Photo

Date of Fire Risk Assessment Date of Next Fire Risk Assessment FRA Frequency (Months) Purpose of Fire Risk Assessment Type of Fire Risk Assessment Fire & Safety Assessor



18 Jul 2024 18 Jul 2027 36

3 year Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Lynn betteridge GIFIRE (Dip) NEBOSH

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name	Cardington
Scheme Address	6 Eastwick Close, Bedford
Postcode	MK42 0ZN
Region	East
Scheme Manager	
Scheme Tel. No	
Scheme Inspection Completed	
Enforcing Fire Authority	Bedfordshire Fire and Rescue Service.
Other staff in attendance	None
Number of on-site Accent staff	None
Number of other (non-Accent) staff	Contract Cleaners in common areas

The Building

Accommodation Type	
Build Date	May 30 2023
Number Of Homes	6
Homes breakdown	Flat
External wall construction	
External wall finish	
Roof construction	
Roof covering	
PEEPs in place where necessary	Yes
Current Evacuation Strategy	Stay Put (Delayed) Evacuation
Conversion or purpose-built	Purpose Built
Number of storeys	3
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
Number of internal Staircases (protected or unprotected?)	1 protected in the block with 2 Means of escape.
Number of External Staircases	None
External Balcony part of escape route?	N/A
Unusual features	None
Building Access Conditions for Fire Brigade	Vehicular Access to one or more elevations

6 Eastwick Close, Bedford

Fire Detection and Warning System	Flats and common areas not linked
Grade of fire alarm	Grade D
Category of fire alarm	LD2 Additional Protection
Emergency Lighting Provision	Non Maintained System - Common Areas
Portable Fire Extinguishers supplied/fitted	No
Fixed Fire Fighting Installations	No

Customers

Number of occupants	12
Occupant tenure type breakdown	General Needs

Fire Safety Related Customer Safety Servicing

Overdue communal gas safety checks	0
Overdue domestic gas safety checks	0
Overdue communal electrical condition checks	0
Overdue domestic electrical condition checks	0
Overdue alarm call pull chord tests	0
Overdue communal PAT testing	0
Overdue customer mobility scooter PAT testing	0
Overdue Monthly Emergency Lighting Switch Tests	1
Overdue Annual Emergency Lighting tests	1
Overdue Weekly Fire Alarm Testing	0
Overdue Fire Panel - Six Monthly Testing	
Overdue Fire Safety Equipment tests	1

Building Fire Safety Surveys - Communal Doors

Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	0

Dwelling Doors

Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo

Date of Fire Risk Assessment	22/07/
FRA Frequency (Months)	36
Purpose of Fire Risk Assessment	3 year
Type of Risk Assessment	Туре ′
Quantity	1
Fire & Safety Assessor	Lynn t
Enforcing Fire Authority	Bedfo
Scheme Tel. No	
Other staff in attendance	None
Number of on-site Accent staff	None
Number of other (non-Accent) staff	Contra
Scheme Inspection completed	
Number of occupants	12
Personal Emergency Evacuation Plans in place	Yes
Current Evacuation Strategy	Stay F
Conversion or purpose-built	Purpo
Number of Storeys	3
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
No. of internal staircases (protected/unprotected)	1 prot
Number of external staircases	None
External balcony part of escape route?	N/A
Unusual features	None



22/07/2024
36
3 year Re-Assessment
Type 1 (Common Parts Only - Non Destructive)
1
Lynn betteridge GIFIRE (Dip) NEBOSH
Bedfordshire Fire and Rescue Service.
None
None
Contract Cleaners in common areas
12
Yes
Stay Put (Delayed) Evacuation
Purpose Built
3
0
No
1 protected in the block with 2 Means of escape.
None
N/A

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade	Vehicular Access to one or more elevations
Surroundings: Residential/Commercial	Residential
Fire Detection and Warning System	Flats and common areas not linked
Grade of Fire Alarm	Grade D
Category of Fire Alarm	LD2 Additional Protection
Emergency Lighting Provision	Non Maintained System - Common Areas
Portable Fire Extinguishers / Fire Blankets supplied / fitted	No
Water Extinguisher(s) present	No
Foam Extinguisher(s) present	No
Dry Powder Extinguisher(s) present	No
Carbon Dioxide Extinguisher(s) present	No
Fire Blanket(s) present	No
Fixed Fire Fighting Installations supplied / fitted	No
Dry Riser(s) present	No
Wet Riser(s) present	No
Sprinkler System present	No
Hosereel(s) present	No
Automatic Opening Vent(s) present	Yes

Electrical Sources of Ignition

Electrical installation within common areas in good condit obvious damage?	tion and no	Yes
Comment		New build all electrical equipment secure at time of inspection.
Valid Electrical Installation Condition Reports held on file Areas & General Needs Flats)	? (Common	Yes
Comment		All certification uploaded to Active H and M files.
Electrical App/PA Testing - tested within past 12 months?		N/A
Comment		
Absence of trailing leads and adapters?		Yes
Comment		
Evidence that mobility scooters are not being stored/char common areas?	ged in	N/A
Comment		
Is there a purpose built mobility scooter store/charging ar	ea?	N/A
MIS-AMS ActiveH - Fire Risk Assessment Report	Page 5 of 13	Generated 23/07/2024 08:38:53

Asset ID: 34800 6 Eastw

6 Eastwick Close, Bedford

Comment

Does the building have a lightning protection system?

Comment

Gas installations

Is there a commercial/domestic gas supply to the scheme?

Comment

Valid LGSR held on file for fixed communal area gas appliances? (Boilers) Comment

Valid LGSR held on file for residential flats that contains gas appliances?

Comment

Are smoke/heat detectors within General Needs flats subject to an annual inspection and the results

Comment

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered to? Comment Adequate security against arson? Comment

Are refuse/recycling bin areas managed and suitably located?

Comment

Are there communal cooking facilities at this scheme?

Comment

Housekeeping

Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items? Comment

Are unnecessary accumulations of combustible materials or waste avoided?

Yes

No

New build and certification uploaded to Active H and M files. No gas appliances in the communal area only to flats.

N/A

Yes

New build all certification uploaded to Active H and M files. Sample of Gas safety for flat 6 checked and dated15/4/2024.

Yes

Gas safety inspection annually.

Yes

Communal areas are designated no smoking and residents are made aware of signage and Accent policy.

Yes

All doors secure at time of inspection tion front and rear access.

Yes

No

Yes

This is not a scheme general needs block.

No

MIS-AMS ActiveH - Fire Risk Assessment Report

Asset ID: 34800 6 Eastwick Close, Bedford

Comment

Are combustible materials and substances separated from ignition sources and stored appropriately?

Comment

Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations?

Comment

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Comment

A very new build and all areas clean and tidy.

N/A

N/A

Yes

This is a New build scheme built in 2023 on further investigation 2024 it was found that the Development team had not designated the 2 blocks as having communal areas.So in july 2024 a New FRA completed.

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of escape in case of fire?

Comment

Escape routes unobstructed and safe to use?

Comment

Exits immediately openable without a key and/or failsafe's function correctly?

Comment

Reasonable distances of travel where there is a single/alternative direction of travel?

Comment

Escape routes lead to final exits and open in direction of escape where necessary?

Comment

Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard? Yes
Comment
Is there reasonable limitation of surface finishes that might promote fire Yes
spread (walls, floors, ceilings)?

Yes

All flats lead into a protected staircase communal area, the travel distance from the flat entrance door of the furthest room is less than 9 mtrs.

Yes

Clear corridor policy exists and residents are reminded.

Yes

Safe egress all doors open on direction of travel and provided with Emergency release.

Yes

Travel distance from flat entrance door to the door of the furthest habital room is within 9 mtrs.

Yes

6 Eastwick Close, Bedford

Comment

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products? Comment

As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard? Comment

Loft hatches fire resisting?

Comment

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?

Comment

Do external walls, doors, windows and anything attached to the exterior, limit fire spread?

Comment

If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?

Comment

Are roller shutter doors that are required to be FR, fire resisting and self-closing?

Comment

Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per current standards?

Comment

Emergency lighting units in good condition and securely fixed to walls/ceilings?

Comment

Records of monthly/annual testing available?

Comment

The surface linings wil not enable fire spread the stairs and hallways meet classification C-s3,d2.

No

Yes

The compartment walls are continued through the roof space to the underside of the roof. Yes

N/A

Yes

The external walls doors and windows will not propagate fire spread around the envelope of the building.A fire is not expected to occupy more than one fire compartment at anyone time.

Yes

New build all certificates have been uploaded to active H and M files. N/A

Yes

Certification uploaded to Active H and M files and meets BS5266-1 and BS EN1838.

Yes

New build all secure.

Yes

New build all certification uploaded to Active H and M files. Annual and monthly test regime will be in place.

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?

Yes

MIS-AMS ActiveH - Fire Risk Assessment Report

Asset ID: 34800 6 Eastwick CI

Commont

6 Eastwick Close, Bedford

Yes
Signage is provided above each fire exit and on other floors the direction of travel all signs in accordance with BS5499-4.
N/A
N/A

Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?	No
Comment	AOV operates via smoke detection in the
	protetected staircase.

No

Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations	No
provided at this scheme?	
Comment	

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under	
the Building Safety Act?	

Comment

Are there other Responsible Persons who share or have fire safety duties in respect of the premises?

Have all details required by regulations been shared with all other Responsible Persons?

Comment

Have all details required by regulations to be shared with us from other Responsible Persons been received and recorded?

Comment

Will this FRA be shared will all other Responsible Persons for the premises?

Comment

How will this sharing be achieved?

Is an office or IL scheme being inspected?

Comment

Asset ID: 34800 6 Eastwick Close, Bedford

IL Schemes & Regional Offices - Are there sufficient numbers of qualified Fire wardens? Comment

Offices - Are there suitable arrangements for ensuring the premises are evacuated?

Comment

Offices - Are there suitable arrangements for evacuating disabled people?

Comment

Offices - Suitable arrangements for meeting the fire service on arrival and proving relevant information?

Comment

Offices/IL Schemes - Is there a suitable assembly point?

Comment

Offices - Are fire drills carried out at appropriate intervals?

Comment

Passenger Lift

Is the scheme fitted with a passenger lift?	No
Comment	

Premises Inspection Box

Is there a premises information box for fire & rescue service use? No
Comment

Evacuation Policy

Are there suitable arrangements for summoning the fire service?

Comment

Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance? Comment

Engagement with Residents

Has information of fire procedures been disseminated to residents?

Yes

Yes

Yes

event of a fire.

Residents call the fire and rescue service in the

Asset ID: 34800	6 Eastwick Close, Bedford	
Comment		When residents move into the flats they are given fire safety advice and also leaflets and a link into the website to look at the FRA the details will be shared and communicated on request fire safety officers will offer support.
Is general fire safety informat	ion disseminated to residents?	Yes
Comment		Leaflets are distributed to the residents on current themes and fire safety campaigns through the website.
FRA Frequency		
Taking the findings of this ass the FRA correct?	sessment into account, is the frequency of	Yes
Comment		

Are there any other observations/actions to raise that are not covered above. No Are there fire related remedial works required at this property, that will affect the fabric of the building? No Comment Were there any unsatisfactory aspects of the Fire Risk Assessment? No (Visible on Building Safety Report). No No

Miscellaneous

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

	HIGH
--	------

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR	MAJOR	X	CRITICAL	

The definition of the above terms is as follows: *FRA Review Frequency*

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).	
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.	
CRITICAL	There is significant potential for serious injury or death of one or more occupants.	

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	intolerable

When the level of risk is established, the action level can be read from the table below:

6 Eastwick Close, Bedford

Risk Level	Guide to actions and appropriate timescales	
Trivial	No action is required	
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.	
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.	
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.	

The Overall Risk Level for this asset is:	Trivial