Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 1028 28A - 32A Cambridge Road, Cambridge

Cover Sheet

Photo

Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

31 May 2023

31 May 2026

36

3 year Re-Assessment

Type 3 (Common Parts and Flats - Non Destructive)

Lynn.betteridge@accentgroup.org

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name Fulbourn

Scheme Address 28A - 32A Cambridge Road, Cambridge

Postcode CB21 5HQ

Region

Scheme Manager

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority Cambridgeshire Fire and Rescue Service

Other staff in attendance None

Number of on-site Accent staff None

Number of other (non-Accent) staff

The Building

Accommodation Type General Needs (S30)

Build Date Dec 6 2010

Number Of Homes 5

Homes breakdown Flat

External wall construction Facing Brick

External wall finish Facing Brick, Paint Render, Timber Clad

Roof construction Timber

Roof covering Interlocking Pitched

PEEPs in place where necessary No

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

Number of External Staircases None

External Balcony part of escape route? N/A

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

28A - 32A Cambridge Road, Cambridge Asset ID: 1028 Fire Detection and Warning System Flats and common areas not linked Grade D Grade of fire alarm Category of fire alarm LD3 Minimum Protection **Emergency Lighting Provision** Non Maintained System - Common Areas Portable Fire Extinguishers supplied/fitted No Fixed Fire Fighting Installations No **Customers** 14 Number of occupants General Needs, Intermediate Occupant tenure type breakdown Fire Safety Related Customer Safety Servicing Overdue communal gas safety checks 0 0 Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 Overdue communal PAT testing 0 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests 1 Overdue Annual Emergency Lighting tests 1 0 Overdue Weekly Fire Alarm Testing Overdue Fire Panel - Six Monthly Testing Overdue Fire Safety Equipment tests 1 **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors Communal Fire doors due for replacement within 5 years 0 **Dwelling Doors**

Dwelling Fire doors due for replacement within 5 years

Failing Dwelling Fire Doors

0

0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



Date of Fire Risk Assessment 31/05/2023

FRA Frequency (Months) 36

Purpose of Fire Risk Assessment 3 year Re-Assessment

Type of Risk Assessment

Type 3 (Common Parts and Flats - Non Destructive)

Quantity

Fire & Safety Assessor Lynn.betteridge@accentgroup.org

Enforcing Fire Authority Cambridgeshire Fire and Rescue Service

Scheme Tel. No

Other staff in attendance None

Number of on-site Accent staff

None

Number of other (non-Accent) staff

Scheme Inspection completed Yes

Number of occupants 14

Personal Emergency Evacuation Plans in place No

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of Storeys 3

Number of floors on which car parking is provided 0

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

Number of external staircases None

External balcony part of escape route? N/A

Unusual features None

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Residential

Fire Detection and Warning System Flats and common areas not linked

Grade of Fire Alarm Grade D

Category of Fire Alarm LD3 Minimum Protection

Emergency Lighting Provision Non Maintained System - Common Areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted No

Water Extinguisher(s) present No

Foam Extinguisher(s) present No

Dry Powder Extinguisher(s) present No

Carbon Dioxide Extinguisher(s) present No

Fire Blanket(s) present

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present No

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present

Yes

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no

obvious damage?

Comment All fixtures and fittings within the communal area are

in good condition

Yes

Yes

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment The electrical report dated to 15th of the seventh

2022 is recorded and held on active h

Electrical App/PA Testing - tested within past 12 months?

N/A

Comment

Absence of trailing leads and adapters? Yes

Comment

Evidence that mobility scooters are not being stored/charged in N/A

common areas?

Comment

28A - 32A Cambridge Road, Cambridge Asset ID: 1028 N/A Is there a purpose built mobility scooter store/charging area? Comment Does the building have a lightning protection system? No Comment Gas installations Yes Is there a commercial/domestic gas supply to the scheme? Comment Yes Valid LGSR held on file for fixed communal area gas appliances? (Boilers) Comment There is no gas supply to the communal areas but each residence flat as a gas safety certificate dated the 30th of the fifth 2023 Yes Valid LGSR held on file for residential flats that contains gas appliances? Comment Yes Are smoke/heat detectors within General Needs flats subject to an annual inspection and the results Comment Gas safety testing of detectors dated 8/5/23 Other Sources of Ignition Is there a no smoking policy in place, which is enforced and adhered Yes Comment Adequate security against arson? Yes Comment On the Dave inspection the block was found to be secure at the front entrance and the rear entrance and only access was by the trade opening. Yes Are refuse/recycling bin areas managed and suitably located? Comment N/A Are there communal cooking facilities at this scheme? General Needs Block. Comment N/A Are reasonable measures taken to prevent fires as a result of cooking? Comment N/A Where there is extraction in communal kitchens, are filters and ductwork changed/cleaned regularly?

Comment

28A - 32A Cambridge Road, Cambridge Asset ID: 1028

Housekeeping

Are all electrical/intake/service cupboards secure and free from general

waste, contractors waste and and residents personal items?

Are unnecessary accumulations of combustible materials or waste

avoided?

Comment

Comment

Comment No flytipping or build up of combustables

Are combustible materials and substances separated from ignition

sources and stored appropriately?

Furniture/furnishings in good condition, fire retardant/resistant and

comply with modern standards and regulations?

Comment General needs block wall finishes plastered.

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Comment

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of escape in case of fire?

Comment

Escape routes unobstructed and safe to use?

Exits immediately openable without a key and/or failsafe's function

correctly? Comment

Comment

Reasonable distances of travel where there is a single/alternative

direction of travel?

Escape routes lead to final exits and open in direction of escape where

necessary?

Comment

Comment

Yes

Generally all locked a few accessed and clear.

Yes

Yes

Yes

Yes

A single communal staircase with 2 exits front and

rear to safe Air.

Yes

Exit signs in place and no obstructions on day of

inspection.

Yes

Exit doors tested for opening.

Yes

Two final exits to safe Air.

Yes

Observation Priority Referred To Required By: Task ID

Door security works.

No Action



Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?

Comment

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?

Comment

As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?

Comment

Loft hatches fire resisting?

Comment

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?

Comment

Do external walls, doors, windows and anything attached to the exterior, limit fire spread?

Comment

If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?

Comment

Are roller shutter doors that are required to be FR, fire resisting and self-closing?

Yes

Yes

Block walls finished in plaster good standard will not promote fire spread.

N/A

Yes

Loft accessed and roof compartmentation meets approved Doc B32.8

Yes

1 hrs fire resisting steel

N/A

Yes

Generally the external walls doors and windows will not propagate fire spread around the envelope put a building but I note there is some external cladding less than 18th of the building frontage that I'm unsure of its flammability.

Yes

Tunstalls the main contractor tested 1/8/2022. Details uploaded to Active"H".

N/A

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 8 of 13

Generated 01/06/2023 16:01:35

28A - 32A Cambridge Road, Cambridge Asset ID: 1028

Comment

Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per

current standards?

Comment

Emergency lighting units in good condition and securely fixed to

walls/ceilings?

Comment

Records of monthly/annual testing available?

Comment Tunstalls the main contractor tests EML records

show last tests recorded on Active H as annual

28/52022 and monthly 8/5/2023.

Yes

Yes

Yes

Yes

Yes

N/A

N/A

No

No

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent

locations within the common areas?

Comment

Directional fire escape signage in place and adequate?

Comment

Is there suitable LIFT signage i.e. do not use in case of fire?

Comment

Do common area fire doors display the correct signage on both sides

where applicable?

Comment No communal doors on this scheme.

Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?

Comment

Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations

provided at this scheme?

Comment

Note there are store cupboard denoted as Dry Riser

on each floor which have no Riser I intend to remove

signage to keep locked.

Management of Fire Safety

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 9 of 13

Generated 01/06/2023 16:01:35

Are these premises regulated by the Building Safety Regulator under

the Building Safety Act?

This scheme 3 floors only so not in scope.

Will this FRA be shared will all Accountable Persons for the premises?

Yes

Yes

Comment

Comment

How will this sharing be achieved?

The FRA will be held on our Recording system "M"

files so access to all.

Are there other Responsible Persons who share or have fire safety

duties in respect of the premises? How will this sharing be achieved? No

Is an office or IL scheme being inspected?

Comment

No

Passenger Lift

Is the scheme fitted with a passenger lift?

No

Comment

Premises Inspection Box

Is there a premises information box for fire & rescue service use?

No

Comment

Comment

Evacuation Policy

Are there suitable arrangements for summoning the fire service?

Yes

Taking FRA findings, is the evacuation policy appropriate for the

scheme as per latest guidance?

Residents have a responsibility to contact the Fire Service.

Yes

Comment Stay put policy.

Engagement with Residents

Has information of fire procedures been disseminated to residents?

Yes

Comment

Is general fire safety information disseminated to residents?

Yes

Comment

When residents move into their property they are given fire safety advice and information they can also access the organisation website for further

information.

FRA Frequency

Taking the findings of this assessment into account, is the frequency of the FRA correct?

Comment

Yes

Miscellaneous

Are there any other observations/actions to raise that are not covered above.

Are there fire related remedial works required at this property, that will affect the fabric of the building?

Can work be conducted without the need for an asbestos survey. If no,

Can work be conducted without the need for an asbestos survey. If no task Customer Safety Surveyor - Asbestos.

Comment

Comment

Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).

No

Yes

Contractor is carrying out remedial work to main and

rear access security doors.

N/A

No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

systems.					
_		evention measures observention measures observention the fire (t			
LOW	X	MEDIUM	нідн		
any procedural	arrangements ob	of the building, the occup served at the time of the a e event of a fire would be:	ssessment, it is consider		
MINOR		MAJOR X	CRITICAL		

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales	
Trivial	No action is required	
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.	
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.	
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.	

The Overall Risk Level for this asset is:	Trivial
	<u> </u>