

This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 33965 Trident House Falcon Court, Stockton on Tees

Cover Sheet

Photo

Date of Fire Risk Assessment Date of Next Fire Risk Assessment FRA Frequency (Months) Purpose of Fire Risk Assessment Type of Fire Risk Assessment Fire & Safety Assessor



06 Nov 2024 06 Nov 2025 12 Annual Re-Assessment Type 1 (Common Parts Only - Non Destructive) Kevin Jones

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name	
Scheme Address	Trident House Falcon Court, Stockton on Tees
Postcode	TS18 3TX
Region	North East
Scheme Manager	
Scheme Tel. No	
Scheme Inspection Completed	Yes
Enforcing Fire Authority	Cleveland
Other staff in attendance	None
Number of on-site Accent staff	Scheme Manager Weekdays
Number of other (non-Accent) staff	Contract Cleaners in common areas

The Building

Accommodation Type	Middlesborough Office (L40)
Build Date	Nov 25 2019
Number Of Homes	0
Homes breakdown	
External wall construction	
External wall finish	
Roof construction	
Roof covering	
PEEPs in place where necessary	N/A
Current Evacuation Strategy	Full (Simultaneous) Evacuation
Conversion or purpose-built	Purpose Built
Number of storeys	1
Number of floors on which car parking is provided	1
Is there a habitable basement?	No
Number of internal Staircases (protected or unprotected?)	none
Number of External Staircases	None
External Balcony part of escape route?	No
Unusual features	None
Building Access Conditions for Fire Brigade	Vehicular Access to one or more elevations

Fire Detection and Warning System	Common areas only
Grade of fire alarm	Grade A
Category of fire alarm	LD1 Maximum Protection
Emergency Lighting Provision	Mixed system - Common areas
Portable Fire Extinguishers supplied/fitted	Yes
Fixed Fire Fighting Installations	No

Customers

Number of occupants	20
Occupant tenure type breakdown	

Fire Safety Related Customer Safety Servicing

Overdue communal gas safety checks	0
Overdue domestic gas safety checks	0
Overdue communal electrical condition checks	0
Overdue domestic electrical condition checks	0
Overdue alarm call pull chord tests	0
Overdue communal PAT testing	0
Overdue customer mobility scooter PAT testing	0
Overdue Monthly Emergency Lighting Switch Tests	0
Overdue Annual Emergency Lighting tests	0
Overdue Weekly Fire Alarm Testing	0
Overdue Fire Panel - Six Monthly Testing	
Overdue Fire Safety Equipment tests	1

Building Fire Safety Surveys - Communal Doors

Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	0

Dwelling Doors

Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo

Date of Fire Risk Assessment	06/11/2024
FRA Frequency (Months)	12
Purpose of Fire Risk Assessment	Annual Re-Assessment
Type of Risk Assessment	Type 1 (Common Parts Only - Non Destructive)
Quantity	1
Fire & Safety Assessor	Kevin Jones
Enforcing Fire Authority	Cleveland
Scheme Tel. No	
Other staff in attendance	None
Number of on-site Accent staff	Scheme Manager Weekdays
Number of other (non-Accent) staff	Contract Cleaners in common areas
Scheme Inspection completed	Yes
Number of occupants	20
Personal Emergency Evacuation Plans in place	N/A
Current Evacuation Strategy	Full (Simultaneous) Evacuation
Conversion or purpose-built	Purpose Built
Number of Storeys	1
Number of floors on which car parking is provided	1
Is there a habitable basement?	No
No. of internal staircases (protected/unprotected)	none
Number of external staircases	None
External balcony part of escape route?	No
Unusual features	None



Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade	Vehicular Access to one or more elevations
Surroundings: Residential/Commercial	Light Commercial
Fire Detection and Warning System	Common areas only
Grade of Fire Alarm	Grade A
Category of Fire Alarm	LD1 Maximum Protection
Emergency Lighting Provision	Mixed system - Common areas
Portable Fire Extinguishers / Fire Blankets supplied / fitted	Yes
Water Extinguisher(s) present	Yes
Foam Extinguisher(s) present	No
Dry Powder Extinguisher(s) present	No
Carbon Dioxide Extinguisher(s) present	Yes
Fire Blanket(s) present	Yes
Fixed Fire Fighting Installations supplied / fitted	No
Dry Riser(s) present	No
Wet Riser(s) present	No
Sprinkler System present	No
Hosereel(s) present	No
Automatic Opening Vent(s) present	No

Electrical Sources of Ignition

Electrical installation within common areas in good condit obvious damage?	ion and no	Yes
Comment		Appears to be in good condition and secure
Valid Electrical Installation Condition Reports held on file? Areas & General Needs Flats)	? (Common	Yes
Comment		Landlord responsable for testing records held in site office.
Electrical App/PA Testing - tested within past 12 months?		Yes
Comment		Certification in date
Absence of trailing leads and adapters?		Yes
Comment		Good houskeeping identified in office spaces
Evidence that mobility scooters are not being stored/charg common areas?	ged in	No
Comment		N/A
Is there a purpose built mobility scooter store/charging are	ea?	No
MIS-AMS ActiveH - Fire Risk Assessment Report	Page 5 of 14	Generated 07/11/2024 16:02:20

Comment

Does the building have a lightning protection system?

Comment

Gas installations

Is there a commercial/domestic gas supply to the scheme?	Yes
Comment	Supply for the eating boilers
Valid LGSR held on file for fixed communal area gas appliances? (Boilers)	Yes
Comment	Landlord hold all records
Valid LGSR held on file for residential flats that contains gas appliances?	N/A
Comment	None residential premis
Are smoke/heat detectors within General Needs flats subject to an annual inspection and the results	N/A
Comment	None residential premis

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered to?	Yes
Comment	No smoking in the office
Adequate security against arson?	Yes
Comment	Swipe card entrance and exit
Are refuse/recycling bin areas managed and suitably located?	Yes
Comment	Designated refuse storage area
Are there communal cooking facilities at this scheme?	No
Comment	Small sink area with microwave for warming foods

Housekeeping

Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items? Comment

Are unnecessary accumulations of combustible materials or waste avoided?

Comment

No

No

Electrical intake cupboards have stored combustable materials , box etc email sent 06/11/2024 to office maanger to manage Yes

Office supplies stored in office limited to essential paperwork amounts

Asset ID:	33965	Trident House Falcon Court, Stockton on	Tees
	ible materials and stored appropriate	substances separated from ignition ely?	Yes
	nishings in good c modern standards	ondition, fire retardant/resistant and and regulations?	Yes
Comment			Sample inspection carried out and complies to standards
Other Sig	nificant Fire	Hazards	
Are all other	significant fire haz	zards adequately controlled?	Yes
Comment			
Means of	Escape from	Fire	
ls it consider escape in ca		g is provided with reasonable means of	Yes
Comment			Two directional escape routes on ground floor
Escape route	es unobstructed a	nd safe to use?	Yes
Comment			Clear designated escape routes
Exits immed correctly?	iately openable wi	thout a key and/or failsafe's function	Yes
Comment			Card swipe exit from both escape routes break glass opening operation
Reasonable direction of t		I where there is a single/alternative	Yes
Comment			Travel distances within correct standards
Escape route necessary?	es lead to final exi	ts and open in direction of escape where	Yes
Comment			
Fire Spre	ad and Devel	opment	
Is it consider	ed that the compa	artmentation is of a reasonable standard?	Yes
Comment			Purpose build office area
la thora road	anable limitation of	f ourface finishes that might promote fire	Vec

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)? Comment

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products? Comment

As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?

Purpose build office area Yes Plaster finished walls and susspended ceilings N/A None provided

N/A

Asset ID: 33965 Trident House Falcon Co	ourt, Stockton	on Tees		
Comment		Ground floor office only		
Loft hatches fire resisting?		N/A		
Comment				
As far as can be reasonably ascertained, is the fire stopping a cross corridor fire doors within suspended ceiling void of a sat standard?		Yes		
Comment		Construction of cross cori brick/block work	dor doors surround	is
Do external walls, doors, windows and anything attached to th exterior, limit fire spread?	е	Yes		
Comment		Traditional construction of concrete floors	f brick and morter w	vith
If Smoke Control Systems (AOV's) are fitted, are the records on testing available?	of annual	N/A		
Comment		None fitted		
Are roller shutter doors that are required to be FR, fire resisting self-closing?	g and	N/A		
Comment		none fitted		
Observation	Priority	Referred To	Required By:	Task ID
Combustable materials in Electrical/gas intake	Internal - Med	ium		

Combustable materials in Electrical/gas intake cupboards



Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per current standards?	Yes
Comment	Appers to be installed to the correct standards
Emergency lighting units in good condition and securely fixed to walls/ceilings?	Yes
Comment	Alk appears to be in good condition and secured
Records of monthly/annual testing available?	Yes
Comment	Landlord hold records

Fire Safety Signs and Notices

~~~~ ч Ц. Trid

Asset ID: 33965 Irident House Falcon Court, Stockton on	lees
Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas? Comment	Yes
Directional fire escape signage in place and adequate?	Yes
Comment	
Is there suitable LIFT signage i.e. do not use in case of fire?	Yes
Comment	Lift in communal area covered by landlords FRA
Do common area fire doors display the correct signage on both sides where applicable? Comment	Yes
Means of giving Warning in case of Fire	
Is the scheme fitted with a communal area fire alarm?	Yes
Comment	
Is fire detection and warning system appropriate for occupancy and fire risk, as per BS 5839-1:2017? Comment	Yes
Is the fire detection and warning system maintained/tested and all certificates saved on file?	Yes
Comment	Landlord carries out all testing
Fire alarm components in good condition and securely fixed to walls/ceilings?	Yes
Comment	All appears to be in good condition and secured
Hold open devices operate at the sounding of the alarm and are in a serviceable condition?	N/A
Comment	None provided
Are there heat detectors located in the Kitchen, Boiler, Plant Room and Laundry?	Yes
Comment	Next to small kitchenette
Is the fire alarm panel remotely monitored, and if so are there records of regular testing?	N/A
	Not remotly monitored , testing periodically crried out by landlord

Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme?	Yes	
Comment		
Portable fire extinguishers - appropriate type/number/position?	Yes	
Comment		

Correct signage displayed by each fire extinguisher?	Yes
Comment	
Fire blanket in communal kitchen, secured to the wall, complete with signage?	Yes
Comment	
Dry risers - Inlet/outlet boxes secured and/or securing straps fitted to outlet valves?	N/A
Comment	
Records available of fire fighting equipment servicing within past 12 months?	Yes
Comment	Cerification up to date

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under the Building Safety Act?	No
Comment	
Are there other Responsible Persons who share or have fire safety duties in respect of the premises?	No
How will this sharing be achieved?	
Is an office or IL scheme being inspected?	Yes
Comment	
IL Schemes & Regional Offices - Are there sufficient numbers of qualified Fire wardens?	N/A
Comment	Due to Hybrid working no fire wardens have been identified all Accent staff carryout periodic fire safety training
Offices - Are there suitable arrangements for ensuring the premises are evacuated?	Yes
Comment	Training provided 6 monthly on office safety signage displayed in office
Offices - Are there suitable arrangements for evacuating disabled people?	Yes
Comment	
Offices - Suitable arrangements for meeting the fire service on arrival and proving relevant information?	Yes
Comment	Staff training and awareness provided 6 monthly
Offices/IL Schemes - Is there a suitable assembly point?	Yes
Comment	Car park to the front of building
Offices - Are fire drills carried out at appropriate intervals?	Yes
Comment	During training

Passenger Lift

Is the scheme fitted with a passenger lift?	Yes
Comment	Lift in communal entrance under the responsability of the landlords FRA
Is the lift in full working order at the time of the FRA?	No
Comment	
Is the lift fitted with a firefighters switch?	No
Comment	
Servicing and insurance inspection - Evidence of regular servicing/maintenance?	Yes
Comment	Landlord is responsable for the lift inspection records
Premises Inspection Box	
Is there a premises information box for fire & rescue service use?	No
Comment	
Evacuation Policy	
Are there suitable arrangements for summoning the fire service?	Yes
Comment	999 call from occupants
Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance?	Yes
Comment	
Engagement with Residents	
Has information of fire procedures been disseminated to residents?	Yes
Comment	Training and awareness essions provided periodcally
Is general fire safety information disseminated to residents?	Yes
Comment	
FRA Frequency	
Taking the findings of this assessment into account, is the frequency of the FRA correct?	Yes
Comment	

Miscellaneous

Are there any other observations/actions to raise that are not covered above.	No
Are there fire related remedial works required at this property, that will affect the fabric of the building?	No
Comment	
Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).	Yes
Some fire doors did not fully close so works orders have been raised with our contractors.	No
Some minor works were required which have been raised with our contractors.	No
Unauthorised items were found in communal areas and arrangements were made for their removal.	Yes
Not all records were up to date, as noted in the table below. Arrangements have been made for these to be completed.	No
A number of fire doors were found to be wedged or propped open . Fire doors are there to keep you safe and me kept shut at all times.	No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW	X	MEDIUM	нідн		
-----	---	--------	------	--	--

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR	MAJOR	X	CRITICAL	

The definition of the above terms is as follows: *FRA Review Frequency*

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	intolerable

When the level of risk is established, the action level can be read from the table below:

Asset ID: 33965

Trident House Falcon Court, Stockton on Tees

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial	