# Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 8779 98-120 Ryedale Way Block 98-120 Ryedale Way, Bradford

#### **Cover Sheet**

Photo

Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

24 Oct 2023

24 Oct 2026

36

3 year Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Steven Manners

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

#### The Scheme

Scheme Name Ryedale Way

Scheme Address 98-120 Ryedale Way Block 98-120 Ryedale Way,

Bradford

Postcode BD15 9AU

Region Yorkshire

Scheme Manager

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority West Yorkshire

Other staff in attendance None

Number of on-site Accent staff

None

Number of other (non-Accent) staff

Contract Cleaners in common areas

#### The Building

Accommodation Type General Needs (S30)

Build Date Jan 1 1971

Number Of Homes 12

Homes breakdown Flat

External wall construction Facing Brick

External wall finish Facing Brick, Hung Tiles

Roof construction Timber

Roof covering Flat Roof, Interlocking Pitched

PEEPs in place where necessary N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys 3

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

1 protected

Number of External Staircases None

External Balcony part of escape route?

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

# 98-120 Ryedale Way Block 98-120 Ryedale Way, Bradford Asset ID: 8779 Fire Detection and Warning System Flats and common areas not linked Grade D Grade of fire alarm Category of fire alarm LD3 Minimum Protection Mixed system - Common areas **Emergency Lighting Provision** Portable Fire Extinguishers supplied/fitted No Fixed Fire Fighting Installations No **Customers** 20 Number of occupants General Needs, Leasehold Occupant tenure type breakdown Fire Safety Related Customer Safety Servicing Overdue communal gas safety checks 0 0 Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 Overdue communal PAT testing 0 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests 1 Overdue Annual Emergency Lighting tests 1 1 Overdue Weekly Fire Alarm Testing Overdue Fire Panel - Six Monthly Testing 1 Overdue Fire Safety Equipment tests **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors Communal Fire doors due for replacement within 5 years 0

Dwelling Fire doors due for replacement within 5 years

**Dwelling Doors** 

Failing Dwelling Fire Doors

0

0

# Fire Risk Assessment Survey Results

### **Scheme and Building Information**

Photo



Date of Fire Risk Assessment 24/10/2023

FRA Frequency (Months) 36

Purpose of Fire Risk Assessment 3 year Re-Assessment

Type of Risk Assessment

Type 1 (Common Parts Only - Non Destructive)

Quantity

Fire & Safety Assessor Steven Manners

Enforcing Fire Authority West Yorkshire

Scheme Tel. No

Other staff in attendance None

Number of on-site Accent staff

None

Number of other (non-Accent) staff

Contract Cleaners in common areas

Scheme Inspection completed Yes

Number of occupants 20

Personal Emergency Evacuation Plans in place N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of Storeys 3

Number of floors on which car parking is provided 0

Is there a habitable basement?

No. of internal staircases (protected/unprotected) 1 protected

Number of external staircases None

External balcony part of escape route?

Unusual features None

# Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Residential

Fire Detection and Warning System Flats and common areas not linked

Grade of Fire Alarm Grade D

Category of Fire Alarm LD3 Minimum Protection

Emergency Lighting Provision Mixed system - Common areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted No

Water Extinguisher(s) present

Foam Extinguisher(s) present

Dry Powder Extinguisher(s) present

Carbon Dioxide Extinguisher(s) present

Fire Blanket(s) present

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present No

#### **Electrical Sources of Ignition**

Electrical installation within common areas in good condition and no

obvious damage?

Comment All in good condition at the time of inspection

Yes

Yes

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment All records are available on ActiveH

Electrical App/PA Testing - tested within past 12 months?

N/A

Comment No leads in communal areas

Absence of trailing leads and adapters? Yes

Comment As above

Evidence that mobility scooters are not being stored/charged in Yes

common areas?

Comment None present at the scheme

Is there a purpose built mobility scooter store/charging area?

N/A

98-120 Ryedale Way Block 98-120 Ryedale Way, Bradford Asset ID: 8779

Not required Comment

Does the building have a lightning protection system? No

Comment

Gas installations

Is there a commercial/domestic gas supply to the scheme? Yes

Comment Gas supply to most residents

Valid LGSR held on file for fixed communal area gas appliances? Yes

(Boilers)

Tested annually, all records are available on ActiveH Comment

Yes Valid LGSR held on file for residential flats that contains gas

appliances?

Comment As above

Yes Are smoke/heat detectors within General Needs flats subject to an

annual inspection and the results

Comment Tested when gas certificate issued

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered Yes

to?

Comment No smoking allowed in the communal areas but

smoking is allowed in residents flats

Adequate security against arson?

Buzz in system at main entrance Comment

Are refuse/recycling bin areas managed and suitably located?

Comment Stored away from the building

Are there communal cooking facilities at this scheme? No

Comment

Housekeeping

Are all electrical/intake/service cupboards secure and free from general

waste, contractors waste and and residents personal items?

All clear at the time of inspection Comment

Are unnecessary accumulations of combustible materials or waste

avoided?

Comment None found at the time of inspection

Are combustible materials and substances separated from ignition

sources and stored appropriately?

Yes

Yes

N/A

98-120 Ryedale Way Block 98-120 Ryedale Way, Bradford Asset ID: 8779

Comment None found at the time of inspection

Furniture/furnishings in good condition, fire retardant/resistant and

comply with modern standards and regulations?

Comment No furniture allowed in the communal areas

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled? Yes

Comment

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of

escape in case of fire?

Comment One protected staircase, communal lobby at each

floor

Yes

Yes

Yes

Yes

N/A

Yes Escape routes unobstructed and safe to use?

Comment All clear at the time of inspection

Exits immediately openable without a key and/or failsafe's function

correctly? Comment

Reasonable distances of travel where there is a single/alternative

direction of travel?

Comment Distance of travel is within the guidelines

Escape routes lead to final exits and open in direction of escape where

necessary?

Comment

Comment

Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard? No

Comment One communal Fire door requires adjusting to close

to rebate

Yes

N/A

Is there reasonable limitation of surface finishes that might promote fire

spread (walls, floors, ceilings)?

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?

Comment None fitted

N/A As far as can be reasonably ascertained, is the compartmentation

within roof spaces of a satisfactory standard?

Comment Flat roof

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 7 of 13

Generated 24/10/2023 16:09:03

Loft hatches fire resisting?

Comment As above

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory

standard? Comment

Do external walls, doors, windows and anything attached to the

exterior, limit fire spread?

Comment Brick built construction

If Smoke Control Systems (AOV's) are fitted, are the records of annual

testing available?

Comment None fitted

Are roller shutter doors that are required to be FR, fire resisting and

self-closing?

Comment None fitted

Observation Priority Referred To Required By: Task ID

Adjust communal Fire door leading to flats 114 to 120 to close to rebate. Hinges are loose Order No 1125751



Repair - Non Building Safety Emergency Manager

Yes

Yes

N/A

N/A



#### **Emergency Escape Lighting**

Is the emergency lighting correctly specified and installed as per

current standards?

Comment Maintained system in communal areas

Emergency lighting units in good condition and securely fixed to

walls/ceilings?

Comment All in good condition at the time of inspection

Records of monthly/annual testing available?

Comment All records are available on ActiveH

# **Fire Safety Signs and Notices**

Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?

Yes

Yes

Yes

Comment Notices displayed throughout the building

Directional fire escape signage in place and adequate?

Comment Notices displayed throughout the building

Is there suitable LIFT signage i.e. do not use in case of fire?

Comment None fitted

Do common area fire doors display the correct signage on both sides

where applicable?

Comment All signage in place at the time of inspection

Yes

Yes

Yes

N/A

N/A

No

Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?

Yes

Comment Break glass to a sounder on each level

Is fire detection and warning system appropriate for occupancy and fire

risk, as per BS 5839-1:2017?

Comment Although communal area fire alarm may be removed

at a later date as the scheme is Stay Put

Is the fire detection and warning system maintained/tested and all

certificates saved on file?

Comment All records are available on ActiveH

Fire alarm components in good condition and securely fixed to

Yes

walls/ceilings?

Comment All in good condition at the time of inspection

Hold open devices operate at the sounding of the alarm and are in a

serviceable condition?

Comment None fitted

Are there heat detectors located in the Kitchen, Boiler, Plant Room and

Laundry?

Comment No communal kitchen or boiler room

Is the fire alarm panel remotely monitored, and if so are there records of

regular testing?

Comment None fitted

Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations

provided at this scheme?

Comment

No

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under

the Building Safety Act?

Comment

Will this FRA be shared will all Accountable Persons for the premises?

Comment FRA Will be provided on M files and emailed if

required

No

Yes

Yes

How will this sharing be achieved?

As above

Are there other Responsible Persons who share or have fire safety

duties in respect of the premises? How will this sharing be achieved?

Is an office or IL scheme being inspected?

Comment

Passenger Lift

Is the scheme fitted with a passenger lift?

Comment

**Premises Inspection Box** 

Is there a premises information box for fire & rescue service use?

Comment

**Evacuation Policy** 

Are there suitable arrangements for summoning the fire service?

Comment Residents are instructed to contact the fire service

by dialing 999

Yes

Taking FRA findings, is the evacuation policy appropriate for the

scheme as per latest guidance?

Comment

**Engagement with Residents** 

Has information of fire procedures been disseminated to residents?

Comment On induction, signage displayed throughout the

building, on website and by leaflet

Is general fire safety information disseminated to residents?

Comment As above

#### 98-120 Ryedale Way Block 98-120 Ryedale Way, Bradford Asset ID: 8779

#### FRA Frequency

Taking the findings of this assessment into account, is the frequency of

the FRA correct?

Yes

No

Comment

#### Miscellaneous

Yes Are there any other observations/actions to raise that are not covered

above.

Action leading to a repair Yes

No Internal administrative Action

Are there fire related remedial works required at this property, that will Yes affect the fabric of the building?

Comment

Yes Can work be conducted without the need for an asbestos survey. If no,

task Customer Safety Surveyor - Asbestos.

Comment

Observation

Were there any unsatisfactory aspects of the Fire Risk Assessment? Yes (Visible on Building Safety Report).

Yes Some fire doors did not fully close so works orders have been raised with our contractors.

No Some minor works were required which have been raised with our contractors.

No Unauthorised items were found in communal areas and arrangements were made for their removal.

No Not all records were up to date, as noted in the table below. Arrangements have been made for these to be completed.

A number of fire doors were found to be wedged or propped open. Fire doors are there to keep you safe and me kept shut at all times.

> Referred To Required By: Task ID

Emergency Lighting and evacuation signage throughout the building





**Priority** 

#### **Risk Calculator - Fire**

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW

MEDIUM

HIGH

2. Taking into account the nature of the building, the occupants, the fire protection afforded and

consequences for life safety in the event of a fire would be:									

any procedural arrangements observed at the time of the assessment, it is considered that the

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales	
Trivial	No action is required	
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.	
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.	
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.	

The Overall Risk Level for this asset is:	Trivial
	<u> </u>