Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 33622 Mountbatten Court Parkside Road

Cover Sheet

Photo

Date of Fire Risk Assessment 24 May 2024

Date of Next Fire Risk Assessment 24 May 2027

FRA Frequency (Months)

Purpose of Fire Risk Assessment 3 year Re-Assessment

Type of Fire Risk Assessment

Type 1 (Common Parts Only - Non Destructive)

36

Fire & Safety Assessor Steven Manners

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name Mountbatten Court

Scheme Address Mountbatten Court Parkside Road

Postcode BD5 8EG

Region Yorkshire

Scheme Manager

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority West Yorkshire

Other staff in attendance None

Number of on-site Accent staff None

Number of other (non-Accent) staff

Contract Cleaners in common areas

The Building

Accommodation Type General Needs (S30)

Build Date

Number Of Homes 4

Homes breakdown Flat

External wall construction Facing Brick

External wall finish Facing Brick

Roof construction Timber

Roof covering Interlocking Pitched

PEEPs in place where necessary N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?) 1 Protected

Number of External Staircases None

External Balcony part of escape route?

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

Asset ID: 33622 Flats only Fire Detection and Warning System Grade D Grade of fire alarm Category of fire alarm LD2 Additional Protection **Emergency Lighting Provision** Non Maintained System - Common Areas Portable Fire Extinguishers supplied/fitted No Fixed Fire Fighting Installations No **Customers** 8 Number of occupants General Needs, Sheltered Schemes Occupant tenure type breakdown Fire Safety Related Customer Safety Servicing Overdue communal gas safety checks 0 0 Overdue domestic gas safety checks Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 Overdue communal PAT testing 0 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests Overdue Annual Emergency Lighting tests 1 0 Overdue Weekly Fire Alarm Testing Overdue Fire Panel - Six Monthly Testing Overdue Fire Safety Equipment tests **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors Communal Fire doors due for replacement within 5 years 0 **Dwelling Doors** 0 Failing Dwelling Fire Doors

Mountbatten Court Parkside Road

Dwelling Fire doors due for replacement within 5 years

0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



Date of Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Risk Assessment

Quantity

Fire & Safety Assessor

Enforcing Fire Authority

Scheme Tel. No

Other staff in attendance

Number of on-site Accent staff

Number of other (non-Accent) staff

Scheme Inspection completed

Number of occupants

Personal Emergency Evacuation Plans in place

Current Evacuation Strategy

Conversion or purpose-built

Number of Storeys

Number of floors on which car parking is provided

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

Number of external staircases

External balcony part of escape route?

Unusual features

24/05/2024

36

3 year Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

1

Steven Manners

West Yorkshire

None

None

Contract Cleaners in common areas

Yes

8

N/A

Stay Put (Delayed) Evacuation

Purpose Built

2

0 No

1 Protected

None

No

None

Mountbatten Court Parkside Road Asset ID: 33622

Fire Risk Assessment Survey Results

Vehicular Access to one or more elevations Building access conditions for Fire Brigade

Surroundings: Residential/Commercial Mixed

Flats only Fire Detection and Warning System

Grade D Grade of Fire Alarm

Category of Fire Alarm LD2 Additional Protection

Non Maintained System - Common Areas **Emergency Lighting Provision**

Portable Fire Extinguishers / Fire Blankets supplied / fitted No

Water Extinguisher(s) present No

No Foam Extinguisher(s) present

Dry Powder Extinguisher(s) present No

Carbon Dioxide Extinguisher(s) present No

Fire Blanket(s) present No

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

No Wet Riser(s) present

No Sprinkler System present

No Hosereel(s) present

Automatic Opening Vent(s) present No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no

obvious damage?

Comment

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment

Electrical App/PA Testing - tested within past 12 months?

Comment There is no electrica equipment that requires

testing in the communal area.

All electrical instalations within the common area are in good condition at the time of inspection.

All electrical certificates can be found on ActiveH and in m-Files. All in date at the time of inspection

Absence of trailing leads and adapters?

As Above Comment

Yes Evidence that mobility scooters are not being stored/charged in

common areas?

Comment There are no mobility scooters present at this

Yes

Yes

N/A

Yes

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 5 of 14

Generated 28/05/2024 16:01:11

Is there a purpose built mobility scooter store/charging area?

Comment Not required at this scheme

Does the building have a lightning protection system?

Comment

Gas installations

Is there a commercial/domestic gas supply to the scheme?

Comment There is a gas supply to each individual flat within

the block

No

Valid LGSR held on file for fixed communal area gas appliances?

N/A

(Boilers)

Comment There are no communal area gas appliances in the

block.

Yes

Valid LGSR held on file for residential flats that contains gas

appliances?

Comment all residential flats have an up to date gas certificate

which can be found in ActiveH and M-Files. Tests

completed around June 2023.

Are smoke/heat detectors within General Needs flats subject to an

annual inspection and the results

Comment Smioke detectors are tested at the same time as

the gas tests. these can also be found on ActiveH

and M-files.

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered Yes

to?

Comment There is a no smoking policy within the communal

areas of the building but residents are allowed to

smoke within their flats.

Adequate security against arson?

Comment There is a single entrance to the propeerty which

has a fob entry system.

Are refuse/recycling bin areas managed and suitably located? Yes

Comment The bins are adjacent to the building up against a

brick wall.

Are there communal cooking facilities at this scheme?

Comment None on the scheme

Housekeeping

Are all electrical/intake/service cupboards secure and free from general

waste, contractors waste and and residents personal items?

Yes

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 6 of 14

Generated 28/05/2024 16:01:11

Mountbatten Court Parkside Road Asset ID: 33622

external walls of the entrance and were locked shut

The electric cupboards for each flat are on the

None found at the time of inspection

None found at the time of inspection

at the time of inspection Yes

Yes

N/A

Are unnecessary accumulations of combustible materials or waste

avoided? Comment

Comment

Comment

Are combustible materials and substances separated from ignition

sources and stored appropriately?

Furniture/furnishings in good condition, fire retardant/resistant and

comply with modern standards and regulations?

Comment

Ther are no items of furniture allowed in the communal area. None found at the time of inspection.

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

There were no other significant fire hazards found at Comment

the time of inspection

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of

escape in case of fire?

Escape routes unobstructed and safe to use?

Exits immediately openable without a key and/or failsafe's function

correctly?

Comment

Comment

Comment

Comment

Reasonable distances of travel where there is a single/alternative

direction of travel?

Escape routes lead to final exits and open in direction of escape where

necessary?

Comment

Yes

N/A

There is only one means of escape for this building.

The travel distance is within the acceptable

guidance.

Yes

The escape route was clear at the time of

inspection.

Yes

Yes

As above, distance is within acceptable limits.

Yes

Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

No

Comment

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?

Comment

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?

Comment

As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?

Comment

Loft hatches fire resisting?

Comment

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?

Comment

Do external walls, doors, windows and anything attached to the exterior, limit fire spread?

Comment

If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?

Comment

Are roller shutter doors that are required to be FR, fire resisting and self-closing?

Comment

Observation

The onlyy compartmentation is aforded by flat entrance doors. one flat entrance door did not self close and was damaged. replacement required.

Yes

The walls on the escape route are of brick construction, there are no items on the walls that would promote fire spread.

N/A

None fitted at this scheme.

Yes

There was no access to the roof space as the loft hatch was locked shut at the time of inspection.

No

Although the loft hatch is not a rated fire resisting loft hatch it was close fitting to the frame and would provide some fire protection from a fire. The area beneath the hatch is sterile. no combustable materials present.

N/A

None on the scheme

Yes

THe scheme is of brick construction with no external cladding.

N/A


None fitted at this scheme

No

As Above

Referred To Required By: Task ID


Cleaners Store has wireless router inside. Was locked shut at the time of inspection . Door in good condition



Priority

Observation Priority Referred To Required By: Task ID

No access to the roof space as loft hatch locked shut at the time of inspection



Observation Priority Referred To Required By: Task ID

Flat 16 Self-closing device missing on door and is catching on the frame. There are holes in the door and it has a none conforming handle and lock. Door and frame needs replacing. Door has a letter bo



Repair - Non Project Manager Emergency (Building Safety) 08/07/2024

1820451





Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per current standards?

Comment

Emergency lighting units in good condition and securely fixed to walls/ceilings?

Comment

Records of monthly/annual testing available?

Comment

Yes

Yes

All lighting was in good condition at the time of inspection

Yes

All records are available on ActiveH and certificates can be found on ActiveH and M-Files.

Annual test:- 23/01/2024

Monthly test :- 13/05/2024

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?

Yes

Mountbatten Court Parkside Road Asset ID: 33622 Comment Yes Directional fire escape signage in place and adequate? Comment Only one direction of travel from the building. N/A Is there suitable LIFT signage i.e. do not use in case of fire? No Lift at this scheme Comment N/A Do common area fire doors display the correct signage on both sides where applicable? Comment There are no communal fire doors on this scheme, gas and electric cupboards are external. Means of giving Warning in case of Fire Is the scheme fitted with a communal area fire alarm? No Comment This scheme has a stay put policy. fire detection is within the individual flats. Fire Extinguishing Equipment No Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme? Not required at this scheme. Comment Management of Fire Safety No Are these premises regulated by the Building Safety Regulator under the Building Safety Act? Comment Does not fit the criteria Are there other Responsible Persons who share or have fire safety No duties in respect of the premises? How will this sharing be achieved? Is an office or IL scheme being inspected? No Comment Passenger Lift No Is the scheme fitted with a passenger lift? Comment

Is there a premises information box for fire & rescue service use?

Premises Inspection Box

No

Mountbatten Court Parkside Road Asset ID: 33622

Comment Not required at this scheme.

Evacuation Policy

Are there suitable arrangements for summoning the fire service? Yes

residents are advised to dial 999 in the event of fire Comment

within their flats.

Yes

Taking FRA findings, is the evacuation policy appropriate for the

scheme as per latest guidance?

Comment This is a purpose built block of flats.

Engagement with Residents

Yes Has information of fire procedures been disseminated to residents?

Comment A letter and leaflets have been distributed to all

residents within the block regarding Fire safety and

Fire doors.

Yes

Yes Is general fire safety information disseminated to residents?

As above Comment

FRA Frequency

Taking the findings of this assessment into account, is the frequency of

the FRA correct?

Comment This is a low risk building, the communal area was

clear at the time of inspection.

Miscellaneous

Yes Are there any other observations/actions to raise that are not covered

above.

Yes Action leading to a repair

No Internal administrative Action

Are there fire related remedial works required at this property, that will No

affect the fabric of the building?

Comment A flat front door needs replacing to keep the

integraty of the compartmentation.

Were there any unsatisfactory aspects of the Fire Risk Assessment?

(Visible on Building Safety Report).

Some fire doors did not fully close so works orders have been raised

with our contractors.

Some minor works were required which have been raised with our

contractors.

Unauthorised items were found in communal areas and arrangements

were made for their removal.

No

Yes

Yes

No

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 11 of 14

Generated 28/05/2024 16:01:11

Not all records were up to date, as noted in the table below.

Arrangements have been made for these to be completed.

A number of fire doors were found to be wedged or propped open. Fire doors are there to keep you safe and me kept shut at all times.

No

No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

systems.				
_		evention measures observention measures observention the fire (t		
LOW	X	MEDIUM	нідн	
any procedural	arrangements ob	of the building, the occup served at the time of the a e event of a fire would be:	ssessment, it is consider	
MINOR		MAJOR X	CRITICAL	

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales	
Trivial	No action is required	
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.	
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.	
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.	

ne Overall Risk Level for this asset is:	Trivial
ne Overali Risk Level for this asset is:	