Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 5955 Shirley Manor Gardens, Bradford

Cover Sheet

Photo

Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

07 Nov 2023

07 Nov 2026

36

3 year Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Steven Manners

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name Shirley Manor Gardens

Scheme Address Shirley Manor Gardens, Bradford

Postcode BD12 8LS

Region Yorkshire

Scheme Manager

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority West Yorkshire

Other staff in attendance None

Number of on-site Accent staff

None

Number of other (non-Accent) staff

Contract Cleaners in common areas

The Building

Accommodation Type General Needs (S30)

Build Date Jan 1 1964

Number Of Homes 42

Homes breakdown Flat, Maisonette

External wall construction Facing Brick

External wall finish Facing Brick, Paint Render

Roof construction Timber

Roof covering Plain Pitched

PEEPs in place where necessary N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

One unprotected

Number of External Staircases None

External Balcony part of escape route?

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

Shirley Manor Gardens, Bradford Asset ID: 5955 Flats only Fire Detection and Warning System Grade D Grade of fire alarm Category of fire alarm LD3 Minimum Protection **Emergency Lighting Provision** Non Maintained System - Common Areas Portable Fire Extinguishers supplied/fitted No Fixed Fire Fighting Installations No **Customers** 80 Number of occupants General Needs, Staff Accommodation Occupant tenure type breakdown Fire Safety Related Customer Safety Servicing Overdue communal gas safety checks 0 0 Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 Overdue communal PAT testing 0 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests 3 3 Overdue Annual Emergency Lighting tests 0 Overdue Weekly Fire Alarm Testing Overdue Fire Panel - Six Monthly Testing Overdue Fire Safety Equipment tests **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors Communal Fire doors due for replacement within 5 years 0 **Dwelling Doors** 0 Failing Dwelling Fire Doors Dwelling Fire doors due for replacement within 5 years 0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



Date of Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Risk Assessment

Quantity

Fire & Safety Assessor

Enforcing Fire Authority

Scheme Tel. No

Other staff in attendance

Number of on-site Accent staff

Number of other (non-Accent) staff

Scheme Inspection completed

Number of occupants

Personal Emergency Evacuation Plans in place

Current Evacuation Strategy

Conversion or purpose-built

Number of Storeys

Number of floors on which car parking is provided

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

Number of external staircases

External balcony part of escape route?

Unusual features

07/11/2023

36

3 year Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

1

Steven Manners

West Yorkshire

None

None

Contract Cleaners in common areas

Yes

80

N/A

Stay Put (Delayed) Evacuation

Purpose Built

3

0

No

One unprotected

None

No

None

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Residential

Fire Detection and Warning System Flats only

Grade of Fire Alarm Grade D

Category of Fire Alarm LD3 Minimum Protection

Emergency Lighting Provision Non Maintained System - Common Areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted No

Water Extinguisher(s) present

Foam Extinguisher(s) present

Dry Powder Extinguisher(s) present No

Carbon Dioxide Extinguisher(s) present

Fire Blanket(s) present

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present No

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no

obvious damage?

Comment Electrical installations in the communal areas are in

good condition. They are all security locked. Some

have been de commissioned

Yes

Yes

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment All records are available on ActiveH

Electrical App/PA Testing - tested within past 12 months?

N/A

Comment No appliances within the communal areas

Absence of trailing leads and adapters? Yes

Comment None found at the time of inspection

Evidence that mobility scooters are not being stored/charged in Yes

common areas?

Comment No mobility scooters at this scheme

Shirley Manor Gardens, Bradford Asset ID: 5955

Is there a purpose built mobility scooter store/charging area?

Not required Comment

Does the building have a lightning protection system? No

Comment

Gas installations

Yes Is there a commercial/domestic gas supply to the scheme?

Some residents flats have been capped Comment

Valid LGSR held on file for fixed communal area gas appliances? Yes

(Boilers)

Comment All records are available on ActiveH

Yes Valid LGSR held on file for residential flats that contains gas

appliances?

All records are available on ActiveH Comment

annual inspection and the results

Comment Tested when CO detection Tested annually

Other Sources of Ignition

Yes Is there a no smoking policy in place, which is enforced and adhered

Are smoke/heat detectors within General Needs flats subject to an

to?

Comment No smoking allowed in communal areas but

smoking is allowed in residents flats

Adequate security against arson?

CCTV on site and door entry system Comment

Are refuse/recycling bin areas managed and suitably located? No

Comment Although the refuse area is located away from the

building there are refuse sacksbuilt up notvin the

bins No

Yes

Yes

No

Are there communal cooking facilities at this scheme?

Comment

Housekeeping

Are all electrical/intake/service cupboards secure and free from general

waste, contractors waste and and residents personal items?

Comment

Are unnecessary accumulations of combustible materials or waste

avoided?

Some cupboards had combustible items stored inside. Email sent to Flytipping an Housing Partner informed

No

No

Page 6 of 14

Generated 09/11/2023 16:03:09

Comment Some combustible waste was not put in bins

therfore refuse collectors will not remove which accumulate over time. Housing Partner informed

and emailed flytipping

Are combustible materials and substances separated from ignition

sources and stored appropriately?


Comment None found at the time of inspection

Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations?

Comment None allowed in the communal areas

Observation Priority Referred To Required By: Task ID

Furniture outside flat14 in communal area. Email sent to fly tipping



Internal - Medium Housing Partner

Yes

N/A

Observation	Priority	Referred To	Required By:	Task ID
Combustible rubbish in communal area opposite flat 28	Internal - Medium	Housing Partner	21/11/2023	1731467



Other Significant Fire Hazards

fly tipping email sent

Are all other significant fire hazards adequately controlled?

Yes

Comment

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of escape in case of fire?

Yes

Comment Purpose built glass with travel distance within the

guidelines

Yes

Yes

Yes

N/A

Manager

Escape routes unobstructed and safe to use?

Comment Some items were found in the communal areas, housing Partner informed and emailed flytipping

Exits immediately openable without a key and/or failsafe's function

Yes

Exits immediately openable without a key and/or failsafe's function

correctly? Comment

Reasonable distances of travel where there is a single/alternative

direction of travel?

Comment All travel distance are within the guidelines

Escape routes lead to final exits and open in direction of escape where

necessary?

Comment

Observation Priority Referred To Required By: Task ID

Repair - Non

Emergency

Fire exit door opposite flat 2 requires adjusting to allow it to be easily opened.

Order Number 1129536



Building Safety

Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment Compartmentation work was carried out after the last inspection

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?

spread (walls, floors, ceilings)?

Comment

inspection

Are fire dampers/shutters provided in ducts/refuse chutes to protect

N/A

means of escape against fire, smoke and combustion products?

Comment

None fitted

As far as can be reasonably ascertained, is the compartmentation N/A

within roof spaces of a satisfactory standard?

Comment

Flat roofs with no roof void

Confinent Tractions with no roof void

Loft hatches fire resisting?

No combustible surface finishes found at the time of

Comment As above

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory

standard?

Comment None fitted

Do external walls, doors, windows and anything attached to the

exterior, limit fire spread?

Comment

If Smoke Control Systems (AOV's) are fitted, are the records of annual

testing available?

Comment None fitted

Are roller shutter doors that are required to be FR, fire resisting and

self-closing?

Comment None fitted

Observation Priority Referred To Required By: Task ID

Flat 7 door is damaged. Repair has been submitted to contractor. Awaiting delivery of door



Internal - Medium

N/A

Yes

N/A

N/A



Observation Priority Referred To Required By: Task ID

Internal - Medium

Digital lock required on electrical cupboard adjacent to flat 17 with code 2104 Order Number 1129553



Building Safety Manager

Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per current standards?

Comment

Yes

Shirley Manor Gardens, Bradford Asset ID: 5955 Yes Emergency lighting units in good condition and securely fixed to walls/ceilings? All in good condition at the time of inspection Comment Records of monthly/annual testing available? Yes All records are available on ActiveH Comment Fire Safety Signs and Notices Yes Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas? Comment All signage is displayed throughout the building Yes Directional fire escape signage in place and adequate? As above Comment Is there suitable LIFT signage i.e. do not use in case of fire? N/A No lift at this scheme Comment Yes Do common area fire doors display the correct signage on both sides where applicable? Comment Means of giving Warning in case of Fire No Is the scheme fitted with a communal area fire alarm? Comment Fire Extinguishing Equipment Is fire extinguishing equipment and/or fixed fire fighting installations No provided at this scheme? Comment Management of Fire Safety Yes Are these premises regulated by the Building Safety Regulator under the Building Safety Act? Comment Will this FRA be shared will all Accountable Persons for the premises? Yes

MIS-AMS ActiveH - Fire Risk Assessment Report

Are there other Responsible Persons who share or have fire safety

How will this sharing be achieved?

duties in respect of the premises? How will this sharing be achieved?

Comment

Page 10 of 14

Generated 09/11/2023 16:03:09

FRA Is available on M files and in ActiveH

As above

No

Shirley Manor Gardens, Bradford Asset ID: 5955 Is an office or IL scheme being inspected? No Comment Passenger Lift No Is the scheme fitted with a passenger lift? Comment **Premises Inspection Box** Is there a premises information box for fire & rescue service use? No Comment **Evacuation Policy** Are there suitable arrangements for summoning the fire service? Yes Comment All residents are instructed to contact the fire service by dialing 999 Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance? Comment **Engagement with Residents** Has information of fire procedures been disseminated to residents? Yes Comment Action notices are displayed throughout the building, information is available on the website and leaflets will be posted on all residents Is general fire safety information disseminated to residents? Yes As above Comment FRA Frequency Yes Taking the findings of this assessment into account, is the frequency of the FRA correct? Comment Housing Partner will keep a close eye on the fly tipping around the bin area and unwanted items on escape routes

Miscellaneous

Are there any other observations/actions to raise that are not covered above.

Yes

Action leading to a repair	Yes
Internal administrative Action	No
Are there fire related remedial works required at this property, that will affect the fabric of the building? Comment	No
Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).	Yes
Some fire doors did not fully close so works orders have been raised with our contractors.	No
Some minor works were required which have been raised with our contractors.	Yes
Unauthorised items were found in communal areas and arrangements were made for their removal.	Yes
Not all records were up to date, as noted in the table below. Arrangements have been made for these to be completed.	No
A number of fire doors were found to be wedged or propped open. Fire	No

doors are there to keep you safe and me kept shut at all times.

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

systems.					
1. Taking into a	ccount the fire pre	evention measures	 observed at th	ne time of this risk	
assessment, it is building is:	s considered that	the hazard from the	e fire (the prob	bability of ignition) a	at this
LOW	X	MEDIUM		HIGH	
any procedural	arrangements ob	of the building, the served at the time on the event of a fire wo	of the assessm	•	
MINOR		MAJOR	X	CRITICAL	

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial
	<u> </u>