# Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 6486 Glamis Walk, Hartlepool

#### **Cover Sheet**

Photo



Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

31 Oct 2024

31 Oct 2025

36

Annual Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Kevin Jones

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

#### The Scheme

Scheme Name Glamis Walk

Scheme Address Glamis Walk, Hartlepool

Postcode TS25 3JW

Region North East

Scheme Manager

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority Cleveland fire authority

Other staff in attendance None

Number of on-site Accent staff None

Number of other (non-Accent) staff None

## The Building

Accommodation Type General Needs (S30)

Build Date Jan 1 1990

Number Of Homes 51

Homes breakdown Flat

External wall construction Concrete Block, Facing Brick, Facing Brick, Facing

Brick, Rendered Blockwork

External wall finish Cement Render, Facing Brick, Paint Render

Roof construction Timber

Roof covering Interlocking Pitched

PEEPs in place where necessary No

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys 2

Number of floors on which car parking is provided 1

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

1 protected per block

Number of External Staircases 0

External Balcony part of escape route?

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

Asset ID: 6486 Glamis Walk, Hartlepool	
Fire Detection and Warning System	Flats and common areas not linked
Grade of fire alarm	Grade D
Category of fire alarm	LD3 Minimum Protection
Emergency Lighting Provision	Non Maintained System - Common Areas
Portable Fire Extinguishers supplied/fitted	No
Fixed Fire Fighting Installations	No
Customers	
Number of occupants	20
Occupant tenure type breakdown	General Needs, Supported Housing
Fire Safety Related Customer Safety Servicing	
Overdue communal gas safety checks	0
Overdue domestic gas safety checks	0
Overdue communal electrical condition checks	0
Overdue domestic electrical condition checks	0
Overdue alarm call pull chord tests	0
Overdue communal PAT testing	0
Overdue customer mobility scooter PAT testing	0
Overdue Monthly Emergency Lighting Switch Tests	9
Overdue Annual Emergency Lighting tests	9
Overdue Weekly Fire Alarm Testing	0
Overdue Fire Panel - Six Monthly Testing	
Overdue Fire Safety Equipment tests	
Building Fire Safety Surveys - Communal Doors	
Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	0
Dwelling Doors	
Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

## **Fire Risk Assessment Survey Results**

## **Scheme and Building Information**

Photo



Date of Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Risk Assessment

Quantity

Fire & Safety Assessor

Enforcing Fire Authority

Scheme Tel. No

Other staff in attendance

Number of on-site Accent staff

Number of other (non-Accent) staff

Scheme Inspection completed

Number of occupants

Personal Emergency Evacuation Plans in place

**Current Evacuation Strategy** 

Conversion or purpose-built

Number of Storeys

Number of floors on which car parking is provided

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

Number of external staircases

External balcony part of escape route?

Unusual features

31/10/2024

12

**Annual Re-Assessment** 

Type 1 (Common Parts Only - Non Destructive)

. .

Kevin Jones

Cleveland fire authority

None

None

None

Yes

20

No

Stay Put (Delayed) Evacuation

Purpose Built

2

1

No

1 protected per block

0

No

None

Glamis Walk, Hartlepool Asset ID: 6486

## Fire Risk Assessment Survey Results

Vehicular Access to one or more elevations Building access conditions for Fire Brigade

Surroundings: Residential/Commercial Mixed

Flats and common areas not linked Fire Detection and Warning System

Grade D Grade of Fire Alarm

Category of Fire Alarm **LD3 Minimum Protection** 

Non Maintained System - Common Areas **Emergency Lighting Provision** 

No Portable Fire Extinguishers / Fire Blankets supplied / fitted

Water Extinguisher(s) present No

No Foam Extinguisher(s) present

Dry Powder Extinguisher(s) present No

No Carbon Dioxide Extinguisher(s) present

No Fire Blanket(s) present

No Fixed Fire Fighting Installations supplied / fitted

Dry Riser(s) present No

No Wet Riser(s) present

No Sprinkler System present

No Hosereel(s) present

Automatic Opening Vent(s) present No

### **Electrical Sources of Ignition**

Electrical installation within common areas in good condition and no

obvious damage?

Comment All appears in good condition and secure

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

All upto date and results uploaded onto Active H Comment

Yes

Yes

Electrical App/PA Testing - tested within past 12 months?

No portable appliances identified in premis Comment

Absence of trailing leads and adapters?

Comment No portable appliances identified in property

No Evidence that mobility scooters are not being stored/charged in

common areas?

Comment

No Is there a purpose built mobility scooter store/charging area?

Comment

No Does the building have a lightning protection system?

Comment Not required for the height of the property

**Gas installations** 

Is there a commercial/domestic gas supply to the scheme? Yes

Comment Gas supply to boilers within flats

N/A Valid LGSR held on file for fixed communal area gas appliances?

(Boilers)

No communal gas supply Comment

Yes Valid LGSR held on file for residential flats that contains gas

appliances?

Comment Results are uploaded to Active H

Yes Are smoke/heat detectors within General Needs flats subject to an

annual inspection and the results

Comment Results are uploaded to Active H

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered Yes

to?

Comment Smoking permitted within flats only

Adequate security against arson? Yes

Comment Locked front and rear doors with thumbturn operated

handle Push button entry from flats.

Are refuse/recycling bin areas managed and suitably located?

Dedicated refuse area well managed by SHP Comment

Are there communal cooking facilities at this scheme? No

Comment

Housekeeping

Are all electrical/intake/service cupboards secure and free from general Yes

waste, contractors waste and and residents personal items?

All cupoards clear and doors secure Comment

Yes

Are unnecessary accumulations of combustible materials or waste

avoided?

Comment Sterile environment identified

Are combustible materials and substances separated from ignition

sources and stored appropriately?

Yes

Comment Good houskeeping evident during inspection

Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations?

Comment No Communal furniture identified

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled? Yes

Comment

Means of Escape from Fire

Yes Is it considered that the building is provided with reasonable means of

escape in case of fire?

Comment Single staircase with two directional means of esacpe on the ground floor

Escape routes unobstructed and safe to use? Yes

Comment Clear means of escape identified

Yes Exits immediately openable without a key and/or failsafe's function

correctly?

Comment Thumbturn door furniture fitted on all final exit doors

Reasonable distances of travel where there is a single/alternative

direction of travel?

Minimal travel distance from all flats Comment

Escape routes lead to final exits and open in direction of escape where

necessary?

Comment Rear door opens in direction of escape front door

opens inwards.

Observation **Priority Referred To** Required By: Task ID

Internal - Medium

Flat doors require repacement repair, 5, 5a, 6a, 11, 13 and 15





**Project Manager** 

(Building Safety)

21/12/2024

1880472

N/A

Yes

No

Observation Priority Referred To Required By: Task ID

Sterile means of escape





## Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?

Comment

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?

Comment

As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?

Comment

Loft hatches fire resisting?

Comment

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?

Comment

Do external walls, doors, windows and anything attached to the exterior, limit fire spread?

Comment

If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?

Comment

Are roller shutter doors that are required to be FR, fire resisting and self-closing?

No

Flat doors; 5, 5a, ,6a, 11, 13, and 15 required repair and relacement due to damage. Repair requested via repairs portal and recored on the works progress traker.

Purpose built block of flats traditional construction of bick and morter tiles roof and plaster finish to walls.

Yes

Plaster finish to walls and ceilings

N/A

None fitted

Yes

Samp[le inspection idicated comparmentation within roof space was to correct stanndards

Yes

60 minuite protection

N/A

No cross corridor doors within premis

No

Traditional construction

N/A

None fitted

N/A

Comment None fitted

### **Emergency Escape Lighting**

Is the emergency lighting correctly specified and installed as per

current standards?

Emergency lighting units in good condition and securely fixed to

walls/ceilings?

Comment

Comment

Records of monthly/annual testing available?

Comment

Observation Priority Referred To Required By: Task ID

Lighting in good condition





Results are uploaded to Active H

Appears to be fitted to correct standard

Appears to be in good condition and secure.

### **Fire Safety Signs and Notices**

Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?

Comment

Directional fire escape signage in place and adequate?

Comment

Is there suitable LIFT signage i.e. do not use in case of fire?

Comment

Do common area fire doors display the correct signage on both sides where applicable?

Comment

Yes

Yes

Yes

Throughpout all the blocks

Yes

Throughout all of the blocks

N/A

No lift within premis

Yes

Understair electrical iontake cupboards all display

signage

Glamis Walk, Hartlepool Asset ID: 6486

Observation **Priority** Referred To Required By: Task ID

Correct synage throughout the property





## Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?

Comment

Yes Is fire detection and warning system appropriate for occupancy and fire risk, as per BS 5839-1:2017?

Comment

Comment

Yes Is the fire detection and warning system maintained/tested and all

certificates saved on file? Comment

Yes Fire alarm components in good condition and securely fixed to

walls/ceilings?

Hold open devices operate at the sounding of the alarm and are in a

serviceable condition?

Comment

Are there heat detectors located in the Kitchen, Boiler, Plant Room and

Laundry?

Is the fire alarm panel remotely monitored, and if so are there records of regular testing?

Comment

Comment

Results are uploaded to Active H

Yes

All appears to be in good condition and secure

N/A

None identified during inspection

N/A

No rooms within premis

No

Observation Priority Referred To Required By: Task ID

Smoke detector in good condition







## Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme?

Comment

No

# Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under the Building Safety Act?

Comment

Are there other Responsible Persons who share or have fire safety duties in respect of the premises?

How will this sharing be achieved?

Is an office or IL scheme being inspected?

Comment

No

No

No

# Passenger Lift

Is the scheme fitted with a passenger lift?

No

Comment

### **Premises Inspection Box**

Is there a premises information box for fire & rescue service use?

No

Comment

# **Evacuation Policy**

Are there suitable arrangements for summoning the fire service?

Comment 999 call from customers

Taking FRA findings, is the evacuation policy appropriate for the

scheme as per latest guidance?

Comment Purpose built blocks of flats

**Engagement with Residents** 

Has information of fire procedures been disseminated to residents?

Comment Induction programme, Customer portal engament

with customers

Yes

Yes

Yes

Is general fire safety information disseminated to residents?

Comment See 17.1.201

FRA Frequency

Taking the findings of this assessment into account, is the frequency of Yes

the FRA correct?

Comment A lot of ASB experiences within blocks

Miscellaneous

Are there any other observations/actions to raise that are not covered No

above.

affect the fabric of the building?

Comment Flat doors reuire repair and replacement

Can work be conducted without the need for an asbestos survey. If no, task Customer Safety Surveyor - Asbestos.

Comment

Are there fire related remedial works required at this property, that will

Were there any unsatisfactory aspects of the Fire Risk Assessment?

(Visible on Building Safety Report).

Some fire doors did not fully close so works orders have been raised

Yes

with our contractors.

Some minor works were required which have been raised with our No

contractors.

Unauthorised items were found in communal areas and arrangements No

were made for their removal.

Not all records were up to date, as noted in the table below.

Arrangements have been made for these to be completed.

A number of fire doors were found to be wedged or propped open. Fire No

doors are there to keep you safe and me kept shut at all times.

#### **Risk Calculator - Fire**

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

systems.					
_		evention measures obse t the hazard from the fire			at this
LOW	X	MEDIUM		HIGH	
any procedural	arrangements ob	of the building, the occuserved at the time of the event of a fire would	e assessment	•	
MINOR		MAJOR X		CRITICAL	

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial
	<u> </u>