# Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 8670 1-39 Astura Court Block 1-39 Astura Court, Leeds

### **Cover Sheet**

Photo



Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

31 Jan 2025

31 Jan 2026

12

Annual Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Steven Manners Tech IOSH MIFSM MFPA

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

### The Scheme

Scheme Name Astura Court

Scheme Address 1-39 Astura Court Block 1-39 Astura Court, Leeds

Postcode LS7 2DL

Region Yorkshire

Scheme Manager

Scheme Tel. No 01132623599

Scheme Inspection Completed Yes

Enforcing Fire Authority West Yorkshire

Other staff in attendance Lavena Lawrence Sheraz Sehgal

Number of on-site Accent staff Scheme Manager Part-Time

Number of other (non-Accent) staff

Contract Cleaners in common areas

### The Building

Accommodation Type CAT2 Housing for Older People (S28)

Build Date Jan 1 1977

Number Of Homes 38

Homes breakdown Bedsit, Flat

External wall construction Facing Brick

External wall finish Facing Brick

Roof construction Timber

Roof covering Flat Roof, Interlocking Pitched

PEEPs in place where necessary

Yes

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?) 2 not protected

Number of External Staircases None

External Balcony part of escape route?

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

1-39 Astura Court Block 1-39 Astura Court, Leeds Asset ID: 8670 Fire Detection and Warning System Flats and common areas not linked Grade of fire alarm Grade D Category of fire alarm LD2 Additional Protection Mixed system - Common areas **Emergency Lighting Provision** Portable Fire Extinguishers supplied/fitted Yes Fixed Fire Fighting Installations No **Customers** 38 Number of occupants Occupant tenure type breakdown CAT2 Housing for Older People, General Needs, Staff Accommodation Fire Safety Related Customer Safety Servicing 0 Overdue communal gas safety checks Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 0 Overdue communal PAT testing 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests 0 0 Overdue Annual Emergency Lighting tests Overdue Weekly Fire Alarm Testing Overdue Fire Panel - Six Monthly Testing 1 1 Overdue Fire Safety Equipment tests **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors 0 Communal Fire doors due for replacement within 5 years **Dwelling Doors** 0 Failing Dwelling Fire Doors

Dwelling Fire doors due for replacement within 5 years

0

## **Fire Risk Assessment Survey Results**

### **Scheme and Building Information**

Photo



Date of Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Risk Assessment

Quantity

Fire & Safety Assessor

**Enforcing Fire Authority** 

Scheme Tel. No

Other staff in attendance

Number of on-site Accent staff

Number of other (non-Accent) staff

Scheme Inspection completed

Number of occupants

Personal Emergency Evacuation Plans in place

**Current Evacuation Strategy** 

Conversion or purpose-built

Number of Storeys

Number of floors on which car parking is provided

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

Number of external staircases

External balcony part of escape route?

Unusual features

31/01/2025

12

Annual Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

1

Steven Manners Tech IOSH MIFSM MFPA

West Yorkshire

01132623599

Lavena Lawrence Sheraz Sehgal

Scheme Manager Part-Time

Contract Cleaners in common areas

Yes

38

Yes

Stay Put (Delayed) Evacuation

Purpose Built

2

0

No

2 not protected

None

No

None

### Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Residential

Fire Detection and Warning System Flats and common areas not linked

Grade of Fire Alarm Grade D

Category of Fire Alarm LD2 Additional Protection

Emergency Lighting Provision Mixed system - Common areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted Yes

Water Extinguisher(s) present

Foam Extinguisher(s) present No

Dry Powder Extinguisher(s) present No

Carbon Dioxide Extinguisher(s) present

Yes

Fire Blanket(s) present Yes

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present No

### **Electrical Sources of Ignition**

Electrical installation within common areas in good condition and no

obvious damage?

Comment All electrical components in good condition at the

time of inspection.

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment Last tested 03/10/2022

Electrical App/PA Testing - tested within past 12 months? Yes

Comment All within test at the time of inspection, see

observations.

Yes

Yes

Absence of trailing leads and adapters? Yes

Comment None found at the time of inspection.

Evidence that mobility scooters are not being stored/charged in Yes

common areas?

Comment No mobility scooters found in communal areas at

the time of inspection.

Is there a purpose built mobility scooter store/charging area?

Comment Thre is a purpose built store within the communal

lounge.

Does the building have a lightning protection system?

Comment

Gas installations

Is there a commercial/domestic gas supply to the scheme? Yes

Comment There is a boiler for communal heating, residents

have a gasssupply to their flats if required.

Valid LGSR held on file for fixed communal area gas appliances?

Yes

(Boilers)

Comment Certificates are available on ActiveH.

Last test date :- 26/02/24

Valid LGSR held on file for residential flats that contains gas

Yes

appliances?

Comment Sample test dates.

Flat 4 :- 24/05/2024 flat 19 :- 18/07/2024 flat 31 :- 12/06/2024

Are smoke/heat detectors within General Needs flats subject to an

annual inspection and the results

Comment Completed by contractors at the time of the gas

check.

Yes

Yes

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered

to?

Comment There are No smoking signs throughout the building.

Smoking is not allowed in the communal areas but residents are allowed to smoke within their flats.

Adequate security against arson? Yes

Comment There is a fob entry system at the main entrance.

All emergency exits are openable from inside only. Ther is a CCTV system throughout the scheme.

Are refuse/recycling bin areas managed and suitably located?

Yes

Comment Refuse is stored within a seperate part of the

building.

Are there communal cooking facilities at this scheme?

Comment Mainly used for coffe mornings rather than cooking

meals.

Yes

Are reasonable measures taken to prevent fires as a result of cooking?

Comment

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 6 of 14

Generated 01/02/2025 16:01:06

1-39 Astura Court Block 1-39 Astura Court, Leeds Asset ID: 8670

Where there is extraction in communal kitchens, are filters and

ductwork changed/cleaned regularly?

Comment There is extraction in the kitchen but no ducting

fitted.

Yes

Yes

Yes

Yes

N/A

Housekeeping

Are all electrical/intake/service cupboards secure and free from general

waste, contractors waste and and residents personal items?

None Found at the time of inspection. Comment

Are unnecessary accumulations of combustible materials or waste

avoided?

Comment None found at the time of inspection.

Are combustible materials and substances separated from ignition

sources and stored appropriately?

Comment one found at the time of inspection.

Furniture/furnishings in good condition, fire retardant/resistant and

comply with modern standards and regulations?

Comment All furniture within the communal lounge was found

to be compliant at the time of inspection.

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Comment Nothing found at the time of inspection.

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of

escape in case of fire?

Comment

Yes Escape routes unobstructed and safe to use?

Comment All clear at the time of inspection.

Exits immediately openable without a key and/or failsafe's function

correctly?

Comment

Reasonable distances of travel where there is a single/alternative

direction of travel?

All means of escape within the guidance. Comment

Escape routes lead to final exits and open in direction of escape where

necessary?

Comment

Yes

Yes

Yes

Yes

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 7 of 14

Generated 01/02/2025 16:01:06

### Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment Compartmentation within the areas inspected wereof

a reasonable standard at the time of inspection.

Is there reasonable limitation of surface finishes that might promote fire

spread (walls, floors, ceilings)?

Comment All notices were visible behind glass screen at the

time of inspection.

N/A

Are fire dampers/shutters provided in ducts/refuse chutes to protect

means of escape against fire, smoke and combustion products?

Comment None fitted.

As far as can be reasonably ascertained, is the compartmentation Yes

within roof spaces of a satisfactory standard?

Comment No access to roof spaces at the time of inspection.

Loft hatches fire resisting?

Comment 1Hour fire resistant loft hatches fitted throughout the

building Yes

N/A

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory

standard? Comment

Do external walls, doors, windows and anything attached to the Yes

exterior, limit fire spread?

Comment Traditionaly built construction.

If Smoke Control Systems (AOV's) are fitted, are the records of annual

testing available?

Comment None fitted.

Are roller shutter doors that are required to be FR, fire resisting and

self-closing?

Comment None Fitted.

Observation	Priority	Referred To	Required By:	Task ID
Replace Laundry room door and frame with FD60S Works Order No. 1253773	Repair - Non Emergency	Project Manager (Building Safety)	30/04/2025	1915283

### **Emergency Escape Lighting**

Is the emergency lighting correctly specified and installed as per

current standards?

Comment

Emergency lighting units in good condition and securely fixed to

walls/ceilings?

Comment All fixtures and fittings in good condition at the time

of inspection.

Yes

Yes

Records of monthly/annual testing available? Yes

Comment All records are available on ActiveH

Last test dates:-Monthly 13/01/2025 Annual 11/06/204

**Fire Safety Signs and Notices** 

Are the correct Fire Action/Advice notices displayed in prominent

Yes

locations within the common areas?

Comment Signage displayed throughout the building.

Directional fire escape signage in place and adequate?

Comment Signage displayed throughout the building.

Is there suitable LIFT signage i.e. do not use in case of fire?

Comment None fitted.

Do common area fire doors display the correct signage on both sides Yes

where applicable?

Comment Signage on both sides of doors where required are

displayed throughout the building.

Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?

Yes

Comment There is a zoned communal alarm throughout the

building not connected to the flats.

Is fire detection and warning system appropriate for occupancy and fire

risk, as per BS 5839-1:2017?

Is the fire detection and warning system maintained/tested and all

certificates saved on file?

Comment All Certificates are available oin ActiveH

Fire alarm components in good condition and securely fixed to No

walls/ceilings?

Comment

Comment All in good condition at the time of inspection.

Hold open devices operate at the sounding of the alarm and are in a

serviceable condition?

Comment All in good condition at the time of inspection.

Are there heat detectors located in the Kitchen, Boiler, Plant Room and Yes

Laundry?
Comment

Is the fire alarm panel remotely monitored, and if so are there records of

regular testing?

Yes

Yes

Yes

Yes

### 1-39 Astura Court Block 1-39 Astura Court, Leeds Asset ID: 8670

Comment All Certificates are available oin ActiveH

> Last test dates:-Weekly 29/01/2025 6Monthly 09/01/2025

Yes

### Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations

provided at this scheme?

Only available in the high risk areas of the scheme. Comment

Portable fire extinguishers - appropriate type/number/position? Yes

Comment

Correct signage displayed by each fire extinguisher? Yes

Comment

Yes Fire blanket in communal kitchen, secured to the wall, complete with

signage? Comment

Dry risers - Inlet/outlet boxes secured and/or securing straps fitted to

outlet valves?

None fitted Comment

Yes Records available of fire fighting equipment servicing within past 12

months?

Comment All extinguishers display las test date

07/2024

N/A

Observation **Priority Referred To** Required By: Task ID

Office extinguisher





### Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under the Building Safety Act?

Comment

Are there other Responsible Persons who share or have fire safety

duties in respect of the premises?

No

No

1-39 Astura Court Block 1-39 Astura Court, Leeds Asset ID: 8670 How will this sharing be achieved? Yes Is an office or IL scheme being inspected? Comment N/A IL Schemes & Regional Offices - Are there sufficient numbers of qualified Fire wardens? Not required. Comment Offices - Are there suitable arrangements for ensuring the premises are Yes Comment Yes Offices - Are there suitable arrangements for evacuating disabled people? Comment Yes Offices - Suitable arrangements for meeting the fire service on arrival and proving relevant information? Comment only during working hours. Yes Offices/IL Schemes - Is there a suitable assembly point? Comment Car Park N/A Offices - Are fire drills carried out at appropriate intervals? Comment Fire drills not required on ILS Passenger Lift Is the scheme fitted with a passenger lift? No Comment **Premises Inspection Box** Is there a premises information box for fire & rescue service use? No Comment **Evacuation Policy** 

Yes Are there suitable arrangements for summoning the fire service?

Comment The fire alarm is monitored and the flats contain a

warden call system.

Yes

Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance?

Comment

### **Engagement with Residents**

#### 1-39 Astura Court Block 1-39 Astura Court, Leeds Asset ID: 8670

Has information of fire procedures been disseminated to residents?

Comment All residents have been issued with an information leaflet explaining fire precautions within their

scheme, information is also given about flat doors. further information can be found on the website. Information is also given on induction to their flat on

arrival.

Yes Is general fire safety information disseminated to residents?

Comment All residents have been issued with an information

leaflet explaining fire precautions within their scheme, information is also given about flat doors. further information can be found on the website. Information is also given on induction to their flat on

arrival.

### **FRA Frequency**

Taking the findings of this assessment into account, is the frequency of the FRA correct?

Comment

Yes

Yes

### Miscellaneous

Yes Are there any other observations/actions to raise that are not covered above.

Action leading to a repair

Internal administrative Action No

No

Are there fire related remedial works required at this property, that will affect the fabric of the building?

Comment

Yes Were there any unsatisfactory aspects of the Fire Risk Assessment?

(Visible on Building Safety Report).

Yes Some fire doors did not fully close so works orders have been raised

with our contractors.

Yes Some minor works were required which have been raised with our

contractors.

No Unauthorised items were found in communal areas and arrangements

were made for their removal.

No Not all records were up to date, as noted in the table below.

Arrangements have been made for these to be completed.

No

A number of fire doors were found to be wedged or propped open. Fire doors are there to keep you safe and me kept shut at all times.

### **Risk Calculator - Fire**

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW	X	MEDIUM		HIGH	
-----	---	--------	--	------	--

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR MAJOR	X	CRITICAL	
-------------	---	----------	--

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).	
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.	
CRITICAL	There is significant potential for serious injury or death of one or more occupants.	

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial
	<u> </u>