Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 8664 Blk1 Group Home 11 Moorcroft Drive 11 Moorcroft Drive, Bradford

Cover Sheet

Photo



Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

01 Oct 2024

01 Oct 2025

12

Annual Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Steven Manners Tech IOSH MIFSM MFPA

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name Cross Banks

Scheme Address Blk1 Group Home 11 Moorcroft Drive 11 Moorcroft

Drive, Bradford

Postcode BD4 6NJ

Region Yorkshire

Scheme Manager

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority West Yorkshire

Other staff in attendance 2 full time carers

Number of on-site Accent staff

None

Number of other (non-Accent) staff

Carers

The Building

Accommodation Type Supported Housing (S50)

Build Date Jan 1 1971

Number Of Homes 4

Homes breakdown Room

External wall construction Facing Brick

External wall finish Pebble Dash

Roof construction Timber

Roof covering Plain Pitched

PEEPs in place where necessary

Yes

Current Evacuation Strategy Full (Simultaneous) Evacuation

Conversion or purpose-built Conversion

Number of storeys 2

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

1 unprotected 1 protected

Number of External Staircases 0

External Balcony part of escape route?

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

Blk1 Group Home 11 Moorcroft Drive 11 Moorcroft Drive, Bradford Asset ID: 8664 Flats and common areas linked Fire Detection and Warning System Grade of fire alarm Grade A Category of fire alarm LD2 Additional Protection Non Maintained System - Common Areas **Emergency Lighting Provision** Portable Fire Extinguishers supplied/fitted Yes Fixed Fire Fighting Installations No **Customers** 3 Number of occupants Supported Housing Occupant tenure type breakdown Fire Safety Related Customer Safety Servicing Overdue communal gas safety checks 0 0 Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 Overdue communal PAT testing 0 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests 1 Overdue Annual Emergency Lighting tests 1 1 Overdue Weekly Fire Alarm Testing Overdue Fire Panel - Six Monthly Testing 1 Overdue Fire Safety Equipment tests 1 **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors Communal Fire doors due for replacement within 5 years 0 **Dwelling Doors** 0 Failing Dwelling Fire Doors

Dwelling Fire doors due for replacement within 5 years

0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



Date of Fire Risk Assessment 01/10/2024

FRA Frequency (Months) 12

Purpose of Fire Risk Assessment Annual Re-Assessment

Type of Risk Assessment

Type 1 (Common Parts Only - Non Destructive)

Quantity

Fire & Safety Assessor Steven Manners Tech IOSH MIFSM MFPA

Enforcing Fire Authority West Yorkshire

Scheme Tel. No

Other staff in attendance 2 full time carers

Number of on-site Accent staff

None

Number of other (non-Accent) staff

Carers

Scheme Inspection completed Yes

Number of occupants 3

Personal Emergency Evacuation Plans in place Yes

Current Evacuation Strategy Full (Simultaneous) Evacuation

Conversion or purpose-built Conversion

Number of Storeys 2

Number of floors on which car parking is provided 0

Is there a habitable basement?

No. of internal staircases (protected/unprotected) 1 unprotected 1 protected

Number of external staircases 0

External balcony part of escape route?

Unusual features None

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Residential

Fire Detection and Warning System Flats and common areas linked

Grade of Fire Alarm Grade A

Category of Fire Alarm LD2 Additional Protection

Emergency Lighting Provision Non Maintained System - Common Areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted Yes

Water Extinguisher(s) present Yes

Foam Extinguisher(s) present Yes

Dry Powder Extinguisher(s) present

Carbon Dioxide Extinguisher(s) present No

Fire Blanket(s) present Yes

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no

obvious damage?

Comment All Electrial Installations were in good condition at

the time of inspection.

Yes

Yes

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment Last test date 31/07/2023

Electrical App/PA Testing - tested within past 12 months? Yes

Comment all labels present on electrical equipment. Last test

date 25/10/2023

Absence of trailing leads and adapters? Yes

Comment None found at the time of inspection.

Evidence that mobility scooters are not being stored/charged in Yes

common areas?

Comment None at the scheme.

Is there a purpose built mobility scooter store/charging area?

N/A

Comment Not required.

Does the building have a lightning protection system?

Comment

Gas installations

Is there a commercial/domestic gas supply to the scheme?

Yes

Comment There is a gas heating system within this scheme.

Valid LGSR held on file for fixed communal area gas appliances?

Yes

(Boilers)

Comment The gas certificate is in date, last tested

15/01/2024.

Yes

Yes

Valid LGSR held on file for residential flats that contains gas

appliances?

Comment This scheme is supported housing. It is a converted

house with bedroos for residents.

Are smoke/heat detectors within General Needs flats subject to an

annual inspection and the results

Comment Although the rooms are not residential flats the

detectors are tested with the fire alarm system.

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered

to?

Comment There is no smoking throughout the building.

signage is vissible throughout.

Adequate security against arson?

Comment There is a buzz in system at the main entrance and

the rear exit is on a magnetic lock.

Are refuse/recycling bin areas managed and suitably located?

Comment There is a seperate area for the refuse bins outside

the property.

Yes

Are there communal cooking facilities at this scheme?

Comment There is a communal kitchen where residents are

supervised when cooking their meals.

Are reasonable measures taken to prevent fires as a result of cooking?

Comment As above the residents are supervised.

Where there is extraction in communal kitchens, are filters and N/A

Where there is extraction in communal kitchens, are filters and N/A ductwork changed/cleaned regularly?

Comment None fitted.

Housekeeping

Are all electrical/intake/service cupboards secure and free from general

waste, contractors waste and and residents personal items?

Comment Nnone found at the time of inspection.

Yes

N/A

Yes

Are unnecessary accumulations of combustible materials or waste

avoided?

Comment None found at the time of inspection.

Are combustible materials and substances separated from ignition

sources and stored appropriately?

Comment None found at the time of inspection.

Furniture/furnishings in good condition, fire retardant/resistant and

comply with modern standards and regulations?

Comment All furniture within the property was suitable.

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Yes

Comment None found at the time of inspection.

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of escape in case of fire?

Comment There are 2 staircases one protected and one not

protected.

Escape routes unobstructed and safe to use?

Comment All clear at the time of inspection.

Exits immediately openable without a key and/or failsafe's function Yes

correctly?

Comment The rear exit is on a Magnetic lock linked to the fire

alar msystem.

Reasonable distances of travel where there is a single/alternative

direction of travel?

Escape routes lead to final exits and open in direction of escape where

necessary?

Comment

Comment

Yes

Yes

Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard? Yes

Comment No breaches were found at the time of inspection.

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 7 of 15

Generated 04/10/2024 16:02:42

Blk1 Group Home 11 Moorcroft Drive 11 Moorcroft Drive, Bradford Asset ID: 8664

Is there reasonable limitation of surface finishes that might promote fire

spread (walls, floors, ceilings)?

Are fire dampers/shutters provided in ducts/refuse chutes to protect

Comment

Comment

Comment

As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?

means of escape against fire, smoke and combustion products?

Loft hatches fire resisting?

Comment

Comment

Comment

Comment

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?

Do external walls, doors, windows and anything attached to the

exterior, limit fire spread?

If Smoke Control Systems (AOV's) are fitted, are the records of annual

testing available?

Are roller shutter doors that are required to be FR, fire resisting and

self-closing?

Observation

Comment

Crack in door frame near top hinge

Yes

There were carpets in some areas of the building and laminated flooring in others. a notice board was provide which is fastened to the wall and covered in perspex.

No

Yes

There was no access to the roof space at this time. the roof space is that acustomed to a dwelling

house.

Yes

N/A

No cross corridor doors within this scheme.

Yes

Traditional construction of brick walls and slate roof.

N/A

None fitted

N/A

None Fitted.

Project Manager (Building Safety)

Referred To

Required By: 01/01/2025

Task ID 1870582

Priority

Repair - Non

Emergency

Door frame to first floor lounge is split. Requires replacing



Repair - Non Emergency

Priority

Project Manager (Building Safety)

Referred To

Required By: 01/01/2025 Task ID 1870581



Observation Priority Referred To Required By: Task ID

Hour rated loft hatch

Observation



Observation Priority Referred To Required By: Task ID

Notice board is covered



Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per current standards?

Comment

Emergency lighting units in good condition and securely fixed to walls/ceilings?

Comment

Yes

Yes

All Emergency lighting was in good conditin at the time of inspection.

Records of monthly/annual testing available? Yes

Comment Records are available on ActiveH

Last test dates Monthly 16/09/2024 Annual 09/05/2024

Yes

Yes

Yes

Yes

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent

locations within the common areas?

Comment Fire notices are displayed throughout the building.

Directional fire escape signage in place and adequate?

Comment Displayed throughout the building

Is there suitable LIFT signage i.e. do not use in case of fire?

Comment None Fitted.

Do common area fire doors display the correct signage on both sides

where applicable?

Comment All present at the time of inspection.

Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?

Comment This is a Fullevacuation site.

Is fire detection and warning system appropriate for occupancy and fire

risk, as per BS 5839-1:2017?

Is the fire detection and warning system maintained/tested and all

certificates saved on file?

Comment THe fire alarm system is tested weekly and 6

Monthly
Last test dates
Weekly 30/09/2024
6 Monthly 09/05/2024

Fire alarm components in good condition and securely fixed to

walls/ceilings?

Comment

Comment All in good condition at the time of inspection.

Hold open devices operate at the sounding of the alarm and are in a

serviceable condition?

Comment Tested at the time of inspection, all working

correctly.

Yes

Yes

Are there heat detectors located in the Kitchen, Boiler, Plant Room and

Laundry?

Comment

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 10 of 15

Generated 04/10/2024 16:02:42

Is the fire alarm panel remotely monitored, and if so are there records of regular testing?

The fire alarm is monitored by the staff on 24/7 Test

Comment

records are available on site and on ActiveH.

Observation Priority Referred To Required By: Task ID

Yes

Yes

Yes

Yes

Yes

N/A

Yes

Fire panel



Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations

provided at this scheme?

Comment

Portable fire extinguishers - appropriate type/number/position?

Comment

Correct signage displayed by each fire extinguisher?

Comment

Fire blanket in communal kitchen, secured to the wall, complete with

signage?

Comment

Dry risers - Inlet/outlet boxes secured and/or securing straps fitted to

outlet valves?

Comment Nnone Fitted.

Records available of fire fighting equipment servicing within past 12

months?

Comment Last tested 09/2024

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under

the Building Safety Act?

Comment

Are there other Responsible Persons who share or have fire safety

duties in respect of the premises?

No

Yes

Have all details required by regulations been shared with all other

Responsible Persons?

Comment A copy f the Fire risk assessment is sent to the

managing company.

Yes

Yes

Yes

Have all details required by regulations to be shared with us from other

Responsible Persons been received and recorded?

Comment As Above

Will this FRA be shared will all other Responsible Persons for the

premises?

Comment As Above

How will this sharing be achieved? Emailed to the management company.

Is an office or IL scheme being inspected?

Comment

Passenger Lift

Is the scheme fitted with a passenger lift?

Comment

Premises Inspection Box

Is there a premises information box for fire & rescue service use?

Comment There is a Fire folder containing PEEPS for each

resident.

Evacuation Policy

Are there suitable arrangements for summoning the fire service?

Comment Staff are on site 24/7 and are aware of the policy.

Taking FRA findings, is the evacuation policy appropriate for the

scheme as per latest guidance?

Comment

Yes

Yes

Engagement with Residents

Has information of fire procedures been disseminated to residents?

Yes

Comment The staff at the scheme conduct regular fire safety

talks with th residents, fire evacuation drils are carried out and recorded in the fire log book.

Is general fire safety information disseminated to residents?

Comment As above.

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 12 of 15

Generated 04/10/2024 16:02:42

FRA Frequency

Taking the findings of this assessment into account, is the frequency of the FRA correct?

Yes

Yes

No

Comment

Miscellaneous

Are there any other observations/actions to raise that are not covered above.

Action leading to a repair Yes

Internal administrative Action No

Are there fire related remedial works required at this property, that will affect the fabric of the building?

Comment

Were there any unsatisfactory aspects of the Fire Risk Assessment?

(Visible on Building Safety Report).

Some fire doors did not fully close so works orders have been raised
with our contractors.

Yes

Some minor works were required which have been raised with our

contractors.

Unauthorised items were found in communal areas and arrangements were made for their removal.

Not all records were up to date, as noted in the table below.

Arrangements have been made for these to be completed.

A number of fire doors were found to be wedged or propped open. Fire

A number of fire doors were found to be wedged or propped open. Fire doors are there to keep you safe and me kept shut at all times.

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW

MEDIUM

HIGH

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR MAJOR X CRITICAL

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Asset ID: 8664

Blk1 Group Home 11 Moorcroft Drive 11 Moorcroft Drive, Bradford

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial
	<u> </u>