Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 8669 Aprilia Court Hunters Park Avenue, Bradford

Cover Sheet

Photo

Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

17 Jan 2025

17 Jan 2026

12

Annual Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Steven Manners Tech IOSH MIFSM MFPA

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name Aprilia Court

Scheme Address Aprilia Court Hunters Park Avenue, Bradford

Postcode BD14 6TE

Region Yorkshire

Scheme Manager

Scheme Tel. No 01274 816440

Scheme Inspection Completed Yes

Enforcing Fire Authority West Yorkshire

Other staff in attendance Zehnum Hussain

Number of on-site Accent staff Scheme Manager Part-Time

Number of other (non-Accent) staff

Contract Cleaners in common areas

The Building

Accommodation Type CAT2 Housing for Older People (S28)

Build Date Jan 1 1978

Number Of Homes 31

Homes breakdown Flat

External wall construction Facing Brick

External wall finish Facing Brick, Hung Tiles

Roof construction Timber

Roof covering Flat Roof, Interlocking Pitched

PEEPs in place where necessary

Yes

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys 2

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?) 3 Protected

Number of External Staircases None

External Balcony part of escape route?

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

Aprilia Court Hunters Park Avenue, Bradford Asset ID: 8669 Fire Detection and Warning System Flats and common areas not linked Grade of fire alarm Grade A Category of fire alarm **LD1 Maximum Protection** Maintained system - Common areas **Emergency Lighting Provision** Portable Fire Extinguishers supplied/fitted Yes Fixed Fire Fighting Installations No **Customers** 45 Number of occupants Occupant tenure type breakdown CAT1 Housing for Older People, CAT2 Housing for Older People, General Needs, Staff Accommodation Fire Safety Related Customer Safety Servicing 0 Overdue communal gas safety checks Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 0 Overdue communal PAT testing 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests 0 0 Overdue Annual Emergency Lighting tests Overdue Weekly Fire Alarm Testing 0 Overdue Fire Panel - Six Monthly Testing 1 1 Overdue Fire Safety Equipment tests **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors 0 Communal Fire doors due for replacement within 5 years **Dwelling Doors** 0 Failing Dwelling Fire Doors

Dwelling Fire doors due for replacement within 5 years

0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



Date of Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Risk Assessment

Quantity

Fire & Safety Assessor

Enforcing Fire Authority

Scheme Tel. No

Other staff in attendance

Number of on-site Accent staff

Number of other (non-Accent) staff

Scheme Inspection completed

Number of occupants

Personal Emergency Evacuation Plans in place

Current Evacuation Strategy

Conversion or purpose-built

Number of Storeys

Number of floors on which car parking is provided

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

Number of external staircases

External balcony part of escape route?

Unusual features

17/01/2025

12

Annual Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

1

Steven Manners Tech IOSH MIFSM MFPA

West Yorkshire

01274 816440

Zehnum Hussain

Scheme Manager Part-Time

Contract Cleaners in common areas

Yes

45

Yes

Stay Put (Delayed) Evacuation

Purpose Built

2

No

3 Protected

None

No

None

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Residential

Fire Detection and Warning System Flats and common areas not linked

Grade of Fire Alarm Grade A

Category of Fire Alarm LD1 Maximum Protection

Emergency Lighting Provision Maintained system - Common areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted Yes

Water Extinguisher(s) present

Foam Extinguisher(s) present No

Dry Powder Extinguisher(s) present No

Carbon Dioxide Extinguisher(s) present

Yes

Fire Blanket(s) present Yes

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present No

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no

obvious damage?

Comment All in good condition at the time of inspection.

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment Electrical condition report certificates are available

on ActiveH

Yes

Yes

Last test date :- 30/11/2020

Electrical App/PA Testing - tested within past 12 months?

Comment Labels visible on electrical equipment.

Last test date :- 08/07/2024

Absence of trailing leads and adapters?

Comment None Found at the time of inspection.

Evidence that mobility scooters are not being stored/charged in Yes

common areas?

Comment None on this scheme. None found at the time of

inspection.

Yes

N/A

Yes

Yes

Is there a purpose built mobility scooter store/charging area?

N/A

Comment Not required.

Does the building have a lightning protection system?

Comment

Gas installations

Is there a commercial/domestic gas supply to the scheme? Yes

Comment There is a boioer room on site, the boilers produce

heating for the entire scheme.

Valid LGSR held on file for fixed communal area gas appliances?

(Boilers)

Comment All gas certs are available on ActiveH

Last test date :- 27/07/2024

Valid LGSR held on file for residential flats that contains gas

appliances?

Comment No gas in residents flats.

Are smoke/heat detectors within General Needs flats subject to an Yes

annual inspection and the results

Comment Tested by Tunstall Annualy.

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered

to?

Comment Smoking is not allowed within the communal areas,

Residents are allowed to smoke within their flats. No smoking signs are visible throughout the building

Adequate security against arson?

Comment THere is a fob entry system to the main entrance,

fire exits are openable from inside onkly with exception to the exits from the communal lounge,

these doors have a digi lock fitted.

Are refuse/recycling bin areas managed and suitably located?

Comment There is an external refuse area. There is an external refuse area.

internaly accessed store accessible on the ground

floor. Yes

Are there communal cooking facilities at this scheme?

Comment There is a small kitchen within the communal lounge

which is mainly used for tea and coffee making.

Are reasonable measures taken to prevent fires as a result of cooking?

Comment

Comment

There is heat detection within the kitchen, An extrsctor fan is situated in the kitchen but it isnt above the cooker.

Where there is extraction in communal kitchens, are filters and

N/A

ductwork changed/cleaned regularly?

The extraction fan has no filters.

Housekeeping

Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items?

Some items were found in the electrical room which were removed at the time of inspection by the SHP.

Comment

Yes

No

Are unnecessary accumulations of combustible materials or waste avoided?

None found at the time of inspection.

Comment

Yes

Are combustible materials and substances separated from ignition sources and stored appropriately?

Nnone found at the time of inspection.

Comment

Yes

Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations?

Furniture is only allowed within the communal lounge, all furniture found at the time of inspection. conforms to regulations.


Comment

Referred To

Required By: Task ID

Observation Priority

Combustible items in corridor requires removing. SHP informed and dealing, has spoken to resident at the time of inspection.



Internal - Low

Observation Priority Referred To Required By: Task ID

Items stored in electrical cupboard adjacent to laundry room need removing. SHP dealing.



Internal - Medium

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Yes

Comment None found at the time of inspection.

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of

escape in case of fire?

Escape routes unobstructed and safe to use?

dealt with by the

Exits immediately openable without a key and/or failsafe's function correctly?

Comment

Reasonable distances of travel where there is a single/alternative

direction of travel?

Comment

Escape routes lead to final exits and open in direction of escape where necessary?

Comment

Comment

Comment

There is more than one direction of travel throughout the scheme, all travel distances are within the guidlines

Yes

Escape routes clear although spme combustable items were found within the corridor which were dealt with by the SHP at the time of inspection.

Yes

One fire exit was a little stiff but openable. The SHP

is dealing and has reported it for repair.

Yes

As above.

Observation Priority Referred To Required By: Task ID

Tools and items of equipment along escape routes require removing. SHP Dealing, a garden shed will be provided to store equipment safely



Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?

Comment

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?

Comment

As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?

Comment

Loft hatches fire resisting?

Comment

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?

Comment

Do external walls, doors, windows and anything attached to the exterior, limit fire spread?

Comment

If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?

Comment

Are roller shutter doors that are required to be FR, fire resisting and self-closing?

Comment

Yes

Comparmentation within service rooms is of a reasonable standard at the time of inspection.

Yes

All notices are behind a glass notice board.

N/A

No access at the time of inspectin to the refuse area at the time of inspection.

N/A

No Access at the time of inspection.

Yes

1 hour loft hatches installed throughout the scheme.

Yes

Cross coridor doors have a Wired glass panel to the ceiling.

Yes

This building is of a traditional construction.

N/A

None Fitted

N/A

None Fitted.

Aprilia Court Hunters Park Avenue, Bradford Asset ID: 8669

Observation **Priority** Referred To Required By: Task ID

Communal Fire door opposite flat 9 requires ease and adjusting to close to rebate.

Work Order 1249398



Repair - Non Emergency

Project Manager (Building Safety) 31/03/2025

1909872



Observation

Ground floor refuse door requires replacement FD60S door warped and doesn't close to latch Work Order 1249396



Priority

Repair - Non **Emergency**

Referred To

Project Manager (Building Safety) Required By:

Task ID

31/03/2025 1909871



Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per current standards?

Comment

Emergency lighting units in good condition and securely fixed to walls/ceilings?

Comment

Records of monthly/annual testing available?

Comment

Yes

Yes

All in good condition and in working order at the time of inspection.

Yes

All records are available on ActiveH. Last Monthly test :- 14/01/2025 Last Drop Test :-24/04/2024

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?

Aprilia Court Hunters Park Avenue, Bradford Asset ID: 8669

of inspection.

Directional fire escape signage in place and adequate?

Comment

Comment

There is adequate escape signage throughout the

Signage visible throughout the Scheme at the time

Scheme.

Is there suitable LIFT signage i.e. do not use in case of fire?

Yes

Yes

Comment

Signage visible adjacent to lift on both floors.

Do common area fire doors display the correct signage on both sides

Yes

where applicable?

Comment

Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?

Yes

Comment

Is fire detection and warning system appropriate for occupancy and fire

risk, as per BS 5839-1:2017?

Yes

Comment

Is the fire detection and warning system maintained/tested and all

certificates saved on file?

Yes

Comment Weekly Tests carried out by THe Scheme Manager,

6 monthly tests carried out by Tunstall and recorded

on ActiveH

Last 6 Month teat date :- 05/11/2024

Fire alarm components in good condition and securely fixed to

walls/ceilings?

Comment

All in good condition at the time of inspection.

Hold open devices operate at the sounding of the alarm and are in a

serviceable condition?

Yes

Yes

Yes

Are there heat detectors located in the Kitchen, Boiler, Plant Room and

Laundry?

Comment

All in good condition at the time of inspection.

Comment

Is the fire alarm panel remotely monitored, and if so are there records of

regular testing?

Yes

As Above Comment

Observation Priority Referred To Required By: Task ID

Secondary Fire Panel and map



Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme?

Comment Only provided in high risk areas, there are no extinguishers within communal areas.

Yes

N/A

Portable fire extinguishers - appropriate type/number/position?

Yes

Comment

Correct signage displayed by each fire extinguisher?

Yes

Comment

Fire blanket in communal kitchen, secured to the wall, complete with

signage?
Comment

Dry risers - Inlet/outlet boxes secured and/or securing straps fitted to outlet valves?

Comment None fitted

Records available of fire fighting equipment servicing within past 12 Yes

months?

Comment Tested on 06/09/224

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under No

the Building Safety Act?

Comment Not in scope.

Are there other Responsible Persons who share or have fire safety No

duties in respect of the premises? How will this sharing be achieved?

Is an office or IL scheme being inspected?

is an embed of 12 deficine being inspected.

Comment

IL Schemes & Regional Offices - Are there sufficient numbers of

qualified Fire wardens?

Comment ILS

Offices - Are there suitable arrangements for ensuring the premises are

evacuated?

Comment There is a communal fire alarm for

residents?visitors?contractors who may be in the communal areas, signage directs them to evacuate

by the nearest exit.

N/A

Yes

Yes

N/A

Offices - Are there suitable arrangements for evacuating disabled

people?

Comment Each resident will have a PCFRA to determine if a

PEEP is required.

Offices - Suitable arrangements for meeting the fire service on arrival

and proving relevant information?

Comment ILS

Offices/IL Schemes - Is there a suitable assembly point?

Comment There is direction to assemble in the carpark gut

ther is no assembley point signage at the time of inspection. A works order will be raised to provide

one.

Offices - Are fire drills carried out at appropriate intervals?

Comment Not required.

Passenger Lift

Is the scheme fitted with a passenger lift?

Comment

Is the lift in full working order at the time of the FRA?

Comment

Is the lift fitted with a firefighters switch?

Comment

Servicing and insurance inspection - Evidence of regular Yes

servicing/maintenance?

Comment All certificates are available on ActiveH.

Last service date :- 08/11/2024

Premises Inspection Box

Is there a premises information box for fire & rescue service use?

Comment A PIB will be fitted in the near future.

Evacuation Policy

Are there suitable arrangements for summoning the fire service?

Comment

Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance?

Comment

Yes

There is a monitored fire alarm system within the communal area and each flat has a warden call system Monitored by Astraline.

Yes

Engagement with Residents

Has information of fire procedures been disseminated to residents?

Comment

Is general fire safety information disseminated to residents?

Comment

Yes

All residents have been provided with leaflets explaining the evacuation proceedure for their scheme, Information on Fire doors has also been delivered to the residents. All information is also available on the company website. New residents are given the information within their induction pack.

Yes

All residents have been provided with leaflets explaining the evacuation proceedure for their scheme, Information on Fire doors has also been delivered to the residents. All information is also available on the company website. New residents are given the information within their induction pack.

FRA Frequency

Taking the findings of this assessment into account, is the frequency of the FRA correct?

Comment

Yes

Miscellaneous

Are there any other observations/actions to raise that are not covered above.

Are there fire related remedial works required at this property, that will affect the fabric of the building?

Comment

Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).

Some fire doors did not fully close so works orders have been raised with our contractors.

Some minor works were required which have been raised with our contractors.

No

No

Yes

Yes

Unauthorised items were found in communal areas and arrangements were made for their removal.	168
Not all records were up to date, as noted in the table below. Arrangements have been made for these to be completed.	No
A number of fire doors were found to be wedged or propped open. Fire	No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

systems.		·		, ,	
_	•	evention measures t the hazard from th		e time of this risk pability of ignition) a	t this
LOW	X	MEDIUM		нівн	
any procedural	arrangements ob	•	of the assessm	e fire protection afforent, it is considered	
MINOR		MAJOR	X	CRITICAL	

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial
	<u> </u>