# Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 35078 1-10 Heron Court Block 7-10, Ramsey

#### **Cover Sheet**

Photo



Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

23 Oct 2023

23 Oct 2026

36

New Build (Initial Assessment)

Type 3 (Common Parts and Flats - Non Destructive)

Lynn.betteridge@accentgroup.org

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

#### The Scheme

Scheme Name St Mary's Road

Scheme Address 1-10 Heron Court Block 7-10, Ramsey

Postcode PE26 2AF

Region

Scheme Manager

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority Cambridgeshire Fire and Rescue Service.

Other staff in attendance Developer and Clark of works

Number of on-site Accent staff

None

Number of other (non-Accent) staff

Contract Cleaners in common areas

## The Building

Accommodation Type

**Build Date** 

Number Of Homes 4

Homes breakdown Flat

External wall construction

External wall finish

Roof construction

Roof covering

PEEPs in place where necessary

Yes

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys

Number of floors on which car parking is provided 1

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

Number of External Staircases None

External Balcony part of escape route? N/A

Unusual features

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

Asset ID: 35078 1-10 Heron Court Block 7-10, Ramsey	
Fire Detection and Warning System	Flats and common areas not linked
Grade of fire alarm	
Category of fire alarm	LD3 Minimum Protection
Emergency Lighting Provision	Maintained system - Common areas
Portable Fire Extinguishers supplied/fitted	No
Fixed Fire Fighting Installations	No
Customers	
Number of occupants	9
Occupant tenure type breakdown	
Fire Safety Related Customer Safety Servicing	
Overdue communal gas safety checks	0
Overdue domestic gas safety checks	0
Overdue communal electrical condition checks	0
Overdue domestic electrical condition checks	0
Overdue alarm call pull chord tests	0
Overdue communal PAT testing	0
Overdue customer mobility scooter PAT testing	0
Overdue Monthly Emergency Lighting Switch Tests	
Overdue Annual Emergency Lighting tests	
Overdue Weekly Fire Alarm Testing	0
Overdue Fire Panel - Six Monthly Testing	
Overdue Fire Safety Equipment tests	
Building Fire Safety Surveys - Communal Doors	
Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	0
Dwelling Doors	
Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

# Fire Risk Assessment Survey Results

## **Scheme and Building Information**

Photo



Date of Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Risk Assessment

Quantity

Fire & Safety Assessor

**Enforcing Fire Authority** 

Scheme Tel. No

Other staff in attendance

Number of on-site Accent staff

Number of other (non-Accent) staff

Scheme Inspection completed

Number of occupants

Personal Emergency Evacuation Plans in place

**Current Evacuation Strategy** 

Conversion or purpose-built

Number of Storeys

Number of floors on which car parking is provided

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

Number of external staircases

External balcony part of escape route?

Unusual features

23/10/2023

36

New Build (Initial Assessment)

Type 3 (Common Parts and Flats - Non Destructive)

1

Lynn.betteridge@accentgroup.org

Cambridgeshire Fire and Rescue Service.

Developer and Clark of works

None

Contract Cleaners in common areas

Yes

9

Yes

Stay Put (Delayed) Evacuation

Purpose Built

3

1

No 1

None

N/A

Ollusual leatures

# Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Residential

Fire Detection and Warning System Flats and common areas not linked

Grade of Fire Alarm

Category of Fire Alarm LD3 Minimum Protection

Emergency Lighting Provision Maintained system - Common areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted No

Water Extinguisher(s) present

Foam Extinguisher(s) present No

Dry Powder Extinguisher(s) present

Carbon Dioxide Extinguisher(s) present

Fire Blanket(s) present

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present

Yes

### **Electrical Sources of Ignition**

Electrical installation within common areas in good condition and no

obvious damage?

Comment New build all in good condition.

Valid Electrical Installation Condition Reports held on file? (Common Yes

Areas & General Needs Flats)

Comment New build all certificates have been uploaded to

active H and M files.

Yes

Electrical App/PA Testing - tested within past 12 months?

N/A

Comment

Absence of trailing leads and adapters? Yes

Comment

Evidence that mobility scooters are not being stored/charged in No

common areas?

Comment

Is there a purpose built mobility scooter store/charging area?

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 5 of 13

Generated 02/11/2023 16:06:52

1-10 Heron Court Block 7-10, Ramsey Asset ID: 35078 Comment No Does the building have a lightning protection system? Comment Gas installations Is there a commercial/domestic gas supply to the scheme? Yes Comment Yes Valid LGSR held on file for fixed communal area gas appliances? (Boilers) Comment New build all certificates have been uploaded to active H and M files. Yes Valid LGSR held on file for residential flats that contains gas appliances? Comment Yes Are smoke/heat detectors within General Needs flats subject to an annual inspection and the results Comment New build all certificates have been uploaded to active H and M Other Sources of Ignition Is there a no smoking policy in place, which is enforced and adhered Yes to? Comment Adequate security against arson? Yes Comment New build all doors secure via Mag lock with emergency release in event of a fire. Are refuse/recycling bin areas managed and suitably located? Yes Comment Allground floor fire stopping in garage area completed. No Are there communal cooking facilities at this scheme? Comment Housekeeping Yes Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items? Comment All clear at time of inspection. Yes Are unnecessary accumulations of combustible materials or waste avoided?

Are combustible materials and substances separated from ignition

sources and stored appropriately?

Comment

Comment

Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations?

Comment

All intake external cupboards have been fire stopped with the correct sealing as previous sealing was deemed not appropriate (pink foam).

Yes

Yes

Yes

Yes

Yes

Yes

Yes

## Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Comment No other hazards found at time of inspection.

## Means of Escape from Fire

Is it considered that the building is provided with reasonable means of

escape in case of fire?

A single communal staircase with final exit. Comment

Escape routes unobstructed and safe to use? Yes

Comment New build all communall areas all clear.

Exits immediately openable without a key and/or failsafe's function correctly?

Comment Emergency release on sounding of the alarm and

push button exit.

Reasonable distances of travel where there is a single/alternative direction of travel?

Comment Means of escape routes meets the code of practice

Doc B1.

Escape routes lead to final exits and open in direction of escape where

necessary?

Comment

Comment Open to safe Air with no obstructions.

#### Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard? Yes

Comment Compartmentation at all 3 levels satisfactory, block

walls plaster and painted finish.

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?

N/A

Yes

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 7 of 13

Generated 02/11/2023 16:06:52

Asset ID: 35078 1-10 Heron Court Block 7-10, Ramsey Comment Yes As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard? Comment The roof compartmentation meets approved code Doc B32.8 loft hatch accessed on the day of inspection. Yes Loft hatches fire resisting? Comment 1 hour fire resisting loft hatch with lock. N/A As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard? No communal fire doors on this scheme Comment Yes Do external walls, doors, windows and anything attached to the exterior, limit fire spread? Comment The external walls doors and windows will not propagate fire spread around the envelope of the building. Yes If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available? Comment New build all certificates have been uploaded to active H and M on the day of inspection the AOV was tested for operation.contract in place for Annual testing N/A Are roller shutter doors that are required to be FR, fire resisting and self-closing? Comment **Emergency Escape Lighting** Yes Is the emergency lighting correctly specified and installed as per current standards? Comment Yes Emergency lighting units in good condition and securely fixed to walls/ceilings? Comment On the day of inspection the block was found to have secure emergency lighting. Records of monthly/annual testing available? Yes Comment New build all certificates have been uploaded to active H and M. Tunstalls is the main contractor for the testing. Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?

Comment

Yes

Directional fire escape signage in place and adequate? Yes

Comment Direction signs on all levels.

Is there suitable LIFT signage i.e. do not use in case of fire? No

Do common area fire doors display the correct signage on both sides

where applicable?

Comment No communal fire doors on this scheme.

Means of giving Warning in case of Fire

No Is the scheme fitted with a communal area fire alarm?

Comment

Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations

provided at this scheme?

Comment

Comment

No

N/A

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under

the Building Safety Act?

Are there other Responsible Persons who share or have fire safety

duties in respect of the premises?

Have all details required by regulations been shared with all other

Responsible Persons?

Comment

Have all details required by regulations to be shared with us from other

Responsible Persons been received and recorded?

Will this FRA be shared will all other Responsible Persons for the

Comment

premises?

Comment

How will this sharing be achieved?

Is an office or IL scheme being inspected?

Comment

No

Scheme 3 floors only not in scope.

Yes

Yes

Communication with the local Fire Authority and

residents.

Yes

All recorded on active H and M all certificates

uploaded.

Yes

All accent staff are given access to the FRA.

Communication with all parties within the Accent

Housing Association and the residents.

No

Asset ID: 35078 1-10 Heron Court Block 7-10, Ramsey	
Passenger Lift	
Is the scheme fitted with a passenger lift?	No
Comment	
Premises Inspection Box	
Is there a premises information box for fire & rescue service use?	No
Comment	
Evacuation Policy	
Are there suitable arrangements for summoning the fire service?	Yes
Comment	Residents call the fire and rescue service in the event of a fire.
Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance?	Yes
Comment	
Engagement with Residents	
Has information of fire procedures been disseminated to residents?	Yes
Comment	When residents move into the flats they are given fire safety advice and also leaflets and directed to the internet website for additional information.
Is general fire safety information disseminated to residents?	Yes
Comment	Fire routine notices are located in the communal area with advice on the stay put policy.further information on fire safety campaigns are also published on the website to look at the FRA or future safety notices ie Christmas safety.
FRA Frequency	
Taking the findings of this assessment into account, is the frequency of the FRA correct?  Comment	Yes
Miscellaneous	
Are there any other observations/actions to raise that are not covered above.	No
Are there fire related remedial works required at this property, that will affect the fabric of the building?	Yes

Page 10 of 13

MIS-AMS ActiveH - Fire Risk Assessment Report

Generated 02/11/2023 16:06:52

1-10 Heron Court Block 7-10, Ramsey Asset ID: 35078

Can work be conducted without the need for an asbestos survey. If no,

task Customer Safety Surveyor - Asbestos.

Comment

Comment

Were there any unsatisfactory aspects of the Fire Risk Assessment?

(Visible on Building Safety Report).

Only on the material used to seal intake cupboards

which has been rectified.

N/A

No

#### **Risk Calculator - Fire**

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

systems.		•			
_	•	evention measures ob t the hazard from the			at this
LOW	X	MEDIUM		HIGH	
any procedural	arrangements ob	e of the building, the observed at the time of ne event of a fire would	the assessme	•	
MINOR		MAJOR		CRITICAL	

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial
	<u> </u>