Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 8651 1-3a Station Road Block 1-1a & 3-3a Station Road, Peterlee

Cover Sheet

Photo



Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

02 Oct 2024

02 Oct 2026

24

2 year Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Kevin Jones

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name Station Rd Easington

Scheme Address 1-3a Station Road Block 1-1a & 3-3a Station Road,

Peterlee

Postcode SR8 3SW

Region North East

Scheme Manager

Scheme Tel. No N/A

Scheme Inspection Completed Yes

Enforcing Fire Authority Durham and Darligton

Other staff in attendance None

Number of on-site Accent staff None

Number of other (non-Accent) staff None

The Building

Accommodation Type General Needs (S30)

Build Date Jan 1 1915

Number Of Homes 4

Homes breakdown Flat

External wall construction Facing Brick

External wall finish Facing Brick, Timber Clad

Roof construction Timber

Roof covering Interlocking Pitched

PEEPs in place where necessary N/A

Current Evacuation Strategy Full (Simultaneous) Evacuation

Conversion or purpose-built Conversion

Number of storeys 2

Number of floors on which car parking is provided 1

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

1 protected

Number of External Staircases 0

External Balcony part of escape route? N/A

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

1-3a Station Road Block 1-1a & 3-3a Station Road, Peterlee Asset ID: 8651 Flats and common areas not linked Fire Detection and Warning System Grade D Grade of fire alarm Category of fire alarm LD3 Minimum Protection Maintained system - Common areas **Emergency Lighting Provision** Portable Fire Extinguishers supplied/fitted No Fixed Fire Fighting Installations No **Customers** 1 Number of occupants **General Needs** Occupant tenure type breakdown Fire Safety Related Customer Safety Servicing Overdue communal gas safety checks 0 0 Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 Overdue communal PAT testing 0 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests 1 Overdue Annual Emergency Lighting tests 1 0 Overdue Weekly Fire Alarm Testing Overdue Fire Panel - Six Monthly Testing Overdue Fire Safety Equipment tests **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors Communal Fire doors due for replacement within 5 years 0 **Dwelling Doors** 0 Failing Dwelling Fire Doors

Dwelling Fire doors due for replacement within 5 years

0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



02/10/2024

1

Date of Fire Risk Assessment

FRA Frequency (Months) 24

Purpose of Fire Risk Assessment 2 year Re-Assessment

Type of Risk Assessment Type 1 (Common Parts Only - Non Destructive)

Quantity

Fire & Safety Assessor Kevin Jones

Enforcing Fire Authority Durham and Darligton

Scheme Tel. No N/A

Other staff in attendance None

Number of on-site Accent staff

None

Number of other (non-Accent) staff

None

Scheme Inspection completed Yes

Number of occupants

Personal Emergency Evacuation Plans in place N/A

Current Evacuation Strategy Full (Simultaneous) Evacuation

Conversion or purpose-built Conversion

Number of Storeys 2

Number of floors on which car parking is provided 1

Is there a habitable basement?

No. of internal staircases (protected/unprotected) 1 protected

Number of external staircases 0

External balcony part of escape route? N/A

Unusual features None

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Residential

Fire Detection and Warning System Flats and common areas not linked

Grade of Fire Alarm Grade D

Category of Fire Alarm LD3 Minimum Protection

Emergency Lighting Provision Maintained system - Common areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted No

Water Extinguisher(s) present No

Foam Extinguisher(s) present

Dry Powder Extinguisher(s) present

Carbon Dioxide Extinguisher(s) present

Fire Blanket(s) present

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no

obvious damage?

Comment Appears in good condition and secured.

Yes

Yes

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment ESC DUE 04/07/2028

Electrical App/PA Testing - tested within past 12 months?

N/A

Comment No portable appliances identified

Absence of trailing leads and adapters?

Comment No portable appiances identified

Evidence that mobility scooters are not being stored/charged in No

common areas?

Comment N/A

Is there a purpose built mobility scooter store/charging area?

Comment

Does the building have a lightning protection system?

Comment Not required for the heightr of building

Gas installations

Is there a commercial/domestic gas supply to the scheme?

Comment

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered Yes

to?

Comment Permitted to smoke in flats only

Adequate security against arson? Yes

Comment Multi lock to main entrance

Are refuse/recycling bin areas managed and suitably located? Yes

Comment Dedicated bin storage area

Are there communal cooking facilities at this scheme?

Comment

Housekeeping

Are all electrical/intake/service cupboards secure and free from general

waste, contractors waste and and residents personal items?

Comment Sterile cupboard identified.

Yes

Yes

N/A

Are unnecessary accumulations of combustible materials or waste

avoided?

Comment Good houskeeping idenified

Are combustible materials and substances separated from ignition Yes

sources and stored appropriately?

Comment Sterile areas identified

Furniture/furnishings in good condition, fire retardant/resistant and

comply with modern standards and regulations?

Comment None supplied in property

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Comment Single staircase with samll entrance lobby and small landing area all clear of flamable materials

MIS-AMS ActiveH - Fire Risk Assessment Report Page 6 of 13 Generated 03/10/2024 16:01:57

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of escape in case of fire?

Comment

Escape routes unobstructed and safe to use?

Comment

Exits immediately openable without a key and/or failsafe's function correctly?

Comment

Reasonable distances of travel where there is a single/alternative

direction of travel?

Escape routes lead to final exits and open in direction of escape where necessary?

Comment

Comment

Yes

Single staircase to single exit door in small

communal area.

Yes

Sterile environment identiied

Yes

Thumbturn operated handle/lock

Yes

Small MOE area minimal travel distance

Yes

Observation Priority Referred To Required By: Task ID

sterile stairway







Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?

Comment

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?

Comment

As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?

Yes

Converted flat from single dweling complarmentation is can not be totally inspected

Yes

Plaster finish throughout

N/A

None provided

N/A

Comment Unable to access roof void loft hatches in flats.

Loft hatches fire resisting?

Comment Unable to access roof void loft hatches in flats.

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory

standard?

Comment No cross coridors in property

Do external walls, doors, windows and anything attached to the

exterior, limit fire spread?

Comment Large dormer type window extention to the frontof

No

N/A

N/A

the property is constructed of timber ply

If Smoke Control Systems (AOV's) are fitted, are the records of annual

testing available?

Comment None fitted

Are roller shutter doors that are required to be FR, fire resisting and

self-closing?

Comment None fitted

Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per Yes

current standards?

Comment Appears to be insalled to the correct standards

Emergency lighting units in good condition and securely fixed to Yes

walls/ceilings?

Comment Appears to be in good condition and secured

Records of monthly/annual testing available? Yes

Comment Most recent test carried out on 02/09/2024

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent

Yes

locations within the common areas?

Comment Positioned on the landing

Directional fire escape signage in place and adequate?

Yes

Comment Positioned above the exit door

Is there suitable LIFT signage i.e. do not use in case of fire?

Comment

Do common area fire doors display the correct signage on both sides N/A

where applicable?

Comment None fitted

Observation **Priority** Referred To Required By: Task ID

signage visable on landing

No Action



Means of giving Warning in case of Fire

Yes Is the scheme fitted with a communal area fire alarm?

Comment Single battery smoke detector on lanading

Is fire detection and warning system appropriate for occupancy and fire

risk, as per BS 5839-1:2017?

Comment

Yes Is the fire detection and warning system maintained/tested and all

certificates saved on file?

Most recent test 05/08/2024 Comment

Fire alarm components in good condition and securely fixed to

Yes walls/ceilings?

Comment Appears to be in good condition and secured

Hold open devices operate at the sounding of the alarm and are in a serviceable condition?

None fitted Comment

Are there heat detectors located in the Kitchen, Boiler, Plant Room and Yes

Fitted in flat kitchens Comment

No

Is the fire alarm panel remotely monitored, and if so are there records of

regular testing?

Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme?

Comment

Laundry?

Comment

No

Yes

N/A

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under

the Building Safety Act?

Comment

Are there other Responsible Persons who share or have fire safety

duties in respect of the premises?

How will this sharing be achieved?

Is an office or IL scheme being inspected?

Comment

No

No

No

Passenger Lift

Is the scheme fitted with a passenger lift?

Comment

No

Premises Inspection Box

Is there a premises information box for fire & rescue service use?

Comment

No

Evacuation Policy

Are there suitable arrangements for summoning the fire service?

Comment

Taking FRA findings, is the evacuation policy appropriate for the

scheme as per latest guidance?

Comment

Yes

99 telephine call from resident

Yes

Engagement with Residents

Has information of fire procedures been disseminated to residents?

Yes

Comment

Customer portal, Induction programme

Is general fire safety information disseminated to residents?

Yes

Comment

Customer portal, Induction programme

FRA Frequency

Taking the findings of this assessment into account, is the frequency of

the FRA correct?

Comment

No

Low risk identified from FRA changed to 2 yearly

inspections

Miscellaneous

Are there any other observations/actions to raise that are not covered above.

Are there fire related remedial works required at this property, that will

affect the fabric of the building?

Comment

Were there any unsatisfactory aspects of the Fire Risk Assessment?

(Visible on Building Safety Report).

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

systems.					
1. Taking into a	ccount the fire pre	evention measures	 observed at th	ne time of this risk	
assessment, it is building is:	s considered that	the hazard from the	e fire (the prob	bability of ignition) a	at this
LOW	X	MEDIUM		HIGH	
any procedural	arrangements ob	of the building, the served at the time on the event of a fire wo	of the assessm	•	
MINOR		MAJOR	X	CRITICAL	

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial
	<u> </u>