

This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

#### Asset ID: 34663 12 Wheelwright Way, Biddenham

#### **Cover Sheet**

Photo

Date of Fire Risk Assessment Date of Next Fire Risk Assessment FRA Frequency (Months) Purpose of Fire Risk Assessment Type of Fire Risk Assessment Fire & Safety Assessor



21 Mar 2023

21 Mar 2026

36

New Build (Initial Assessment)

Type 3 (Common Parts and Flats - Non Destructive)

Lynn.betteridge@accentgroup.org

This report has been validated by:

Name:

Date:

Comment:

### The Scheme

Scheme Name	Deep Spinney
Scheme Address	12 Wheelwright Way, Biddenham
Postcode	MK40 4XA
Region	East
Scheme Manager	
Scheme Tel. No	
Scheme Inspection Completed	Yes
Enforcing Fire Authority	Cambridgeshire Fire and Rescue Service I could tal
Other staff in attendance	None
Number of on-site Accent staff	None
Number of other (non-Accent) staff	Contract Cleaners in common areas

### The Building

Accommodation Type	General Needs (S30)
Build Date	Mar 29 2023
Number Of Homes	4
Homes breakdown	Flat
External wall construction	
External wall finish	
Roof construction	
Roof covering	
PEEPs in place where necessary	N/A
Current Evacuation Strategy	Stay Put (Delayed) Evacuation
Conversion or purpose-built	Purpose Built
Number of storeys	2
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
Number of internal Staircases (protected or unprotected?)	One protected
Number of External Staircases	None
External Balcony part of escape route?	No
Unusual features	None
Building Access Conditions for Fire Brigade	Vehicular Access to one or more elevations

Fire Detection and Warning System	Flats and common areas not linked
Grade of fire alarm	Grade D
Category of fire alarm	LD3 Minimum Protection
Emergency Lighting Provision	Maintained system - Common areas
Portable Fire Extinguishers supplied/fitted	No
Fixed Fire Fighting Installations	No

#### Customers

Number of occupants	4
Occupant tenure type breakdown	

### Fire Safety Related Customer Safety Servicing

Overdue communal gas safety checks	0
Overdue domestic gas safety checks	0
Overdue communal electrical condition checks	0
Overdue domestic electrical condition checks	0
Overdue alarm call pull chord tests	0
Overdue communal PAT testing	0
Overdue customer mobility scooter PAT testing	0
Overdue Monthly Emergency Lighting Switch Tests	
Overdue Annual Emergency Lighting tests	
Overdue Weekly Fire Alarm Testing	0
Overdue Fire Panel - Six Monthly Testing	
Overdue Fire Safety Equipment tests	

### **Building Fire Safety Surveys - Communal Doors**

Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	0

### **Dwelling Doors**

Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

## Fire Risk Assessment Survey Results

### Scheme and Building Information

Photo

Date of Fire Risk Assessment	21/03/2023
FRA Frequency (Months)	36
Purpose of Fire Risk Assessment	New Build (Initial Assessment)
Type of Risk Assessment	Type 3 (Common Parts and Flats - Non Destructive)
Quantity	1
Fire & Safety Assessor	Lynn.betteridge@accentgroup.org
Enforcing Fire Authority	Cambridgeshire Fire and Rescue Service I could tal
Scheme Tel. No	
Other staff in attendance	None
Number of on-site Accent staff	None
Number of other (non-Accent) staff	Contract Cleaners in common areas
Scheme Inspection completed	Yes
Number of occupants	4
Personal Emergency Evacuation Plans in place	N/A
Current Evacuation Strategy	Stay Put (Delayed) Evacuation
Conversion or purpose-built	Purpose Built
Number of Storeys	2
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
No. of internal staircases (protected/unprotected)	One protected
Number of external staircases	None
External balcony part of escape route?	No
Unusual features	None



# Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade	Vehicular Access to one or more elevations
Surroundings: Residential/Commercial	Residential
Fire Detection and Warning System	Flats and common areas not linked
Grade of Fire Alarm	Grade D
Category of Fire Alarm	LD3 Minimum Protection
Emergency Lighting Provision	Maintained system - Common areas
Portable Fire Extinguishers / Fire Blankets supplied / fitted	No
Water Extinguisher(s) present	No
Foam Extinguisher(s) present	No
Dry Powder Extinguisher(s) present	No
Carbon Dioxide Extinguisher(s) present	No
Fire Blanket(s) present	No
Fixed Fire Fighting Installations supplied / fitted	No
Dry Riser(s) present	No
Wet Riser(s) present	No
Sprinkler System present	No
Hosereel(s) present	No
Automatic Opening Vent(s) present	Yes

### **Electrical Sources of Ignition**

Electrical installation within common areas in good condit obvious damage? Comment	ion and no	Yes
Valid Electrical Installation Condition Reports held on file? Areas & General Needs Flats)	? (Common	Yes
Comment		These are new build flats and we'll have certification for electrical installation
Electrical App/PA Testing - tested within past 12 months?		N/A
Comment		
Absence of trailing leads and adapters?		Yes
Comment		
Evidence that mobility scooters are not being stored/charg common areas?	ged in	No
Comment		
Is there a purpose built mobility scooter store/charging are	ea?	No
MIS-AMS ActiveH - Fire Risk Assessment Report	Page 5 of 13	Generated 22/03/2023 13:48:43

#### Comment

Does the building have a lightning protection system? No Comment

#### **Gas installations**

Is there a commercial/domestic gas supply to the scheme?	Yes
Comment	
Valid LGSR held on file for fixed communal area gas appliances? (Boilers)	Yes
Comment	
Valid LGSR held on file for residential flats that contains gas appliances?	Yes
Comment	
Are smoke/heat detectors within General Needs flats subject to an annual inspection and the results	Yes
Comment	

### **Other Sources of Ignition**

Is there a no smoking policy in place, which is enforced and adhered to?	Yes
Comment	
Adequate security against arson?	Yes
Comment	
Are refuse/recycling bin areas managed and suitably located?	Yes
Comment	
Are there communal cooking facilities at this scheme?	No
Comment	

### Housekeeping

Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items? Comment	Yes
Are unnecessary accumulations of combustible materials or waste avoided? Comment	Yes
Are combustible materials and substances separated from ignition sources and stored appropriately? Comment	Yes

Furniture/furnishings in good condition, fire retardant/resistant and N/A comply with modern standards and regulations?

#### **Other Significant Fire Hazards**

Are all other significant fire hazards adequately controlled?	Yes
Comment	

#### Means of Escape from Fire

Is it considered that the building is provided with reasonable means of escape in case of fire?	Yes
Comment	
Escape routes unobstructed and safe to use?	Yes
Comment	
Exits immediately openable without a key and/or failsafe's function correctly?	Yes
Comment	
Reasonable distances of travel where there is a single/alternative direction of travel?	Yes
Comment	
Escape routes lead to final exits and open in direction of escape where necessary?	Yes
Comment	

#### **Fire Spread and Development**

Is it considered that the compartmentation is of a reasonable standard?	Yes
Comment	
Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?	Yes
Comment	
Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?	N/A
Comment	
As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?	Yes
Comment	Access to the roof space retained and compartmentation deemed satisfactory
Loft hatches fire resisting?	Yes
Comment	

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?	N/A
Comment	
Do external walls, doors, windows and anything attached to the exterior, limit fire spread?	Νο
Comment	
If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?	Yes
Comment	This is a new build and a certification was presented on the actual completion of installation and operation
Are roller shutter doors that are required to be FR, fire resisting and self-closing?	N/A
Comment	
Emergency Escape Lighting	
Is the emergency lighting correctly specified and installed as per current standards?	Yes
Comment	
Emergency lighting units in good condition and securely fixed to walls/ceilings?	Yes
Comment	
Records of monthly/annual testing available?	Yes
Comment	As this is a new build the monthly and annual

#### **Fire Safety Signs and Notices**

Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?	Yes
Comment	Needs to be installed by contractor when decoration of new build flats has been completed
Directional fire escape signage in place and adequate?	N/A
Comment	
Is there suitable LIFT signage i.e. do not use in case of fire?	N/A
Comment	
Do common area fire doors display the correct signage on both sides where applicable?	N/A
Comment	

### Means of giving Warning in case of Fire

testing regime will not take place for 12-months

Is the scheme fitted with a communal area fire alarm?	Yes
Comment	AOV
Is fire detection and warning system appropriate for occupancy and fire risk, as per BS 5839-1:2017?	Yes
Comment	
Is the fire detection and warning system maintained/tested and all certificates saved on file?	Yes
Comment	
Fire alarm components in good condition and securely fixed to walls/ceilings?	Yes
Comment	
Hold open devices operate at the sounding of the alarm and are in a serviceable condition?	N/A
Comment	
Are there heat detectors located in the Kitchen, Boiler, Plant Room and Laundry?	Yes
Comment	
Is the fire alarm panel remotely monitored, and if so are there records of regular testing?	N/A
Comment	

### Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations	No
provided at this scheme?	
Comment	

### Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under the Building Safety Act? Comment	Yes
Will this FRA be shared will all Accountable Persons for the premises?	Yes
Comment	
How will this sharing be achieved?	Communication
Are there other Responsible Persons who share or have fire safety duties in respect of the premises?	Yes
Have all details required by regulations been shared with all other Responsible Persons?	Yes
Comment	
Have all details required by regulations to be shared with us from other Responsible Persons been received and recorded?	Yes

Comment	
Will this FRA be shared will all other Responsible Persons for the premises?	Yes
Comment	
How will this sharing be achieved?	Communication
Is an office or IL scheme being inspected?	No
Comment	

### Passenger Lift

Is the scheme fitted with a passenger lift?	No
Comment	

### **Premises Inspection Box**

Is there a premises information box for fire & rescue service use?	No
Comment	

### **Evacuation Policy**

Are there suitable arrangements for summoning the fire service?	Yes
Comment	
Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance?	Yes
Comment	

### **Engagement with Residents**

Has information of fire procedures been disseminated to residents?	Yes
Comment	When residents take ownership of their flat which has communal access the fire safety pack is given to the residents with all the information required and also a link to the website to fire safety in the home
Is general fire safety information disseminated to residents?	Yes
Comment	General quarantine notices are found in the communal area next to the main exit and access door
FRA Frequency	
Taking the findings of this assessment into account, is the frequency of the FRA correct?	Yes

#### Asset ID: 34663

Comment

#### Miscellaneous

Are there any other observations/actions to raise that are not covered above.	No
Are there fire related remedial works required at this property, that will affect the fabric of the building?	No
Comment	
Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).	No

#### **Risk Calculator - Fire**

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW	X	MEDIUM		HIGH	
-----	---	--------	--	------	--

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR	MAJOR	X	CRITICAL	

The definition of the above terms is as follows: *FRA Review Frequency* 

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	intolerable

When the level of risk is established, the action level can be read from the table below:

#### Asset ID: 34663

#### 12 Wheelwright Way, Biddenham

Risk Level	Guide to actions and appropriate timescales	
Trivial	No action is required	
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.	
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.	
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.	

The Overall Risk Level for this asset is:	Trivial