

## **ACCENT HOUSING - FIRE RISK ASSESSMENT**



Region: North West

Scheme Name: Stark St

Scheme Address: Ramsden St

**Barrow in Furness** 

**LA14 2HQ** 

Date of Assessment: 01/08/2024

Date of Next Assessment: 01/08/2027

FRA Frequency: 3 Year Re-Assessment

Fire & Safety Assessor Ian Potter

This Fire Risk Assessment has been conducted upon the instruction of Accent Housing.

Scheme Details		Stark St
Region:		North West
Scheme Name:		Stark St
Site Address:	Street:	Ramsden St
	Town:	Barrow in Furness
	Post Code:	LA14 2HQ
Block & Asset No.		Block 6-8 Asset 9459
Block & Asset No.		Block 10-12 Asset 9460
Block & Asset No.		Block 14-16 Asset 9461
Date of this Assessment		01/08/2024
Date of Next Review		01/08/2027
Fire Risk Assessment Frequency		3 Years
Purpose of Fire Risk Assessment		3 Year Re-Assessment
Fire & Safety Assessor		lan Potter
Director of Assets and Compliance		Alex Liburd
Housing Partnership Manager		Jamie Trotter
Contract Manager		Karen Anthony
Scheme Manager/Customer Partner		Elayne Lindsay
Other staff in attendance		None
Use of Building		General Needs
		6 per block (6x 1 bed flats per
Approximate Number of occupants		block
Occupancy Profile		Mixed
Familiarity of the occupants		Fully Familiar
Likely state of the Occupants		Alert
PEEPs in place where necessary		N/A
Number of on-site Accent staff		None
		Contract cleaners in common
Number of other (non-Accent) staff		areas
Support Agency (Supported Housing)		N/A
Current Evacuation Strategy.		Stay Put (Delayed) Evacuation
Evidence that residents have been notified of the		Advice notices displayed in
evacuation procedure		common areas
History of fires in the building		None
Business Continuity Plan in place?		Yes
		Type 1 (Common Parts Only -
Scope of Assessment		Non Destructive)
Applicable Fire Safety Guidance		Purpose-built flats guide

Building Details	Stark St
Construction Date	1993
	Joisted or Load Bearing Masonry
Construction Type	(Traditional)
Roof Finish	Pitched-Slate Tile
External Wall Finish	Brick
Are there any areas of external wall cladding	No
Are there any balconies	No
Conversion or purpose-built	Purpose Built
Number of flats (self-contained)/rooms (HMOS, shared	
houses)	6 per block
Number of storeys above ground	Two
Number of storeys below ground	None
Is there a habitable basement?	No
Number of internal Staircases per Block	
(protected or unprotected?)	One-Protected
Number of External Staircases per Block	None
External Balcony part of escape route?	No
Unusual features	None
Building complexity	Simple
Building Access Conditions for Fire Brigade	Vehicular Access to one or more
	elevations
Surroundings: Residential/Commercial	Mixed
Fire Provision Currently in P	
Fire Detection and Warning System	Flats only
Grade of fire alarm	Grade D
Category of fire alarm	LD2 Additional Protection
	AOV in each staircase activated
Additional Comments:	by detector
Evacuation Alert System (EAS)	No
	Non Maintained System -
Emergency Lighting Provision	Common Areas
Portable Fire Extinguishers	None fitted
Fixed Fire Fighting Installations	None fitted

		Significant Findings - Fire					
	Sta				01/08/2024		
Action Ref:	Potential Area of Fire Risk	Yes-No-N/A	Observation/Comments/ Actions Required	Risk Rating	Target Completion Date	Referred To:	
			Fire Hazards				
1	Electrical Sources of Ignition:						
1.1	Electrical Installation within common areas (Fixed Wiring, sockets, switches, light fittings) in good condition and no obvious damage	Yes	All good at time of inspection				
1.2	Valid Electrical Installation Condition Reports held on file.(Common Areas)	Yes	Last tested Dec 2020 for all blocks - due 2025				
1.3	Valid Electrical Installation Condition Reports held on file. (General Needs Flats)	Yes	All checked and in date on ActiveH				
1.4	Electrical App/PA Testing - all portable appliances tested within past 12 months	N/A	None in communal areas	•			
1.5	Absence of trailing leads and adapters	Yes	None seen at time of inspection	•			
1.6	Mobility Scooters - Stored/charged in common areas, purpose built store/resident flat	N/A	None seen at time of inspection				
	2 Smoking:						
2.1	Are there any risks associated with smoking in the building?	Yes	Residents allowed to smoke in flats and external areas. No evidence of smoking in communal area seen at time of inspection.				
_	Arson:						
	Adequate security against arson?	Yes	All front doors have door entry system. All secure at time of inspection.	•			
3.2	Is there an absence of unnecessary fire load in close proximity to building?	Yes	None seen at time of inspection				

4	Heating Installations (Portable/fixed)					
-	Gas Installations - Common Areas & Gener	al Ne	eeds Residential flats.			
4.1	If portable heaters are used, are there suitable controls?	N/A	None found at time of inspection			
4.2	Are fixed heating installations subject to regular maintenance?	N/A	None installed in communal areas			
4.3	Valid LGSC held on file for each residential flat that contains gas appliances.	Yes	All certs in date on ActiveH			
5	Cooking:					
5.1	Are reasonable measures taken to prevent fires as a result of cooking?	N/A	No Cooking facilities in Communal areas	•		
5.2	Where there is extraction ventilation in communal kitchens are filters changed/ cleaned and ductwork cleaned regularly?	N/A	See above			
6	Lightning Protection System:					
6.1	Does the building have a lightning protection system, If so, is it adequately maintained?	N/A	Not required due to height			
7	Housekeeping:					
7.1	Is the standard of housekeeping adequate?	oN	Housekeeping generally good Block 6-8, Mail and paper flyers scattered on the floor nr the main entrance Block 14-18, Kitchen cabinets in second floor hallway. HP to arrange removal - Emailed 09/08/24	Med	31/8/24	Customer Partner
	Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and residents personal items.	Yes	None seen at time of inspection			
7.3	Are combustible materials separated from ignition sources and stored appropriately?	Yes	None seen at time of inspection			
7.4	Are unnecessary accumulations of combustible materials or waste avoided?	No	See 7.1 above	•		

8	Are hazardous materials stored appropriately (i.e. oxygen cylinders, flammable materials, explosive products, oxidising products, aerosols)  Furniture/furnishings on escape routes and Furniture/furnishings in good condition, fire		No hazardous materials stored  er communal areas:  None in communal area		
	retardant and complies with 1988 Regulations.	N/A		•	
9	Other Significant Fire Hazards:				
9.1	Are there other significant fire hazards that are inadequately controlled?	oN	None seen at time of inspection	-	
		Fire	Protection Measures		
	Means of Escape from Fire:				
10.1	Is it considered that the building is provided with reasonable means of escape in case of fire?	Yes	Visually all compartmentation appears sound in common areas	•	
10.2	Escape routes unobstructed and safe to use?	Yes	No obstructions to MOE at time of inspection	•	
10.3	Exits easily and immediately openable where necessary, without a key?	Yes	Thumbturn/Push button on exit doors and Break glass release for all	-	
10.4	Reasonable distances of travel where there is a single/alternative direction of travel?	Yes	All travel distances within required limits (7m and 30m)	-	
10.5	Escape routes lead to final exits and open in direction of escape where necessary?	Yes	Inward opening final exit doors. Acceptable due to occupancy numbers.	-	
10.6	Do failsafe's on locked exit doors function correctly?	Yes		•	
	Is it considered that the building is provided with reasonable arrangements for means of escape for disabled people?	Yes	Ground floor only	-	
	Measures to Limit Fire Spread and Develop	men			
11.1	Is it considered that the compartmentation is of a reasonable standard?	Yes	Compartmentation appears sound from areas that can be observed. Loft hatches locked except block 10-12. Checked loft area of this block and no breaches found	•	

11.2	Is there reasonable limitation of surface finishes that might promote fire spread (walls,	Yes	No surfaces that would support combustion			
	floors, ceilings)?					
11.3	Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion	N/A	None on scheme			
	products?		0 444			
11.4	Compartmentation within roof spaces of a satisfactory standard?	Yes	See 11.1 above.	•		
11.5	Loft hatches fire resisting?	Yes	FR loft hatches fitted	•		
11.6	Fire stopping above cross-corridor fire doors within suspended ceiling void of a satisfactory standard	N/A	Solid ceiling above doors			
11.7	Smoke Control Systems (AOV's) Are records of annual testing available?	Yes	All Tested 14th July 24 and tested by Assessor at time of inspection.			
11.8	Roller shutter doors (fire resisting)	N/A	None at scheme	•		
11.9	Do the external walls, windows, balconies etc pose a risk of significant fire spread?	No	Brick construction	-		
12			de - construction, hinges, closure devices, intum	esce	nt/smoke s	eal condition,
	glazing systems and maximum gaps betwe	en d	oor and frame.			
12.1	Communal fire doors to FD30s standard and in a serviceable condition,	Yes	All checked and working as required	•		
12.2	"Fire door keep shut/locked" signage displayed on both sides of all applicable doors.	Yes	Checked	•		
12.3	Hold open devices operate at the sounding of the alarm and are in a serviceable condition	N/A	None at scheme	-		
13	Flat entrance doors (Internal Common Area	s)				
13.1	Do flat entrance doors open onto internal escape routes?	Yes	All checked and appear from the outside to be in good condition and compliant.	•		
14	Flats with a single direction of escape to a	sing	le escape stairway. (External Balcony)			

444			lat ( )		1	<del>                                     </del>
14.1	Do the flat entrance doors that open onto an	1	None at scheme			
	external balcony have to be passed during an	N/A		•		
	escape?					
14.2	Are the separating walls between the flats		None at scheme			
	and the balcony floor that have to be passed	A				
	during an escape, fire-resisting up to a height	N/A		•		
	of 1.1m?					
15	Emergency Escape Lighting:					
	Is the emergency lighting correctly specified	S				
	and installed as per BS 5266-1:2016	Yes		•		
15.2	Are all emergency lighting units in good		All visually appear in good order			
10.2	condition and securely fixed to walls/ceilings	Yes	This violatily appear in good order			
15.5	, , , , , , , , , , , , , , , , , , ,		T			
15.9	Are records of monthly testing available?	sə,	Tested 13th July 2024			
15 10	Are records of annual testing available?	es	3hr Drop test conducted on 24th July 2024			
13.10	The records of affilial testing available!	Ύe	Ton Drop test conducted on 24th July 2024	•		
16	Fire Safety Signs and Notices:					
16.1	Are the correct Fire Action/Advice notices	(0	All replaced at time of inspection			
	displayed in prominent locations within the	Yes				
	common areas?					
16.3	Directional fire escape signage in place and	SS				
	adequate?	Yes		•		
16.4	Is there a suitable LIFT sign i.e. do not use in	A	No lift at scheme			
	case of fire.	N/A		•		
17	Means of giving Warning in case of Fire:					
17.1	Is the fire detection and warning system	(2)	Alarms in Flats only. Part 6 Grade D only			
	appropriate for the occupancy and fire risk?	Yes				
17.2	Is the fire detection and warning system		See above			
	correctly specified and installed as per BS	N/A				
	5839-1:2017	_				
17.3	Is the fire detection and warning system		See above			
	maintained/tested and all certificates saved	Ø				
	on file. (BS 5839-1:2017)	N/A		•		
	, ,					

17 /	Are there heat detectors located in the		See above		<u> </u>	
17.4	Kitchen, Boiler, Plant Room and Laundry?	N/A	See above			
	•					
17.5	Is the fire alarm panel remotely monitored,		See above			
	and if so are there records of regular testing?	N/A				
		_				
17.6	Are smoke/heat detectors within General		All tested and in date on ActiveH as part of			
	Needs flats subject to an annual inspection		Landlord Gas Safety Check			
	and the results recorded on an in date	Yes	·	•		
	Landlord Gas Safety Record (LGSR)					
	, , ,					
18	Fire Extinguishing Equipment:					
18.1	Portable fire extinguishers - appropriate	N N N	None at scheme			
	type/number/position?	Ž		•		
18.2	Correct signage displayed by each fire	N/A	See above			
	extinguisher?	Ž		•		
18.3	Fire blanket in communal kitchen, secured to	Ø	See above			
	the wall, complete with signage?	N/A/N		'		
18.4	Hose Reels - fitted, maintained?	N/A	None fitted			
10.5		Z	N. 614			
18.5	Dry/wet risers - Full access to all inlet/outlet		None fitted			
	boxes. All inlet/outlets secured and/or	NA				
	securing straps fitted to outlet valves?	_				
18.6	Records available of fire fighting equipment	_	None fitted			
	servicing within past 12 months	N/A		•		
19		N	lanagement of Fire Safety			
19.1	Are there suitable arrangements for	SS	Residents call 999			
	summoning the fire service?	Yes		'		
19.2	Do relevant staff carry out regular fire safety	S	Annually by HP. Last one Dec 23			
	checks	Yes		•		
10.3	Sheltered Schemes & Regional Offices - Are					
19.5	there sufficient number of qualified Fire	N/A/A				
	wardens.	Ž		•		
	Iwaiuciis.					

19.4	Offices - Are there suitable arrangements for ensuring the premises are evacuated?	N/A			
19.5	Offices - Are there suitable arrangements for evacuating disabled people?	N/A		-	
19.6	Offices - Are there suitable arrangements for meeting the fire service on arrival and providing relevant information?	N/A			
19.7	Offices/IL Schemes - Is there a suitable assembly point?	N/A			
19.8	Offices - Are fire drills carried out at appropriate intervals?	N/A			
20	Evacuation Policy				
20.1	Taking the findings of the FRA into account, is the evacuation policy appropriate for the scheme?	Yes	The findings support a stay put policy		

## Photographs - Fire 01/08/2024 Stark St




Photo No. 1

Mail and Flyers behind front door of Block 6-8




Photo No. 2

Kitchen cabinets in 2nd Floor stairway Block 14-16

## 6. Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

(please insert x below)

LOW

MEDIUM

HIGH

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

(please insert x below)

MINOR

MAJOR

CRITICAL

The definition of the above terms is as follows:

FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant
	(other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely
	to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trivial	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

Action Plan - Fire					
Stark St		01/08/2024			
Trivial					
Potential area of fire risk	Observation/Comments / Actions Required	Risk Rating	Completion Date	Referred To:	Task ID No.
Fire Hazards					
Housekeeping:					
Is the standard of housekeeping adequate?	Housekeeping generally good Block 6-8, Mail and paper flyers scattered on the floor nr the main entrance Block 14-18, Kitchen cabinets in second floor hallway. HP to arrange removal - Emailed 09/08/24	Med	31/08/24	Customer Partner	

Action Plan - Fire Page 13 of 13