28 May 2024



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 24573 Cranmore Court

Cover Sheet

Photo

Date of Fire Risk Assessment Date of Next Fire Risk Assessment FRA Frequency (Months) Purpose of Fire Risk Assessment Type of Fire Risk Assessment Fire & Safety Assessor



28 May 2024 28th May 2025 12 Annual Re-Assessment Type 1 (Common Parts Only - Non Destructive) Gary Bredin AFireE

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

Asset ID: 24573

Cranmore Court

The Scheme

Scheme Name	Cranmore Court
Scheme Address	Cranmore Court
Postcode	GU16 6EP
Region	South
Scheme Manager	Tracey Wilkinson
Scheme Tel. No	- Scheme
Inspection Completed	Yes Enforcing Fire
Authority	Surrey FRS Other staff in
attendance	None
Number of on-site Accent staff	Scheme Manager Weekdays
Number of other (non-Accent) staff	Contract Cleaners in common areas

The Building

Accommodation Type	CAT2 Housing for Older People (S28)
Build Date	Jan 1 1967
Number Of Homes	57
Homes breakdown	Bedsit, Flat, Bungalow
External wall construction	Concrete Block, Facing Brick, Facing Brick
External wall finish	Facing Brick, UPVC Cladding
Roof construction	Timber
Roof covering	Flat Roof, Interlocking Pitched, Plain Pitched
PEEPs in place where necessary	Yes
Current Evacuation Strategy	Stay Put (Delayed) Evacuation
Conversion or purpose-built	Purpose Built
Number of storeys	2
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
Number of internal Staircases (protected or unprotected?)	4 protected
Number of External Staircases	1 Not designed as a fire escape
External Balcony part of escape route?	
Unusual features	None
Building Access Conditions for Fire Brigade	Vehicular Access to one or more elevations

Asset ID: 24573 Cr

Cranmore Court

Fire Detection and Warning System	Flats and common areas linked
Grade of fire alarm	Grade A
Category of fire alarm	LD1 Maximum Protection
Emergency Lighting Provision	Non Maintained System - Common Areas
Portable Fire Extinguishers supplied/fitted	Yes
Fixed Fire Fighting Installations	No

Customers

Number of occupants	50
Occupant tenure type breakdown	General Needs, CAT2 Housing for Older People, Sheltered Schemes

Fire Safety Related Customer Safety Servicing

Overdue communal gas safety checks	0
Overdue domestic gas safety checks	0
Overdue communal electrical condition checks	0
Overdue domestic electrical condition checks	0
Overdue alarm call pull chord tests	0
Overdue communal PAT testing	0
Overdue customer mobility scooter PAT testing	0
Overdue Monthly Emergency Lighting Switch Tests	6
Overdue Annual Emergency Lighting tests	6
Overdue Weekly Fire Alarm Testing	2
Overdue Fire Panel - Six Monthly Testing	1
Overdue Fire Safety Equipment tests	6

Building Fire Safety Surveys - Communal Doors

Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	153

Dwelling Doors

Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo

Date of Fire Risk Assessment
FRA Frequency (Months)
Purpose of Fire Risk Assessment
Type of Risk Assessment
Quantity
Fire & Safety Assessor
Enforcing Fire Authority
Scheme Tel. No
Other staff in attendance
Number of on-site Accent staff
Number of other (non-Accent) staff
Scheme Inspection completed
Number of occupants
Personal Emergency Evacuation Plans in place
Current Evacuation Strategy
Conversion or purpose-built
Number of Storeys
Number of floors on which car parking is provided
Is there a habitable basement?
No. of internal staircases (protected/unprotected)
Number of external staircases
External balcony part of escape route?
Unusual features



28/05/2024
12
Annual Re-Assessment
Type 1 (Common Parts Only - Non Destructive)
1
Gary Bredin AFireE
Surrey FRS
-
None
Scheme Manager Weekdays
Contract Cleaners in common areas
Yes
50
Yes
Stay Put (Delayed) Evacuation
Purpose Built
2
0
No
4 protected
1 Not designed as a fire escape

None

Fire Risk Assessment Survey Results

Vehicular Access to one or more elevations
Residential
Flats and common areas linked
Grade A
LD1 Maximum Protection
Non Maintained System - Common Areas
Yes
No
Yes
No
Yes
Yes
No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no obvious damage? Comment	Yes
Valid Electrical Installation Condition Reports held on file? (Common Areas & General Needs Flats) Comment	Yes
Electrical App/PA Testing - tested within past 12 months?	Yes
Comment	January 2024
Absence of trailing leads and adapters?	Yes
Comment	
Evidence that mobility scooters are not being stored/charged in common areas? Comment	No
Is there a purpose built mobility scooter store/charging area?	No
······································	

Comment

Does the building have a lightning protection system?	N/A
Comment	
Is the protection system adequately maintained?	N/A
Comment	

Priority

Referred To

Required By: Task ID

Observation

All PA Testing in date



Gas installations

Is there a commercial/domestic gas supply to the scheme?	Yes
Comment Valid LGSR held on file for fixed communal area gas appliances? (Boilers) Comment	Yes
Valid LGSR held on file for residential flats that contains gas appliances?	Yes
Comment	
Are smoke/heat detectors within General Needs flats subject to an annual inspection and the results	Yes
Comment	
Other Sources of Ignition	
Is there a no smoking policy in place, which is enforced and adhered to?	Yes
Comment	
Adequate security against arson?	Yes
Comment	
Are refuse/recycling bin areas managed and suitably located?MIS-AMS ActiveH - Fire Risk Assessment ReportPage 6 of 16	Yes Generated 01/06/2024 16:00:30

Comment

The bin area is a good distance from the building And		То	
Observation	Priority	Referred	Required By: Task ID
Comment		Safety lable present an standards	d conform to the latest
Furniture/furnishings in good condition, fire retardant/resistant an comply with modern standards and regulations?	ıd	Yes	
Comment			
Are combustible materials and substances separated from ignitic sources and stored appropriately?	on	Yes	
Comment		All boiler rooms were c	lear at the time of the audit
Are unnecessary accumulations of combustible materials or was avoided?	te	Yes	
Are all electrical/intake/service cupboards secure and free from g waste, contractors waste and and residents personal items? Comment	general	Yes	
Housekeeping			
Comment			
Comment Where there is extraction in communal kitchens, are filters and ductwork changed/cleaned regularly?		Kitchen only used to wa Yes	arm food.
Are reasonable measures taken to prevent fires as a result of co	oking?	Yes	
Comment			
Are there communal cooking facilities at this scheme?		Yes	

was clear at the time of the audit.

ANMORE COURT MAIN ENTRANCE PRIVATE CAR PARK	
Producers with the Producers will be Produced to Produce Producers and Produced to Produce Pro	
And the second s	The second second

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Comment

Means of Escape from Fire

MIS-AMS ActiveH - Fire Risk Assessment Report

No

Is it considered that the building is provided with reasonable means of escape in case of fire?	Yes
Comment	
Escape routes unobstructed and safe to use?	Yes
Comment	
Exits immediately openable without a key and/or failsafe's function correctly?	Yes
Comment	All tested during the audit
Reasonable distances of travel where there is a single/alternative direction of travel?	Yes
Comment	
Escape routes lead to final exits and open in direction of escape where necessary?	Yes

Comment

Observation	Priority	Referred To	Required By:	Task ID
Various chairs and items are being left in the communal	Internal - Low	Housing Partner	10/06/2024	1821976

walk ways . Scheme partner informed and will arrange removal.





Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?	Yes
Comment Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?	Yes
Comment Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products? Comment	Yes
As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard? Comment Loft hatches fire resisting?	This area not checked during the audit.

Comment

As far as can be reasonably ascertained, is the fire stopping above Yes cross corridor fire doors within suspended ceiling void of a satisfactory standard? Comment Do external walls, doors, windows and anything attached to the Yes exterior, limit fire spread? Comment If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available? Comment

Are roller shutter doors that are required to be FR, fire resisting and self-closing?

Comment

Observation	Priority	Referred To	Required By:	Task ID
Communal reception area. End door set to flats A1 to C1 are not closing as designed. These require ease and adjusting.	Internal - Medium	Customer Safety Manager	31/07/2024	1821975





Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per current standards?	Yes
Comment	
Emergency lighting units in good condition and securely fixed to walls/ceilings?	Yes
Comment	
Records of monthly/annual testing available?	Yes
Comment	
Fire Safety Signs and Notices	
Are the correct Fire Action/Advice notices displayed in prominent	Yes

locations within the common areas?

Comment	
Directional fire escape signage in place and adequate?	Yes
Comment	
Is there suitable LIFT signage i.e. do not use in case of fire?	Yes
Comment	
Do common area fire doors display the correct signage on both sides where applicable?	Yes
Comment	

Observation	Priority	Referred To	Required By:	Task ID

Priority

Good signage throughout the scheme.



Observation

Emergency action notices are posted throughout the building.



Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?	Yes
Comment Is fire detection and warning system appropriate for occupancy and fire risk, as per BS 5839-1:2017?	Yes
Comment	
Is the fire detection and warning system maintained/tested and all certificates saved on file?	Yes
Comment	

Referred

То

Required By:

Task ID

Fire alarm components in good condition and securely fixed to walls/ceilings?		Yes		
Comment				
Hold open devices operate at the sounding of the alarm and are serviceable condition?	in a	No		
Comment Are there heat detectors located in the Kitchen, Boiler, Plant Roo Laundry?	om and	Some require attention. Yes	Scheme partner infor	med.
Comment				
Is the fire alarm panel remotely monitored, and if so are there re regular testing?	cords of	Yes		
Comment		Monitored out of hours.		
Fire Extinguishing Equipment				
Is fire extinguishing equipment and/or fixed fire fighting installation provided at this scheme? Comment	ons	Yes		
		Vac		
Portable fire extinguishers - appropriate type/number/position?		Yes		
Comment				
Correct signage displayed by each fire extinguisher?		Yes		
Comment				
Fire blanket in communal kitchen, secured to the wall, complete signage?	with	Yes		
Comment				
Dry risers - Inlet/outlet boxes secured and/or securing straps fitte outlet valves?	ed to	N/A		
Comment				
Records available of fire fighting equipment servicing within past months?	: 12	Yes		
Comment				
Observation	Priority	Referred To	Required By:	Task ID

All extinguishers were found to be up to date next test date. January 2025



Management of Fire Safety N/A Are these premises regulated by the Building Safety Regulator under the Building Safety Act? Comment Will this FRA be shared will all Accountable Persons for the premises? Yes Comment How will this sharing be achieved? These are held on Mfiles and shared when requested Yes Are there other Responsible Persons who share or have fire safety duties in respect of the premises? Have all details required by regulations been shared with all other **Responsible Persons?** Comment Have all details required by regulations to be shared with us from other Responsible Persons been received and recorded? Comment Will this FRA be shared will all other Responsible Persons for the Yes premises? Comment How will this sharing be achieved? This is accessible through Mfiles Is an office or IL scheme being inspected? Comment Yes IL Schemes & Regional Offices - Are there sufficient numbers of qualified Fire wardens? Comment Offices - Are there suitable arrangements for ensuring the premises are Yes evacuated? Comment Yes Offices - Are there suitable arrangements for evacuating disabled people? Comment N/A Offices - Suitable arrangements for meeting the fire service on arrival and proving relevant information? Comment Yes Offices/IL Schemes - Is there a suitable assembly point? Comment Offices - Are fire drills carried out at appropriate intervals? Yes MIS-AMS ActiveH - Fire Risk Assessment Report Page 13 of 16 Generated 01/06/2024 16:00:30

Asset ID: 24573 Cranmore Court Comment

Passenger Lift

Is the scheme fitted with a passenger lift?	Yes
Comment	
Is the lift in full working order at the time of the FRA?	Yes
Comment	
Is the lift fitted with a firefighters switch?	No
Comment Servicing and insurance inspection - Evidence of regular servicing/maintenance?	Yes
Comment	

Premises Inspection Box

Is there a premises information box for fire & rescue service use?	N/A
Comment Are there arrangements to check the premises information box is kept up to date?	N/A
Comment	

Evacuation Policy

Are there suitable arrangements for summoning the fire service?	Yes
Comment Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance?	Warden call monitored system. Yes
Comment	

Engagement with Residents

Has information of fire procedures been disseminated to residents?	Yes
Comment	These are posted throughout the scheme
Is general fire safety information disseminated to residents?	Yes
Comment	
FRA Frequency	
Taking the findings of this assessment into account, is the frequency of the FRA correct?	Yes

Comment

Miscellaneous

Are there any other observations/actions to raise that are not covered above.	No
Are there fire related remedial works required at this property, that will affect the fabric of the building?	No
Comment	
Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).	No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:



2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:



The definition of the above terms is as follows: *FRA Review Frequency*

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Asset ID: 24573

Cranmore Court

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset	Trivial
is:	