Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 31014 Blk 1 1-29 Napier Place, Peterborough

Cover Sheet

Photo

The state of the s

Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

22 Apr 2024

22 Apr 2025

12

Annual Re-Assessment

Type 3 (Common Parts and Flats - Non Destructive)

Lynn.betteridge@accentgroup.org

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name Napier Place

Scheme Address Blk 1 1-29 Napier Place, Peterborough

Postcode PE2 6XN

Region

Scheme Manager Gill Bettles

Scheme Tel. No

Scheme Inspection Completed

Enforcing Fire Authority Cambridgeshire Fire and Rescue Service

Other staff in attendance Scheme manager

Number of on-site Accent staff Scheme Manager Weekdays

Number of other (non-Accent) staff

Contract Cleaners in common areas

The Building

Accommodation Type CAT2 Housing for Older People (S28)

Build Date Jan 1 1988

Number Of Homes 30

Homes breakdown Flat

External wall construction Facing Brick

External wall finish Facing Brick, Hung Tiles

Roof construction Timber

Roof covering Interlocking Pitched, Plain Pitched

PEEPs in place where necessary

Yes

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys 1

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

None

Number of External Staircases None

External Balcony part of escape route?

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

Blk 1 1-29 Napier Place, Peterborough Asset ID: 31014 Fire Detection and Warning System Flats and common areas linked Grade A Grade of fire alarm Category of fire alarm **LD1 Maximum Protection Emergency Lighting Provision** Non Maintained System - Common Areas Portable Fire Extinguishers supplied/fitted Yes Fixed Fire Fighting Installations No **Customers** 55 Number of occupants General Needs, CAT2 Housing for Older People Occupant tenure type breakdown Fire Safety Related Customer Safety Servicing Overdue communal gas safety checks 0 0 Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 Overdue communal PAT testing 0 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests 1 Overdue Annual Emergency Lighting tests 1 0 Overdue Weekly Fire Alarm Testing Overdue Fire Panel - Six Monthly Testing 1 Overdue Fire Safety Equipment tests 1 **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors Communal Fire doors due for replacement within 5 years 0 **Dwelling Doors** 0 Failing Dwelling Fire Doors

Dwelling Fire doors due for replacement within 5 years

0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



22/04/2024

12

1

Date of Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment Annual Re-Assessment

Type of Risk Assessment

Type 3 (Common Parts and Flats - Non Destructive)

Quantity

Fire & Safety Assessor Lynn.betteridge@accentgroup.org

Enforcing Fire Authority Cambridgeshire Fire and Rescue Service

Scheme Tel. No

Other staff in attendance Scheme manager

Number of on-site Accent staff Scheme Manager Weekdays

Number of other (non-Accent) staff

Contract Cleaners in common areas

Scheme Inspection completed

Number of occupants 55

Personal Emergency Evacuation Plans in place Yes

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of Storeys

Number of floors on which car parking is provided 0

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

None

Number of external staircases None

External balcony part of escape route?

Unusual features None

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Mixed

Fire Detection and Warning System Flats and common areas linked

Grade of Fire Alarm Grade A

Category of Fire Alarm LD1 Maximum Protection

Emergency Lighting Provision Non Maintained System - Common Areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted Yes

Water Extinguisher(s) present

Foam Extinguisher(s) present No

Dry Powder Extinguisher(s) present No

Carbon Dioxide Extinguisher(s) present

Yes

Fire Blanket(s) present Yes

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present No

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no

obvious damage?

Comment

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment A valid ELC report is uploaded to Active H and M

files.

Yes

Yes

Electrical App/PA Testing - tested within past 12 months? Yes

Comment Tested by Aron services on 6/82023. All mobility

scooters tested same date and uploaded to Active H

and M files.

Absence of trailing leads and adapters? Yes

Comment

Evidence that mobility scooters are not being stored/charged in

common areas?

Yes

Comment Scheme has a total of 13 mobility scooters on site 4

in purpose built storage with detection. The others in the own garden area and batteries removed and

charged indoors.

Is there a purpose built mobility scooter store/charging area?

Yes

Comment The mobility scooter store if fire protected and all

chargers are PAT tested.

Does the building have a lightning protection system?

Comment

Gas installations

Is there a commercial/domestic gas supply to the scheme? Yes

Comment The scheme is covered by a commercial heating

system tested and dated 5/8/23. Uploaded to active

H and M files.

Yes

N/A

Yes

Yes

Yes

Valid LGSR held on file for fixed communal area gas appliances?

(Boilers) Comment

Valid LGSR held on file for residential flats that contains gas

appliances?

Comment

Are smoke/heat detectors within General Needs flats subject to an

annual inspection and the results

Comment Tested by tunstalls and collecting station Astraline

via Warden call system.

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered

to?

Comment

Adequate security against arson? Yes

Comment CCTV coverage in all communal areas and external.

ACCESS VIA FOB.

Are refuse/recycling bin areas managed and suitably located?

Comment

Are there communal cooking facilities at this scheme? Yes

Comment

Are reasonable measures taken to prevent fires as a result of cooking? Yes

Comment

Where there is extraction in communal kitchens, are filters and

ductwork changed/cleaned regularly?

Yes

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 6 of 14

Generated 22/04/2024 16:03:03

Comment Ceramic Hob cooker and induction extraction

Housekeeping

Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items?

Comment

Are unnecessary accumulations of combustible materials or waste avoided?

Comment

Are combustible materials and substances separated from ignition sources and stored appropriately?

Comment

Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations?

Comment

Yes

Yes

Yes

Yes

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Comment

Yes

This is a well maintained scheme and Set's high

standards.

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of escape in case of fire?

Comment

Yes

Yes

Yes

Escape routes unobstructed and safe to use?

Comment

Exits immediately openable without a key and/or failsafe's function

correctly?

Comment

Reasonable distances of travel where there is a single/alternative

direction of travel?

Yes

Comment

Escape routes lead to final exits and open in direction of escape where

necessary? Comment Yes

Fire Spread and Development

Blk 1 1-29 Napier Place, Peterborough Asset ID: 31014

Is it considered that the compartmentation is of a reasonable standard?

Comment A full compartmentation survey carried out in 2019

Is there reasonable limitation of surface finishes that might promote fire

spread (walls, floors, ceilings)?

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?

Comment

As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?

Loft hatches fire resisting?

Comment As far as can be reasonably ascertained, is the fire stopping above

cross corridor fire doors within suspended ceiling void of a satisfactory

standard? Comment

Comment

Comment

Do external walls, doors, windows and anything attached to the

exterior, limit fire spread? Comment

If Smoke Control Systems (AOV's) are fitted, are the records of annual

testing available?

Comment

Are roller shutter doors that are required to be FR, fire resisting and

self-closing?

Comment

Comment

Comment

Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per current standards?

Emergency lighting units in good condition and securely fixed to walls/ceilings?

Records of monthly/annual testing available?

Comment

and considerable works completed in 2021.

Yes

Yes

N/A

Yes

Yes

N/A

Yes

The external walls doors and windows will not propagate fire spread around the envelope of the

building.

N/A

Yes

Yes

Kitchen shutter linked.

Contractor ensures compliance.

Yes

All in good condition at the time of inspection.

Yes

Tunstalls the main contractor tests completed on a monthly test 2/4/24 basis and the annual drop test was completed on the 3/8/2023 all uploaded to active H and M files.

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent

locations within the common areas?

Comment

Directional fire escape signage in place and adequate?

Comment

Is there suitable LIFT signage i.e. do not use in case of fire?

Comment

Do common area fire doors display the correct signage on both sides

where applicable?

Comment

Yes

Yes

Yes

N/A

Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?

Comment

Is fire detection and warning system appropriate for occupancy and fire

risk, as per BS 5839-1:2017?

Comment

Is the fire detection and warning system maintained/tested and all

certificates saved on file?

Comment

Fire alarm components in good condition and securely fixed to

walls/ceilings?

Comment

Hold open devices operate at the sounding of the alarm and are in a

serviceable condition?

Comment

Are there heat detectors located in the Kitchen, Boiler, Plant Room and

Laundry?

Comment

Is the fire alarm panel remotely monitored, and if so are there records of

regular testing?

Comment

Yes

Yes

Yes

The contractor Tunstalls service the alarm system

every 6 months and is tested by the scheme

manager weekly and recorded.

The Fire panel test result are uploaded to Active H

and M files.

Yes noted at time of inspection.

Yes

Tested at time of inspection and doors comunal on mag locks operate effectively protecting MOE.

Yes

Yes

The alarms are monitored by Astraline the contact centre.

Fire Extinguishing Equipment

Asset ID: 31014 Blk 1 1-29 Napier Place, Peterborough Yes Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme? Comment Portable fire extinguishers - appropriate type/number/position? Yes Comment Yes Correct signage displayed by each fire extinguisher? Comment Yes Fire blanket in communal kitchen, secured to the wall, complete with signage? Comment N/A Dry risers - Inlet/outlet boxes secured and/or securing straps fitted to outlet valves? Comment Yes Records available of fire fighting equipment servicing within past 12 months? Comment The fire extinguishers are tested by Morgan Fire yearly last recorded date 8/2024. Labels affixed all uploaded to active H and M files. Management of Fire Safety Are these premises regulated by the Building Safety Regulator under Yes the Building Safety Act? Comment Will this FRA be shared will all Accountable Persons for the premises? Yes Comment Communication with Fire Authority and residents. Communication with all parties. How will this sharing be achieved? Are there other Responsible Persons who share or have fire safety Yes duties in respect of the premises? Yes Have all details required by regulations been shared with all other Responsible Persons? Comment Fire Authority. Section 38 Building regs provide fire service info from the responsible person. Yes Have all details required by regulations to be shared with us from other Responsible Persons been received and recorded? Comment All recorded on active H if residents or any other person's wish to look at the FRA the details will be shared and communicated on request. Will this FRA be shared will all other Responsible Persons for the Yes premises? Comment How will this sharing be achieved? Communication and media

Is an office or IL scheme being inspected?

Yes

Blk 1 1-29 Napier Place, Peterborough Asset ID: 31014 Comment N/A IL Schemes & Regional Offices - Are there sufficient numbers of qualified Fire wardens? Comment Scheme manager receives evacuation training and basic fire E learning.only on site Monday to Friday office hours. N/A Offices - Are there suitable arrangements for ensuring the premises are Only if scheme manager on site. Comment Yes Offices - Are there suitable arrangements for evacuating disabled people? Comment Each resident has a PEEPS assessment and most vulnerable people are identified. N/A Offices - Suitable arrangements for meeting the fire service on arrival and proving relevant information? Only office hours. Comment Offices/IL Schemes - Is there a suitable assembly point? Yes Comment Offices - Are fire drills carried out at appropriate intervals? N/A Comment ILs scheme not required but all residents informed of stay put policy. Passenger Lift Is the scheme fitted with a passenger lift? No Comment **Premises Inspection Box** N/A Is there a premises information box for fire & rescue service use? Comment N/A Are there arrangements to check the premises information box is kept up to date? Comment **Evacuation Policy**

Are there suitable arrangements for summoning the fire service?

Comment Warden call and phone call.

Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance?

Comment

Yes

Yes

Engagement with Residents

Has information of fire procedures been disseminated to residents?

Yes

Comment

Is general fire safety information disseminated to residents?

Yes

Comment

When residents move into the flats they are given fire safety advice and also leaflets and a link into the website to look at the FRA the details will be shared and communicated on request.

FRA Frequency

Taking the findings of this assessment into account, is the frequency of the FRA correct?

Yes

Comment

Miscellaneous

Are there any other observations/actions to raise that are not covered

above.

Are there fire related remedial works required at this property, that will affect the fabric of the building?

Comment

Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).

No

No

No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

systems.				
_		evention measures observention measures observention the fire (t		
LOW	X	MEDIUM	нідн	
any procedural	arrangements ob	of the building, the occup served at the time of the a e event of a fire would be:	ssessment, it is consider	
MINOR		MAJOR X	CRITICAL	

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales	
Trivial	No action is required	
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.	
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.	
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.	

The Overall Risk Level for this asset is:	Trivial
	<u> </u>