Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 8691 1-18 Crow Nest Court Block 1-18 Crow Nest Court, Mirfield

Cover Sheet

Photo



Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

19 Sep 2024

19 Sep 2027

36

3 year Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Steven Manners TECH IOSH MIFSM MFPA

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name Crow Nest Court

Scheme Address 1-18 Crow Nest Court Block 1-18 Crow Nest Court,

Mirfield

Postcode WF14 9SP

Region Yorkshire

Scheme Manager

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority West Yorkshire

Other staff in attendance None

Number of on-site Accent staff Scheme Manager Part-Time

Number of other (non-Accent) staff

Contract Cleaners in common areas

The Building

Accommodation Type General Needs (S30)

Build Date Jan 1 1977

Number Of Homes 18

Homes breakdown Flat

External wall construction Concrete Block

External wall finish Facing Brick

Roof construction Timber

Roof covering Flat Roof, Plain Pitched

PEEPs in place where necessary N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys 3

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

One Protected

Number of External Staircases None

External Balcony part of escape route?

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

1-18 Crow Nest Court Block 1-18 Crow Nest Court, Mirfield Asset ID: 8691 Flats only Fire Detection and Warning System Grade D Grade of fire alarm Category of fire alarm LD3 Minimum Protection Non Maintained System - Common Areas **Emergency Lighting Provision** Portable Fire Extinguishers supplied/fitted No Fixed Fire Fighting Installations No **Customers** 32 Number of occupants General Needs, Leasehold, Sheltered Schemes Occupant tenure type breakdown Fire Safety Related Customer Safety Servicing Overdue communal gas safety checks 0 0 Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 Overdue communal PAT testing 0 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests 1 Overdue Annual Emergency Lighting tests 1 0 Overdue Weekly Fire Alarm Testing Overdue Fire Panel - Six Monthly Testing Overdue Fire Safety Equipment tests **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors Communal Fire doors due for replacement within 5 years 0 **Dwelling Doors** 0 Failing Dwelling Fire Doors Dwelling Fire doors due for replacement within 5 years 0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



Date of Fire Risk Assessment 19/09/2024

FRA Frequency (Months) 36

Purpose of Fire Risk Assessment 3 year Re-Assessment

Type of Risk Assessment

Type 1 (Common Parts Only - Non Destructive)

Quantity

Fire & Safety Assessor Steven Manners TECH IOSH MIFSM MFPA

Enforcing Fire Authority West Yorkshire

Scheme Tel. No

Other staff in attendance None

Number of on-site Accent staff Scheme Manager Part-Time

Number of other (non-Accent) staff

Contract Cleaners in common areas

Scheme Inspection completed Yes

Number of occupants 32

Personal Emergency Evacuation Plans in place N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of Storeys 3

Number of floors on which car parking is provided 0

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

One Protected

Number of external staircases

None

External balcony part of escape route?

Unusual features None

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Residential

Fire Detection and Warning System Flats only

Grade of Fire Alarm Grade D

Category of Fire Alarm LD3 Minimum Protection

Emergency Lighting Provision Non Maintained System - Common Areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted No

Water Extinguisher(s) present No

Foam Extinguisher(s) present No

Dry Powder Extinguisher(s) present

Carbon Dioxide Extinguisher(s) present

Yes

Fire Blanket(s) present

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no

obvious damage?

Comment All electrical outlets were in good condition at the

time of inspection.

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Communal area Electrical certificate held on File,

Last test date :- 15/09/2023

residents flats also have test records on File. Tested

as and when required.

Yes

Yes

Nο

Electrical App/PA Testing - tested within past 12 months?

N/A

Comment No Electrical equipment within the communal area

that requires testing.

Absence of trailing leads and adapters? N/A

Comment As Above.

Evidence that mobility scooters are not being stored/charged in

common areas?

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 5 of 14

Generated 20/09/2024 16:02:14

Comment

Is there a purpose built mobility scooter store/charging area?

Comment

Does the building have a lightning protection system?

Comment

A mobility scooter was found outside Flat No 5, Housing Partner informed. Resident needs to store within their flat or outside.

No

The scheme has Garages that could be used to store scooters if required.

No

Gas installations

Is there a commercial/domestic gas supply to the scheme?

Comment

Valid LGSR held on file for fixed communal area gas appliances? (Boilers)

Comment

Valid LGSR held on file for residential flats that contains gas appliances?

Comment

Are smoke/heat detectors within General Needs flats subject to an annual inspection and the results

Comment

Observation

Yes

There are gas supplies to residents flats. Not all residents have a connected gas supply.

N/A

No Communal gas supply.

Yes

All residents with a gas supply have test certificates , they can be found on ActiveH.

Yes

Priority

Carried out at the same time as the Gas checks and held on file for individual flats.

Referred To

Required By:

Task ID

Gas supply to some flats within the building





Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered to?

Comment

Adequate security against arson?

Yes

No smoking allowed in the communal areas but residents are allowed to smoke within their flats.

Yes

Comment There is a fob entry system to the front and rear of

the building.

Yes

Yes

N/A

N/A

Yes

Yes

Yes

Are refuse/recycling bin areas managed and suitably located? Yes

Comment There refuse store is part of the building, and was

neat and tidy at the time of inspection.

Are there communal cooking facilities at this scheme?

Comment

Housekeeping

Are all electrical/intake/service cupboards secure and free from general

waste, contractors waste and and residents personal items?

Comment All clear at the time of inspection.

Are unnecessary accumulations of combustible materials or waste

avoided?

Comment None found at the time of inspection.

Are combustible materials and substances separated from ignition

sources and stored appropriately?

Comment None found at the time of inspection.

Furniture/furnishings in good condition, fire retardant/resistant and

comply with modern standards and regulations?

Comment No furniture allowed within the communal areas of

the scheme.

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Comment None found at the time of inspection.

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of

Reasonable distances of travel where there is a single/alternative

escape in case of fire?

Comment There is a single direction of travel which leads to a protected staircase, the travel distance is within the

guidelines.

Escape routes unobstructed and safe to use?

Comment See observations re mobility scooter.

Exits immediately openable without a key and/or failsafe's function Yes

correctly?

Comment All exits were openable at the time of inspection.

direction of travel?

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 7 of 14

Generated 20/09/2024 16:02:14

Comment

Escape routes lead to final exits and open in direction of escape where necessary?

Yes

Comment

Observation Priority Referred To Required By: Task ID

Fire signage and action plan





Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?

Comment

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?

Comment

As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?

Comment

Loft hatches fire resisting?

Comment

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?

Comment

Do external walls, doors, windows and anything attached to the exterior, limit fire spread?

Comment

If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?

Comment

Yes

Ther ewere no breaches of compartmentation at the time of inspection.

Yes

The walls are brick in construction and the ceiling is plastered.

N/A

None fitted

N/A

There is no access to the roof space within the communal area.

N/A

None fitted.

N/A

No cross corridor doors at this scheme.

Yes

This building is of a traditional construction,.

N/A

None fitted.

Are roller shutter doors that are required to be FR, fire resisting and

self-closing?

N/A

Comment None fitted.

Observation Priority Referred To Required By: Task ID

Internal bin store





Observation Priority Referred To Required By: Task ID


Mobility scooter in communal corridor outside flat 5 needs to be stored within the flat



Housing Partner

02/10/2024

1865098





Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per current standards?

Comment

Emergency lighting units in good condition and securely fixed to walls/ceilings?

Comment

Records of monthly/annual testing available?

Comment

Yes

Yes

All emergency lighting fittings were in good condition at the time of inspection.

Yes

Tests are carried out by Tunstall. Last Monthly test :-16/09/2024 Last Annual :- 13/11/2023

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?

Yes

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 9 of 14

Generated 20/09/2024 16:02:14

Comment Notices are displayed throughout the building.

Directional fire escape signage in place and adequate?

Comment Notices are displayed throughout the building.

Is there suitable LIFT signage i.e. do not use in case of fire?

Comment No lift fitted.

Do common area fire doors display the correct signage on both sides

where applicable?

Comment All signs in place at the time of inspection.

Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?

Comment

Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations Yes

provided at this scheme?

Comment CO2 extimnguisher within the electrical cupboard

only.

N/A

No

Yes

Portable fire extinguishers - appropriate type/number/position?

Comment

Correct signage displayed by each fire extinguisher?

Yes

Comment

Fire blanket in communal kitchen, secured to the wall, complete with N/A

signage?
Comment

Dry risers - Inlet/outlet boxes secured and/or securing straps fitted to

outlet valves?

Comment none fitted

Records available of fire fighting equipment servicing within past 12 Yes

months?

Comment The label on the extinguisher was up to date.

records of testing can be found on ActiveH.

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under

the Building Safety Act?

Comment Not in scope.

Are there other Responsible Persons who share or have fire safety No

duties in respect of the premises?

MIS-AMS ActiveH - Fire Risk Assessment Report Page 10 of 14 Generated 20/09/2024 16:02:14

1-18 Crow Nest Court Block 1-18 Crow Nest Court, Mirfield Asset ID: 8691 How will this sharing be achieved? No Is an office or IL scheme being inspected? Comment Passenger Lift Is the scheme fitted with a passenger lift? No Comment **Premises Inspection Box** Is there a premises information box for fire & rescue service use? No Comment **Evacuation Policy** Are there suitable arrangements for summoning the fire service? Yes Comment residents are advised to dial 999. Yes Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance? Comment **Engagement with Residents** Yes Has information of fire procedures been disseminated to residents? Comment A leaflt has been delivered to each resident regarding fire safety and genral information regarding the Fire door to their flat. Fire action notices are displayed throughout the building and information can be found on the website. Yes Is general fire safety information disseminated to residents? Comment A leaflt has been delivered to each resident regarding fire safety and genral information regarding the Fire door to their flat. Fire action notices are displayed throughout the building and information can be found on the website. FRA Frequency Yes Taking the findings of this assessment into account, is the frequency of the FRA correct?

Comment

with the exception of the mobility scooter, passive fire precautions are in place at the time of inspection.

Miscellaneous

Are there any other observations/actions to raise that are not covered above.

No

Are there fire related remedial works required at this property, that will affect the fabric of the building?

No

Comment

Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).

Yes

Some fire doors did not fully close so works orders have been raised with our contractors.

No

Some minor works were required which have been raised with our

No

Unauthorised items were found in communal areas and arrangements were made for their removal.

Yes

Not all records were up to date, as noted in the table below. Arrangements have been made for these to be completed. No

A number of fire doors were found to be wedged or propped open. Fire doors are there to keep you safe and me kept shut at all times.

No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW

MEDIUM

HIGH

2. Taking into account the nature of the building, the occupants, the fire protection afforded and

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR MAJOR	X	CRITICAL	
-------------	---	----------	--

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial