

This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

#### Asset ID: 24614 Royal Huts Avenue

#### **Cover Sheet**

Photo

Date of Fire Risk Assessment Date of Next Fire Risk Assessment FRA Frequency (Months) Purpose of Fire Risk Assessment Type of Fire Risk Assessment Fire & Safety Assessor



27 Feb 2025 27 Feb 2028 36 3 year Re-Assessment Type 1 (Common Parts Only - Non Destructive) Gary Bredin AlFireE

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

**Royal Huts Avenue** 

#### The Scheme

Scheme Name	Royal Huts Avenue
Scheme Address	Royal Huts Avenue
Postcode	
Region	South
Scheme Manager	
Scheme Tel. No	-
Scheme Inspection Completed	Yes
Enforcing Fire Authority	Surrey Fire and Rescue service
Other staff in attendance	None
Number of on-site Accent staff	None
Number of other (non-Accent) staff	Contract Cleaners in common areas

## The Building

Accommodation Type	General Needs (S30), Shared Ownership (S40)
Build Date	May 9 2003
Number Of Homes	17
Homes breakdown	Flat, House
External wall construction	Facing Brick
External wall finish	Facing Brick, Hung Tiles
Roof construction	Timber
Roof covering	Plain Pitched
PEEPs in place where necessary	Yes
Current Evacuation Strategy	Stay Put (Delayed) Evacuation
Conversion or purpose-built	Purpose Built
Number of storeys	3
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
Number of internal Staircases (protected or unprotected?)	1 protected
Number of External Staircases	None
External Balcony part of escape route?	N/A
Unusual features	None
Building Access Conditions for Fire Brigade	Vehicular Access to one or more elevations

#### **Royal Huts Avenue**

Fire Detection and Warning System	Flats only
Grade of fire alarm	Grade D
Category of fire alarm	LD3 Minimum Protection
Emergency Lighting Provision	Non Maintained System - Common Areas
Portable Fire Extinguishers supplied/fitted	No
Fixed Fire Fighting Installations	No

#### Customers

Number of occupants	25
Occupant tenure type breakdown	General Needs, Leasehold, Shared Ownership

## Fire Safety Related Customer Safety Servicing

Overdue communal gas safety checks	0
Overdue domestic gas safety checks	0
Overdue communal electrical condition checks	0
Overdue domestic electrical condition checks	0
Overdue alarm call pull chord tests	0
Overdue communal PAT testing	0
Overdue customer mobility scooter PAT testing	0
Overdue Monthly Emergency Lighting Switch Tests	0
Overdue Annual Emergency Lighting tests	0
Overdue Weekly Fire Alarm Testing	0
Overdue Fire Panel - Six Monthly Testing	
Overdue Fire Safety Equipment tests	

## **Building Fire Safety Surveys - Communal Doors**

Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	0

## **Dwelling Doors**

Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

## Fire Risk Assessment Survey Results

## Scheme and Building Information

Photo

Date of Fire Risk Assessment
FRA Frequency (Months)
Purpose of Fire Risk Assessment
Type of Risk Assessment
Quantity
Fire & Safety Assessor
Enforcing Fire Authority
Scheme Tel. No
Other staff in attendance
Number of on-site Accent staff
Number of other (non-Accent) staff
Scheme Inspection completed
Number of occupants
Personal Emergency Evacuation Plans in place
Current Evacuation Strategy
Conversion or purpose-built
Number of Storeys
Number of floors on which car parking is provided
Is there a habitable basement?
No. of internal staircases (protected/unprotected)
Number of external staircases
External balcony part of escape route?
Unusual features



27/02/2025	
36	
3 year Re-Assessment	
Type 1 (Common Parts Only - Non Destructive)	
1	
Gary Bredin AlFireE	
Surrey Fire and Rescue service	
-	
None	
None	
Contract Cleaners in common areas	
Yes	
25	
Yes	
Stay Put (Delayed) Evacuation	
Purpose Built	
3	
0	
No	
1 protected	
None	
N/A	
None	

## Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade	Vehicular Access to one or more elevations
Surroundings: Residential/Commercial	Residential
Fire Detection and Warning System	Flats only
Grade of Fire Alarm	Grade D
Category of Fire Alarm	LD3 Minimum Protection
Emergency Lighting Provision	Non Maintained System - Common Areas
Portable Fire Extinguishers / Fire Blankets supplied / fitted	No
Water Extinguisher(s) present	No
Foam Extinguisher(s) present	No
Dry Powder Extinguisher(s) present	No
Carbon Dioxide Extinguisher(s) present	No
Fire Blanket(s) present	No
Fixed Fire Fighting Installations supplied / fitted	No
Dry Riser(s) present	No
Wet Riser(s) present	No
Sprinkler System present	No
Hosereel(s) present	No
Automatic Opening Vent(s) present	No

### **Electrical Sources of Ignition**

Electrical installation within common areas in good condition and no obvious damage? Comment	Yes
Valid Electrical Installation Condition Reports held on file? (Common Areas & General Needs Flats)	Yes
Comment	Last test April 2024
Electrical App/PA Testing - tested within past 12 months?	N/A
Comment	
Absence of trailing leads and adapters?	Yes
Comment	
Evidence that mobility scooters are not being stored/charged in common areas?	Yes
Comment	
Is there a purpose built mobility scooter store/charging area?	No

#### Asset ID: 24614 Royal Huts Avenue

Comment	
Does the building have a lightning protection system?	N/A
Comment	
Is the protection system adequately maintained?	N/A
Comment	

#### **Gas installations**

Is there a commercial/domestic gas supply to the scheme?	No
Comment	

## Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered to?	Yes
Comment	
Adequate security against arson?	Yes
Comment	
Are refuse/recycling bin areas managed and suitably located?	Yes
Comment	
Are there communal cooking facilities at this scheme?	No
Comment	

## Housekeeping

Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items?	Yes
Comment	
Are unnecessary accumulations of combustible materials or waste avoided?	Yes
Comment	
Are combustible materials and substances separated from ignition sources and stored appropriately?	N/A
Comment	
Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations?	N/A
Comment	

## **Other Significant Fire Hazards**

#### **Royal Huts Avenue** Asset ID: 24614

Are all other significant fire hazards adequately controlled?				

Comment

#### Means of Escape from Fire

Is it considered that the building is provided with reasonable means of escape in case of fire?	Yes
Comment	
Escape routes unobstructed and safe to use?	Yes
Comment	
Exits immediately openable without a key and/or failsafe's function correctly?	Yes
Comment	Double action lock in use
Reasonable distances of travel where there is a single/alternative direction of travel?	Yes
Comment	
Escape routes lead to final exits and open in direction of escape where necessary?	Yes
Comment	

Observa	tion			Priority	Referred To	Required By:	Task ID
		 	 e				

All escape routes were clear at the time of the audit.



Observation

Internal - Medium

Emergency lighting lumin levels need looking at and changed to a maintained system if required.



## Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?	Yes
Comment	
Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)? Comment	Yes
Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?	N/A
Comment	
As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?	N/A
Comment	This area was not checked during the audit.
Loft hatches fire resisting?	Yes
Comment	
As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?	Yes
Comment	
Do external walls, doors, windows and anything attached to the exterior, limit fire spread?	Yes
Comment	
If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?	N/A
Comment	
Are roller shutter doors that are required to be FR, fire resisting and self-closing?	N/A
Comment	
Emergency Escape Lighting	
Is the emergency lighting correctly specified and installed as per current standards?	No
Comment	Low light levels were noted in both blocks during the audit. Job raised to assess the lighting.
Emergency lighting units in good condition and securely fixed to walls/ceilings?	Yes
Comment	
Records of monthly/annual testing available?	Yes
Comment	Last test April 2024.

## **Fire Safety Signs and Notices**

Observation	Priority	Referred To	Required By:	Task ID
Comment				
Do common area fire doors display the correct signage on bo where applicable?	oth sides	Yes		
Comment				
Is there suitable LIFT signage i.e. do not use in case of fire?		N/A		
Comment				
Directional fire escape signage in place and adequate?		Yes		
Comment				
Are the correct Fire Action/Advice notices displayed in promi locations within the common areas?	nent	Yes		

Observation \_\_\_\_\_ Priority \_\_\_\_ Referred To \_\_\_\_ Required By: Task ID \_\_\_\_\_ All notices are posted in the notice boards located in

the main entrances.



## Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?		No
Comment		
Fire Extinguishing Equipment		
Is fire extinguishing equipment and/or fixed fire fighting provided at this scheme?	g installations	No
Comment		
Management of Fire Safety		
Are these premises regulated by the Building Safety F the Building Safety Act?	Regulator under	N/A
Comment		
Will this FRA be shared will all Accountable Persons for	or the premises?	Yes
MIS-AMS ActiveH - Fire Risk Assessment Report	Page 9 of 13	Generated 27/02/2025 16:01:59

#### Asset ID: 24614 Royal Huts Avenue

# Comment

How will this sharing be achieved?	This is available on M files for all to access
Are there other Responsible Persons who share or have fire safety duties in respect of the premises?	Yes
Have all details required by regulations been shared with all other Responsible Persons? Comment	N/A
Have all details required by regulations to be shared with us from other Responsible Persons been received and recorded? Comment	N/A
Will this FRA be shared will all other Responsible Persons for the premises? Comment	N/A
How will this sharing be achieved?	This is available on request
Is an office or IL scheme being inspected?	No
Comment	
Passenger Lift	
Is the scheme fitted with a passenger lift?	No
Comment	
Premises Inspection Box	
Is there a premises information box for fire & rescue service use?	No
Comment	
Evacuation Policy	
Are there suitable arrangements for summoning the fire service?	Yes
Comment	It's the responsibility of the customers to summon the emergency services
Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance? Comment	Yes
Engagement with Residents	
Has information of fire procedures been disseminated to residents?	Yes
Comment	
Is general fire safety information disseminated to residents?	Yes
MIS-AMS ActiveH - Fire Risk Assessment Report Page 10 of 13	Generated 27/02/2025 16:01:59

Comment

#### **FRA Frequency**

Taking the findings of this assessment into account, is the frequency of the FRA correct?	Yes
Comment	
Miscellaneous	
Are there any other observations/actions to raise that are not covered above.	No
Are there fire related remedial works required at this property, that will affect the fabric of the building?	No
Comment	
Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).	No

#### **Risk Calculator - Fire**

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW	MEDIUM	нідн	
-----	--------	------	--

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR	MAJOR	X	CRITICAL	
		Λ		

The definition of the above terms is as follows: *FRA Review Frequency* 

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).		
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.		
CRITICAL	There is significant potential for serious injury or death of one or more occupants.		

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	intolerable

When the level of risk is established, the action level can be read from the table below:

#### **Royal Huts Avenue**

Risk Level	Guide to actions and appropriate timescales	
Trivial	No action is required	
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.	
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.	
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.	

The Overall Risk Level for this asset is:	Trivial