

ACCENT HOUSING - FIRE RISK ASSESSMENT



Region: North West

Scheme Name : Dyehouse Lane

Scheme Address : Dyehouse Lane

New Mills SK22 4BA

Date of Assessment: 15/09/2022

Date of Next Assessment: 15/09/2025

FRA Frequency: 3 Year Re-Assessment

Fire & Safety Assessor Ian Potter

This Fire Risk Assessment has been conducted upon the instruction of Accent Housing.

Scheme Details		Dyehouse Lane		
Region:		North West		
Scheme Name:		Dyehouse Lane		
Site Address:	Street:	Dyehouse Lane		
	Town:	New Mills		
	Post Code:	SK22 4BA		
Block & Asset No.		Block 1 9426		
Scheme Tel. No:		N/A		
Date of this Assessment		15/09/2022		
Date of Next Review		15/09/2025		
Fire Risk Assessment Frequency		3 Years		
Purpose of Fire Risk Assessment		3 Year Re-Assessment		
Fire & Safety Assessor		lan Potter		
Director of Customer Experience		Shaun Finegan		
Customer Partnership Manager		Jamie Trotter		
Contract Manager		Susan Polvani		
Scheme Manager/Customer Partner		Andrew Summerscales		
Other staff in attendance		None		
Use of Building		General Needs		
Approximate Number of occupants		6		
Occupancy Profile		Mixed		
Familiarity of the occupants		Fully Familiar		
Likely state of the Occupants		Alert		
PEEPs in place where necessary		N/A		
Number of on-site Accent staff		None		
		Contract cleaners in common		
Number of other (non-Accent) staff		areas		
Support Agency (Supported Housing)		N/A		
Current Evacuation Strategy.		Full (Simultaneous) Evacuation		
Evidence that residents have been noti	fied of the	Advice notices displayed in		
evacuation procedure		common areas		
History of fires in the building		None		
Business Continuity Plan in place?		Yes		
		Type 1 (Common Parts Only -		
Scope of Assessment		Non Destructive)		
Applicable Fire Safety Guidance		LACORS Guide		

Building Details	Dyehouse Lane
Construction Date	1937
	Joisted or Load Bearing Masonry
Construction Type	(Traditional)
Roof Finish	Pitched-Slate Tile
External Wall Finish	Stone
Are there any areas of external wall cladding	No
Are there any balconies	No
Conversion or purpose-built	Conversion
Number of flats (self-contained)/rooms (HMOS, shared	
houses)	6
Number of storeys above ground	Two
Number of storeys below ground	None
Is there a habitable basement?	No
Number of internal Staircases per Block	
(protected or unprotected?)	One-Unprotected
Number of External Staircases per Block	None
External Balcony part of escape route?	N/A
Unusual features	None
Building complexity	Simple
Building Access Conditions for Fire Brigade	Vehicular Access to one or more
	elevations
Surroundings: Residential/Commercial	Residential
Fire Provision Currently in P	lace
Fire Detection and Warning System	Common areas only
Grade of fire alarm	Grade B
Category of fire alarm	LD3 Minimum Protection
Additional Comments:	
Evacuation Alert System (EAS)	No
Additional Comments:	
	Non Maintained System -
Emergency Lighting Provision	Common Areas
Additional Comments:	
Portable Fire Extinguishers	None fitted
Additional Comments:	
Fixed Fire Fighting Installations	None fitted
Additional Comments:	

	Significant Findings - Fire							
	Dyehouse Lane					15/09/2022		
Action Ref:	Potential Area of Fire Risk	Yes-No-N/A	Observation/Comments/ Actions Required	Risk Rating	Target Completion Date	Referred To:		
			Fire Hazards					
1	Electrical Sources of Ignition:							
1.1	Electrical Installation within common areas (Fixed Wiring, sockets, switches, light fittings) in good condition and no obvious damage	Yes						
1.2	Valid Electrical Installation Condition Reports held on file.(Common Areas)	Yes	18/07/2022 on ActiveH					
1.3	Valid Electrical Installation Condition Reports held on file. (General Needs Flats)	N/A	Housing Association not responsible for this					
1.4	Electrical App/PA Testing - all portable appliances tested within past 12 months	N/A	None in Communal areas					
1.5	Absence of trailing leads and adapters	Yes		•				
1.6	Mobility Scooters - Stored/charged in common areas, purpose built store/resident flat	N/A	None in Communal areas					
2								
2.1	Are there any risks associated with smoking in the building?	Yes	Smoking allowed in flats					
3	Arson:							
3.1	Adequate security against arson?	Yes	Secure front door	•				
3.2	Is there an absence of unnecessary fire load in close proximity to building?	Yes		1				

4	Heating Installations (Portable/fixed)					
	Gas Installations - Common Areas & General Needs Residential flats.					
4.1	If portable heaters are used, are there suitable controls?	N/A	None in Communal areas	•		
	Are fixed heating installations subject to regular maintenance?	N/A		•		
4.3	Valid LGSC held on file for each residential flat that contains gas appliances.	N/A	No gas supply	ı		
5	Cooking:					
5.1	Are reasonable measures taken to prevent fires as a result of cooking?	N/A	No communal kitchen	•		
5.2	Where there is extraction ventilation in communal kitchens are filters changed/ cleaned and ductwork cleaned regularly?	N/A				
6	Lightning Protection System:					
6.1	Does the building have a lightning protection system, If so, is it adequately maintained?	N/A	Not required			
7	Housekeeping:					
7.1	Is the standard of housekeeping adequate?	Yes		•		
7.2	Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and residents personal items.	Yes		•		
7.3	Are combustible materials separated from ignition sources and stored appropriately?	Yes		•		
7.4	Are unnecessary accumulations of combustible materials or waste avoided?	Yes		•		
7.5	Are hazardous materials stored appropriately (i.e. oxygen cylinders, flammable materials, explosive products, oxidising products, aerosols)	N/A	None in Communal areas	ı		
8	Furniture/furnishings on escape routes and other communal areas:					

0.4	Francis and franciscis are in a seal and differential		Nama in Camanaumal and a		l	Ī
	Furniture/furnishings in good condition, fire	⋖	None in Communal areas			
	retardant and complies with 1988	N A		'		
	Regulations.					
9	Other Significant Fire Hazards:					
9.1	Are there other significant fire hazards that	9				
	are inadequately controlled?	Z		'		
		Fire	Protection Measures			
10	Means of Escape from Fire:					
10.1	Is it considered that the building is provided					
	with reasonable means of escape in case of	Yes				
	fire?	>				
10.2	Escape routes unobstructed and safe to use?	S				
		Yes		'		
10.3	Exits easily and immediately openable where	es				
	necessary, without a key?	≺e		'		
	Reasonable distances of travel where there is	တ				
	a single/alternative direction of travel?	Yes		'		
	Escape routes lead to final exits and open in					
	direction of escape where necessary?	Yes		•		
	Do failsafe's on locked exit doors function					
	correctly?	N N		٠.		
	Is it considered that the building is provided	_	Not suitable for disabled tenants			
	with reasonable arrangements for means of	^o Z	Not suitable for disabled terialits	١.		
	<u> </u>	Z		•		
	escape for disabled people?		4.			
	Measures to Limit Fire Spread and Develop		ն 	1	T T	ı
	Is it considered that the compartmentation is	ès				
	of a reasonable standard?	>				
	Is there reasonable limitation of surface	S				
	finishes that might promote fire spread (walls,	Yes		'		
	floors, ceilings)?					
	Are fire dampers/shutters provided in		None fitted			
	ducts/refuse chutes to protect means of	N N		١.		
	escape against fire, smoke and combustion	Z				
	products?					

44.4	Common automa autoti au susithi in una ef au anna af a		T		ı	
11.4	Compartmentation within roof spaces of a	N/A				
	satisfactory standard?					
11.5	Loft hatches fire resisting?	Yes		•		
11.6	Fire stopping above cross-corridor fire doors within suspended ceiling void of a satisfactory standard	N/A	None fitted			
11.7	· · · · · · · · · · · · · · · · · · ·		None fitted			
11.7	Smoke Control Systems (AOV's) Are records of annual testing available?	N/A	None fitted			
11.8	Roller shutter doors (fire resisting)	N/A	None fitted	•		
11.9	Do the external walls, windows, balconies etc pose a risk of significant fire spread?	N _o				
12	Communal Area Fire Doors (Inspection to i	nclu	de - construction, hinges, closure devices, intum	esce	nt/smoke s	eal condition,
	glazing systems and maximum gaps betwe		——————————————————————————————————————			·
12.1	Communal fire doors to FD30s standard and	⋖	None fitted			
	in a serviceable condition,	È		'		
12.2	"Fire door keep shut/locked" signage		`			
'	displayed on both sides of all applicable	N/A		١.		
	doors.	Z				
12.3	Hold open devices operate at the sounding of		None fitted			
12.0	the alarm and are in a serviceable condition	N/A	Trono mad	١.		
	and and and an about the desired desired desired and the desired desir	Z				
13	Flat entrance doors (Internal Common Area	s)				
	Do flat entrance doors open onto internal		If yes, see "Residents Front Doors Sheet"			
	escape routes?	Yes		'		
14	Flats with a single direction of escape to a	sina	le escape stairway. (External Balcony)			
	Do the flat entrance doors that open onto an	9	If yes, see "Residents Front Doors Sheet"			
''	external balcony have to be passed during an	Ø	1. Jos, soo residente i font bools officet			
	escape?	N/A		'		
	'					
14.2	Are the separating walls between the flats					
	and the balcony floor that have to be passed	N/A		١.		
	during an escape, fire-resisting up to a height	Z				
	of 1.1m?					
15	Emergency Escape Lighting:					

	Is the emergency lighting correctly specified and installed as per BS 5266-1:2016	Yes			
15.2	Are all emergency lighting units in good condition and securely fixed to walls/ceilings	Yes			
15.9	Are records of monthly testing available?	Yes	04/10/22 by Tunstall		
15.10	Are records of annual testing available?	Yes	3 hour drop test 05/11/21 by Tunstall		
16	Fire Safety Signs and Notices:				
	Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?	Yes			
16.3	Directional fire escape signage in place and adequate?	Yes		•	
16.4	Is there a suitable LIFT sign i.e. do not use in case of fire.	N/A	None fitted	-	
17	Means of giving Warning in case of Fire:				
17.1	Is the fire detection and warning system appropriate for the occupancy and fire risk?	Yes			
17.2	Is the fire detection and warning system correctly specified and installed as per BS 5839-1:2017	Yes		•	
17.3	Is the fire detection and warning system maintained/tested and all certificates saved on file. (BS 5839-1:2017)	SəA	19/05/22 by Tunstall	•	
17.4	Are there heat detectors located in the Kitchen, Boiler, Plant Room and Laundry?	W/A			
17.5	Is the fire alarm panel remotely monitored, and if so are there records of regular testing?	Other	Not Monitored		

47.0	A		NI		I	1
17.6	Are smoke/heat detectors within General		No gas supply			
	Needs flats subject to an annual inspection	⋖				
	and the results recorded on an in date	N N		'		
	Landlord Gas Safety Record (LGSR)					
18	Fire Extinguishing Equipment:					
	Portable fire extinguishers - appropriate	⋖	None fitted			
	type/number/position?	N		•		
18.2	Correct signage displayed by each fire	⋖				
	extinguisher?	Z V		'		
18.3	Fire blanket in communal kitchen, secured to	⋖				
	the wall, complete with signage?	NA		•		
18.4	Hose Reels - fitted, maintained?	N/A	None fitted			
18.5	Dry/wet risers - Full access to all inlet/outlet		None fitted			
10.0	boxes. All inlet/outlets secured and/or	4				
	securing straps fitted to outlet valves?	N N		٠.		
	ecounting outage intout to outlot valvee.					
18.6	Records available of fire fighting equipment		None Fitted			
	servicing within past 12 months	N N				
19		N	lanagement of Fire Safety			
19.1	Are there suitable arrangements for	Yes				
	summoning the fire service?	۶		•		
19.2	Do relevant staff carry out regular fire safety	es	11/05/22 on file			
	checks	×		'		
19.3	Sheltered Schemes & Regional Offices - Are					
	there sufficient number of qualified Fire	N N				
	wardens.					
19.4	Offices - Are there suitable arrangements for	N/A				
	ensuring the premises are evacuated?	Ž				
19.5	Offices - Are there suitable arrangements for	N/A				
	evacuating disabled people?	Ž				

	Offices - Are there suitable arrangements for meeting the fire service on arrival and providing relevant information?	N/A	•	
	Offices/IL Schemes - Is there a suitable assembly point?	N/A	-	
	Offices - Are fire drills carried out at appropriate intervals?	N/A	-	
20	Evacuation Policy			
20.1	Taking the findings of the FRA into account, is the evacuation policy appropriate for the scheme?	Yes	-	
21	Miscellaneous			

Residents Front Doors

Dyehouse Lane

15/09/2022

Flat entrance doors to FD30s specification (Inspection to include - Door condition, construction, closure devices, intumescent/smoke seal condition, glazing systems, fire rated letterplate, door furniture and maximum gaps between door and frame/threshold.

Flat No.	Access Gained	Asset No.	Observation/Comments / Actions Required	Risk Rating	Completion Date	Referred To:
1	No		Door to a decent standard, self closing and close fitting in frame. No letter plate or spy hole. External examination only.	-		
2	No		Door to a decent standard, self closing and close fitting in frame. No letter plate or spy hole. External examination only.	-		
3	No		Door to a decent standard, self closing and close fitting in frame. No letter plate or spy hole. Smoke seals and intumescent strips fitted.	-		
4	No		Door to a decent standard, self closing and close fitting in frame. No letter plate or spy hole. External examination only.	-		
5	No		Door to a decent standard, self closing and close fitting in frame. No letter plate or spy hole. External examination only.	-		
6	No		Door to a decent standard, self closing and close fitting in frame. No letter plate or spy hole. External examination only.	-		

6. Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

(please insert x below)

LOW

MEDIUM

HIGH

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

(please insert x below)

MINOR X

MAJOR

CRITICAL

The definition of the above terms is as follows:

FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant				
	(other than the occupant sleeping in a bedroom in which a fire occurs).				
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely				
	to lead to fatalities.				
CRITICAL	There is significant potential for serious injury or death of one or more occupants.				

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trivial	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.