# Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 24418 Esher Road

#### **Cover Sheet**

Photo



Date of Fire Risk Assessment 30 May 2023

Date of Next Fire Risk Assessment 30 May 2026

FRA Frequency (Months) 36

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor Gary Bredin

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name Esher Road

Scheme Address Esher Road

Postcode GU15 4AL

Region South

Scheme Manager

Scheme Tel. No -

Scheme Inspection Completed Yes

Enforcing Fire Authority Surrey FRS

Other staff in attendance None

Number of on-site Accent staff None

Number of other (non-Accent) staff

Contract Cleaners in common areas

The Building

Accommodation Type Garage and Car Parking Bays (S45), General Needs

(S30), Peerless General Needs - LSVT (S29)

Build Date Jan 1 1965

Number Of Homes 57

Homes breakdown Garage, Maisonette, Bungalow

External wall construction Facing Brick

External wall finish Facing Brick, Hung Tiles, Paint Render, UPVC

Cladding

Roof construction Timber

Roof covering Flat Roof, Interlocking Pitched, Plain Pitched

PEEPs in place where necessary N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys 3

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?) 1 protected

Number of External Staircases None

External Balcony part of escape route? Yes

Unusual features Marionette style accommodation

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

Asset ID: 24418 Flats only Fire Detection and Warning System Grade D Grade of fire alarm Category of fire alarm LD3 Minimum Protection **Emergency Lighting Provision** Non Maintained System - Common Areas Portable Fire Extinguishers supplied/fitted No Fixed Fire Fighting Installations No **Customers** 60 Number of occupants Occupant tenure type breakdown Garage and Car Parking Bays, General Needs, Leasehold Fire Safety Related Customer Safety Servicing 0 Overdue communal gas safety checks Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 0 Overdue communal PAT testing 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests 3 3 Overdue Annual Emergency Lighting tests Overdue Weekly Fire Alarm Testing 0 Overdue Fire Panel - Six Monthly Testing Overdue Fire Safety Equipment tests **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors 0 Communal Fire doors due for replacement within 5 years **Dwelling Doors** 0 Failing Dwelling Fire Doors Dwelling Fire doors due for replacement within 5 years 0

**Esher Road** 

# **Fire Risk Assessment Survey Results**

### **Scheme and Building Information**

Photo



Date of Fire Risk Assessment 30/05/2023

FRA Frequency (Months) 36

Purpose of Fire Risk Assessment

Type of Risk Assessment

Quantity

Fire & Safety Assessor Gary Bredin

Enforcing Fire Authority Surrey FRS

Scheme Tel. No -

Other staff in attendance None

Number of on-site Accent staff

None

Number of other (non-Accent) staff

Contract Cleaners in common areas

1

Scheme Inspection completed Yes

Number of occupants 60

Personal Emergency Evacuation Plans in place N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of Storeys 36

Number of floors on which car parking is provided 0

Is there a habitable basement?

No. of internal staircases (protected/unprotected) 1 protected

Number of external staircases None

External balcony part of escape route? Yes

Unusual features Marionette style accommodation

# **Fire Risk Assessment Survey Results**

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Residential

Fire Detection and Warning System Flats only

Grade of Fire Alarm Grade D

Category of Fire Alarm LD3 Minimum Protection

Emergency Lighting Provision Non Maintained System - Common Areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted No

Water Extinguisher(s) present

Foam Extinguisher(s) present No

Dry Powder Extinguisher(s) present

Carbon Dioxide Extinguisher(s) present No

Fire Blanket(s) present

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present No

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present No

### **Electrical Sources of Ignition**

Electrical installation within common areas in good condition and no

obvious damage?

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment

Comment

Electrical App/PA Testing - tested within past 12 months?

N/A

Comment

Absence of trailing leads and adapters? Yes

Comment

Comment

Evidence that mobility scooters are not being stored/charged in No

common areas?

Is there a purpose built mobility scooter store/charging area?

Yes

Yes

Asset ID: 24418	Esher Road		
Comment			
Does the building have a light	ning protection system?	No	
Comment			
Gas installations			
Is there a commercial/domest	c gas supply to the scheme?	Yes	
Comment			
Valid LGSR held on file for fixe (Boilers)	ed communal area gas appliances?	Yes	
Comment			
Valid LGSR held on file for resappliances?  Comment	idential flats that contains gas	Yes	
	nin General Needs flats subject to an ults	Yes	
Comment			
Other Sources of Ignit	ion		
Is there a no smoking policy ir to?	place, which is enforced and adhered	Yes	
Comment			
Adequate security against ars	on?	Yes	
Comment			
Are refuse/recycling bin areas	managed and suitably located?	Yes	
Comment			
Are there communal cooking f	acilities at this scheme?	No	
Comment			
Housekeeping			
Are all electrical/intake/service waste, contractors waste and Comment	e cupboards secure and free from genera and residents personal items?	l Yes	
Are unnecessary accumulation avoided?  Comment	ns of combustible materials or waste	Yes	
Are combustible materials and sources and stored appropriate Comment	I substances separated from ignition ely?	Yes	

Asset ID: 24418 Esh	ner Road	
Furniture/furnishings in good condit comply with modern standards and Comment		N/A
Other Significant Fire Haz	ards	
Are all other significant fire hazards	adequately controlled?	No
Comment		
Means of Escape from Fire	e	
Is it considered that the building is pescape in case of fire?  Comment	provided with reasonable means of	Yes
Escape routes unobstructed and sa	fe to use?	Yes
Comment		
Exits immediately openable without correctly?  Comment	a key and/or failsafe's function	Yes
Reasonable distances of travel whe direction of travel?  Comment	ere there is a single/alternative	Yes
necessary?	d open in direction of escape where	Yes
Comment		
Fire Spread and Developn	nent	
Is it considered that the compartme	ntation is of a reasonable standard?	Yes
Comment		
Is there reasonable limitation of sur spread (walls, floors, ceilings)? Comment	face finishes that might promote fire	Yes
Are fire dampers/shutters provided means of escape against fire, smok		N/A
As far as can be reasonably ascerta within roof spaces of a satisfactory Comment	-	Yes
Loft hatches fire resisting?		N/A

Comment

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?  Comment  Do external walls, doors, windows and anything attached to the exterior, limit fire spread?  Comment  If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?  Comment  Are roller shutter doors that are required to be FR, fire resisting and self-closing?  Comment  Emergency Escape Lighting  Is the emergency lighting correctly specified and installed as per current standards?  Comment  Emergency lighting units in good condition and securely fixed to walls/ceilings?
exterior, limit fire spread?  Comment  If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?  Comment  Are roller shutter doors that are required to be FR, fire resisting and self-closing?  Comment  Emergency Escape Lighting  Is the emergency lighting correctly specified and installed as per current standards?  Comment  Emergency lighting units in good condition and securely fixed to walls/ceilings?
testing available? Comment  Are roller shutter doors that are required to be FR, fire resisting and self-closing? Comment  Emergency Escape Lighting  Is the emergency lighting correctly specified and installed as per current standards? Comment  Emergency lighting units in good condition and securely fixed to walls/ceilings?
Self-closing?  Comment  Emergency Escape Lighting  Is the emergency lighting correctly specified and installed as per current standards?  Comment  Emergency lighting units in good condition and securely fixed to walls/ceilings?
Is the emergency lighting correctly specified and installed as per current standards?  Comment  Emergency lighting units in good condition and securely fixed to walls/ceilings?
current standards?  Comment  Emergency lighting units in good condition and securely fixed to  walls/ceilings?
walls/ceilings?
Comment  Records of monthly/annual testing available?  Yes
Comment Testing available:
Fire Safety Signs and Notices
Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?  Comment
Directional fire escape signage in place and adequate?
Comment
Is there suitable LIFT signage i.e. do not use in case of fire?  N/A
Comment
Do common area fire doors display the correct signage on both sides  Yes
where applicable?  Comment
Comment

### Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme?

Comment

Portable fire extinguishers - appropriate type/number/position?

Comment

Correct signage displayed by each fire extinguisher?

Comment

Fire blanket in communal kitchen, secured to the wall, complete with signage?

Comment

Dry risers - Inlet/outlet boxes secured and/or securing straps fitted to outlet valves?

Comment

Records available of fire fighting equipment servicing within past 12

months?

Comment

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under the Building Safety Act?

Comment

Will this FRA be shared will all Accountable Persons for the premises?

Comment

How will this sharing be achieved?

Are there other Responsible Persons who share or have fire safety duties in respect of the premises?

Have all details required by regulations been shared with all other

Responsible Persons?

Comment

Have all details required by regulations to be shared with us from other

Responsible Persons been received and recorded?

Comment

Will this FRA be shared will all other Responsible Persons for the premises?

Comment

How will this sharing be achieved?

Is an office or IL scheme being inspected?

N/A

N/A

N/A

N/A

N/A

N/A

Yes

Yes

access.

This will be stored on MFiles for all 8nternal staff to

Yes

Yes

Yes

Yes

This will be located on M Files.

N/A

Asset ID: 24418 Esher Road	
Comment	
IL Schemes & Regional Offices - Are there sufficient numbers of qualified Fire wardens?  Comment	N/A
Offices - Are there suitable arrangements for ensuring the premises are evacuated?  Comment	N/A
Offices - Are there suitable arrangements for evacuating disabled people?	N/A
Comment  Offices - Suitable arrangements for meeting the fire service on arrival and proving relevant information?  Comment	N/A
Offices/IL Schemes - Is there a suitable assembly point?	N/A
Comment	
Offices - Are fire drills carried out at appropriate intervals?	N/A
Comment	
Passenger Lift	
Is the scheme fitted with a passenger lift?	No
Comment	
Premises Inspection Box	
Is there a premises information box for fire & rescue service use?	No
Comment	
Evacuation Policy	
Are there suitable arrangements for summoning the fire service?	Yes
Comment	
Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance?  Comment	Yes
Engagement with Residents	
Has information of fire procedures been disseminated to residents?	Yes
Comment	Theses are posted in the information boards in all

blocks.

Asset ID:	24418	Esher Road	
Is general fire	e safety informatio	on disseminated to residents?	Yes
Comment			
FRA Freq	uency		
Taking the fir	•	essment into account, is the frequency of	Yes
Comment			
Miscellan	eous		
Are there any above.	y other observatio	ns/actions to raise that are not covered	Yes
Action leadin	g to a repair		Yes
Internal admi	inistrative Action		Yes
affect the fab	related remedial ric of the building	works required at this property, that will?	No
Comment			
	ny unsatisfactory uilding Safety Rep	aspects of the Fire Risk Assessment? port).	Yes
Some fire do with our cont	•	ose so works orders have been raised	Yes
Some minor	works were requir	red which have been raised with our	Yes

Unauthorised items were found in communal areas and arrangements

A number of fire doors were found to be wedged or propped open. Fire

Not all records were up to date, as noted in the table below.

Arrangements have been made for these to be completed.

doors are there to keep you safe and me kept shut at all times.

contractors.

were made for their removal.

No

No

No

### **Risk Calculator - Fire**

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

Systems.					
	•	ention measures obse e hazard from the fire			
LOW		MEDIUM	,	нідн	
any procedural a	rrangements obse	the building, the occ rved at the time of the event of a fire would l	e assessment, it is	otection afforded and considered that the	
MINOR		MAJOR	CRI	ITICAL	

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Moderate	