

This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 5949

Pye Nest Court, Liversedge

Cover Sheet

Photo



Date of Fire Risk Assessment Date of Next Fire Risk Assessment FRA Frequency (Months) Purpose of Fire Risk Assessment Type of Fire Risk Assessment Fire & Safety Assessor 28 Apr 2023 28 Apr 2026 36 3 year Re-Assessment Type 3 (Common Parts and Flats - Non Destructive) Steven Manners

This report has been validated by:

Name:

Date:

Comment:

The Scheme

Pye Nest Court
Pye Nest Court, Liversedge
WF15 8BH
Yorkshire
Yes
West Yorkshire
None
None
Contract Cleaners in common areas
YYYY

The Building

Accommodation Type	CAT2 Housing for Older People (S28), General Needs (S30)
Build Date	Jan 1 1978
Number Of Homes	22
Homes breakdown	Flat
External wall construction	Facing Brick, Natural Stone
External wall finish	Artificial/Natural Stone
Roof construction	Timber
Roof covering	Interlocking Pitched
PEEPs in place where necessary	N/A
Current Evacuation Strategy	Stay Put (Delayed) Evacuation
Conversion or purpose-built	Purpose Built
Number of storeys	2
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
Number of internal Staircases (protected or unprotected?)	1 per block
Number of External Staircases	None
External Balcony part of escape route?	No
Unusual features	None
Building Access Conditions for Fire Brigade	Vehicular Access to one or more elevations

Pye Nest Court, Liversedge

Fire Detection and Warning System	Flats only
Grade of fire alarm	Grade D
Category of fire alarm	LD3 Minimum Protection
Emergency Lighting Provision	Non Maintained System - Common Areas
Portable Fire Extinguishers supplied/fitted	No
Fixed Fire Fighting Installations	No

Customers

Number of occupants	30
Occupant tenure type breakdown	General Needs, Leasehold, Sheltered Schemes

Fire Safety Related Customer Safety Servicing

Overdue communal gas safety checks	0
Overdue domestic gas safety checks	0
Overdue communal electrical condition checks	0
Overdue domestic electrical condition checks	0
Overdue alarm call pull chord tests	0
Overdue communal PAT testing	0
Overdue customer mobility scooter PAT testing	0
Overdue Monthly Emergency Lighting Switch Tests	3
Overdue Annual Emergency Lighting tests	3
Overdue Weekly Fire Alarm Testing	0
Overdue Fire Panel - Six Monthly Testing	
Overdue Fire Safety Equipment tests	

Building Fire Safety Surveys - Communal Doors

Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	0

Dwelling Doors

Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo

	Starra ang Carrait Starra ang Carrait
Date of Fire Risk Assessment	28/04/
FRA Frequency (Months)	36
Purpose of Fire Risk Assessment	3 year
Type of Risk Assessment	Туре З
Quantity	1
Fire & Safety Assessor	Stever
Enforcing Fire Authority	West
Scheme Tel. No	
Other staff in attendance	None
Number of on-site Accent staff	None
Number of other (non-Accent) staff	Contra
Scheme Inspection completed	Yes
Number of occupants	30
Personal Emergency Evacuation Plans in place	N/A
Current Evacuation Strategy	Stay F
Conversion or purpose-built	Purpo
Number of Storeys	2
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
No. of internal staircases (protected/unprotected)	1 per t
Number of external staircases	None
External balcony part of escape route?	No
Unusual features	None



28/04/2023
36
3 year Re-Assessment
Type 3 (Common Parts and Flats - Non Destructive)
1
Steven Manners
West Yorkshire
None
None
Contract Cleaners in common areas
Yes
30
N/A
Stay Put (Delayed) Evacuation
Purpose Built
2
0
No
1 per block
None
No
None

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade	Vehicular Access to one or more elevations
Surroundings: Residential/Commercial	Residential
Fire Detection and Warning System	Flats only
Grade of Fire Alarm	Grade D
Category of Fire Alarm	LD3 Minimum Protection
Emergency Lighting Provision	Non Maintained System - Common Areas
Portable Fire Extinguishers / Fire Blankets supplied / fitted	No
Water Extinguisher(s) present	No
Foam Extinguisher(s) present	No
Dry Powder Extinguisher(s) present	No
Carbon Dioxide Extinguisher(s) present	No
Fire Blanket(s) present	No
Fixed Fire Fighting Installations supplied / fitted	No
Dry Riser(s) present	No
Wet Riser(s) present	No
Sprinkler System present	No
Hosereel(s) present	No
Automatic Opening Vent(s) present	No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no obvious damage? Comment	Yes All in good condition at the time of inspection
Valid Electrical Installation Condition Reports held on file? (Common Areas & General Needs Flats)	Yes
Comment	All records are available on ActiveH
Electrical App/PA Testing - tested within past 12 months?	N/A
Comment	None on site
Absence of trailing leads and adapters?	Yes
Comment	None on site
Evidence that mobility scooters are not being stored/charged in common areas?	Yes
Comment	None on scheme
Is there a purpose built mobility scooter store/charging area?	No

Pye Nest Court, Liversedge

Comment

 Does the building have a lightning protection system?
 No

 Comment
 Not required

Gas installations

Is there a commercial/domestic gas supply to the scheme?

Comment

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered to?	Yes
Comment	No smoking allowed in communal areas
Adequate security against arson?	Yes
Comment	
Are refuse/recycling bin areas managed and suitably located?	Yes
Comment	
Are there communal cooking facilities at this scheme?	No
Comment	No communal kitchen

Housekeeping

Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items?	Yes
Comment	None present at the time of inspection
Are unnecessary accumulations of combustible materials or waste avoided?	Yes
Comment	None found at the time of inspection
Are combustible materials and substances separated from ignition sources and stored appropriately? Comment	N/A
Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations?	N/A
Comment	None permitted at general needs scheme
Other Significant Fire Hazards	
Are all other significant fire hazards adequately controlled?	N/A
Comment	

No None on site

MIS-AMS ActiveH - Fire Risk Assessment Report

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of escape in case of fire? Comment	Yes
Escape routes unobstructed and safe to use?	Yes
Comment	No obstructions at the time of inspection
Exits immediately openable without a key and/or failsafe's function correctly? Comment	Yes
Comment	
Reasonable distances of travel where there is a single/alternative direction of travel?	Yes
Comment	Distance of travel within guidelines
Escape routes lead to final exits and open in direction of escape where necessary?	Yes
Comment	

Fire Spread and Development

CommentYesIs there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?YesCommentNo flammables on schemeAre fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?NoCommentNone fittedAs far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard? CommentYesLoft hatches fire resisting?N/ACommentN/ACommentN/ACommentN/ADo external walls, doors, windows and anything attached to the exterior, limit fire spread? CommentYesDo external walls, doors, windows and anything attached to the exterior, limit fire spread?N/AIf Smoke Control Systems (AOV's) are fitted, are the records of annual exterior gavailable?N/A	Is it considered that the compartmentation is of a reasonable standard?	Yes
In this is the formation in matter of variable interview intervie	Comment	
Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?NoCommentNone fittedAs far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?YesCommentYesLoft hatches fire resisting?N/ACommentN/ACommentN/ACommentN/ADo external walls, doors, windows and anything attached to the exterior, limit fire spread? CommentYesIf Smoke Control Systems (AOV's) are fitted, are the records of annualN/A		Yes
As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?None fittedCommentYesLoft hatches fire resisting?N/ACommentV/AAs far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?N/ADo external walls, doors, windows and anything attached to the exterior, limit fire spread?YesIf Smoke Control Systems (AOV's) are fitted, are the records of annualN/A	Comment	No flammables on scheme
As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard? Comment Loft hatches fire resisting? N/A Comment As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard? Comment Do external walls, doors, windows and anything attached to the exterior, limit fire spread? Comment If Smoke Control Systems (AOV's) are fitted, are the records of annual N/A		No
Within roof spaces of a satisfactory standard? Comment Loft hatches fire resisting? N/A Comment N/A As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard? N/A Comment N/A Do external walls, doors, windows and anything attached to the exterior, limit fire spread? Yes Comment If Smoke Control Systems (AOV's) are fitted, are the records of annual N/A	Comment	None fitted
Loft hatches fire resisting?N/ACommentN/AAs far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?N/ACommentCommentDo external walls, doors, windows and anything attached to the exterior, limit fire spread?YesCommentIf Smoke Control Systems (AOV's) are fitted, are the records of annualN/A		Yes
Comment N/A As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard? N/A Comment Comment Do external walls, doors, windows and anything attached to the exterior, limit fire spread? Yes Comment If Smoke Control Systems (AOV's) are fitted, are the records of annual N/A	Comment	
As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard? Comment Do external walls, doors, windows and anything attached to the exterior, limit fire spread? Comment If Smoke Control Systems (AOV's) are fitted, are the records of annual N/A	Loft hatches fire resisting?	N/A
cross corridor fire doors within suspended ceiling void of a satisfactory standard? Comment Do external walls, doors, windows and anything attached to the exterior, limit fire spread? Comment If Smoke Control Systems (AOV's) are fitted, are the records of annual N/A	Comment	
Do external walls, doors, windows and anything attached to the exterior, limit fire spread? Comment If Smoke Control Systems (AOV's) are fitted, are the records of annual N/A	cross corridor fire doors within suspended ceiling void of a satisfactory	N/A
exterior, limit fire spread? Comment If Smoke Control Systems (AOV's) are fitted, are the records of annual	Comment	
If Smoke Control Systems (AOV's) are fitted, are the records of annual N/A	exterior, limit fire spread?	Yes
	Comment	
		N/A

Asset ID: 5949 Pye Nest Court, Liversedge

Comment	None fitted
Are roller shutter doors that are required to be FR, fire resisting and self-closing?	N/A
Comment	None fitted

Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per current standards?	Yes
Comment	
Emergency lighting units in good condition and securely fixed to walls/ceilings?	Yes
Comment	All in good condition at the time of inspection
Records of monthly/annual testing available?	Yes
Comment	All records are available on ActiveH

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?	Yes
Comment	Notices are displayed throughout the building
Directional fire escape signage in place and adequate?	Yes
Comment	
Is there suitable LIFT signage i.e. do not use in case of fire?	N/A
Comment	No lifts in the scheme
Do common area fire doors display the correct signage on both sides where applicable?	Yes

Comment

Means of giving Warning in case of Fire

Comment

Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations	
provided at this scheme?	
Comment	

No Alarms in flats only

No

Not required

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under the Building Safety Act?	No
Comment	
Are there other Responsible Persons who share or have fire safety duties in respect of the premises?	Νο
How will this sharing be achieved?	
Is an office or IL scheme being inspected?	No
Comment	
Passenger Lift	
Is the scheme fitted with a passenger lift?	No
Comment	
Premises Inspection Box	
Is there a premises information box for fire & rescue service use?	No
Comment	
Evacuation Policy	
Are there suitable arrangements for summoning the fire service?	Yes
Comment	Residents are instructed to contact the fire service by dialing 999
Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance?	Yes
Comment	
Engagement with Residents	
Has information of fire procedures been disseminated to residents?	Yes
Comment	All fire related information is included in the handover pack
Is general fire safety information disseminated to residents?	Yes
Comment	As above and by leaflets, information available on the website and notices are displayed throughout the building

FRA Frequency

Asset ID: 5949 Pye Nest Court, Liversedge

Taking the findings of this assessment into account, is the frequency of	Yes
the FRA correct?	
Commont	

Comment

Miscellaneous

Are there any other observations/actions to raise that are not covered above.	No
Are there fire related remedial works required at this property, that will affect the fabric of the building?	No
Comment	
Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).	No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

	HIGH
--	------

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR	MAJOR	V	CRITICAL	
	MAJOR		ORITICAL	

The definition of the above terms is as follows: *FRA Review Frequency*

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	intolerable

When the level of risk is established, the action level can be read from the table below:

Pye Nest Court, Liversedge

Risk Level	Guide to actions and appropriate timescales	
Trivial	No action is required	
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.	
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.	
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.	

The Overall Risk Level for this asset is:	Trivial	