# Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 9299 1-7 Halliwell Court Block 1-7 Halliwell Court, Chorley

#### **Cover Sheet**

Photo



Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

14 Sep 2023

14 Sep 2026

36

3 year Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Ian Potter

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

#### The Scheme

Scheme Name Halliwell Court

Scheme Address 1-7 Halliwell Court Block 1-7 Halliwell Court, Chorley

Postcode PR7 2AX

Region North West

Scheme Manager

Scheme Tel. No N/A
Scheme Inspection Completed Yes

Enforcing Fire Authority Lancashire

Other staff in attendance None

Number of on-site Accent staff None

Number of other (non-Accent) staff

Contract Cleaners in common areas

#### The Building

Accommodation Type CAT2 Housing for Older People (S28)

Build Date Jan 1 1984

Number Of Homes 7

Homes breakdown Flat

External wall construction Facing Brick

External wall finish Facing Brick, UPVC Cladding

Roof construction Timber

Roof covering Interlocking Pitched

PEEPs in place where necessary N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys 3

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?) 1 Protected

Number of External Staircases 0

External Balcony part of escape route?

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

Flats and common areas not linked Fire Detection and Warning System Grade of fire alarm Grade A Category of fire alarm LD3 Minimum Protection Non Maintained System - Common Areas **Emergency Lighting Provision** Portable Fire Extinguishers supplied/fitted No Fixed Fire Fighting Installations No **Customers** 5 Number of occupants Occupant tenure type breakdown General Needs, Staff Accommodation, Sheltered Fire Safety Related Customer Safety Servicing 0 Overdue communal gas safety checks Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 0 Overdue communal PAT testing 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests Overdue Annual Emergency Lighting tests 1 Overdue Weekly Fire Alarm Testing 1 Overdue Fire Panel - Six Monthly Testing 1 Overdue Fire Safety Equipment tests **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors 0 Communal Fire doors due for replacement within 5 years **Dwelling Doors** 0 Failing Dwelling Fire Doors

1-7 Halliwell Court Block 1-7 Halliwell Court, Chorley

Dwelling Fire doors due for replacement within 5 years

Asset ID: 9299

0

### **Fire Risk Assessment Survey Results**

#### **Scheme and Building Information**

Photo



Date of Fire Risk Assessment 14/09/2023

FRA Frequency (Months) 36

Purpose of Fire Risk Assessment 3 year Re-Assessment

Type of Risk Assessment Type 1 (Common Parts Only - Non Destructive)

Quantity

Fire & Safety Assessor lan Potter

Enforcing Fire Authority Lancashire

Scheme Tel. No N/A

Other staff in attendance None

Number of on-site Accent staff

None

Number of other (non-Accent) staff

Contract Cleaners in common areas

Scheme Inspection completed Yes

Number of occupants 5

Personal Emergency Evacuation Plans in place N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of Storeys 3

Number of floors on which car parking is provided 0

Is there a habitable basement?

No. of internal staircases (protected/unprotected) 1 Protected

Number of external staircases 0

External balcony part of escape route?

Unusual features None

#### **Fire Risk Assessment Survey Results**

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Residential

Fire Detection and Warning System Flats and common areas not linked

Grade of Fire Alarm Grade A

Category of Fire Alarm LD3 Minimum Protection

Emergency Lighting Provision Non Maintained System - Common Areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted No

Water Extinguisher(s) present No

Foam Extinguisher(s) present No

Dry Powder Extinguisher(s) present

Carbon Dioxide Extinguisher(s) present

Fire Blanket(s) present

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present No

#### **Electrical Sources of Ignition**

Electrical installation within common areas in good condition and no

obvious damage?

Comment None seen

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Communal 06/01/22

All checked and in date for flats

Yes

Yes

Yes

Electrical App/PA Testing - tested within past 12 months? Yes

Comment No communal appliances

Absence of trailing leads and adapters? Yes

Comment None seen

Evidence that mobility scooters are not being stored/charged in

common areas?

Comment None seen

Is there a purpose built mobility scooter store/charging area?

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 5 of 13

Generated 22/09/2023 16:09:45

Comment Not required

Does the building have a lightning protection system?

Comment Not required

**Gas installations** 

Is there a commercial/domestic gas supply to the scheme?

Comment No gas supply

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered

to?

Comment Smoking allowed in flats

Yes

Generated 22/09/2023 16:09:45

Adequate security against arson? Yes

Comment Secure door entry

Are refuse/recycling bin areas managed and suitably located? Yes

Comment External

Are there communal cooking facilities at this scheme?

Comment

Housekeeping

Are all electrical/intake/service cupboards secure and free from general Yes

waste, contractors waste and and residents personal items?

Comment All clear

Are unnecessary accumulations of combustible materials or waste Yes

avoided?

Comment None seen

Are combustible materials and substances separated from ignition Yes

sources and stored appropriately?

Comment None seen

Furniture/furnishings in good condition, fire retardant/resistant and N/A

comply with modern standards and regulations?

Comment No communal furniture

Page 6 of 13

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Comment None seen

#### 1-7 Halliwell Court Block 1-7 Halliwell Court, Chorley Asset ID: 9299

#### Means of Escape from Fire

Is it considered that the building is provided with reasonable means of

escape in case of fire?

Single protected staircase Comment

Yes

Yes

Yes

Yes

None fitted

Generated 22/09/2023 16:09:45

Escape routes unobstructed and safe to use? Yes

Comment

Yes Exits immediately openable without a key and/or failsafe's function

correctly?

Comment Checked

Reasonable distances of travel where there is a single/alternative

direction of travel?

Escape routes lead to final exits and open in direction of escape where

necessary?

Comment

Comment

Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard? No

Comment Guest flat door damaged. Not in use now and no

significant fire hazards

Is there reasonable limitation of surface finishes that might promote fire

spread (walls, floors, ceilings)?

Painted Comment

N/A Are fire dampers/shutters provided in ducts/refuse chutes to protect

means of escape against fire, smoke and combustion products?

Comment

Yes As far as can be reasonably ascertained, is the compartmentation

within roof spaces of a satisfactory standard? Checked

Loft hatches fire resisting? Yes

Comment

exterior, limit fire spread?

Comment

N/A As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory

standard?

No suspended ceiling Comment

Do external walls, doors, windows and anything attached to the Yes

**Brick** Comment

N/A If Smoke Control Systems (AOV's) are fitted, are the records of annual

testing available?

MIS-AMS ActiveH - Fire Risk Assessment Report Page 7 of 13

Comment None fitted

Are roller shutter doors that are required to be FR, fire resisting and

self-closing?

Comment None fitted

Observation	Priority	Referred To	Required By:	Task ID
The Guest flat door on the second floor has been forced open and left insecure. The flat is no longer in use but the door requires securing and electricity isolating	Internal - Medium	Area Housing Manager	31/10/2023	1713304

N/A

If the flat is to be used, for





#### **Emergency Escape Lighting**

Is the emergency lighting correctly specified and installed as per	Yes
--	-----

Comment

Comment

Emergency lighting units in good condition and securely fixed to Yes

walls/ceilings?

current standards?

Records of monthly/annual testing available?

Comment Annual 01/11/22

Monthly 11/09/23

#### **Fire Safety Signs and Notices**

Are the correct Fire Action/Advice notices displayed in prominent

Yes

locations within the common areas?

Comment Checked

Directional fire escape signage in place and adequate?

Comment

Is there suitable LIFT signage i.e. do not use in case of fire?

Comment No lift

Do common area fire doors display the correct signage on both sides

Yes

where applicable?

Comment

#### Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?

Yes

Comment

Is fire detection and warning system appropriate for occupancy and fire

risk, as per BS 5839-1:2017?

Comment

Is the fire detection and warning system maintained/tested and all

certificates saved on file?

Comment Tested 27th March 23

Fire alarm components in good condition and securely fixed to Yes

walls/ceilings?

Comment

Hold open devices operate at the sounding of the alarm and are in a N/A

serviceable condition?

Comment None fitted

Are there heat detectors located in the Kitchen, Boiler, Plant Room and

Laundry?

Comment

Is the fire alarm panel remotely monitored, and if so are there records of

regular testing?

Comment Not remotely monitored

#### Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme?

Comment

No

No

N/A

N/A

Yes

#### **Management of Fire Safety**

Are these premises regulated by the Building Safety Regulator under

the Building Safety Act?

Comment Under 18m

Are there other Responsible Persons who share or have fire safety

No

duties in respect of the premises? How will this sharing be achieved?

Is an office or IL scheme being inspected?

Comment

## 1-7 Halliwell Court Block 1-7 Halliwell Court, Chorley Asset ID: 9299 Passenger Lift Is the scheme fitted with a passenger lift? No Comment **Premises Inspection Box** No Is there a premises information box for fire & rescue service use? Not required **Evacuation Policy** Are there suitable arrangements for summoning the fire service? Yes 999 Comment Taking FRA findings, is the evacuation policy appropriate for the Yes scheme as per latest guidance? Stay put Comment **Engagement with Residents** Has information of fire procedures been disseminated to residents? Yes Comment By Housing Partner at commencement of tenancy and notices Is general fire safety information disseminated to residents? Yes Via webpage Comment FRA Frequency Yes Taking the findings of this assessment into account, is the frequency of the FRA correct? Comment Low risk **Miscellaneous** No Are there any other observations/actions to raise that are not covered above. No Are there fire related remedial works required at this property, that will

# Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).

Yes

affect the fabric of the building?

Comment

Some fire doors did not fully close so works orders have been raised with our contractors.	No
Some minor works were required which have been raised with our contractors.	Yes
Unauthorised items were found in communal areas and arrangements were made for their removal.	No
Not all records were up to date, as noted in the table below.  Arrangements have been made for these to be completed.	No
A number of fire doors were found to be wedged or propped open. Fire doors are there to keep you safe and me kept shut at all times.	No

#### **Risk Calculator - Fire**

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW MEDIUM HIGH

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR MAJOR CRITICAL

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial
	<u> </u>