Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 705 18 - 23 Pilton Close, Peterborough

Cover Sheet

Photo

09 Feb 2023

09 Feb 2026

36

3 year Re-Assessment

Type 3 (Common Parts and Flats - Non Destructive)

Lynn.betteridge@accentgroup.org

Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

This report has been validated by:

Name: A 2 Town

Date: 22/02/2023

Comment: Report appears complete and acurate

Asset ID: 705 18 - 23 Pilton Close, Peterborough

The Scheme

Scheme Name Paston

Scheme Address 18 - 23 Pilton Close, Peterborough

Postcode PE4 7PU

Region East

Scheme Manager

Scheme Tel. No None

Scheme Inspection Completed Yes

Enforcing Fire Authority Cambridgeshire Fire and Rescue.

Other staff in attendance None

Number of on-site Accent staff None

Number of other (non-Accent) staff

Contract Cleaners in common areas

The Building

Accommodation Type General Needs (S30)

Build Date Jan 1 1983

Number Of Homes 6

Homes breakdown Flat

External wall construction Facing Brick

External wall finish Facing Brick

Roof construction Timber

Roof covering Interlocking Pitched

PEEPs in place where necessary No

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys 3

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

Number of External Staircases None

External Balcony part of escape route?

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

18 - 23 Pilton Close, Peterborough Asset ID: 705 Fire Detection and Warning System Flats only Grade D Grade of fire alarm Category of fire alarm LD3 Minimum Protection **Emergency Lighting Provision** Maintained system - Common areas Portable Fire Extinguishers supplied/fitted No Fixed Fire Fighting Installations No **Customers** 14 Number of occupants General Needs, Leasehold Occupant tenure type breakdown Fire Safety Related Customer Safety Servicing Overdue communal gas safety checks 0 0 Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 Overdue communal PAT testing 0 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests Overdue Annual Emergency Lighting tests 1 Overdue Weekly Fire Alarm Testing 0 Overdue Fire Panel - Six Monthly Testing Overdue Fire Safety Equipment tests **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors Communal Fire doors due for replacement within 5 years 0 **Dwelling Doors** Failing Dwelling Fire Doors 0 Dwelling Fire doors due for replacement within 5 years 0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



Date of Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Risk Assessment

Quantity

Fire & Safety Assessor

Enforcing Fire Authority

Scheme Tel. No

Other staff in attendance

Number of on-site Accent staff

Number of other (non-Accent) staff

Scheme Inspection completed

Number of occupants

Personal Emergency Evacuation Plans in place

Current Evacuation Strategy

Conversion or purpose-built

Number of Storeys

Number of floors on which car parking is provided

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

Number of external staircases

External balcony part of escape route?

Unusual features

09/02/2023

36

3 year Re-Assessment

Type 3 (Common Parts and Flats - Non Destructive)

1

Lynn.betteridge@accentgroup.org

Cambridgeshire Fire and Rescue.

None

None

None

Contract Cleaners in common areas

Yes

14

No

Stay Put (Delayed) Evacuation

Purpose Built

3

0

No 1

None

No

None

18 - 23 Pilton Close, Peterborough Asset ID: 705

Fire Risk Assessment Survey Results

Vehicular Access to one or more elevations Building access conditions for Fire Brigade

Surroundings: Residential/Commercial

Fire Detection and Warning System Flats only

Grade D Grade of Fire Alarm

Category of Fire Alarm **LD3 Minimum Protection**

Maintained system - Common areas **Emergency Lighting Provision**

Portable Fire Extinguishers / Fire Blankets supplied / fitted No

Water Extinguisher(s) present No

No Foam Extinguisher(s) present

Dry Powder Extinguisher(s) present No

Carbon Dioxide Extinguisher(s) present No

No Fire Blanket(s) present

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

No Wet Riser(s) present

No Sprinkler System present

No Hosereel(s) present

Automatic Opening Vent(s) present No

Electrical Sources of Ignition

Yes Electrical installation within common areas in good condition and no

obvious damage?

Comment No dame identified.

Yes Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Details are recorded on ACTIVE H dated 4/2/19. Comment

N/A Electrical App/PA Testing - tested within past 12 months?

Comment

Absence of trailing leads and adapters? Yes

Comment

Comment

No Evidence that mobility scooters are not being stored/charged in

common areas?

No Is there a purpose built mobility scooter store/charging area?

Asset ID: 705 18 - 23 Pilton Close, Peterborough	
Comment	
Does the building have a lightning protection system?	No
Comment	
Gas installations	
Is there a commercial/domestic gas supply to the scheme?	Yes
Comment	Flats only.
Valid LGSR held on file for fixed communal area gas appliances? (Boilers)	Yes
Comment	Sample flat gas safety checks dated26/11/22.
Valid LGSR held on file for residential flats that contains gas appliances? Comment	Yes
Are smoke/heat detectors within General Needs flats subject to an annual inspection and the results	Yes
Comment	The annual inspections are carried out by the Gas supplier and tested annually all flats on this scheme I've had their gas safety certificate uploaded to activate
Other Sources of Ignition	
	Yes
Is there a no smoking policy in place, which is enforced and adhered to?	
to? Comment	
to? Comment Adequate security against arson?	Yes
to? Comment	On day of inspection entry secure access by
to? Comment Adequate security against arson?	
to? Comment Adequate security against arson? Comment	On day of inspection entry secure access by keypad.
to? Comment Adequate security against arson? Comment Are refuse/recycling bin areas managed and suitably located?	On day of inspection entry secure access by keypad.
to? Comment Adequate security against arson? Comment Are refuse/recycling bin areas managed and suitably located? Comment	On day of inspection entry secure access by keypad. Yes
to? Comment Adequate security against arson? Comment Are refuse/recycling bin areas managed and suitably located? Comment Are there communal cooking facilities at this scheme?	On day of inspection entry secure access by keypad. Yes
to? Comment Adequate security against arson? Comment Are refuse/recycling bin areas managed and suitably located? Comment Are there communal cooking facilities at this scheme?	On day of inspection entry secure access by keypad. Yes
to? Comment Adequate security against arson? Comment Are refuse/recycling bin areas managed and suitably located? Comment Are there communal cooking facilities at this scheme? Comment	On day of inspection entry secure access by keypad. Yes
to? Comment Adequate security against arson? Comment Are refuse/recycling bin areas managed and suitably located? Comment Are there communal cooking facilities at this scheme? Comment Housekeeping Are all electrical/intake/service cupboards secure and free from general	On day of inspection entry secure access by keypad. Yes

Page 6 of 12

Generated 09/02/2023 12:51:24

MIS-AMS ActiveH - Fire Risk Assessment Report

18 - 23 Pilton Close, Peterborough Asset ID: 705 Yes Are combustible materials and substances separated from ignition sources and stored appropriately? Comment Yes Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations? Comment Other Significant Fire Hazards Yes Are all other significant fire hazards adequately controlled? Comment No hazards found at time of inspection. Means of Escape from Fire Yes Is it considered that the building is provided with reasonable means of escape in case of fire? Comment Exit and egress easily identifiable only one direction of travel. Escape routes unobstructed and safe to use? Yes Comment Yes Exits immediately openable without a key and/or failsafe's function correctly? Comment Yes Reasonable distances of travel where there is a single/alternative direction of travel? Comment Yes Escape routes lead to final exits and open in direction of escape where necessary? Comment the escape routes the code of practise document B1 for means of escape in the event of Fire. Fire Spread and Development Is it considered that the compartmentation is of a reasonable standard? Yes Comment Yes Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)? At each level compartmentation meets code B3. Comment N/A Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?

within roof spaces of a satisfactory standard?

As far as can be reasonably ascertained, is the compartmentation

Comment

Yes

18 - 23 Pilton Close, Peterborough Asset ID: 705 Comment The roof compartmentation meets approved code Doc B 3.28. Loft hatches fire resisting? Yes Comment The loft hatch is fire resistant to 1 hr certificate and was installed in 2022. Yes As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard? Comment The smoke lobby compartmentation framework contains Georgian glass and a fire door this is fitted floor to ceiling. Yes Do external walls, doors, windows and anything attached to the exterior, limit fire spread? Comment No combustible materials the external walls/doors/windows will not propagate fire spread around the envelope of the building. No If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available? Comment N/A Are roller shutter doors that are required to be FR, fire resisting and self-closing? Comment **Emergency Escape Lighting** Is the emergency lighting correctly specified and installed as per Yes current standards? Comment Emergency lighting units in good condition and securely fixed to Yes walls/ceilings? Comment Checked by tunstall contactor and recorded on Active H. Records of monthly/annual testing available? Yes

Comment Records recorded on active H and test completed by tunstalls annually dated 12/9/22 monthly 3/1/23.

Yes

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent

locations within the common areas?

Comment

Comment

Comment New fire routine notices installed.

Directional fire escape signage in place and adequate? Yes

Is there suitable LIFT signage i.e. do not use in case of fire?

18 - 23 Pilton Close, Peterborough Asset ID: 705 Yes Do common area fire doors display the correct signage on both sides where applicable? Comment Means of giving Warning in case of Fire No Is the scheme fitted with a communal area fire alarm? Comment Fire Extinguishing Equipment No Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme? Comment Management of Fire Safety Are these premises regulated by the Building Safety Regulator under Yes the Building Safety Act? Comment Will this FRA be shared will all Accountable Persons for the premises? Yes Communication with Fire authority and residents. Comment As above. How will this sharing be achieved? Are there other Responsible Persons who share or have fire safety Yes duties in respect of the premises? Yes Have all details required by regulations been shared with all other Responsible Persons? Comment Have all details required by regulations to be shared with us from other Yes Responsible Persons been received and recorded? Comment Will this FRA be shared will all other Responsible Persons for the Yes premises? Comment How will this sharing be achieved? No Is an office or IL scheme being inspected? Comment **Passenger Lift**

Is the scheme fitted with a passenger lift?

No

Asset ID: 705 18 - 23 Pilton Close, Peterborough	
Comment	
Premises Inspection Box	
Is there a premises information box for fire & rescue service use?	No
Comment	
Evacuation Policy	
Are there suitable arrangements for summoning the fire service?	Yes
Comment	Residents responsible for contacting the fire and Rescue Service.
Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance?	Yes
Comment	
Engagement with Residents	
Has information of fire procedures been disseminated to residents?	Yes
Comment	
Is general fire safety information disseminated to residents?	Yes
Comment	When residents move into there flats they are given
	fire safety advice and information.
FRA Frequency	
Taking the findings of this assessment into account, is the frequency of the FRA correct?	Yes
Comment	
Miscellaneous	
Are there any other observations/actions to raise that are not covered above.	No
Are there fire related remedial works required at this property, that will affect the fabric of the building? Comment	No
Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).	No

Asset ID: 705 18 - 23 Pilton Close, Peterborough

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

systems.				
_		evention measures observention measures observention the fire (t		
LOW	X	MEDIUM	нідн	
any procedural	arrangements ob	of the building, the occup served at the time of the a e event of a fire would be:	ssessment, it is consider	
MINOR		MAJOR X	CRITICAL	

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Asset ID: 705 18 - 23 Pilton Close, Peterborough

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial
	<u> </u>