

This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 9133 **6 Piccadilly Road Block 6-6a Piccadilly Road, Burnley**

Cover Sheet

Photo



Date of Fire Risk Assessment	15 Aug 2024
Date of Next Fire Risk Assessment	15 Aug 2026
FRA Frequency (Months)	24
Purpose of Fire Risk Assessment	2 year Re-Assessment
Type of Fire Risk Assessment	Type 1 (Common Parts Only - Non Destructive)
Fire & Safety Assessor	Ian Potter

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name	Burnley Rehabilitations b
Scheme Address	6 Piccadilly Road Block 6-6a Piccadilly Road, Burnley
Postcode	BB11 4QF
Region	North West
Scheme Manager	
Scheme Tel. No	N/A
Scheme Inspection Completed	Yes
Enforcing Fire Authority	Lancashire
Other staff in attendance	None
Number of on-site Accent staff	None
Number of other (non-Accent) staff	Contract Cleaners in common areas

The Building

Accommodation Type	General Needs (S30)
Build Date	Jan 2 1900
Number Of Homes	2
Homes breakdown	Flat
External wall construction	Natural Stone
External wall finish	Artificial/Natural Stone
Roof construction	Timber
Roof covering	Slate Pitched
PEEPs in place where necessary	N/A
Current Evacuation Strategy	Full (Simultaneous) Evacuation
Conversion or purpose-built	Conversion
Number of storeys	2
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
Number of internal Staircases (protected or unprotected?)	One - not communal
Number of External Staircases	None
External Balcony part of escape route?	No
Unusual features	None
Building Access Conditions for Fire Brigade	Vehicular Access to one or more elevations

Asset ID: 9133

6 Piccadilly Road Block 6-6a Piccadilly Road, Burnley

Fire Detection and Warning System	Flats and common areas not linked
Grade of fire alarm	Grade A
Category of fire alarm	LD3 Minimum Protection
Emergency Lighting Provision	Non Maintained System - Common Areas
Portable Fire Extinguishers supplied/fitted	No
Fixed Fire Fighting Installations	No

Customers

Number of occupants	2
Occupant tenure type breakdown	General Needs, Supported Housing

Fire Safety Related Customer Safety Servicing

Overdue communal gas safety checks	0
Overdue domestic gas safety checks	0
Overdue communal electrical condition checks	0
Overdue domestic electrical condition checks	0
Overdue alarm call pull chord tests	0
Overdue communal PAT testing	0
Overdue customer mobility scooter PAT testing	0
Overdue Monthly Emergency Lighting Switch Tests	1
Overdue Annual Emergency Lighting tests	1
Overdue Weekly Fire Alarm Testing	1
Overdue Fire Panel - Six Monthly Testing	1
Overdue Fire Safety Equipment tests	

Building Fire Safety Surveys - Communal Doors

Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	0

Dwelling Doors

Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



Date of Fire Risk Assessment	15/08/2024
FRA Frequency (Months)	24
Purpose of Fire Risk Assessment	2 year Re-Assessment
Type of Risk Assessment	Type 1 (Common Parts Only - Non Destructive)
Quantity	1
Fire & Safety Assessor	Ian Potter
Enforcing Fire Authority	Lancashire
Scheme Tel. No	N/A
Other staff in attendance	None
Number of on-site Accent staff	None
Number of other (non-Accent) staff	Contract Cleaners in common areas
Scheme Inspection completed	Yes
Number of occupants	2
Personal Emergency Evacuation Plans in place	N/A
Current Evacuation Strategy	Full (Simultaneous) Evacuation
Conversion or purpose-built	Conversion
Number of Storeys	2
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
No. of internal staircases (protected/unprotected)	One - not communal
Number of external staircases	None
External balcony part of escape route?	No
Unusual features	None

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade	Vehicular Access to one or more elevations
Surroundings: Residential/Commercial	Residential
Fire Detection and Warning System	Flats and common areas not linked
Grade of Fire Alarm	Grade A
Category of Fire Alarm	LD3 Minimum Protection
Emergency Lighting Provision	Non Maintained System - Common Areas
Portable Fire Extinguishers / Fire Blankets supplied / fitted	No
Water Extinguisher(s) present	No
Foam Extinguisher(s) present	No
Dry Powder Extinguisher(s) present	No
Carbon Dioxide Extinguisher(s) present	No
Fire Blanket(s) present	No
Fixed Fire Fighting Installations supplied / fitted	No
Dry Riser(s) present	No
Wet Riser(s) present	No
Sprinkler System present	No
Hosereel(s) present	No
Automatic Opening Vent(s) present	No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no obvious damage?	Yes
Comment	All appear to be in good condition at time of inspection
Valid Electrical Installation Condition Reports held on file? (Common Areas & General Needs Flats)	Yes
Comment	All checked and in date on ActiveH
Electrical App/PA Testing - tested within past 12 months?	N/A
Comment	None in communal area
Absence of trailing leads and adapters?	Yes
Comment	None seen at time of inspection
Evidence that mobility scooters are not being stored/charged in common areas?	Yes
Comment	None seen at time of inspection
Is there a purpose built mobility scooter store/charging area?	N/A

Asset ID: 9133

6 Piccadilly Road Block 6-6a Piccadilly Road, Burnley

Comment See above

Does the building have a lightning protection system? No

Comment Not required

Gas installations

Is there a commercial/domestic gas supply to the scheme? Yes

Comment Gas supply to flats

Valid LGSR held on file for fixed communal area gas appliances?
(Boilers) N/A

Comment No communal gas supply

Valid LGSR held on file for residential flats that contains gas
appliances? Yes

Comment All in date on ActiveH

Are smoke/heat detectors within General Needs flats subject to an
annual inspection and the results Yes

Comment Part of LGSC

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered
to? Yes

Comment Residents allowed to smoke in flats and external
areas

Adequate security against arson? No

Comment Front door unlocked at time of inspection

Are refuse/recycling bin areas managed and suitably located? Yes

Comment External

Are there communal cooking facilities at this scheme? No

Comment None in communal areas

Housekeeping

Are all electrical/intake/service cupboards secure and free from general
waste, contractors waste and residents personal items? No

Comment Recent installation of Gas meter preventing
cupboard doors

Are unnecessary accumulations of combustible materials or waste
avoided? No

Comment Vacuum cleaner stored in communal hallway

Are combustible materials and substances separated from ignition
sources and stored appropriately? Yes

Asset ID: 9133

6 Piccadilly Road Block 6-6a Piccadilly Road, Burnley

Comment

None seen at time of inspection

Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations?

N/A

Comment

None in communal area

Observation	Priority	Referred To	Required By:	Task ID
Meter cupboard doors are prevented from closing due to recent installation of new gas meter. Gas meter to be reinstalled to ensure cupboard fire doors can close into frame	Internal - Medium	Customer Safety Manager	30/09/2024	1853449



Observation	Priority	Referred To	Required By:	Task ID
Vacuum cleaner stored in communal area. Requires removing	Internal - Low	Housing Partner	30/09/2024	1853452



Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Yes

Comment

None seen at time of inspection

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of escape in case of fire?

Yes

Comment

Short distance from Flat to final exit

Escape routes unobstructed and safe to use?

Yes

Comment

No obstructions seen at time of inspection

Exits immediately openable without a key and/or failsafe's function correctly?

No

Comment

No thumbturn on final exit door

Reasonable distances of travel where there is a single/alternative direction of travel?

Yes

Comment

Under 7 m

Escape routes lead to final exits and open in direction of escape where necessary?

Yes

Comment

Final exit opens inwards but no issue due to occupancy level

Observation	Priority	Referred To	Required By:	Task ID
Key lock on main exit door. Change to thumbturn on internal side	Repair - Non Emergency	Project Manager (Building Safety)	30/09/2024	1853451



Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

No

Comment

No self closers on both Flat front doors

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?

Yes

Comment

Painted walls

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?

N/A

Comment

None fitted

As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?

Yes

Comment

Unable to gain access to roof spaces

Loft hatches fire resisting?

N/A

Comment

No loft hatch in communal area

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?

N/A

Comment

None fitted

Do external walls, doors, windows and anything attached to the exterior, limit fire spread?

Yes

Asset ID: 9133

6 Piccadilly Road Block 6-6a Piccadilly Road, Burnley

Comment Stone construction

If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available? N/A

Comment None fitted

Are roller shutter doors that are required to be FR, fire resisting and self-closing? N/A

Comment None fitted

Observation	Priority	Referred To	Required By:	Task ID
Self closers not fitted to both Flat doors	Repair - Non Emergency	Project Manager (Building Safety)	30/09/2024	1853450



Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per current standards? Yes

Comment Enough luminaries in communal area

Emergency lighting units in good condition and securely fixed to walls/ceilings? Yes

Comment No damage seen at time of inspection

Records of monthly/annual testing available? Yes

Comment Annual drop test 21st May 24
Monthly test 14th August 24

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas? Yes

Comment Checked

Directional fire escape signage in place and adequate? N/A

Comment One way out

Is there suitable LIFT signage i.e. do not use in case of fire? N/A

Comment No lift

Do common area fire doors display the correct signage on both sides where applicable? Yes

Comment Checked

Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm? Yes

Comment Zoned alarm system with communal detection

Is fire detection and warning system appropriate for occupancy and fire risk, as per BS 5839-1:2017? Yes

Comment

Is the fire detection and warning system maintained/tested and all certificates saved on file? Yes

Comment Tested 21st May 24

Fire alarm components in good condition and securely fixed to walls/ceilings? Yes

Comment No damage seen at time of inspection

Hold open devices operate at the sounding of the alarm and are in a serviceable condition? N/A

Comment None fitted

Are there heat detectors located in the Kitchen, Boiler, Plant Room and Laundry? N/A

Comment None in communal area

Is the fire alarm panel remotely monitored, and if so are there records of regular testing? No

Comment N/A

Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme? No

Comment Not required

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under the Building Safety Act? No

Comment Under 11m

Are there other Responsible Persons who share or have fire safety duties in respect of the premises? No

How will this sharing be achieved?

Is an office or IL scheme being inspected? No

Comment General needs flats

Passenger Lift

Is the scheme fitted with a passenger lift?

No

Comment

None fitted

Premises Inspection Box

Is there a premises information box for fire & rescue service use?

No

Comment

Not required

Evacuation Policy

Are there suitable arrangements for summoning the fire service?

Yes

Comment

999 by residents

Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance?

Yes

Comment

Full evacuation

Engagement with Residents

Has information of fire procedures been disseminated to residents?

Yes

Comment

By notice, website and Annual letter

Is general fire safety information disseminated to residents?

Yes

Comment

By letter annually

FRA Frequency

Taking the findings of this assessment into account, is the frequency of the FRA correct?

Yes

Comment

2 yearly

Miscellaneous

Are there any other observations/actions to raise that are not covered above.

No

Are there fire related remedial works required at this property, that will affect the fabric of the building?

No

Comment

Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).

No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW MEDIUM HIGH

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR MAJOR CRITICAL

The definition of the above terms is as follows:

FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trivial	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is: **Trivial**